MIL-S-3725E
2 November 1983
SUPERSEDING
MIL-S-3725D
27 October 1972

MILITARY SPECIFICATION

SHELTER HALF, TENT

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This document covers one type and size shelter half which is one half of a small tent. Two shelter halves, when joined, form a tent with both ends closable.

2. APPLICABLE DOCUMENTS

2.1 Government documents. Unless otherwise specified, the following documents of the issue in effect on date of invitation for bids or request for proposal, form a part of this document to the extent specified herein:

SPECIFICATIONS

FEDERAL

A-A-203	-	Paper, Kraft, Untreated
V-T-285	-	Thread, Polyester
CCC-C-419	-	Cloth, Duck, Cotton, Unbleached, Plied-Yarns
CCC-D-950	-	Dyeing and Aftertreating Processes for Cotton Cloths
DDD-L-20	-	Label: For Clothing, Equipage and Tentage (General Use)
PPP-B-636	-	Boxes, Shipping, Fiberboard

Beneficial comments, (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: US Army Natick Research and Development Center, Natick, MA 01760 by using the self-addressed Standardization Document Improvement Proposal (DD form 1426) appearing at the end of this document or by letter.

FSC 8340

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

MILITARY

MIL-P-501	-	Pins, Tent, Metal
MIL-P-608	-	Pole Section, Tent: Upright and Adapter, Tent Pole
MIL-L-1709	-	Lines, Tent
MIL-C-2399	-	Cement, Liquid, Tent Patching
MIL-F-10884	-	Fasteners, Snap
MIL-G-16491	-	Grommet, Metallic
MIL-R-30500	-	Rope, Polyester

STANDARDS

FEDERAL

FED-STD-751	-	Stitches, Seams, and Stitchings

MILITARY

MIL-STD-105	-	Sampling Procedures and Tables for Inspection by Attributes
MIL-STD-129	-	Marking for Shipment and Storage
MIL-STD-147	-	Palletized Unit Loads

DRAWINGS

U.S. ARMY NATICK RESEARCH AND DEVELOPMENT CENTER

5-4-29	-	Shelter Half, Tent; Illustration and Sections
5-4-30	-	Shelter Half, Tent; Details

(Copies of documents required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

* 2.2 Other publications. Unless otherwise specified, the following document of the issue in effect on date of invitation for bids or request for proposal, form a part of this document to the extent specified herein.

AMERICAN SOCIETY FOR TESTING AND MATERIALS (ASTM)

D 3951 - Standard Practice for Commercial Packaging

(Applications for copies should be addressed to the American Society for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

TABLE VI. General tests.

(Technical society and technical association documents are generally available for reference from libraries. They are also distributed among technical groups and using Federal agencies.)

* 2.3 Order or precedence. In the event of a conflict between the text of this document and the references cited herein, the text of this document shall take precedence.

3. REQUIREMENTS

3.1 Guide sample. Samples, when furnished, are solely for guidance and information to the contractor (see 6.3). Variations from this document may appear in the sample in which case this document shall govern.

3.2 First article. When specified a sample shall be subjected to first article inspection (see 4.3, 6.2 and 6.5).

* 3.3 Materials (see 6.6).

* 3.3.1 Cloth, duck, cotton. The cloth, before finishing, shall be 8.25 ounce per square yard conforming to type III of CCC-C-419.

* 3.3.1.1 Color and treatment. The 8.25 ounce cotton duck shall be dyed Olive Green 107 to match standard sample (see 6.3) and shall be water repellent and mildew resistant treated, conforming to type I, class B of CCC-D-950.

3.3.2 Thread, polyester. The thread for all stitching shall conform to type I, class 1, sub-class B of V-T-285. Size F shall be used for all stitching except size E shall be used for the looper of the type 401 stitching and for bartacking.

3.3.2.1 Color. The thread shall be dyed Olive Drab S-1, C.A. 66022, and shall show fastness to weathering equal to or better than the standard sample (see 6.3). If no standard sample is available, the thread shall show good fastness to weathering.

* 3.3.3 Lines, tent. The tent lines shall conform to MIL-L-1709. The guy line shall be type XIII and the footstops shall be type II. Alternatively, the lines may be polyester, conforming to MIL-R-30500. The finished requirements shall be as in MIL-L-1709.

3.3.4 Grommets. The grommets shall be type II, class 3, size No. 2J conforming to MIL-G-16491.

3.3.5 Fasteners, snap. The snap fasteners shall consist of a socket and stud-eyelet combination, conforming to style 2, finish 2, of MIL-F-10884. The stud-eyelet combination shall be size 1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

* 3.3.6 Pins, tent, metal. When required (see 6.2), five (5) tent pins conforming to type I of MIL-P-501 shall be included with the shelter half.

* 3.3.7 Pole section, tent. When required (see 6.2), three (3) tent poles conforming to item 1 sections of MIL-P-608 shall be included with the shelter half.

3.4 Construction. The construction shall conform in all respects to the drawings listed in Section 2 and as specified herein.

3.4.1 Shelter half body. The shelter half body shall be of single panel, two panel or three panel construction depending upon width of material furnished. When using two or three panel construction the panels shall be joined in accordance with the applicable method of section G-G of Drawing 5-4-30 or in accordance with section H-H of Drawing 5-4-29. Location of seam(s) is optional. Seams shall be vertical as shown on Drawing 5-4-30. The finished dimensions of the shelter half body prior to folding the ends shall be as shown on Drawing 5-4-30.

3.4.2 Shelter half doors. The doors shall be of single panel or two panel construction. For two panel construction the joining seam shall be in accordance with section D-D or H-H on Drawing 5-4-29. Location of seam is optional. Seam shall be vertical as shown on Drawing 5-4-30 . The finished dimensions of the shelter half doors prior to folding the edges shall be as shown on Drawing 5-4-30.

3.4.3 Stitching, machine. All stitching, except bartacks, shall conform to FED-STD-751 as follows:

For all stitching except stitching indicated by Z on drawings.	-	Type 301, 7 to 9 stitches per inch.
For all stitching indicated by Z on drawings.	-	Type 401, 7 to 9 stitches per inch.

3.4.3.1 Stitch margins. Unless otherwise specified, all stitching margins shall be 1/8 inch $\pm$ 1/16 inch.

3.4.3.2 Type 301 stitching. Ends of all stitching shall be backstitched or overstitched 1 inch minimum except where ends are turned under in a hem or held down by other stitching. Thread tension shall be maintained so that there will be no loose stitching resulting in loose bobbin or top thread, or excessively tight stitching resulting in puckering of the materials sewn. The lock shall be embedded in the materials sewn.

Source: https://assist.dla.mil -- Downloaded: 20261O-16T21:21Z
Check the source to verify that this is the current version before use.

3.4.3.2.1 Repairs of type 301 stitching. Repairs of type 301 stitching shall be as follows:

a. When thread breaks or bobbin run-outs occur during sewing, the stitching shall be repaired by restarting the stitching a minimum of 1 inch back of the end of the stitching. 1/

b. Thread breaks or two or more consecutive skipped or runoffs stitches noted during inspection of the item (in-process or end item) shall be repaired by overstitching. The stitching shall start a minimum of 1 inch in back of the defective area, continue over the defective area and continue a minimum of 1 inch beyond the defective area onto the existing stitching. Loose or excessively tight stitching shall be repaired by removing the defective stitching, without damaging the materials, and restitching in the required manner. 1/

1/ When making the above repairs the ends of the stitching are not required to be backstitched.

3.4.3.3 Type 401 stitching. Ends of stitching for joining the doors to the body, at the bottom edge of the shelter half, shall be secured with bartacks across the seams as shown on Drawing 5-4-29. Thread tension shall be maintained so that there will be no loose stitching. All repairs shall be in accordance with 3.4.3.2.1.a and 3.4.3.2.1.b. Repairs in type 401 stitching may be made using type 301 stitching. The chain portion of the stitching shall not appear on the outside of the shelter half.

3.4.3.4 Automatic stitching. Automatic machines may be used to perform any of the required stitch patterns provided the requirements for the stitch pattern, stitches per inch, size and type of thread are met, and at least three or more tying, overlapping or back stitches are used to secure the ends of the stitching.

3.4.3.5 Bartacks. Unless otherwise specified, bartacks shall be 1/2 $\pm$ 1/16 inch long, 1/8 $\pm$ 1/32 inch wide, and shall contain 28 stitches. Bartacks shall be free from thread breaks and loose stitching.

* 3.4.3.6 Lubrication of thread. There shall be no additional lubrication of the thread by any means prior to or during sewing other than that applied by the thread manufacturer at the time of manufacture (see 4.4.1.1).

3.4.3.7 Thread ends. All thread ends shall be trimmed to a length of not more than 1/4 inch.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

3.4.4 Attachment of guy line and footstops. The guy line shall be attached to either one of the guy line loops on the shelter half by passing the looped end through the loop on the shelter half and then passing the free end through the looped end of the line. Loops shall be pulled up tightly. The footstops shall be attached to the shelter half as shown on Drawing 5-4-29.

* 3.4.5 Setting of grommets . Holes punched to receive the grommets shall be smaller than the outside diameter of the grommet barrel so that the barrel must be forced through the hole. The grommets shall be securely clinched without cutting the material. Roll of the clinched grommet shall not contain more than three scores (splits).

* 3.4.6 Setting of snap fasteners. The snap fasteners shall be located as shown on the drawings with all studs on the outside and the sockets on the inside. If a hole is punched before inserting the barrel of the eyelet, it shall be smaller than the outside diameter of the eyelet barrel so that the barrel must be forced through the hole. The fasteners shall be securely clinched without cutting the material. The eyelet shall not contain more than three scores (splits).

3.4.7 Location marks. Location and notice marks shall not be drilled except for locating snap fasteners or grommets.

3.4.8 Repairs. In addition to the stitching repairs allowed in 3.4.3 a maximum of one hole or tear per shelter half may be repaired providing that the hole or tear does not exceed 1/2 inch in length or diameter; does not occur on a joining seam or on the peripheral edge; is not within one inch of the outer edge of a grommet or snap fastener, or the edge of a joining seam or hem. For "L" shaped tears the 1/2 inch dimension shall apply only to the longest length of the tear. The hole or tear shall be repaired as follows:

a. Place the damaged area over a flat surface with the outside surface of the shelter half facing up. (Outside surface is side with "US" marking.).

b. Prepare a circular patch of a size such that when centered on the hole or tear that it extends a minimum of 3/4 inch from the nearest edge of the hole or tear.

c. Prepare a circular template having a cutout 3/8 $\pm$ 1/16 inch larger in diameter than the patch. Center the template over the damaged area and mark off the circle using a ball point pen.

Source: https://assist.dla.mil -- Downloaded: 202610-16T21:21Z
Check the source to verify that this is the currentversion before use.

d. Coat the surface of the patch and the area to be patched that was marked off with the template with cement conforming to MIL-C-2399. The cement shall be evenly and smoothly applied and shall be worked well into the fabric. Allow the cement to dry to a gummy state and apply a second coat to the same surfaces.

NOTE: As an option, in lieu of using the template for marking off the area to be coated with cement the template may be held in position and the cement applied to the area within the circle.

e. With the cement still wet, position the patch centrally over the cemented area on the shelter half and press the cemented surfaces together. Roll excess cement and air bubbles from under patch with a roller.

f. Complete the repair by sealing the edge of the patch all around with the tip of a finger or by using an appropriate tool.

3.5 Marking. The identification marking shall be applied in the location shown on the drawing and shall conform to type IV, class 5 of DDD-L-20. The letters "US" shall be applied in the location and in the size characters indicated on the drawing and shall conform to type IV, class 9 of DDD-L-20. Fastness of the class 9 marking shall be as specified for class 5 marking.

3.6 Workmanship . The finished shelter half tent shall conform to the quality established by this document. The occurrence of defects shall not exceed the applicable acceptable quality levels.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in the document where such inspections are deemed necessary to assure supplies and services conform to prescribed requirements.

4.1.1 Certificate of compliance. Where certificates of compliance are submitted, the Government reserves the right to check test such items to determine the validity of the certification.

* 4.2 Classification of inspection. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).
b. Quality conformance inspection (see 4.4).

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

* 4.3 First article inspection. When a first article is required (see 6.2), it shall be examined for the defects specified in 4.4.3 and 4.4.4. The presence of any defects shall be cause for rejection of the first article.

4.4 Quality conformance inspection. Unless otherwise specified, sampling for inspection shall be performed in accordance with MIL-STD-105.

4.4.1 Component and material inspection. In accordance with 4.1, components and materials shall be inspected in accordance with all the requirements of referenced documents, unless otherwise excluded, amended, modified, or qualified in this document or applicable purchase documents.

4.4.1.1 Certification. The contractor shall furnish a certificate of compliance for the requirement of 3.4.3.6 prohibiting the use of additional thread lubricants prior to or during sewing.

4.4.2 In-process inspection. Inspection of sub-assemblies shall be made to ascertain that construction details which cannot be examined in the finished product are in accordance with specified requirements. The Government reserves the right to exclude from consideration for acceptance any material or service for which in-process inspection has indicated nonconformance.

* 4.4.3 End item visual examination. The end item shall be examined for the defects listed below. The lot size shall be expressed in units of shelter half tents. The sample unit shall be one completely fabricated shelter half tent or one completely fabricated shelter half with pins and poles, as specified (see 6.2). The inspection level shall be II and the acceptable quality level (AQL), expressed in terms of defects per hundred units, shall be 2.5 for major defects and 15.0 for total (major and minor combined) defects.

Examine	Defect	Classification Major	Minor
Cloth	Any hole, cut, or tear.	X	
	Any abrasion marks, broken or missing yarns, or multiple floats clearly visible at normal inspection distance (approximately 3 feet).	X	
	Needle chews:		
	- Any (Except on guy line loops).	X	
	- On guy line loops, up to 1/8 inch in length.		X
	- On guy line loops, more than 1/8 inch in length.	X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

Examine	Defect	Classification Major	Minor
Hardware, general	Broken or malformed; corroded areas; burrs or sharp edges.	X	
	Finish omitted or not as specified.	X	
Snap fasteners	Clinched excessively tight, cutting surrounding material.	X	
	Clinched loosely, permitting either component to rotate freely in the hole in the material or permitting separation of components.	X	
	Any snap fastener reversed.	X	
	Incorrect style.	X	
	Number of snap fasteners more or less than specified.	X	
	Three or more scores (splits) in any one eyelet.		X
Grommets	Clinched excessively tight, cutting surrounding material.	X	
	Improperly set, i.e., two or more teeth exposed inside of barrel, clinched loosely permitting grommet to rotate in hole or insecurely clinched such that grommet and washer become disengaged.	X	
	Size or type not as specified.	X	
	Washer installed on incorrect side of material.		X
	Grommet barrel split.		X
	Roll of a grommet contains more than three scores (splits).		X
Tent pins	Not type specified (when specified in 6.2).	X	
	Not quantity required (when specified in 6.2).	X	
Tent pole sections	Not type specified (when specified in 6.2).	X	
	Not quantity required (when specified in 6.2).	X	

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

Examine	Defect	Classfication Major	Minor
Seams and stitching:			
Open seams (on stitch types 301 and 401)	Up to and including 1/2 inch.		X
	More than 1/2 inch.	X	
	Any seam open on both rows of stitching.	X	
NOTE:	A seam shall be classified as an open seam when one or more stitches joining a seam are broken, or when two or more consecutive skipped or run-off stitches occur. On double stitched seams, a seam shall be considered open when either one or both sides of the seam are open.		
Raw edges (except where required)	More than 1/2 inch when securely caught in stitching.		X
NOTE:	Raw edges not securely caught in stitching shall be classified as open seams.		
Seam and stitch type	Wrong seam or stitch type.	X	
	Seams pleated or badly puckered.		X
Stitch tension	Tension loose, resulting in loose bobbin or top thread.		X
	Tension tight, resulting in puckering of material.		X

Source: https://assist.dla.mil -- Downloaded: 202610-16T21:21Z
Check the source to verify that this is the currentversion before use.

Examine	Defect	Classification Major	Classification Minor
Seams and stitching: (cont'd)			
Stitches per inch	One or two stitches less than minimum specified.		X
	Three or more stitches less than minimum specified.	X	
	One or more stitches in excess of maximum specified.		X
NOTE:	(1) Variation in the number of stitches per inch caused by operator speeding up the machine and pulling the material in order to sew over heavy places, or in turning corners shall be classified as follows:		
	(a) Within the minor defect classification - No defect.		
	(b) Within the major defect classification - Minor defect.		
	(2) Except for stitching for forming tucks in ridge, defects are to be scored when condition exists on any one seam for a length of 3 inches or more or when the combined length of several areas exceeds 6 inches.		
Thread breaks, skipped stitches or run-offs	Overstitched less than 1 inch in each direction beyond the defective stitching area.		X
NOTE:	Thread breaks or two or more consecutive skipped or run-off stitches not overstitched shall be classified as open seams.		

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

Examine	Defect	Classification Major	Minor
Seams and stitching: (cont'd)			
Stitching ends (on type 301 stitching)	Ends of stitching not secured as specified (except when caught in other stitching or turned under in a hem).		X
Stitching indicated by Z on drawings (Type 401 stitching)	Chain portion of stitching on outside of shelter half.		X
Rows of stitching	Any row missing.	X	
Bartacks	Any bartack misplaced causing end of any row of type 401 stitching to be not secured.	X	
	Any bartack omitted.	X	
	Stitching loose, incomplete, or broken.		X
	Number of stitches not as specified.		X
Components and assembly	Any required component or operation omitted, (unless otherwise classified herein).	X	
Door panels	Ridge corner not formed, i.e., intersection of door and body panels at ridge not formed and stitched with triangular stitch pattern as required.	X	
Loops for guy lines	Raw edge at end not turned under at assembly.		X
Guy line	Cut, chafed, or abraded.	X	
	Not attached to loop as specified.		X
Footstops	Cut, chafed, or abraded.	X	
	Not attached as specified.		X

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

Examine	Defect	Classification Major	Minor
Patching	Patch not firmly adhered, located in unauthorized area or on wrong side; more than one patch.	X	
	Cement not extended beyond edge of patch.		X
Grommet reinforcement	Mis-located, i.e., grommet not through reinforcement around entire periphery (check by feel).		X
	When using optional construction raw edge exposed along top edge.		X
Identification marking	Omitted, incorrect, illegible, misplaced, or size of characters not as specified.		X
Cleanness	Grease, ink, or oil stains clearly noticeable.		X
	Thread ends not trimmed throughout as specified.		X

* 4.4.4 End item dimensional examination. The end item shall be examined for conformance to defects listed below. The lot size shall be expressed in units of shelter half tents. The sample unit shall be one completely fabricated shelter half tent. The inspection level shall be S-3 and the AQL, expressed in terms of defects per hundred units, shall be 4.0 for major defects and 10.0 for total (major and minor combined) defects.

Examine	Defect	Classification Major	Minor
Overall dimensions	Smaller than nominal dimensions, less applicable minus tolerance indicated on drawings, but not smaller than nominal dimensions less twice the applicable minus tolerance.		X

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

Examine	Defect	Classification Major	Classification Minor
Overall dimensions (cont'd)	Smaller than nominal dimensions, less twice the applicable minus tolerance.	X	
	Larger than nominal dimensions and applicable plus tolerance.	X	
Snap fasteners	Snap fasteners misplaced by more than applicable tolerance but not more than twice applicable tolerance:		
	(1) One or two fasteners.		X
	(2) Three or more fasteners.	X	
	Any snap fastener misplaced by more than twice the applicable tolerance.	X	
Door and body joining seams (applicable individual seam, top or bottom)	Edges of door(s) and body at top or bottom of joining seams not finished even:		
	(1) By more than 3/8 inch, but not more than 1/2 inch.		X
	(2) By more than 1/2 inch.	X	
Patch	Patch not specified size overlapping damaged area:		
	(1) Less than 3/4 inch, but not less than 3/8 inch.		X
	(2) Less than 3/8 inch.	X	
	NOTE: Size of patch relative to damaged area to be checked from opposite side except when patch is located on opposite side of hemmed edges.		
All other dimensions not classified herein including stitch margin or gage	Any not within specified tolerance.		X
	NOTE: Stitch margin or gage defects shall be scored only when condition exists on major portion of the seam.		

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

* 4.4.5 Packaging inspection. An examination shall be made to determine that preservation, packing, and marking comply with the section 5 requirements. Defects shall be scored in accordance with the list below. The sample unit shall be one shipping container fully packaged except that it need not be closed. Examination for closure defects listed below shall be made on shipping containers fully packaged. The lot size shall be the number of shipping containers in the inspection lot. The inspection level shall be S-2 and the AQL, expressed in terms of defects per hundred units shall be 2.5.

Examine	Defect
Marking (exterior)	Omitted; incorrect; illegible; of improper size, location, sequence, or method of application.
Materials	Any component missing, damaged, or not as specified.
Workmanship	Inadequate application of components, such as: incomplete closure of container flaps, improper taping, loose strapping or inadequate stapling. Bulged or distorted container.
Content	Number per container is more or less than required.

4.4.6 Inspection for palletization. An inspection shall be made to determine that the palletization complies with the section 5 requirements. Defects shall be scored in accordance with the list below. The sample unit shall be one palletized unit load fully packaged. The lot size shall be the number of palletized unit loads in the inspection lot. The inspection level shall be S-1 and the AQL, expressed in terms of defects per hundred units, shall be 6.5.

Examine	Defect
Finished dimensions	Length, width, or height exceeds specified maximum requirements.
Palletization	Pallet pattern not as specified. Interlocking of loads not as specified. Load not bonded with required straps as specified.
Weight	Exceeds maximum load limits.
Marking	Omitted; incorrect; illegible; of improper size location, sequence, or method of application.

Source: https://assist.dla.mil -- Downloaded: 202610-16T21:21Z
Check the source to verify that this is the currentversion before use.

5. PACKAGING

* 5.1 Preservation. Preservation shall be level A or Commercial as specified (see 6.2).

5.1.1 Level A.

* 5.1.1.1 Shelter half. Each shelter half shall be laid out flat with the guy line attached and placed toward the center. The triangular ends shall be folded to the center forming a rectangle. The top and bottom edges shall be folded over to meet at the center and then folded in half, covering the fasteners, to approximately 14-1/2 inches. The shelter half shall then be folded into eighths by folding the two side edges to the center, then in half, edge to edge, twice, resulting in dimensions of approximately 14 by 10 by 3-1/2 inches.

* 5.1.1.2 Shelter half with tent pins and poles. When procured as a complete assembly (see 6.2), the shelter half tent shall be folded as specified in 5.1.1. Three tent pole sections, as specified in 3.3.7 shall be wrapped in 30 pounds basis weight kraft paper, approximately 36 by 18 inches, conforming to A-A-203 and placed next to the folded shelter half adjacent to the longest dimension. Five tent pins, as specified in 3.3.6 shall be wrapped in a sheet of 50 pound basis weight kraft paper, approximately 36 by 18 inches, conforming to A-A-203 and placed next to the folded shelter half along the shorter end. Each shelter half assembly shall then be placed within a one-piece folder conforming to PPP-B-636, type CF, class domestic, variety SW, grade 125. The approximate inside dimensions of the box shall be 16 inches in length, 10-1/2 inches in width and 3-1/2 inches in depth. Each box shall be closed in accordance with method II of the appendix of PPP-B-636.

* 5.1.2 Commercial. Each shelter half or shelter half with tent pins and poles, shall be preserved in accordance with ASTM D 3951.

5.2 Packing. Packing shall be level A, B, or Commercial as specified (see 6.2).

* 5.2.1 Level A packing.

* 5.2.1.1 Shelter half. Twelve shelter halves, preserved as specified in 5.1 shall be packed in a snug-fitting fiberboard shipping container, conforming to style RSC-L, grade V2s of PPP-B-636. The inside of each shipping container shall be fitted with a box liner conforming to type CF, class weather-resistant, variety DW, grade V15c of PPP-B-636. Level A unit packs shall be packed flat, two in depth, six in height, alternately reversed within a shipping container. Inside dimensions of each container shall approximate 14 inches in length, 10 inches in width and 21 inches in depth. Approximate dimensions are furnished as a guide only. Each container shall be closed in accordance with method V as specified in the appendix of PPP-B-636.

Source: https://assist.dla.mil -- Downloaded: 202640-16T21:21Z
Check the source to verify that this is the currentversion before use.

* 5.2.1.2 Shelter half with tent pins and poles. When procured as a complete assembly (see 6.2) twelve shelter halves, preserved as specified in 5.1, shall be packed in a snug-fitting fiberboard shipping container conforming to style RSC, type SF, class weather-resistant of PPP-B-636. Level A unit packs shall be packed flat, two in depth, and six in height within a shipping container. Inside dimensions of each container shall approximate 22 inches in length, 16 inches in width, and 15 inches in depth. Approximate dimensions are furnished as a guide only. Each container shall be closed in accordance with method V as specified in the appendix of PPP-B-636.

5.2.2 Level B packing.

* 5.2.2.1 Shelter half. Twelve shelter halves, preserved as specified in 5.1, shall be packed in a snug-fitting shipping container conforming to style RSC-L, type CF (variety SW) or SF, class domestic, grade 275 of PPP-B-636. The inside of each shipping container shall be fitted with a box liner conforming to type CF, class domestic, variety DW, grade 275 of PPP-B-636. Level A unit packs shall be packed flat two in depth, six in height, alternately reversed within a shipping container. Inside dimensions of each container shall approximate 14 inches in length, 10 inches in width and 21 inches in depth. Approximate dimensions are furnished as a guide only. Each shipping container shall be closed in accordance with method V as specified in the appendix of PPP-B-636.

* 5.2.2.2 Shelter half with tent pins and poles. When procured as a complete assembly (see 6.2) twelve shelter halves, preserved as specified in 5.1, shall be packed in a snug-fitting fiberboard shipping container conforming to style RSC, type CF (variety SW) or SF, class domestic, grade 275 of PPP-B-636. Inside dimensions of each container shall approximate 22 inches in length, 16 inches in width and 21 inches in depth. Approximate dimensions are furnished as a guide only. Level A unit packs shall be packed flat, two in depth and six in height. Each shipping container shall be closed in accordance with method V as specified in the appendix of PPP-B-636.

* 5.2.3 Commercial. Shelter halves, preserved as specified in 5.1, shall be packed in accordance with ASTM D 3951.

5.3 Palletization. When specified (see 6.2), shelter halves packed as specified in 5.2, shall be palletized in accordance with load type I of MIL-STD-147. The pallet pattern shall be in accordance with the appendix of MIL-STD-147. Interlocking of loads shall be effected by reversing the pattern of each course. Each prepared load shall be bonded with primary and secondary straps in accordance with bonding means K and L.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

* 5.4 Marking. In addition to any special marking required by the contract or purchase order, unit packs and shipping containers and palletized unit loads shall be marked in accordance with MIL-STD-129 or ASTM D 3951, as applicable.

6. NOTES

6.1 Intended use. The shelter half may be used by itself as a fly for shade and shelter or when joined together with another shelter half provides a shelter for two men. Snap fasteners are provided to join the shelter halves.

* 6.2 Ordering data. Acquisition documents should specify the following:

(a) Title, number and date of this document.
(b) When a first article sample is required (see 3.2, 4.3 and 6.5).
(c) Selection of the applicable levels of preservation and packing (see 5.1 and 5.2).
(d) When palletization is not required (see 5.3).
(e) When pins and poles are required (see 3.3.6, 3.3.7, 4.4.3, 5.1.1.2, 5.2.1.2 and 5.2.2.2).

6.3 Samples. For access to samples address the contracting activity issuing the invitation for bids.

6.4 Components. The following components, ordered with the shelter half or issued in the field, are required to erect the shelter half tent:

5 each pin, tent, aluminum, 9-inch.
3 each pole, tent, single section.

6.5 First article. When a first article is required, it shall be inspected and approved under the appropriate provisions of DAR 7-104.55. The first article should be a preproduction sample. The first article should consist of one complete shelter half, tent. The contracting officer should include specific instructions in all acquisition instruments regarding arrangements for inspection and approval of the first article.

* 6.6 Recycled material. It is encouraged that recycled material be used when practical as long as it meets the requirements of the document (see 3.3).

6.7 Changes from previous issue. The margins of this document are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous issue were made. This was done as a convenience only, and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

6.8 International standardization agreements. Certain provisions of this document are the subject of international standardization agreement as cited in NATO, STANAG NO. 2882, relative to camouflage requirements for tents, shelters and subsidiary components. When amendment, revision, or cancellation of this document is proposed which will affect or violate the international agreement concerned, the preparing activity will take appropriate reconciliation action through international standardization channels including departmental standardization offices, if required.

Custodians:

Army - GL
Navy - NU
Air Force - 99

Preparing activity:

Army - GL

Project No. 8340-0444

Review activities:

Army - MD
Air Force - 32

User activities:

Navy - YD, MC
Air Force - 45
DLA - CT

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY
US Army Natick Research and Development Center
Natick, Massachusetts 01760

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300
DRDNA-ES

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

Commander
US Army Natick Research and Development Center
ATTN: DRDNA-ES
Natick, MA 01760

Source: https://assist.dla.mil -- Downloaded: 2026-10-16T21:21Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-S-3725E	Shelter Half, Tent

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ USER
	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

DD FORM 82 MAR 1426 PREVIOUS EDITION IS OBSOLETE.

NATICK OP, 1 APR 83

Source: https://... 2640-16T21:21Z
Check the source to verify that this is the current version before use.