MILITARY SPECIFICATION

ANTENNA GROUP, OE-82(C)/WSC-1(V)

This amendment forms a part of Military Specification MIL-A-28865(EC), dated 11 September 1981, and is approved for use by the Naval Electronic Systems Command, Department of the Navy, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title: Delete and substitute: "Antenna Group, OE-82(C)/WSC-1(V)".

1.1, line 2: Delete "OE-82( )/WSC-1(V)" and substitute "OE-82(C)/WSC-1(V)".

2.1, "SPECIFICATIONS", "MILITARY": Delete "MIL-A-8625 Anodic Coatings, For Aluminum And Aluminum Alloys" and delete "MIL-S-8660 Silicone Compound".

2.1, "SPECIFICATIONS", "MILITARY", after "MIL-S-901", add:

"MIL-C-5541 Chemical Conversion Coatings In Aluminum And Aluminum Alloys".

2.1, "SPECIFICATIONS", "MILITARY", after "MIL-P-24441", add:

"MIL-C-26074 Coating, Electroless Nickel, Requirements For".

2.1, "SPECIFICATIONS", "MILITARY", after "MIL-C-28838", add:

"MIL-S-46163 Sealing, Lubricating, And Wicking Compounds, Thread Locking, Anaerobic, Single Component".

PAGE 2

2.1, "STANDARDS", "MILITARY": Delete "MIL-STD-118-114" and substitute "MIL-STD-188-114".

PAGE 3

3.1.1.1, line 2: Delete "3.1.1.1.11" and substitute "3.1.1.1.12".

3.1.1.1.8, line 2, after last sentence: Add "Hybrid mounting holes shall contain inserts and shall be sealed with a polysulfide sealant.".

PAGE 4

3.1.1.1.11: Delete the text and substitute: "The element base shall be anodized in accordance with MIL-C-5541, Class 3. The element hybrid assembly shall be sealed with a polysulfide type sealant."

3.1.1.2, line 2: Delete "3.1.1.2.14" and substitute "3.1.1.2.15".

PAGE 5

After "3.1.1.2.14", add the following new paragraph:

"3.1.1.2.15 Bearing gear assembly. Bearing gear assembly shall be electroless nickel plated in accordance with MIL-C-26074, Grade A (0.001 inch thickness).".

3.1.1.7, line 6: Delete "3.5.1.6" and substitute "3.5.1.8".

3.1.1.10: Delete.

3.1.1.11: Delete and substitute:

"3.1.1.11 Thread locking. Thread locking compound as specified in MIL-S-46163, Type II, shall be applied to the threads of every screw used to mount antenna subassemblies.".

FSC 5985

Source: https://assist.dla.mil - Downloaded: 2026-10-20T20:13Z
Check the source to verify that this is the current version before use.

PAGE 7

3.1.1.3, line 2: Delete "3.1.1.3.7" and substitute "3.1.1.3.8".

PAGE 8

3.1.1.3.4.2: Delete the text and substitute: "The switching time shall be not greater than 25 ms.".

After "3.1.1.3.7", add the following new paragraph:

"3.1.1.3.8 Relief valve. A relief valve shall be incorporated for use with the dry air system. The relief valve shall be set at a maximum of 10 psig. The valve shall be fed off a tee inside the SA-2000 and shall be mounted in the bulkhead of the SA-2000 in such a way as to vent excess air to the exterior of the switching unit.".

PAGE 12

3.3, line 2: Delete "and 3.3.2.".

PAGE 14

3.7, line 2: Delete "3.7.4" and substitute "3.7.9".

After "3.7.4", add the following new paragraphs:

"3.7.5 Safety criteria. The antenna group design shall conform to the safety criteria requirements specified in 3.7.5.1 through 3.7.5.3.

"3.7.5.1 Critical controls. Critical controls, the accidental activation of which may cause damage to the antenna group, injury to personnel or degradation of system function, shall be designed and located so that the controls are not susceptible to being moved accidentally.

"3.7.5.2 Noise, hearing conversation. Sound levels produced by the antenna group shall not exceed an A-weighted sound pressure level of 80 dB.

"3.7.5.3 Weight marking. Antenna group components weighing in excess of 35 pounds shall have the weight clearly marked on the external surface of the antenna group and readily visible during installation and removal. The marking shall be as permanent as the normal life expectancy of the unit to which is is applied.

"3.7.6 Antenna group accessibility. Exterior doors, hinged covers, and slide drawers shall have automatic latch/quick release devices which must be actuated before they can be opened, and stops to lock them in the open position for each maintenance configuration. Design shall be such that sufficient clearance is provided in each maintenance configuration to allow required tasks to be performed without undue discomfort, danger, or effort.

"3.7.7 Electrical cable protection. Antenna group design shall preclude damage to electrical cabling during all conditions of assembly, removal, insertion, and tilting of the antenna group.

"3.7.8 Printed circuit assembly protection. With power applied to the antenna group, removal or insertion of printed circuit assemblies shall not damage the assembly or any other part of the antenna group. Each assembly shall be keyed to prevent incorrect insertion.

"3.7.9 Power supply protection. Fault conditions ranging from open circuits shall cause no damage to the power supply.".

PAGE 15

After 4.2c, add:

"d. Safety verification (see 4.5.8)"

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T20:13Z
Check the source to verify that this is the current version before use.

PAGE 16

Table IV: Add the following new entry:

"Safety verification 3.7.5 4.5.8 6.5".

PAGE 17

4.5.1, line 2: Delete "4.5.6" and substitute "4.5.8".

4.5.6, line 2: Delete "3.5.1.10" and substitute "3.5.1.14"; line 5: Delete "3.5.1.9" and substitute "3.5.1.13".

After "4.5.7", add the following new paragraph:

"4.5.8 Leakage current. Leakage current shall be measured on one unit of the first month's production. Thereafter, leakage current shall be measured on one unit per 100 successive units produced.".

PAGE 20

6.2d and e: Delete "(see 4.5.5)" and substitute "(see 4.5.6)".

Preparing activity:
NAVY-EC

(Project 5985-N508(EC))

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T20:13Z
Check the source to verify that this is the current version before use.