MIL-S-28867(EC)
AMENDMENT 2
14 November 1983
SUPERSEDING
AMENDMENT 1
25 August 1983

MILITARY SPECIFICATION

SWITCH, FREQUENCY STANDARD, SA-2424/W

This amendment forms a part of Military Specification MIL-S-28867(EC), dated 2 October 1981 and is approved for use by the Naval Electronic Systems Command, Department of the Navy, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title and throughout the specification: Delete "transfer".

Title, after "STANDARD", add ", SA-2424/W".

PAGE 2

2.1.1, "STANDARDS", "MILITARY": Delete "MIL-STD-781 Reliability Design Qualification and Production Acceptance Tests: Exponential Distribution".

After "MIL-STD-1472", add:

"HANDBOOK

"MILITARY

"MIL-HDBK-472 Maintainability Prediction"

PAGE 4

* FIGURE 2: Delete and substitute the attached new FIGURE 2.

PAGE 5

* FIGURE 3: Delete and substitute the attached new FIGURE 3.

PAGE 7

* 3.2.1.6, line 2: Delete "0.1 dB" and substitute "0.5 dB".

PAGE 8

* TABLE I, under the "Junction Box" column: Delete "J-30" and substitute "J-29 (A and B)".

PAGE 9

* TABLE I, under the "Junction Box" column: Delete "J-29-1", "J-29-2", "J-29-3", and J-29-4" and substitute: "J-29-C", "J-29-D", "J-29-E", and "J-29-F".

PAGE 10

* FIGURE 5: Delete and substitute the attached new FIGURE 5.

PAGES 11, 12, and 13

* FIGURE 6: Delete and substitute the attached new FIGURE 6.

PAGE 14

* TABLE II: Delete and substitute the attached new TABLE II.

Source: https://assist.dla.mil -- Downloaded: 20260410-20T20:14Z
Check the source to verify that this is the current version before use.

PAGE 15

3.2.3 and 3.2.3.1: Delete.

PAGE 16

3.2.5.7: Delete.

3.3.2, line 2: Delete "RE02, electric field radiated emissions, when carrying working level signals" and substitute "RS02 and RS03.".

PAGE 18

4.4.1, first sentence: Delete and substitute: "Except for workmanship screen, production inspection shall be performed on every equipment offered for delivery."

4.4.1: Add as a second sentence: "Workmanship screen shall be performed on two equipments out of the first 12 produced. Thereafter, workmanship screen shall be performed on one equipment out of every 10 equipments produced. Should a failure occur, all equipments of the 12 and 10 equipments lots shall be corrected."

PAGE 19

TABLE IV, "Reliability": Delete entry in its entirety.

TABLE IV, "Thermal test": Delete entry in its entirety.

PAGE 20

4.6.5.1, lines 1 and 2: Delete "on each equipment".

PAGE 21

4.6.5.2, line 1: Delete "Each".

4.6.7: Delete.

PAGE 23

FIGURE 9: Add "or equivalent" after "O-1695 #1".

FIGURE 10: Add "or equivalent" after "O-1695 #1" and "O-1695 #2".

PAGE 24

* 4.6.10.4, line 2: Delete "0.1 dB" and substitute "0.5 dB".

PAGE 25

4.6.10.6, title: Delete "ower" and substitute "Power".

4.6.11: Delete last two sentences and substitute: "The test for RS03 shall be from 2 MHz to 30 MHz at 10 V per meter."

4.7: Delete.

4.8: Delete the text and substitute: "The maintainability requirements of 3.2.4 shall be verified in accordance with Procedure II of MIL-HDBK-472."

Source: https://assist.dla.mil -- Downloaded: 20260-20T20:14Z
Check the source to verify that this is the current version before use.

6.2.2: Delete:

"4.6.7	Report, Thermal Survey	DI-R-7036
4.7	Reports, Reliability Test and Demonstration	DI-R-7034
4.7	Procedures, Reliability Tests	DI-R-7035".

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Preparing activity:
NAVY - EC

(Project No. 6625-N817(EC))

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T20:14Z
Check the source to verify that this is the current version before use.





FIGURE 2. Relay box wiring d



cam.

Source: https://assist.dla.mil -- Downloaded: 202610-20T20:14Z
Check the source to verify that this is the current version before use.





FIGURE 3. Transfer switch enclosures.


Source: https://assist.dla.mil -- Downloaded: 2026-10-20T20:14Z
Check the source to verify that this is the current version before use.



REF. DES.	DESCRIPTION	PART NUMBER
K1	RELAY, BREAK BEFORE MAKE	T-BAR 931-36CG-28-3-MS OR EQUIVALENT
S1	SWITCH, SPST, NORMALLY OPEN	MS23308 - 222
L1	INDICATOR GREEN	LH73/1, LC12GN
L2	INDICATOR YELLOW	LH73/1, LC12YN
J1/P1	CONNECTOR	MS27486E11B98P & MS27487T11B98S & MS27506B-10-2
J2/P2	CONNECTOR	MS27486E11B98PC & MS27487T11B98SC & MS27506B-10-2

FIGURE 5. Remote control unit wiring diagram.

Source: https://assist.dla.mil -- Downloaded: 20260-20T20:14Z
Check the source to verify that this is the current version before use.



NOTES:
1. 1 PPS OUTPUT ON REAR NOT PRESENTLY AVAILABLE.
2. / - NORMALLY CLOSED CONTACT.
   X - NORMALLY OPEN CONTACT.

FIGURE 6. Transfer switch interconnection wiring diagram (sheet 1).

Source: https://assist.dla.mil -- Downloaded: 20260-20T20:14Z
Check the source to verify that this is the current version before use.





FIGURE 6. Transfer switch interconnection wiring diagram (sheet 2). - Continued

Source: https://assist.dla.mil Downloaded: 2026-10-20T20:14Z
Check the source to verify that this is the current version before use.



Source: https://assist.dla.mil -- Downloaded: 202610-20T20:14Z
Check the source to verify that this is the current version before use.

FIGURE 6. Transfer switch interconnection wiring diagram (sheet 3). - Continued

TABLE II. Connector types.

FREQUENCY STANDARD				RELAY BOX				
J	CONN.	P	CONN.	J	CONN.	P	CONN.	REMARKS
32	AMPH. 31-357-1022*	32	AMP 2-392082-2*	2	AMP 2-330063-1*	2	AMP-2-392082-2*	BNC
30	MS3452W10SL-3P	30	MS3456W10SL-3S &	1	MS3452W10SL-3P	1	MS3456W10SL-3S &	3 PINS
21	MS3452W10SL-4P		M85049/52-1-10-A	4	MS3452W10SL-4P		M85049/52-1-10-A	
31	AMPH. 31-357-1022*	21	MS3456W10SL-4S &	3	AMP 2-330063-1*	4	MS3456W10SL-4S	2 PINS
TBD	MS3452W10SL-4P		M85049/52-1-10-A	30	MS3452W10SL-4P		M80549/52-1-10-A	
29	MS3452W10SL-3P	31	AMP 2-392082-2*	25	MS3452W10SL-3P	3	AMP 2-392082-2*	BNC
28	MS3452W10SL-3P	TBD	MS3456W10SL-4S	26	MS3452W10SL-3P	30	MS3456W10SL-4S &	2 PINS
20	MS3452W10SL-4P		M85049/52-1-10-A	27	MS3452W10SL-4P		M85049/52-1-10-A	
27	MS3452W10SL-4P	29	MS3456W10SL-3S	28	MS3452W10SL-4P	25	MS3456W10SL-3S &	3 PINS
24	M81511/21EB02S1		M85049/52-1-10-A	29	MS3402D-18-1P		M85049/52-1-10-A	
		28	MS3456W10SL-3S &	31	MS27496E11B98PC	26	MS3456W10SL-3S &	3 PINS
			M85049/52-1-10-A	5,6	AMP 2-330063-1*		M85049/52-1-10-A	
		20	MS3456W10SL-4S	7,8	AMP 2-330063-1*	27	MS3456W10SL-4S &	2 PINS
			M85049/52-1-10-A	9,10	AMP-2-330063-1*		M85049/52-1-10-A	
		27	MS3456W10SL-4S &	11,12	AMP 2-330063-1*	28	MS3456W10SL-4S &	2 PINS
			M85049/52-1-10-A	13,14	AMP 2-330063-1*		M85049/52-1-10-A	
		24	M81511/26EB02P1	15,16	MS27496E11B98P	29	MS3406D-18-1S &	5 PINS
				17,18	MS27496E11B98P		MS3437B-25A	
				19,20	MS27496E11B98PA	31	MS27467T11B98SC	
				21,22	MS27496E11B98PB		MS27506B-10-2	
				23,24	M28840/10AA1G1	5,6	AMP 2-392082-2*	BNC
						7,8	AMP 2-392082-2*	BNC
						9,10	AMP 2-392082-2*	BNC
						11,12	AMP 2-392082-2*	BNC
						13,14	AMP 2-392082-2*	BNC
						15,16	MS27467T11B98S &	3 PINS
							MS27506B-10-2	
						17,18	MS27467T11B98S &	3 PINS
							MS27506B-10-2	
						19,20	MS27467T11B98S &	3 PINS
							MS27506B-10-2	
						21,22	MS27467T11B98SB &	3 PINS
							MS27506B-10-2	
						23,24	M22840/16AA1F1	7 PINS

Source: https://assist.dla.mil -- Downloaded: 2026-02-20T20:14Z
Check the source to verify that this is the current version before use.

TABLE II. Connector types. (Continued)

	REMOTE CONTROL UNIT				PP-7398/WRR-7			
J	CONN.	P	CONN.	J	CONN.	P	CONN.	
1 2	MS27496E11B98P MS27496E11B98PC	1 2	MS27467T11B98S & MS27506B-10-2 MS27467T11B98SC & MS27506B-10-2	20	MS3452W108L-3P	20	MS3456W10SL-3S & M85049/52-1-10-A	

* Or equal

Source: https://assist.dla.mil -- Downloaded: 2026/10-20T20:14Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T20:14Z
Check the source to verify that this is the current version before use.