MILITARY SPECIFICATION

ACTIVATOR, ANTITANK MINE: PRACTICE, M1;
PARTS FOR AND LOADING, ASSEMBLING AND PACKING

This amendment forms a part of Military Specification MIL-A-63529(AR), dated 2 February 1982, and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

4.3.1: Delete the following:

"Cup, Closing	9340720	10"
"Cup, Igniter	9340721	10"
"Igniter Cup Assembly	9340722	10"

PAGE 5

Delete all references to the following:

Cup, Closing; Cup, Igniter; Igniter Cup Assembly (items deleted from the package).

In the "Paragraph Reference" column, change "4.4.2.8" to "4.4.2.5".

PAGE 7

4.4.2.1: Defect No. 201: Delete "Color ... Visual".

Change defect numbers "202" and "203" to "201" and "202", resp.

PAGE 11

4.4.2.5: Delete the entire paragraph.

PAGE 12

4.4.2.6: Delete the entire paragraph.

PAGE 13

4.4.2.7: Delete the entire paragraph.

FSC 1345

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:03Z
Check the source to verify that this is the current version before use.

4.4.2.8: Change paragraph number from "4.4.2.8" to "4.4.2.5".

Defect No. 105: Reword this defect to read, "Cement seal missing from either closing disc".

Defect No. 108: Reword this defect to read, "Part missing (smoke composition, fuse, photoflash powder, plug, gasket, cushion, either closing disc)".

Add Major defect 109 to read:

"109 Tape around body peeling, incorrect color or missing 0.40% - 3.2 - Visual".

Custodian:
Army-AR

Preparing activity:
Army-Ar

(Project 1345-A229)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:03Z
Check the source to verify that this is the current version before use.