MILITARY SPECIFICATION

CARRIER, GUIDED MISSILE EQUIPMENT, XM730

This amendment forms a part of Military Specification MIL-C-62092(AT), dated 5 April 1968.

Page 3, paragraph 3.4.1.1, delete in its entirety and substitute:

"3.4.1.1 Seals. During fording or amphibious operations the bearing seals shall prevent entrance of foreign matter into the bearings. All bearing seals shall prevent the leaking of lubricants from the bearings."

Page 4, paragraph 3.4.1.2, delete in its entirety and substitute:

"3.4.2.1.2 Personnel heater installation. The personnel heater shall defrost windshield as well as heating cab of vehicle".

Page 5, paragraph 3.4.7.1, delete in its entirety and substitute:

"3.4.7.1 Generating system voltage (alternator). The regulator shall be adjusted, after 20 minutes of operation, with an electrical load that shall cause a 14 volt drop (to warm up the system) across the alternator field. The alternator shall develope an output of 50 ± 5 amperes with the voltage regulator adjusted so that the system voltage will be 28 ± .2 volts and an alternator speed of 4,000 ± 100 RPM. The final voltage, without external load, shall be within the regulation limits of 28 ± 0.5 volts. All electrical contacts and connections shall maintain positive contact under all vehicle operating conditions."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:16Z
Check the source to verify that this is the current version before use.

Page 6, paragraph 3.4.13, line 1, delete "for made."

Page 6, paragraph 3.5.2, delete in its entirety and substitute:
"Oil pressure and temperature. Prior to start of the break-in run, the engine shall be operated at 600 RPM to 800 RPM until lubricating oil is at operating pressure and temperature. If at any time during the break-in run the engine has been stopped for at least 15 minutes, the engine shall again be operated, as above, before continuing the break-in run. Proper oil pressure and temperatures shall be maintained during operation on level ground, 60 per cent grades, and 30 per cent slopes."

Page 8, pargraph 3.6.7.1, line 5, delete" defect" and substitute "defeat".

Page 14, Table III Item 105, delete" 6.5-b" and substitute" 6.5-d"

Page 22, paragraph 4.5.3.3, line 4, delete" 4.5.3.11" and substitute "4.5.3.10."

Custodian:
Army - AT

Preparing activity:
Army - AT

Project No. 2320-A699

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:16Z
Check the source to verify that this is the current version before use.