MILITARY SPECIFICATION

PROJECTILE, 155MM, ILLUMINATING M485A2, METAL PARTS ASSEMBLY

"This amendment forms a part of Military Specification MIL-P-48043A (AR), dated 26 October 1983, and is approved for use by the U.S. Army Armament Munitions and Chemical Command, and is available for use by all Agencies of the Department of Defense."

PAGE 3

3.2 At the end of second sentence add the following: "unless followed by a stress relief".

PAGE 7

4.3.1 Last paragraph: In the third sentence delete " or extrude" and add "or centrifugally cast".

PAGE 8

TABLE I, Base Plug: Add as follows:

"Macro Etch	2	3.1	4.5.1.3"

TABLE I, Body Assembly: Add as follows:

"Rotating Band bandseat clearance	2	3.5.4	4.5.2
Sidewall contact	2	3.5.3	4.5.2.3
Mechanical Properties of rotating band	2	3.5.5	4.5.2.4"

PAGE 11

4.4.2.1 Major: Delete 102 in its entirety.

PAGE 12

4.4.2.2 Major, 105: Under column "Examination" delete and replace with "Runout of underside of flange with press fit diameter".

4.4.2.2 Major: Add 108 as follows:

"108	Macro Etch	*	3.1	4.4.3.1.3/4.5.1.3".

FSC 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

PAGE 14

4.4.2.3, Major: Add 125 as follows:

"125 Runout of rear face with bourrelet diameter 0.40% 3.1 Gage".

Also in Category column, below "125" add "126".

PAGE 15

4.4.2.3, Minor, 208: Delete "Gage" and substitute "Visual".

PAGE 17

4.4.2.5 Delete "4.4.2.5" in its entirety.

Add "4.4.2.5", see page 4. (attached)

PAGE 19

4.4.2.7, After "Critical" add the following:

"Special, a. - Cover support missing (8 places).... 100%....3.1 ... Visual".

Change Dwg "7549275" to Dwg "8837839".

PAGE 20

4.4.2.8 Add new CD "4.4.2.8", (see page 5). (attached)

4.4.3.1.3 Add new paragraph as follows:

"4.4.3.1.3 Macro Etch (base plug). Sample test quantities of base plugs shall be subject to a Macro Etch Test to comply with the cross forging requirement in accordance with 4.5.1.3."

PAGE 23

4.5.1.3 Add new paragraph as follows:

"4.5.1.3 Macro Etch (base plug). One base plug from each standard heat treatment lot and one from each miscellaneous heat treatment lot shall be subjected to a Macro Etch Test (chemical analysis). The base plug shall be sectional through its diameter and one of the sectioned surfaces prepared by

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

grinding the surface to a flat. This part shall then be immersed in a macro etch solution of 50 percent hydrocholoric acid and 50 percent water and heated to a temperature of 180°F, minimum. The base part shall remain in the macro etch solution until flow lines become clearly visible. The part shall then be rinsed with water, dried and visually examined for compliance with dwg 9214146."

PAGE 27

5.2.1.1 Delete Dwg "7549275" to "8837839".

PAGE 28

5.3 Delete Dwg "7549275" to "8837839".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Body Assembly (after banding)				9362659
					NEXT HIGHER ASSEMBLY 9214142
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Magnetic particle stamp missing (indicating failure to pass test)		100%	3.1	Visual
Major					
101	Runout of rotating band with bourrelet and internal base diameter		0.40%	3.1	Gage
102	Diameter of rotating band		0.40%	3.1	Gage
103	Diameter between rotating bands		0.40%	3.1	Gage
104	Length from rear face to rear shoulder of rotating band		0.40%	3.1	Gage
105	Rotating band bandseat clearance		*	3.5.4	4.4.3.2/4.5.2
106	Sidewall contact		*	3.5.3	4.4.3.2.3/4.5.2.3
107	Mechanical properties of rotating band		*	3.5.5	4.4.3.2.4/4.5.2.4
Minor					
201	Width of rotating band		0.65%	3.1	Gage
202	Depth of undercut front and rear of rotating band (if applicable)		0.65%	3.1	Gage
203	Width of undercut front and rar of rotating band (if appliable)		0.65%	3.1	Gage
204	Radii or chamfer missing or incorrect		0.65%	3.1	Visual
205	Width of groove in rotating band		0.65%	3.1	Visual
206	Evidence of poor workmanship		0.65%	3.1	Visual

NOTES: *Sampling size as specified in applicable test method paragraph.

Source: https://assist.dla.mil - Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.8	Body Assembly (after painting)	1 OF 1	9362659
			NEXT HIGHER ASSEMBLY 9214142

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of bourrelet, max.		100%	3.1	Gage
102	Salt spray		*	3.1	4.5.3
Minor					
201	Protective coating inadequate or damaged		0.65%	3.1	Visual
202	Paint on threads		0.65%	3.11	Visual
203	Paint on base fit area		0.65%	3.11	Visual
204	Evidence of poor workmanship		0.65%	3.11	Visual

NOTES: *Sampling size as specified in applicable test method paragraph.

Source: https://assistdla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-A805)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:10Z
Check the source to verify that this is the current version before use.