NOTICE OF CANCELLATION

INCH-POUND

MS14302
NOTICE 2
20 November 2002
SUPERSEDING
NOTICE 1
5 March 1999

MILITARY STANDARD

# PIPE, COPPER, SEAMLESS, STANDARD SIZES

MS14302, dated 15 June 1973, is hereby canceled. Future acquisitions should refer to ASTM B42, "Standard Specification for Seamless Copper Pipe, Standard Sizes." This cancellation notice provides additional information not included in cancellation notice 1.

Table I provides a detailed cross-reference of cancelled MS14302 Part or Identifying Numbers (PINs) and replacement ASTM B42 PINs. MS PINs, which are not in use, are not included in the cross-reference table.

(Copies of ASTM B42 may be purchased from the American Society for Testing and Materials, 100 Barr Harbor Drive, West Conshohocken, PA 19426.)

Custodians:
Air Force -99
Army - AT
Navy - MC
DLA - CC

Review activities:
Air Force - 11
Army – AR
Navy - SA

Preparing activity:
DLA - CC

(Project 4710-0279)



AMSC N/A

FSC 4710

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T13:39Z
Check the source to verify that this is the current version before use.

TABLE I. - Cross-reference data. 1/

| Cancelled MS PIN | Replacement ASTM PIN |
|---|---|
| MS14302AHBS | B42C12000H80-001R1440 |
| MS14302AHBXXXX | B42C12000H80-001RXXXX |
| | |
| MS14302ALBS | B42C12000H55-001R1440 |
| MS14302ALBXXXX | B42C12000H55-001RXXXX |
| | |
| MS14302AABS | B42C12000O61-001R1440 |
| MS14302AABXXXX | B42C12000O61-001RXXXX |
| | |
| MS14302BHBS | B42C12000H80-002R1440 |
| MS14302BHBXXXX | B42C12000H80-002RXXXX |
| | |
| MS14302BLBS | B42C12000H55-002R1440 |
| MS14302BLBXXXX | B42C12000H55-002RXXXX |
| | |
| MS14302BABS | B42C12000O61-002R1440 |
| MS14302BABXXXX | B42C12000O61-002RXXXX |
| | |
| MS14302CHBS | B42C12000H80-003R1440 |
| MS14302CHBXXXX | B42C12000H80-003RXXXX |
| | |
| MS14302CLBS | B42C12000H55-003R1440 |
| MS14302CLBXXXX | B42C12000H55-003RXXXX |
| | |
| MS14302CABS | B42C12000O61-003R1440 |
| MS14302CABXXXX | B42C12000O61-003RXXXX |
| | |
| MS14302DHBS | B42C12000H80-004R1440 |
| MS14302DHBXXXX | B42C12000H80-004RXXXX |
| | |
| MS14302DLBS | B42C12000H55-004R1440 |
| MS14302DLBXXXX | B42C12000H55-004RXXXX |
| | |
| MS14302DABS | B42C12000O61-004R1440 |
| MS14302DABXXXX | B42C12000O61-004RXXXX |
| | |
| MS14302EHBS | B42C12000H80-006R1440 |
| MS14302EHBXXXX | B42C12000H80-006RXXXX |
| | |
| MS14302ELBS | B42C12000H55-006R1440 |
| MS14302ELBXXXX | B42C12000H55-006RXXXX |
| | |
| MS14302EABS | B42C12000O61-006R1440 |
| MS14302EABXXXX | B42C12000O61-006RXXXX |
| | |
| MS14302FHBS | B42C12000H80-010R1440 |
| MS14302FHBXXXX | B42C12000H80-010RXXXX |
| | |
| MS14302FLBS | B42C12000H55-010R1440 |
| MS14302FLBXXXX | B42C12000H55-010RXXXX |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T13:39Z
Check the source to verify that this is the current version before use.

TABLE I. - Cross-reference data - Continued. 1/

| Cancelled MS PIN | Replacement ASTM PIN |
|---|---|
| MS14302FABS | B42C12000O61-010R1440 |
| MS14302FABXXXX | B42C12000O61-010RXXXX |
| | |
| MS14302GHBS | B42C12000H80-012R1440 |
| MS14302GHBXXXX | B42C12000H80-012RXXXX |
| | |
| MS14302GLBS | B42C12000H55-012R1440 |
| MS14302GLBXXXX | B42C12000H55-012RXXXX |
| | |
| MS14302GABS | B42C12000O61-012R1440 |
| MS14302GABXXXX | B42C12000O61-012RXXXX |
| | |
| MS14302HHBS | B42C12000H80-014R1440 |
| MS14302HHBXXXX | B42C12000H80-014RXXXX |
| | |
| MS14302HLBS | B42C12000H55-014R1440 |
| MS14302HLBXXXX | B42C12000H55-014RXXXX |
| | |
| MS14302HABS | B42C12000O61-014R1440 |
| MS14302HABXXXX | B42C12000O61-014RXXXX |
| | |
| MS14302JHBS | B42C12000H80-020R1440 |
| MS14302JHBXXXX | B42C12000H80-020RXXXX |
| | |
| MS14302JLBS | B42C12000H55-020R1440 |
| MS14302JLBXXXX | B42C12000H55-020RXXXX |
| | |
| MS14302JABS | B42C12000O61-020R1440 |
| MS14302JABXXXX | B42C12000O61-020RXXXX |
| | |
| MS14302KHBS | B42C12000H80-024R1440 |
| MS14302KHBXXXX | B42C12000H80-024RXXXX |
| | |
| MS14302LHBS | B42C12000H80-030R1440 |
| MS14302LHBXXXX | B42C12000H80-030RXXXX |
| | |
| MS14302MHBS | B42C12000H80-034R1440 |
| MS14302MHBXXXX | B42C12000H80-034RXXXX |
| | |
| MS14302NHBS | B42C12000H80-040R1440 |
| MS14302NHBXXXX | B42C12000H80-040RXXXX |
| | |
| MS14302PHBS | B42C12000H80-050R1440 |
| MS14302PHBXXXX | B42C12000H80-050RXXXX |
| | |
| MS14302QHBS | B42C12000H80-060R1440 |
| MS14302QHBXXXX | B42C12000H80-060RXXXX |



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T13:39Z
Check the source to verify that this is the current version before use.

TABLE I. - Cross-reference data - Continued. 1/

| Cancelled MS PIN | Replacement ASTM PIN |
|---|---|
| MS14302RHBS | B42C12000H80-080R1440 |
| MS14302RHBXXXX | B42C12000H80-080RXXXX |
| | |
| MS14302SHBS | B42C12000H80-100R1440 |
| MS14302SHBXXXX | B42C12000H80-100RXXXX |
| | |
| MS14302THBS | B42C12000H80-120R1440 |
| MS14302THBXXXX | B42C12000H80-120RXXXX |

1/ The “XXXX” represents the length in inches and eighths, where the first 3 “X”s represent inches and the last “X” represents eighths.
Example: Part number for a 6 inch pipe size, hard drawn temper, tolerance to be plus or minus, with a specific length of 25 1/8 inches is MS14302RHB0251 with the replacement ASTM PIN as B42C12000H80-080R0251.



Source: https://assist.dla.mil -- Downloaded: 2026-10-23T13:39Z
Check the source to verify that this is the current version before use.