INCH-POUND

MIL-R-83536/22
AMENDMENT 4
15 June 1999
SUPERSEDING
AMENDMENT 3
30 September 1996

MILITARY SPECIFICATION SHEET

RELAYS, ELECTROMAGNETIC, ESTABLISHED RELIABILITY, 3PDT, LOW LEVEL TO 10 AMPERES, PERMANENT MAGNET DRIVE, HERMETICALLY SEALED, ALL WELDED, TRANSIENT SUPPRESSED DC COIL

This amendment forms a part of MIL-R-83536/22, dated 27 March 1992, and is approved for use by all Departments and Agencies of the Department of Defense.


PAGE 1

FIGURE 1, side view: Delete "SERIAL NUMBER SHALL BE MARKED ON TOP OF RELAYS" and "MARKING (EITHER SIDE)".

PAGE 2

* FIGURE 1, delete and substitute:

"



"

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T09:08Z
Check the source to verify that this is the current version before use.

PAGE 3


FIGURE 1, side view: Delete "SERIAL NUMBER SHALL BE MARKED ON TOP OF RELAYS".

FIGURE 1, side view: Delete "MARKING (EITHER SIDE)" and substitute "MARKING (SEE NOTES 8 AND 9)".

PAGE 4

* FIGURE 1, delete and substitute:

"



TRACK MOUNT

"


Source: https://assist.dla.mil -- Downloaded: 2026-10-23T09:08Z
Check the source to verify that this is the current version before use.

PAGE 5

FIGURE 1, above figure title: Add "CIRCUIT DIAGRAM".

FIGURE 1, add the following circuit diagram:

"



CIRCUIT DIAGRAM
(ALTERNATE INTERNAL
DIODE CONFIGURATION)

"

PAGE 6

FIGURE 1, note 11, add the following sentence: "Gaskets are not supplied with track mount relays."

PAGE 7

Delete "Contact voltage drop or resistance:" and substitute "Contact voltage drop and resistance:".

PAGE 8

Coil transient suppression: Add "(42 V dc maximum)".

PAGE 11

Vibration (random), both paragraphs, lines 2 and 3: Delete "15 minutes each plane".

Weight: Delete "(28.15 g's)" and substitute "(28.15 grams)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T09:08Z
Check the source to verify that this is the current version before use.

TABLE V, delete and substitute:

" TABLE V. Supersession data.

Superseded PIN M6106/	Replacement PIN M83536/22-
24-003	025
29-003	017
29-004	017
29-007	018
29-008	018
29-011	019
29-012	019
29-015	020
29-016	020
29-019	021
29-020	021
29-023	022
29-024	022
29-027	023
29-028	023
29-031	024
29-032	024

"

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodians:
Army - CR
Navy - EC
Air Force - 11
DLA - CC

Review activities:
Air Force - 99

Preparing activity:
DLA - CC

(Project 5945 - 1007)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T09:08Z
Check the source to verify that this is the current version before use.