MIL-C-46389A(MU)
AMENDMENT 2
29 May 1967
SUPERSEDING
AMENDMENT 1
14 September 1965

MILITARY SPECIFICATION

CORRECTOR, CANT: XM4

This amendment forms a part of Military Specification MIL-C-46389A(MU), dated 14 February 1964.

Paragraph 2.1: Delete "SQAP-8626191 - Supplementary Quality Assurance Provisions for Level 8626191".

Paragraph 3.5.2: Delete paragraph and substitute the following:

"3.5.2 Rotation.- With the rotational lock disengaged and the cant corrector stabilized at an ambient temperature of 72°F, the adjusting screws of the brackets shall be adjusted so that there is free rotation of the housing containing the level vial. The torque required to rotate the housing containing the level vial shall be between 8 and 16 ounce-inches. The housing shall be operable (rotate) at the extreme temperatures of 3.4.1."

Paragraph 4.2.2, first sentence: Delete "and Supplementary Quality Assurance Provisions, SQAP-8626161."

Paragraph 4.3: In tabulated data, change "4.6.1" to 4.5.1" (two places).

Paragraph 4.5.6: In last sentence, change "3.5.1" to 3.4.1".

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 1290- A190

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:49Z
Check the source to verify that this is the current version before use.

FSC 1290