# MILITARY SPECIFICATION

## CARTRIDGE, CALIBER .50, SPOTTER-TRACER, M48A1

This amendment forms a part of MIL-C-46396A(MU), dated 15 January 1965.

Paragraph 3.4: Delete and substitute:

"3.4 Bullet Sensitivity.- The bullet shall not detonate when the nose of the cartridge is caused to impact against a stationary steel plate with a velocity at the point of impact of 55-5 ft/sec.

Paragraph 4.3.3.1 - Table II: Change "Drop sensitivity 2/" to "Bullet sensitivity 2/".

Paragraph 4.4.2: Change "Drop sensitivity" to "Bullet sensitivity".

Add paragraph - "4.4.2.1 "Alternate Method.- The alternate method shown in the bullet sensitivity section of the IEL may be used. The bullets shall be extracted from the cartridge cases and inserted into the bullet holder. The pressure of the air gun used shall be adjusted so that the bullet holder assembly is propelled at a velocity of 55-5 feet per second, at the point of striking normal on a flat rigid steel plate."

Custodian:

Army - MU

Preparing activity:

Army - MU

Project No. 1305-A425

FSC 1305

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T05:50Z
Check the source to verify that this is the current version before use.