MIL-C-46558C(AR)
23 November 1981
SUPERSEDING
MIL-C-46558B(MU)
30 September 1965

MILITARY SPECIFICATION

CHARGE, DEMOLITION, HE, LINEAR, M58, W/FUZE; AND CHARGE, DEMOLITION, INERT, LINEAR, M68, W/INERT FUZE, LOADING, ASSEMBLING AND PACKING

This specification is approved for use by U.S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers requirements and quality assurance provisions for the loading, assembling and packing for one type of mine clearing device designated as Charge, Demolition, HE, Linear, M58, w/Fuze and Charge Demolition, Inert, Linear, M68, w/Inert Fuze.

2. APPLICABLE DOCUMENTS

2.1 Issues of documents. The following documents of the issue in effect on date of invitation for bids or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes

FSC 1375

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

DRAWINGS

U.S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

8845322 - Charge, Demolition, HE, Linear, M58, w/Fuze; and
Charge, Demolition, Inert, Linear, M68, w/Inert Fuze.

(Copies of specifications, standards drawings, and publications required by suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the Contracting Officer.)

3. REQUIREMENTS

3.1 Materials. Materials and parts shall be in accordance with applicable drawings and specifications.

3.2 Demolition charge. The demolition charge shall comply with all requirements specified on drawing (dwg) 8845322 and associated drawings and with all requirements specified in applicable specifications and standards.

3.3 Pallet and cover assembly. The pallet and cover assembly shall comply with all requirements specified on Dwg. 1289930, Department of the Navy Drawing, Bureau of Ships, and associated drawings and with all requirements specified in applicable specifications and standards.

3.4 Arresting cable assembly

3.4.1 Strength. Each spliced end of the nylon rope in the arresting cable assembly shall withstand a tensile load equal to 4000 ± 200 pounds of force when applied at a spot approximately fifty inches from the splice with no evidence of splice slippage or other damage.

3.4.2 Withdrawal of arming plug. During the test for the strength requirement (3.4.1) to the spliced end of the arresting cable to which the arming pin assembly of the inert fuze (see 6.4) is assembled, the arming plug shall be withdrawn a distance sufficient to effect fuze arming when the applied tensile load reaches approximately 100 pounds.

3.4.3 Electrical continuity and resistance. All electrical circuits in the arresting cable assembly shall have electrical continuity and the direct current resistance of each conductor when incorporated in the nylon rope shall not exceed 4.0 ohms per each length of 100 feet.

3.5 Workmanship. All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner. They shall be clean and free of burrs, sharp edges, unblended radii, surface defects, chips, dirt, grease, rust, corrosion products, and other foreign matter. The cleaning method used

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

shall not be injurious to any part nor shall the parts be contaminated by the cleaning agent. Surface coatings shall be continuous except for a few slight scratches. All required marking shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspection. The following types of inspection shall be conducted on this item:

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First article inspection

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated:

Part Description	Drawing	Quantity
Arresting Cable Assembly	8845251	1
Fuze Connector Assembly	8827716	1
Arming Wire Assembly	8845248	1
Shaft Fuze Connector	8827719	1
Thimble	8827720	1
Fuze Connector Front Half Assembly	8845246	1
Connector, Fuze, Front Half	8827717	1
Connector, Fuze, Rear Half	8827718	1
Connector, Rocket, Harness	8845259	1
Plug Arming	8845247	1
Washer	8845249	1

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER: See Below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Connector, Rocket Harness (Dwg 8845259) Examination for defects	1		3.1	4.4.2.1
	Shaft, Fuze Connector (Dwg 8827719) Examination for defects	1		3.1	4.4.2.2
	Connector, Fuze, Rear Half (Dwg 8827718) Examination for defects	1		3.1	4.4.2.3
	Connector, Fuze, Front Half (Dwg 8827717) Examination for defects	1		3.1	4.4.2.4
	Fuze Connector Front Half Assembly (Dwg 8845246) Examination for defects	1		3.1	4.4.2.5
	Fuze Connector Assembly (Dwg 8827716) Examination for defects	1		3.1	4.4.2.6

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check this source to verify that this is the current version before use.

TABLE I. FIRST ARTICLE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Arresting Cable Assembly (Dwg 8845251)	1			
	Examination for defects			3.1	4.4.2.9
	Continuity and resistance test	Note a		3.4.3	4.4.2.9
	Strength test			3.4.1	4.4.2.8
	Arming test			3.4.2	4.4.2.8
	Thimble (Dwg 8827720)	1			
	Examination for defects			3.1	4.4.2.10
	Plug Arming (Dwg 8845247)	1			
	Examination for defects			3.1	4.4.2.11
	Washer (Dwg 8845249)	1			
	Examination for defects			3.1	4.4.2.12
	Arming Wire Assembly (Dwg 8845248)	1			
	Examination for defects			3.1	4.4.2.13

NOTES:

a. Must be done prior to strength and arming tests.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Connector, Rocket Harness		8845259
			NEXT HIGHER ASSEMBLY
			8845322

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of large hole, min		0.40%	3.1	Gage
102	Diameter of small hole, min		0.40%	3.1	Gage
103	Minor diameter of thread, min		0.40%	3.1	Gage
104	Pitch diameter of thread		0.40%	3.1	Gage
105	Width of larger slot, min		0.40%	3.1	Gage
106	Width of smaller slot, min		0.40%	3.1	Gage
107	Depth of larger slot, min		0.40%	3.1	Gage
108	Depth of smaller slot, min		0.40%	3.1	Gage
Minor					
201	Protective finish missing, inadequate, or improper		0.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.2	Shaft, Fuze Connector		8827719
			NEXT HIGHER ASSEMBLY 8845246

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter		0.40%	3.1	Gage
102	Shaft not straight		0.40%	3.1	Gage
103	Overall length		0.40%	3.1	Gage
Minor					
201	Length of slot		0.65%	3.1	Gage
202	Width of slot		0.65%	3.1	Gage
203	Protective finish missing, inadequate, or improper		0.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Connector, Fuze, Rear Half		8827718
			NEXT HIGHER ASSEMBLY 8827716

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of arresting cable slot and detonator cord holes		0.40%	3.1	Gage
102	Location of shaft locating hole		0.40%	3.1	Gage
103	Location of ball lock pin hole		0.40%	3.1	Gage
104	Width of arresting cable slot, min		0.40%	3.1	Gage
105	Depth of arresting cable slot, min		0.40%	3.1	Gage
106	Minor diameter of thread, min		0.40%	3.1	Gage
107	Pitch diameter of thread		0.40%	3.1	Gage
108	Diameter of large holes, min		0.40%	3.1	Gage
109	Depth of large holes, min		0.40%	3.1	Gage
110	Height of fuze clearance boss		0.40%	3.1	Gage
111	Diameter of center hole, min		0.40%	3.1	Gage
Minor					
201	Protective finish missing, inadequate, or improper		0.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2024-04-27T06:09:16Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.4	Connector, Fuze, Front Half		8827717
			NEXT HIGHER ASSEMBLY
			8845246

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Concentricity of large counterbore to center hole		0.40%	3.1	Gage
102	Concentricity of small counterbore to center hole		0.40%	3.1	Gage
103	Location of slot and detonator cord holes		0.40%	3.1	Gage
104	Diameter of center hole		0.40%	3.1	Gage
105	Diameter of large counterbore		0.40%	3.1	Gage
106	Width of slot		0.40%	3.1	Gage
107	Depth of slot		0.40%	3.1	Gage
108	Minor diameter of large thread, min		0.40%	3.1	Gage
109	Pitch diameter of large thread		0.40%	3.1	Gage
110	Location of fuze positioning screw holes		0.40%	3.1	Gage
111	Minor diameter of fuze positioning screw holes thread		0.40%	3.1	Gage
112	Pitch diameter of fuze positioning screw holes thread		0.40%	3.1	Gage
113	Diameter of small counterbore		0.40%	3.1	Gage
Minor					
201	Depth of large counterbore		0.65%	3.1	Gage
202	Depth of small counterbore		0.65%	3.1	Gage
203	Protective finish missing, inadequate, or improper		0.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-12T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Fuze Connector Front Half Assembly				8845246
					NEXT HIGHER ASSEMBLY 8827716
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of shaft slot		0.40%	3.1	Gage
102	Minor diameter of tapped hole, min		0.40%	3.1	Gage
103	True position of tapped hole		0.40%	3.1	Gage
104	Shaft holding pin loose or improperly assembled		0.40%	3.1	Gage
105	Shaft above flush		0.40%	3.1	Gage
Minor					
201	Protrusion of fuze locating screws		0.65%	3.1	Gage
202	Depth of tapped hole counterbore, max		0.65%	3.1	Gage
203	Adhesive missing from locating screws		0.65%	3.1	Visual
204	Cap missing or improperly assembled		0.65%	3.1	Visual
205	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-02-27T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Fuze Connector Assembly		8827716
			NEXT HIGHER ASSEMBLY 8845254

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance front to rear half		0.40%	3.1	Gage
102	Protrusion of shaft locating pin		0.40%	3.1	Gage
Minor					
201	Component missing or improperly assembled		0.65%	3.1	Visual
202	Ball pin loose		0.65%	3.1	Manual
203	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Arresting Cable Assembly, Prior to Assembly to Fuze Connector				8845251
					NEXT HIGHER ASSEMBLY
					8845322
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Distance between thimbles		0.65%	3.1	Gage
202	Thimbles loose		0.65%	3.1	Manual
203	Splice improper		0.65%	3.1	Visual
204	Lead wires missing at either end		0.65%	3.1	Visual
205	Insufficient tucks		0.65%	3.1	Visual
206	Splice tucks not in rope strand lays		0.65%	3.1	Visual
207	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Arresting Cable Assembly, Prior to Addition of Shorting Loop				8845251
					NEXT HIGHER ASSEMBLY 8845322
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Strength test		100%	3.4.1	4.5.1
102	Arming test		100%	3.4.2	4.5.1
Minor					
201	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.9	Arresting Cable Assembly		8845251
			NEXT HIGHER ASSEMBLY
			8845322

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Shorting loop missing or assembled improperly		100%	3.1	Visual
Major					
101	Distance from container connector assembly to end of cable min		0.40%	3.1	Gage
102	Distance from end of holder arming assembly to thimble connector hole		0.40%	3.1	Gage
103	Electrical connectors not potted		0.40%	3.1	Visual
104	Continuity and resistance test		100%	3.4.3	4.5.2
Minor					
201	Any component missing or improperly assembled		0.65%	3.1	Visual/Manual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: http://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current revision before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.10	Thimble				8827720
					NEXT HIGHER ASSEMBLY 8845251
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Overall width, max		0.40%	3.1	Gage
102	Overall diameter, max		0.40%	3.1	Gage
Minor					
201	Protective finish missing, inadequate or improper		0.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Plug, Arming				8845247
					NEXT HIGHER ASSEMBLY
					8847488
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Minor diameter of thread, min		0.40%	3.1	Gage
102	Pitch diameter of thread		0.40%	3.1	Gage
103	Depth of thread, min		0.40%	3.1	Gage
Minor					
201	Overall height		0.65%	3.1	Gage
202	Depth of small diameter hole		0.65%	3.1	Gage
203	Protective finish missing, inadequate or improper		0.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Washer				8845249
					NEXT HIGHER ASSEMBLY
					8847488
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter, max		0.40%	3.1	Gage
102	Angle of countersink		0.40%	3.1	Gage
Minor					
201	Diameter of hole		0.65%	3.1	Gage
202	Thickness		0.65%	3.1	Gage
203	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: http://assist.daps.dla.mil | Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.13	Arming Wire Assembly		8845248
			NEXT HIGHER ASSEMBLY 8847488

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Terminal ball not swaged properly		0.40%	3.1	Visual/Manual
102	Cable protrusion from front of terminal ball, max		0.40%	3.1	Gage
Minor					
201	End of cable not impregnated with brazing filler metal		0.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14	Charge, Demolition HE, Linear, M58, w/Fuze and Charge, Demolition Inert, Linear, M68, w/ Inert Fuze, Prior to Assembly of Charge	1 OF 1	8845322
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Arresting cable not flat		0.40%	3.1	Visual
102	Arresting cable improperly faked		0.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.15	Charge, Demolition HE, Linear, M58, w/Fuze and Charge, Demolition Inert, Linear, M68, w/ Inert Fuze, After Assembly of Charge	1 OF 1	8845322
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Linear charge improper type		0.40%	3.1	Visual
102	Faking of first layer improper		0.40%	3.1	Visual
103	Layer not reverse faked		0.40%	3.1	Visual
104	Layer with incorrect number of rows		0.40%	3.1	Visual
105	Line missing from locked safety switch to charge		0.40%	3.1	Visual
106	Insufficient slack at fuze connector or arresting cable assembly		0.40%	3.1	Manual
Minor					
201	Knots in line to switch not coated		0.65%	3.1	Visual
202	Utility kit missing		0.65%	3.1	Visual
203	Component missing		0.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.16	Charge, Demolition HE, Linear, M58, w/Fuze and Charge, Demolition Inert, Linear, M68, w/ Inert Fuze, Prior to Assembling Cover	1 OF 1	8845322
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Warning stencil (or decal) on pallet cover or pallet back missing or illegible		100%	3.1	Visual
Major					
101	Fuze missing or improper type		0.40%	3.1	Visual
Minor					
201	Fuze insecure		0.65%	3.1	Manual
202	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.17	Charge, Demolition HE, Linear, M58, w/Fuze and Charge, Demolition Inert, Linear, M68, w/ Inert Fuze	1 OF 1	8845322
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cover fastener inoperable		0.40%	3.1	Manual
Minor					
201	Cover fastener not tight		0.65%	3.1	Manual
202	Marking color incorrect		0.65%	3.1	Visual
203	Marking missing, misleading or unidentifiable		0.65%	3.1	Visual
204	Protective coating damaged		0.65%	3.1	Visual
205	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-46558C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.18	Charge, Demolition HE, Linear, M58, w/Fuze and Charge, Demolition Inert, Linear, M68, w/ Inert Fuze, Strapped	1 OF 1	8845322
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Strapping loose, broken, or improperly applied		0.65%	3.1	Visual/Manual
202	Destination marking missing, misleading or unidentifiable		0.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.5	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection tables.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the 'Paragraph Reference/Inspection Method' column in the tables starting with paragraph 4.4.2.1. The contractor shall submit, for approval, inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Method of inspection

4.5.1 Strength and arming test. The arming plug of the arresting cable assembly shall be assembled to the arming pin assembly of the inert fuze (see 6.4). The test unit shall then be assembled to the applicable test equipment. The required force shall be applied to one end of the nylon rope at a spot approximately fifty inches from the splice and held for 1/2 minute then released. Observation shall be made for splice slippage, other damage, and fuze arming (the fuze is armed when the rotor rotates and places the three explosive cavities in line). Any assembly failing one or more of the requirements shall be classified defective and removed from the lot.

4.5.2 Electrical continuity and resistance tests. Continuity and resistance of all circuits in the cable assembly are to be tested using the approved test equipment. Any arresting cable assembly which does not have continuity in all circuits or exceeds the resistance requirements shall be classified defective and removed from the lot.

5. PACKAGING

5.1 Strapping. The demolition charge shall be prepared for shipment by applying two 1 1/4 inch steel straps around the assembly. The straps shall be located 6 inches toward the center from each skid. Sufficient padding shall be placed under the strapping to prevent damage to corners.

5.2 Marking. Marking shall be in accordance with drawing 8845322.

6. NOTES

6.1 Intended use. The components covered by this specification are intended for use on the M58 Demolition Charge and the M68 Inert Demolition Charge.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander, U.S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

6.4 Furnished items. The procuring activity shall furnish the contractor one (1) parts assembly of Fuze, M1134, for testing fuze arming by the arresting cable.

6.5 The item covered by this specification was formerly designated as Demolition Kit, Projected Charge, HE, M125 and Demolition Kit, Projected Charge, Inert, M126.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project No.: 1375-A209

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

FOLD

DEPARTMENT OF THE ARMY

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

BUSINESS REPLY CARD

FIRST CLASS PERMIT NO. 12062 WASHINGTON D. C.

POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

COMMANDER
US ARMY ARMAMENT RESEARCH & DEVELOPMENT COMMAND
ATTN: DRDAR-QAT
DOVER, NEW JERSEY 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS: This form is provided to solicit beneficial comments which may improve this document and enhance its use. DoD contractors, government activities, manufacturers, vendors, or other prospective users of the document are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity. A response will be provided to the submitter, when name and address is provided, within 30 days indicating that the 1426 was received and when any appropriate action on it will be completed.
NOTE: This form shall not be used to submit requests for waivers, deviations or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

DOCUMENT IDENTIFIER *(Number)* AND TITLE

MIL-C-46558C Charge, Demolition, HE, Linear, M58

NAME OF ORGANIZATION AND ADDRESS OF SUBMITTER

☐ VENDOR ☐ USER ☐ MANUFACTURER

1. ☐ HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE? ☐ IS ANY PART OF IT TOO RIGID, RESTRICTIVE, LOOSE OR AMBIGUOUS? PLEASE EXPLAIN BELOW.

A. GIVE PARAGRAPH NUMBER AND WORDING

B. RECOMMENDED WORDING CHANGE

C. REASON FOR RECOMMENDED CHANGE(S)

2. REMARKS

SUBMITTED BY *(Printed or typed name and address — Optional)*

TELEPHONE NO.

DATE

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:17Z
Check the source to verify that this is the current version before use.

DD FORM 1 OCT 76 1426 EDITION OF 1 JAN 72 WILL BE USED UNTIL EXHAUSTED.