MIL-F-46570D(AR)
15 January 1982
SUPERSEDING
MIL-F-46570C(MU)
9 June 1967

MILITARY SPECIFICATION

FUZE, DEMOLITION KIT, M1134 WITH DETONATORS, PARTS FOR

This specification is approved for use by the U. S. Army Armament Research and Development Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the parts, assembling, and packing for one type of fuze designated as Fuze, Demolition Kit, M1134.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified, the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-I-13857	Impregnation of Metal Castings
MIL-D-20462	Detonator, Electric, M36A1, Loading, Assembling, and Packing
MIL-A-48078	Ammunition, Standard Quality Assurance Provisions, General Specification For.

FSC 1375

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-105	Sampling Procedures and Tables for Inspection by Attributes.
MIL-STD-1169	Packaging, Packing, and Marking for Shipment of Inert Ammunition Components.

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this specification to the extent specified herein.

DRAWINGS

U. S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

PRODUCT AND PACKAGING DRAWINGS

8799682 - Carton, Packing, Ammunition for Fuze, Demolition Kit, M1134
8799683 - Container, Fiberboard, Ammunition for Fuze, Demolition Kit, M1134
9216413 - Fuze, Demolition Kit, M1134

INSPECTION EQUIPMENT DRAWINGS

U. S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

EL-9216413 - Fuze, Demolition Kit, M1134 PTS

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer).

2.1.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Materials. Materials shall be in accordance with applicable drawings and specifications.

3.2 Fuze assembly. The fuze assembly shall comply with all requirements specified on drawing (dwg.) 9216413 and with all requirements specified in applicable specifications.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

3.3 Electrical continuity.

3.3.1 Unarmed. The electrical resistance, indicative of acceptable shorting, shall not exceed 0.2 ohms when measured between the pins of the external connector, with the arming pin assembly, fully inserted into the complete fuze. The test shall be performed as specified in 4.5.3.

3.3.2 Armed. To indicate acceptable continuity , the electrical resistance between the pins of the external connector shall be no less than 3.0 ohms nor greater than 5.5 ohms when the arming pin assembly is sufficiently withdrawn to arm the fuze. The test shall be performed as specified in 4.5.3.

3.4 Non-Arming and arming. The fuze, less container, shall not arm when a withdrawal force of 15 $\pm$ 0.5 pounds is applied to the arming pin assembly. Arming shall occur when a force of 35 pounds, maximum, is applied. The fuze is considered armed when the arming pin disconnect releases from the arming pin assembly and the detonator, rotor lead, and booster lead cavities are completely aligned. After arming, the fuze shall return to the unarmed position (The rotor lead cavity not visible through the booster lead cavity) when the arming pin assembly is fully re-inserted into the fuze. The test shall be performed in accordance with 4.5.4.

3.5 Forty foot drop test.

3.5.1 Non-function. The unarmed fuze shall neither arm nor function when dropped in a free fall from a height of 40 feet onto 12 inches of hard packed dry earth as evidenced by a satisfactory electrical check (see 3.3.1). During the drop, the center hole of the fuze shall be perpendicular to the direction of the fall.

3.5.2 Functioning. After successful completion of testing in accordance with 3.5.1, the fuze shall function as evidenced by the detonation of both detonators. Testing of both phases shall be as specified in 4.5.5.

3.6 Leak test. The complete fuze shall show no evidence of leakage when tested as specified in 4.5.2.

3.7 Salt spray. The nut, arming pin assembly, container assembly, and disconnect arming pin shall be subjected to and pass the salt spray test when performed in accordance with 4.5.6.

3.8 Torque test. The rotor spring shall meet the requirements on the applicable drawing when tested in accordance with 4.5.1.

3.9 Impregnation. The impregnation process shall be checked in accordance with and meet all the requirements of the applicable specification.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

3.10 First article. This specification makes provisions for first article inspection. Requirements for submission of first article samples by the contractor shall be as specified in the contract.

3.11 Workmanship. All parts and assemblies shall be fabricated and finished in a thorough, workmanlike manner. They shall be clean and free of burrs, sharp edges, distortion, unblended radii, surface defects, chips, dirt, grease, rust, weld splatter, corrosion products, and other foreign material. The cleaning method used shall not be injurious to any part nor shall the parts be contaminated by the cleaning agents. Surface coatings shall be continuous except for a few slight scratches not exposing base metal. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspection. The following types of inspection shall be conducted on this item:

a. First article inspection

b. Quality conformance inspection

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provision of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated:

a. Five each of the following:

Part Description	Drawing
Nut	8800627
Cover, Lead Cup	8800610
Spacer, Rotor	8800629
Cup, Rotor, Lead	8800612
Rotor	8800609
Cup, Booster, Lead	8800606
Retainer, Rotor	8800607
Container	8800602
Tube Center	8800624
Guide, Arming	8800598
Disconnect, Arming Pin	8800597
Connector Cable (modified)	8800615
Ground Plate	9345288

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

Part Description	Drawing
Connector Filtered	9345289
Block, Terminal, Upper	8800618
Block, Terminal, Lower	8800617
Plate End	8800603
Terminal, Arming, Pin	8800600
Pin, Arming	8800599
Bushing Insulating	8800632

b. Thirty of the following:

Part Description	Drawing
Spring, Rotor	8800630

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 4		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Nut (Dwg. 8800627)				
	Examination for defects	5		3.1	4.4.2.2
	Salt spray	5-0-1		3.7	4.5.6
	Cover, lead cup (Dwg. 8800610)				
	Examination for defects	5		3.1	4.4.2.3
	Spacer, rotor (Dwg. 8800629)				
	Examination for defects	5		3.1	4.4.2.4
	Cup, rotor, lead (Dwg. 8800612)				
	Examination for defects	5		3.1	4.4.2.5
	Rotor (Dwg. 8800609)				
	Examination for defects	5		3.1	4.4.2.6

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection - continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 2 OF 4		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Cup, booster, lead (Dwg. 8800606)				
	Examination for defects	5		3.1	4.4.2.7
	Retainer rotor (Dwg. 8800607)				
	Examination for defects	5		3.1	4.4.2.8
	Container (Dwg. 8800602)				
	Examination for defects	5		3.1	4.4.2.9
	Tube center (Dwg. 8800624)				
	Examination for defects	5		3.1	4.4.2.11
	Guide, arming (Dwg. 8800598)				
	Examination for defects	5		3.1	4.4.2.12
	Disconnect, arming pin (Dwg. 8800597)				
	Examination for defects	5		3.1	4.4.2.13
	Salt Spray	5-0-1		3.7	4.5.6

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 3 OF 4		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Connector cable (modified) (Dwg. 8800615) Examination for defects	5		3.1	4.4.2.31
	Ground plate (Dwg. 9345288) Examination for defects	5		3.1	4.4.2.20
	Connector (Dwg. 8800633) Examination for defects	5		3.1	4.4.2.21
	Block, terminal, upper (Dwg. 8800618) Examination for defects	5		3.1	4.4.2.23
	Block, terminal, lower (Dwg. 8800617) Examination for defects	5		3.1	4.4.2.24
	Plate end (Dwg. 8800603) Examination for defects	5		3.1	4.4.2.25

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 4 OF 4		DRAWING NUMBER See Below NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Terminal, arming pin (Dwg. 8800600)				
	Examination for defects	5		3.1	4.4.2.26
	Pin, arming (Dwg. 8800599)				
	Examination for defects	5		3.1	4.4.2.27
	Spring rotor (Dwg. 8800630)				
	Examination for defects	5		3.1	4.4.2.28
	Torque test	30-0-1		3.8	4.5.1
	Bushing, insulating (Dwg. 8800632)				
	Examination for defects	5		3.1	4.4.2.29

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. An inspection lot shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot shall contain:

a. Parts of only one lot number from one supplier

b. M36A1 detonators from only one lot number from one supplier.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Washer, detonator				8800628
					NEXT HIGHER ASSEMBLY
					9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Thickness, minimum (min.)		.65%	3.1	Gage
202	Outside diameter, maximum (max.)		.65%	3.1	Gage
203	Inside diameter, minimum (min.)		.65%	3.1	Gage
204	Protective coating incomplete or inadequate		.65%	3.1	Visual
205	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8800627
4.4.2.2	Nut				NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Perpendicularity of either face with pitch diameter of thread		.40%	3.1	Gage
102	Pitch diameter		.40%	3.1	Gage
103	Minor diameter, min.		.40%	3.11	Gage
104	Salt spray	5-0-1		3.7	4.5.6
Minor					
201	Location of wrench holes		.65%	3.1	Gage
202	Thickness, min.		.65%	3.1	Gage
203	Protective coating incomplete or inadequate		.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Cover, Lead Cup				8800610
					NEXT HIGHER ASSEMBLY 8800604/8800608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness		.40%	3.1	Gage
102	Diameter, max.		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Spacer, rotor				8800629
					NEXT HIGHER ASSEMBLY
					9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total length, min.		.40%	3.1	Gage
Minor					
201	Protective finish incomplete or inadequate		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Cup, rotor, lead				8800612
					NEXT HIGHER ASSEMBLY
					8800611
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness through bottom		.40%	3.1	Gage
102	Outside diameter of bottom, max.		.40%	3.1	Gage
103	Total length, max.		.40%	3.1	Gage
Minor					
201	Diameter of flange		.65%	3.1	Gage
202	Protective finish incomplete or inadequate		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Rotor				8800609
					NEXT HIGHER ASSEMBLY 8800608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contour		.40%	3.1	Gage
102	Location of holes		.40%	3.1	Gage
103	Diameter of lead assembly holes, min.		.40%	3.1	Gage
104	Diameter of lead assembly counterbore, min.		.40%	3.1	Gage
105	Depth of lead assembly counterbore, min.		.40%	3.1	Gage
106	Diameter of pivot hole, min.		.40%	3.1	Gage
107	Diameter of arming pin hole, min.		.40%	3.1	Gage
Minor					
201	Total thickness		.65%	3.1	Gage
202	Protective finish incomplete or inadequate		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Cup, booster, lead		8800606
			NEXT HIGHER ASSEMBLY 8800605

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness through bottom		.40%	3.1	Gage
102	Outside diameter of bottom, max.		.40%	3.1	Gage
103	Total length, max.		.40%	3.1	Gage
Minor					
201	Diameter of flange		.65%	3.1	Gage
202	Protective finish incomplete or inadequate		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Retainer, rotor				8800607
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Concentricity of "O" ring shoulder with inside diameter		.40%	3.1	Gage
102	Concentricity of outside diameter with inside diameter		.40%	3.1	Gage
103	Total thickness		.40%	3.1	Gage
104	Outside diameter, max.		.40%	3.1	Gage
105	Location of holes		.40%	3.1	Gage
106	Inside diameter, min.		.40%	3.1	Gage
107	Diameter of lead cup hole		.40%	3.1	Gage
108	Diameter of lead cup hole counterbore, min.		.40%	3.1	Gage
109	Depth of lead cup hole counterbore		.40%	3.1	Gage
110	Diameter of "O" ring shoulder		.40%	3.1	Gage
Minor					
201	Protective coating incomplete or inadequate		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Container				8800602
					NEXT HIGHER ASSEMBLY
					8800601
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total length		.40%	3.1	Gage
102	Distance from end to end plate recess		.40%	3.1	Gage
103	Inside diameter, min.		.40%	3.1	Gage
104	Minor diameter, min		.40%	3.1	Gage
105	Pitch diameter		.40%	3.1	Gage
106	Concentricity of recess at threads with pitch diameter of threads		.40%	3.1	Gage
107	Concentricity of end plate recess with pitch diameter of threads		.40%	3.1	Gage
Minor					
201	Length of thread, min.		.65%	3.1	Gage
202	Thread undercut or relief missing		.65%	3.1	Visual
203	Weld limiting groove missing		.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.10	Container Assembly		8800601
			NEXT HIGHER ASSEMBLY 9216413

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Width of weld, max.		.40%	3.1	Gage
102	End plate distorted		.40%	3.1	Visual
103	Salt spray	5-0-1		3.7	4.5.6
Minor					
201	Weld protrudes beyond edge of container		.65%	3.1	Gage
202	Protective coating incomplete or inadequate		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.11	Tube, center				8800624
					NEXT HIGHER ASSEMBLY
					8800613
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length of center cavity		.40%	3.1	Gage
102	Distance from aft shoulder to forward face of detonator holding boss		.40%	3.1	Gage
103	Diameter of detonator holding boss		.40%	3.1	Gage
104	Diameter of rotor contacting surface		.40%	3.1	Gage
105	Diameter of disc assembly contacing surface		.40%	3.1	Gage
106	Distance from face of detonator holding boss to end of rotor contacting surface		.40%	3.1	Gage
107	Location of detonator holes		.40%	3.1	Gage
108	Location of hole in rear surface		.40%	3.1	Gage
109	Location of fuze positioning slot in relation to detonator holes		.40%	3.1	Gage
110	Pitch diameter large male thread		.40%	3.1	Gage
111	Major diameter, large male thread, max.		.40%	3.1	Gage
112	Pitch diameter small male thread		.40%	3.1	Gage
113	Major diameter small male thread, max.		.40%	3.1	Gage
114	Impregnation test	1/			1/

NOTES:

1/ Sampling, testing, and rejecting shall be in accordance with MIL-I-13857.

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.11	Tube, center - Cont.				8800624
					NEXT HIGHER ASSEMBLY
					8800613
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor 201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.12	Guide, arming				8800598
					NEXT HIGHER ASSEMBLY
					8800596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total length		.40%	3.1	Gage
102	Total diameter		.40%	3.1	Gage
103	Pitch diameter		.40%	3.1	Gage
104	Minor diameter, min.		.40%	3.1	Gage
105	Distance from arming pin surface to front of scarf groove, max.		.40%	3.1	Gage
106	Distance from rear surface to rear of scarf groove, max.		.40%	3.1	Gage
107	Distance from side to top of scarf lip		.40%	3.1	Gage
108	Concentricity of "O" ring groove with outside diameter		.40%	3.1	Gage
109	Diameter of terminal, arming pin holes		.40%	3.1	Gage
110	True position of terminal arming pin holes		.40%	3.1	Gage
111	Depth of groove on side		.40%	3.1	Gage
112	Distance from arming pin surface to forward end of groove on side		.40%	3.1	Gage
113	Distance from arming pin surface to rear end of groove on side		.40%	3.1	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.12	Guide, arming - Cont.				8800598
					NEXT HIGHER ASSEMBLY
					8800596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major					
114	Distance from side to bottom scarf groove		.40%	3.1	Gage
Minor					
201	Length of thread		.65%	3.1	Gage
202	Width of "O" ring groove		.65%	3.1	Gage
203	Diameter of "O" ring groove		.65%	3.1	Gage
204	Protective coating incomplete or inadequate		.65%	3.1	Visual
205	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.13	Disconnect, arming pin		8800597
			NEXT HIGHER ASSEMBLY
			9216413

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter of thread		.40%	3.1	Gage
102	Major diameter of thread, max.		.40%	3.1	Gage
103	Diameter of cotter pin hole, min.		.40%	3.1	Gage
104	Diameter of non threaded length, max.		.40%	3.1	Gage
105	Distance from threaded end to front of scarf groove, max.		.40%	3.1	Gage
106	Total length		.40%	3.1	Gage
107	Width of scarf groove, min.		.40%	3.1	Gage
108	Distance from side to top of scarf lip		.40%	3.1	Gage
109	Concentricity of "O" ring groove with unthreaded diameter		.40%	3.1	Gage
110	Distance from threaded end to cotter pin hole		.40%	3.1	Gage
111	Distance from side to bottom of scarf groove		.40%	3.1	Gage
112	Salt spray	5-0-1		3.7	4.5.6

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.13	Disconnect, arming pin - cont'd.				8800597
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Length of thread		.65%	3.1	Gage
202	Distance from threaded end to front of "O" ring groove		.65%	3.1	Gage
203	Distance from rear surface to rear of "O" ring groove		.65%	3.1	Gage
204	Diameter of "O" ring groove		.65%	3.1	Gage
205	Protective finish improper or inadequate		.65%	3.1	Visual
206	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.14	Arming pin assembly		8800596
			NEXT HIGHER ASSEMBLY 9216413

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length of exposed terminal arming pins		.40%	3.1	Gage
102	Length of exposed arming pin, max		.40%	3.1	Gage
103	Protective finish incomplete or inadequate		.40%	3.1	Visual
104	Salt spray	5-0-1		3.7	4.5.6
Minor					
201	Arming pin not staked securely		.65%	3.1	Manual
202	Terminal arming pin not brazed		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Center tube and terminal block assembly				8800613
					NEXT HIGHER ASSEMBLY
					9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Any component missing or loose		.40%	3.1	Visual/Manual
Minor 201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Assembly, prior to assembly of container and nut				9216413
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor action not free		.40%	3.1	Manual
102	Arming pin assembly set-screw not backed off		.40%	3.1	Manual
103	Any component missing or improper		.40%	3.1	Visual
104	Detonator missing		.40%	3.1	Visual
105	Detonator bushing missing		.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Assembly				9216413
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	Red warning stencil or decal missing or illegible		100%	3.1	Visual
Major					
101	Cotter pin incorrect or improperly assembled		.40%	3.1	Visual
102	Gap at container-center tube junction		.40%	3.1	Visual
103	Dust cap missing		.40%	3.1	Visual
104	Nut or container more than hand tight		.40%	3.1	Manual
105	Leak Test		100%	3.6	4.5.2
106	Electrical continuity test armed & unarmed		100%	3.3	4.5.3
107	Non-arming, arming test		100%	3.4	4.5.4
108	Forty foot drop	10-0-1		3.5	4.5.5
Minor					
201	Lubricant missing from nut and container threads		.65%	3.1	Visual
202	Protective finish incomplete or inadequate		.65%	3.1	Visual
203	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Carton sealed				8799682
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Contents loose		.65%	3.1	Manual
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Shipping container				8799683
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents exposed		.40%	3.1	Visual
102	Contents loose		.40%	3.1	Manual
103	Cover insecure		.40%	3.1	Manual
Minor					
201	Marking missing, misleading or unidentifiable		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	Ground plate				9345288
					NEXT HIGHER ASSEMBLY 9345289
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes		.40%	3.1	Gage
102	Diameter of small end		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.1	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Connector				8800633
					NEXT HIGHER ASSEMBLY 9345289
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter flange thread		.40%	3.1	Gage
102	Major diameter of large thread, max.		.40%	3.1	Gage
103	Pitch diameter of small thread		.40%	3.1	Gage
104	Major diameter of small thread, max.		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Spacer				8800621
					NEXT HIGHER ASSEMBLY
					8800613
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Total length		.65%	3.1	Gage
202	Total diameter		.65%	3.1	Gage
203	Wall thickness		.65%	3.1	Gage
204	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.23	Block, terminal, upper				8800618
					NEXT HIGHER ASSEMBLY 8800613
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of holes		.40%	3.1	Gage
102	True position of holes		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.24	Block, terminal, lower				8800617
					NEXT HIGHER ASSEMBLY
					8800613
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of four upper holes		.40%	3.1	Gage
102	Location of two lower holes		.40%	3.1	Gage
103	Pitch diameter of thread (6 places)		.40%	3,1	Gage
104	Minor diameter of thread, min. (6 places)		.40%	3.1	Gage
105	Length of thread of two lower holes, min.		.40%	3.1	Gage
106	True position of holes (2 places)		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.25	Plate, end				8800603
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total diameter, max.		.40%	3.1	Gage
102	Diameter of hole, min.		.40%	3.1	Gage
103	Concentricity of hole with outside diameter		.40%	3.1	Gage
Minor					
201	Total thickness		.65%	3.1	Gage
202	Evidence of poor workmanship		1.00%	3.11	Gage

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.26	Terminal, arming pin				8800600
					NEXT HIGHER ASSEMBLY
					8800596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Total diameter		.40%	3.1	Gage
Minor					
201	Total length		.65%	3.1	Gage
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.27	Pin, arming				8800599
					NEXT HIGHER ASSEMBLY 8800596
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Pitch diameter of thread		.40%	3.1	Gage
102	Major diameter of thread, max.		.40%	3.1	Gage
Minor					
201	Length of thread		.65%	3.1	Gage
202	Total length		.65%	3.1	Gage
203	Protective finish incomplete or inadequate		.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.28	Spring rotor				8800630
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Torque test	30-0-1		3.8	4.5.1
102	Inside diameter of coil, min.		.40%	3.1	Gage
103	Outside diameter of coil, max.		.40%	3.1	Gage
Minor					
201	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.29	Bushing, insulating				8800632
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter of flange, max.		.40%	3.1	Gage
102	Outside diameter of body, max.		.40%	3.1	Gage
103	Diameter of hole		.40%	3.1	Gage
Minor					
201	Thickness of flange, min.		.65%	3.1	Gage
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.30	Bar, Stop				8800631
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Overall length		.65%	3.1	Gage
202	Height of ends		.65%	3.1	Gage
203	Protective finish missing, improper or inadequate		.65%	3.1	Visual
204	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Connector cable (modified)				8800615
					NEXT HIGHER ASSEMBLY
					8800614
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Connector no cut to proper width		.40%	3.1	Gage
102	Diameter of center hole		.40%	3.1	Gage
Minor					
201	Insert not rotated to proper position		.65%	3.1	Gage
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46570D(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.32	Connector, filtered				9345289
					NEXT HIGHER ASSEMBLY 9216413
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Filters not present		.40%	3.1	Visual
Minor					
201	Length of exposed filters, max.		.65%	3.1	Gage
202	Evidence of poor workmanship		1.00%	3.11	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in Table I and Table II herein as well as the following paragraph.

4.4.3.1 Check test for deterioration of detonators (see MIL-D-20462). If the total time between original acceptance of any detonator lot and the assembly of that lot into the fuzes exceeds two years, or if the detonators have been subjected to adverse conditions, however brief, at any time since previous tests, the detonator lot shall be subjected to and must satisfactorily pass the check test for deterioration specified in MIL-D-20462 immediately before the detonator lot is assembled into the fuzes. This test shall be performed by the contractor on detonators selected by the Government inspector at the facility assembling the detonators into the fuzes (see 6.5).

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the 'Paragraph Reference/Inspection Method' column in Table II starting with paragraph 4.4.2.1 and on EL-9216413. The contractor shall submit, for approval, inspection equipment designs in accordance with the terms of the contract. See section 6 of MIL-A-48078, and 6.3 and 6.4 herein.

4.5 Method of inspection.

4.5.1 Rotor spring torque test. The springs shall be assembled to the applicable test fixture and the torque required to rotate the legs of the spring parallel one to the other shall be recorded. Any spring which fails to comply with the specified drawing requirement shall be classified defective.

4.5.2 Leak test. The fuze assembly shall be tested utilizing the approved equipment and procedures. Any fuze assembly which fails to comply with the applicable requirement shall be classified defective and removed from the lot.

4.5.3 Electrical continuity test. The assembly shall be connected to the approved test fixture and the electrical resistance of the lead circuit shall be measured with the fuze first in the unarmed position and then with the fuze in the armed position. Any assembly which fails to comply with the specified requirement shall be classified defective and removed from the lot. This test shall be performed behind a suitable barricade.

4.5.4 Non-arming and arming test. The fuze less cotter pin or ring assembly (as applicable) shall be assembled to the approved test fixture and the specified force required for arming shall be applied to the arming pin disconnect in a direction so as to withdraw the pin from the assembly. If the arming pin disconnect does not withdraw sufficiently enough to allow the rotor to move to the armed position, the assembly shall be classified defective and removed from the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

After arming, the pin disconnect shall be re-inserted into the assembly. If the rotor fails to return to the fully unarmed position, the assembly shall be classified defective and removed from the lot. If the fuze passes the arming test and the rotor has returned to the fully unarmed position, the specified force required for non-arming shall be applied in the same manner as for arming as specified above. If the arming pin disconnect withdraws from the assembly sufficiently enough to allow the rotor to move to the armed position, the assembly shall be classified defective and removed from the lot. After the non-arming test, the cotter pin or ring assembly (as applicable) shall be assembled to the fuze.

4.5.5 Forty foot drop test. The unarmed fuze shall be assembled to the approved test equipment and submitted to the required free fall. Observation shall be made for exterior damage likely to cause a malfunction and shall then be tested for compliance with 3.3.1. Any unit which functions to any extent or which fails to comply with the requirements of 3.3.1 shall be classified defective. If acceptable, the leads from the electrical power source shall be connected to the external connector pins, the fuze armed and 22 volts applied to effect functioning. Failure of one or more detonators to function shall cause the assembly to be classified defective.

4.5.6 Salt spray test. After application of the protective coating specified on the applicable drawing, the samples shall be subjected to the salt spray test for the period specified on the applicable drawing. If one or more units of the sample show evidence of corrosion after testing, the lot of components represented by the sample shall be rejected.

5. PACKAGING

5.1 Packaging.

5.1.1 Assembled fuze. The assembled fuze shall be packaged in accordance with dwg. 8799682, except that the inner and outer cartons shall not be sealed and the barrier bag and labels shall not be used.

5.2 Packing.

5.2.1 Assembled fuze. The packaged outer cartons shall be packed in accordance with dwg. 8799683.

5.2.2 Rotor lead cups, rotor lead covers, booster lead cups, and barrier bags. The rotor lead cups, rotor lead covers, booster lead cups, and barrier bags shall be packed in accordance with MIL-STD-1169.

5.3 Marking. All marking shall be in accordance with MIL-STD-1169.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.

5.4 Shipping. When component parts from more than one lot are shipped as a carload, each lot shall be kept separate and the division between lots clearly indicated.

6. NOTES

6.1 Intended use. The parts covered by this specification are intended for use on a Demolition Fuze with other demolition items.

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander, U.S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801.

6.4 Army designs. Army designed inspection equipment (See EL-9216413) is not mandatory for use. The contractor may design alternate inspection equipment or use comparable commercial equipment to facilitate his operations. Such contractor prepared designs or commercial equipment must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for appoval as specified in 6.3.

6.5 Cost of check test. The contracting officer will arrange for the contractor to be reimbursed for the expense incurred in the performance of the check test for deterioration of the assemblies. The test shall be conducted at Government expense without cost to the contractor who loaded the detonator assemblies or to the contractor assembling the detonator assemblies into the fuzes, and shall not constitute a basis for rejection against either contractor except where deterioration has occurred as a direct result of carelessness in handling, storage, etc., permitted while the detonator assembly lot was under the jurisdiction of either contractor.

6.6 Grouping of detonators. The resistance of all M36A1 detonators to be used in conjunction with the M1134 fuze shall be measured using the specified measuring procedure. Detonators whose resistance is less than 10 ohms shall be placed in Group I. Detonators whose resistance is equal to or greater than 10 ohms shall be placed in Group II. The M1134 fuze shall be loaded either by using two detonators from Group I or one detonator from Group I and one detonator from Group II.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1375-A236)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:19Z
Check the source to verify that this is the current version before use.