MIL-F-46571E(AR)
15 January 1982
SUPERSEDING
MIL-F-46571D(MU)
9 June 1967

MILITARY SPECIFICATION

FUZE, DEMOLITION KIT, M1134, LOADING ASSEMBLING, AND PACKING

This specification is approved for use by the U. S. Army Armament Research and Develoment Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the loading, assembling, and packing of one type of fuze designated as Fuze, Demolition Kit, M1134.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified, the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078	Ammunition, Standard Quality Assurance Provisions, General Specification For.

STANDARDS

MILITARY

MIL-STD-105	Sampling Procedures and Tables for Inspection by Attributes.

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Command, Attn. DRDAR-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

2.1.2 Other Government documents, drawings, and publications. The following other Government documents form a part of this specification to the extent specified herein.

DRAWINGS

U. S. ARMY ARMAMENT RESEARCH AND DEVELOPMENT COMMAND

PRODUCT AND PACKAGING DRAWINGS

8799682 - Carton, Packing, Ammunition, for Fuze
8799683 - Container, Fiberboard, Ammunition, for Fuze, Demolition Kit, M1134
8800595 - Fuze, Demolition Kit, M1134
8800605 - Booster Lead
8800611 - Rotor Lead
8847494 - Relay Cup, Loading Assembly

INSPECTION EQUIPMENT DRAWINGS

EL-8800595 - Fuze, Demolition Kit, M1134 LAP

(Copies of specifications, standards, drawings, and publications required by the suppliers in connection with specific procurement functions should be obtained from the procuring activity or as directed by the contracting officer).

2.1.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with applicable drawings and specifications.

3.2 Fuze. The loaded fuze shall comply with all requirements specified on Drawing (dwg.) 8800595 and with all requirements specified in applicable specifications.

3.2 Rotor functioning. The rotor assembly in the completely loaded fuze, less container, shall rotate smoothly to the fully armed position when the arming pin assembly is sufficiently retracted to permit arming.

3.4 Electrical continuity of complete fuze.

3.4.1 Safe position. While the arming pin assembly is fully inserted into the completely loaded and assembled fuze, the electrical resistance shall not exceed 0.2 ohms when measured between the pins of the external connector.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

3.4.2 Armed position. When the arming pin assembly is sufficiently retracted to permit arming of the completely loaded and assembled fuze, the electrical resistance between the pins of the external connector, shall not be less than 3 ohms nor more than 5.5 ohms.

3.5 Leak test. The complete fuze shall show no evidence of leakage when tested as specified in 4.5.4

3.6 Explosive functioning. The fuze shall function satisfactorily when tested as specified in 4.5.5.

3.7 Specific gravity of booster. The specific gravity of the booster lead assembly shall be in accordance with the requirements of the applicable drawing when tested as specified in 4.5.1.

3.8 Specific gravity of rotor. The specific gravity of the rotor lead assembly shall be in accordance with the requirements of the applicable drawing when tested as specified in 4.5.1.

3.9 Workmanship. All parts shall be loaded and assembled in a thorough workmanlike manner. They shall be clean and free of burrs, distortion, dirt, grease, corrosion products and other foreign matter. The cleaning method used shall not be injurious to any other part nor shall the parts be contaminated by the cleaning agent. Surface coatings shall be continuous except for a few light scratches not exposing base metal. All required markings shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspection. The following types of inspection shall be conducted on this item:

a. First article inspection

b. Quality conformance inspection

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated:

Part Description	Drawing	Quantity
Rotor Lead Assembly	8800611	20
Rotor Assembly	8800608	5
Booster Lead Assembly	8800605	20
Disc Assembly	8800604	5

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

Part Description	Drawings	Quantity
Fuze, Demolition Kit, M1134 Loading Assembly (prior to assembly of "O" ring, container, and nut)	8800595	5
Fuze, Demolition Kit, M1134 Loading Assembly	8800595	10

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Rotor Lead Assembly (Dwg. 8800611)				
	Examination for defects	20		3.1	4.4.2.1
	Specific gravity test	20		3.8	4.5.1
	Rotor Assembly (Dwg. 8800608)				
	Examination for defects	5		3.1	4.4.2.2
	Booster Lead Assembly (Dwg. 8800605)				
	Examination for defects	20		3.1	4.4.2.3
	Specific gravity test	20		3.8	4.5.1
	Disc Assembly (Dwg. 8800604)				
	Examination for defects	5		3.1	4.4.2.4
	Fuze, Demolition Kit, M1134 Loading Assembly (prior to assembly of "O" ring, container, and nut) (Dwg. 8800595)				
	Examination for defects	5		3.1	4.4.2.5
	Rotor functioning	5		3.3	4.5.2

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH CATEGORY	TITLE / EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	DRAWING NUMBER / NEXT HIGHER ASSEMBLY / PARAGRAPH REFERENCE /INSPECTION METHOD
	SHEET 2 OF 2				See Below
	Fuze, Demolition Kit, M1134 Loading Assembly (Dwg. 8800595)				
	Examination for defects	10		3.1	4.4.2.6
	Electrical continuity safe position	10		3.4.1	4.5.3/EL-8800595
	Electrical continuity armed position	10		3.4.2	4.5.3/EL-8800595
	Leak test	10		3.5	4.5.4/EL-8800595
	Explosive functioning	10		3.6	4.5.5/EL-8800595

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of Demolition Kit Fuzes shall contain:

a. Fuze metal part assemblies of one lot number from one supplier.

b. Composition A5 from not more than one lot or, if made inhouse, from not more than one batch or homogeneous blend of batches.

4.4.2 Examination. See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Test Tables, Table II, sampling plans and procedures for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Rotor lead assembly				8800611
					NEXT HIGHER ASSEMBLY 8800608
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance base to shoulder maximum (max.)		.40%	3.1	Gage
102	Diameter		.40%	3.1	Gage
103	Charge above flush		.40%	3.1	Gage
104	Specific gravity incorrect	20-0-1		3.8	4.5.1
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Rotor assembly				8800608
					NEXT HIGHER ASSEMBLY 8800595
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Rotor lead cup missing (2 places)		.40%	3.1	Visual
102	Lead cup cover above flush (2 places)		.40%	3.1	Gage
103	Lead cup cover improperly staked		.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 8800605
4.4.2.3	Booster lead assembly				NEXT HIGHER ASSEMBLY 8800604
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance base to shoulder max.		.40%	3.1	Gage
102	Diameter		.40%	3.1	Gage
103	Charge above flush		.40%	3.1	Gage
104	Specific gravity incorrect	20-0-1		3.7	4.5.1
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Disc assembly				8800604
					NEXT HIGHER ASSEMBLY 8800595
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Booster lead assembly missing		.40%	3.1	Visual
102	Lead cup cover above flush		.40%	3.1	Gage
103	Lead cup cover improperly staked		.40%	3.1	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil - Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.5	Fuze, Demolition Kit, M1134 Loading Assembly prior to assembly of "O" ring, container, and nut				8800595
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any component missing or damaged		.40%	3.1	Visual
102	Screws holding disc assembly loose		.40%	3.1	Manual
103	Rotor functioning		100%	3.3	4.5.2
Minor					
201	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

MIL-F-46571E(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.6	Fuze, Demolition Kit, M1134, Loading Assembly				8800595
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Electrical continuity safe position		100%	3.4.1	4.5.3/EL-8800595
2	Cotter pin missing		100%	3.1	Visual
3	Red warning stencil (or decal) missingor illegible		100%	3.1	Visual
Major					
101	Dust cap missing		.40%	3.1	Visual
102	Torque of nut		.40%	3.1	Manual
103	Torque of container		.40%	3.1	Manual
104	Electrical continuity armed position		100%	3.4.2	4.5.3/EL-8800595
105	Leak test		100%	3.5	4.5.4/EL-8800595
106	Explosive functioning	10-0-2 30-1-2		3.6	4.5.5/EL-8800595
Minor					
201	Protective coating damaged		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

DRDAR-QA Form 160 Jul 77 Replaces SARPA-QA Form 2567 Feb 74 Which is Obsolete

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Inner carton, sealed				8799682
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Contents loose		.40%	3.1	Manual
Minor					
201	Marking misleading, missing or unidentifiable		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Barrier bag, sealed				8799682
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Area for subsequent seals missing		.40%	3.1	Visual
102	Air not exhausted		.40%	3.1	Visual
103	Carton corners not blunted		.40%	3.1	Visual - Manual
Minor					
201	Marking incorrect, incomplete, or illegible		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.9	Outer carton, sealed				8799682
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Carton damaged		.40%	3.1	Visual
102	Contents loose		.40%	3.1	Manual
103	Closing flaps insecure		.40%	3.1	Manual
Minor					
201	Marking incorrect, incomplete, or illegible		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

TABLE II. Quality conformance inspection - Continued

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.10	Shipping container				8799683
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Carton damaged		.40%	3.1	Visual
102	Contents loose when tilted		.40%	3.1	Manual
103	Closing flalps not secure		.40%	3.1	Manual
Minor					
201	Marking missing, misleading or unidentifiable		.65%	3.1	Visual
202	Evidence of poor workmanship		1.00%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in Tables I and II herein.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the 'Paragraph Reference/Inspection Method' column in Table II starting with paragraph 4.4.2.1 and on EL-8800595. The contractor shall submit, for approval, inspection equipment designs in accordance with the terms of the contract. See section 6 of MIL-A-48078 and 6.3 herein.

4.5 Method of inspection.

4.5.1 Specific gravity of booster lead and rotor lead assemblies. The sample shall be weighed and the weight recorded as A. The exposed explosive surface of each lead assembly shall be coated with a thin coat of molten wax. After the wax has solidified, the sample shall be weighed and the weight recorded as B. A 50 cubic centimeter (cc) pycnometer (specific gravity bottle) shall be filled with distilled water at 20, plus or minus 2 degrees centigrade (C.) and weighed. The weight of the empty pycnometer shall be substracted from the water filled pycnometer and this weight difference recorded as D. The sample shall be transferred to the pycnometer, all air bubbles shall be removed, water (at 20 degrees C. plus or minus 2 degrees C.) shall be added, if necessary to fill the pycnometer and the pycnometer and contents weighed. The weight of the empty pycnometer shall be subtracted from the preceding weight determination and the result recorded as E. The explosive and wax shall be removed from the lead cups (toluene followed by acetone with a final washing in toluene is suggested) and the clean cups shall be weighed, the weight shall be recorded as F and the cups transferred to the pycnometer. With approximately 35 cc of water in the pycnometer, the water and lead cups shall be boiled under vacuum to remove all air bubbles. The pycnometer and its contents shall be cooled to 20 degrees C., plus or minus 2 degrees C., distilled water at the same temperature added to fill the pycnometer and weighed. The weight of the empty pycnometer shall be subtracted from the preceeding weight determination and the result recorded as G. Weight B shall be subtracted from weight E and this difference subtracted from weight D, this result shall be recorded as J. Weight B shall be subtracted from weight A and the difference shall be divided by the specific gravity of the wax at 20 degrees C. plus or minus 2 degrees C. The result of the preceeding calculation shall be recorded as K. Weight F shall be subtracted from weight A and this result shall be recorded as L.

The specific gravity of the explosive shall be calculated as follows:

$$\text{Specific gravity} = \frac{L}{H - (J + K)}$$

where:

L = weight of explosive in grams

H = weight of water displaced by loaded, waxed sample in grams which is equivalent to volume in cubic centimeters.

J = weight of water displaced by empty lead cups in grams which is equivalent to volume in cubic centimeters.

K = weight of water displaced in grams is equivalent to volume of wax in cubic centimeters.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

4.5.2 Rotor functioning. The fuze less container, shall be assembled to the applicable test equipment. The arming pin assembly shall be retracted sufficiently to permit functioning of the rotor. Observation shall be made for rotor movement (In the fully armed position, one end surface of the rotor shall be visually flush with the edges of the adjacent plates). The assembly shall be classified defective if the rotor fails to move smoothly to the fully armed position.

WARNING: This test may be hazardous and should be performed behind a suitable barricade containing a window or series of mirrors, etc., for visual observation.

4.5.3 Electrical continuity. The fuze shall be assembled to the applicable test equipment and the arming pin assembly shall be retracted sufficiently to permit functioning of the rotor. The resistance shall be measured between the pins of the external connector. The arming pin assembly shall be completely reseated and the resistance measured between the pins of the external connector. The fuze shall be classified defective if the resistance fails to conform to the requirements for the fuze in the armed position while the arming pin assembly is retracted or if the resistance exceeds the specific requirement for the fuze in the safe position when the arming pin assembly is fully seated. The test equipment should limit the current to 1 milliampere to preclude inadvertent functioning of the electric detonators.

WARNING: This test may be dangerous and should be performed behind a suitable barricade.

4.5.4 Leak test. The fuze assembly shall be tested utilizing the applicable test equipment and applicable procedure specified in 4.4.2.6. Any fuze assembly which fails to comply with the applicable requirement shall be classified defective.

4.5.5 Explosive functioning. The fuze shall be held firmly in a fixture or clamp with the longitudinal axis of the fuze held horizontally. Two pieces of 100 grain detonating cord approximately 12 inches long with relays (see dwg. 8847494) attached to one end of each shall be positioned to align the relay end of the detonating cord with the booster charges in the fuze and firmly held to leave a minimum gap 1/16 inch between the fuze container surface and the end of the relay. An external electrical power source of 22 volts direct current shall be connected to the pins of the external connector through an open switch. The arming pin assembly shall be retracted completely and the switch to the external electrical power source closed. The fuze shall be classified defective if one or both detonating cords fail to function completely.

5. PACKAGING

5.1 Preservation and packaging.

5.1.1 Level A. The fuze shall be preserved, packaged and marked in accordance with dwg. 8799682.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.

5.2 Packing.

5.2.1 Level A. The packaged fuze shall be packed and marked in accordance with dwg. 8799683.

6. NOTES

6.1 Intended use. The item covered by this specification is intended to be used as a Demolition Fuze with other demolition items.

6.2 Ordering dates. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. See MIL-A-48078. Submit equipment designs as required to Commander, U.S. Army Armament Research and Development Command, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801.

6.4 Army designs. Army designed inspection equipment (See EL-8800595) is not mandatory for use. The contractor may design alternate inspection equipment or use comparable commercial equipment to facilitate his operations. Such contractor prepared designs or commercial equipment selections must be approved by the Government prior to fabrication or procuring of the equipment. Designs shall be submitted for approval as specified in 6.3.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1375-A237)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T06:20Z
Check the source to verify that this is the current version before use.