NOTICE OF INACTIVATION

NOT MEASUREMENT SENSITIVE

TOP-10-2-152
NOTICE 1
25-Mar-2026

TEST OPERATIONS PROCEDURE

Textile Repair Shop, Trailer Mounted

TOP-10-2-152, dated 25-Nov-1968, is inactive for new design and is no longer used, except for replacement purposes.

Custodians:
Army - TE

Preparing Activity:
Army - TE

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil

AMSC N/A

AREA ENVR

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T14:54Z
Check the source to verify that this is the current version before use.