INCH-POUND

MIL-DTL-7560D
AMENDMENT 1
22 January 1999

DETAIL SPECIFICATION

VALVE ASSEMBLY, OXYGEN CYLINDER, BAILOUT

This amendment forms a part of MIL-DTL-7560D, dated 20 June 1997, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 2

Add "2.2.2 Non-Government publication. The following document forms a part of this document to the extent specified herein. Unless otherwise specified, the issues of the documents which are DOD adopted are those listed in the issue of the DODISS cited in the solicitation. Unless otherwise specified, the issues of documents not listed in the DODISS are the issues of the documents cited in the solicitation (see 6.2).

AMERICAN NATIONAL STANDARDS INSTITUTE/AMERICAN SOCIETY FOR QUALITY (ANSI/ASQ)

ANSI/ASQ Z1.4 - Sampling Procedures and Tables for Inspection by Attributes (DOD-adopted)

(Application for copies should be addressed to American Society for Quality, P.O. Box 3066, Milwaukee, WI 53201-3066, or to the American National Standards Institute, 11 West 42nd Street, 13th Floor, New York, NY 10036.)"

PAGE 4

4.3.1.1, delete paragraph and add "4.3.1.1 Procedure. These components shall be sampled in accordance with ANSI/ASQ Z1.4 at the "normal" inspection level."

DISTRIBUTION STATEMENT A. Approved for public release; distribution unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T08:35Z
Check the source to verify that this is the current version before use.

Delete Table I, II and III, replace with:

TABLE I. Valve Assembly - quality conformance inspection, sampling, and acceptance criteria

Inspection	Method	Sample size; ANSI Z1.4	Acceptance criteria
Visual examination see table IV		Each valve	Reject all defective valves
Examination of dimensions	4.5.2	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Leakage	4.6.1.1	Each valve	Acceptance number - 0 Rejection number - 1
Retaining pin removal force	4.6.1.2	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Fill and operation	4.6.1.3	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Actuating cable housing attachment	4.6.1.4	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Actuating cable assembly attachment	4.6.1.5	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Operation at high and low temperature	4.6.1.6	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Hose fitting to hose attachment	4.6.1.8	4.3.1; S-2	Acceptance number - 0 Rejection number - 1

TABLE II. Flow controller - Quality conformance inspection, sampling, and acceptance criteria

Inspection	Method	Sample size; ANSI Z1.4	Acceptance criteria
Visual examination	Table IV	Each flow controller	Reject all defective flow controllers
Examination of dimensions	4.5.2	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Total flow	4.6.2.1	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Flow at high and low temperatures	4.6.2.2	4.3.1; S-2	Acceptance number - 0 Rejection number - 1

TABLE III. Break-off nipple, conformance inspection, sampling, and acceptance criteria

Inspection	Method	Sample size; ANSI Z1.4	Acceptance criteria
Visual examination	Table IV	Each nipple	Reject all defective nipples
Examination of dimensions	4.5.2	4.3.1; S-2	Acceptance number - 0 Rejection number - 1
Leakage	4.6.3.1	Each nipple	Reject all defective nipples
Fracture	4.6.3.1	4.3.1; S-4	Acceptance number - 0 Rejection number - 1

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T08:35Z
Check the source to verify that this is the current version before use.

Custodians:
Army – AV
Navy – AS
Air Force – 99

Reviewing Activities:
Air Force – 11
DLA - GS

Preparing activity:
Air Force – 71

Agent:
Air Force – 99

(Project 1660-0807)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T08:35Z
Check the source to verify that this is the current version before use.