MILITARY SPECIFICATION

LIGHT, SIGNAL, HAND HELD, AIRCRAFT, TYPE MA-1

This amendment forms a part of Military Specification MIL-L-7569A (USAF) dated 11 August 1969.

Page 2, paragraph 2.1, delete "MS33586 Metal, Definition of Dissimilar" and substitute "MIL-STD-889 Dissimilar Metals".

Page 2, paragraph 3.4.2, delete reference to "MS33586" and substitute "MIL-STD-889".

Page 2, paragraph 3.5, delete the fourth sentence and substitute the following: "The electrical circuit shall be designed such that there is no shock hazard present under any conditions."

Page 2, paragraph 3.5, in the fifth sentence delete reference to "MS28925" and substitute "Figure 1A".

Page 3, paragraph 3.5.1, in the fifth sentence delete "MS28925" and substitute "MS28925-20."

Page 3, paragraph 3.5.1, in the sixth sentence delete "MS28925" and substitute "MS28925-21."

Page 3, paragraph 3.5.4, delete the first sentence and add the following: "The light assembly shall be furnished complete with a molded coil-type retractable rubber-covered cord. The cable shall contain a sufficient number of conductors to provide power to lamps, through the switch, and prevent shock to the user. In general, this will mean a two conductor cable for a plastic housing and a three conductor cable for a metal housing."

Page 3, paragraph 3.8, delete the first sentence and substitute the following: "The dimensions shall conform to those shown in Figure 1A".

Page 4, delete "Figure 1" and substitute "Figure 1A".


Custodian:
Air Force-71

Preparing activity:
AirForce-71

Reviewing activity:
Air Force-71

FSC 5850

Source: https://assist.dla.mil -- Downloaded: 202640-17T08:36Z
Check the source to verify that this is the current version before use.



LIGHT ASSEMBLY
FIGURE 1A
Page 2 of 2

Source: https://assist.dla.mil -- Downloaded: 20260-17T08:36Z
Check the source to verify that this is the current version before use.