MILITARY SPECIFICATION

SIGNALS, ILLUMINATION, AIRCRAFT, DOUBLE-STAR
AN-M37A2 THROUGH AN-M42A2 (ALTERNATIVE CASE)
PARTS AND LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-S-48251 (PA) dated 26 September 1973.

PAGE 11

4.3.2.3 Delete: "Major: AQL 0.65 percent" and substitute "Major: AQL 1.00 percent"

Add: "Major 105. Length of protruding quick-match (with baffle when applicable) . . . . . 03012"

PAGE 13

4.3.2.5 Delete: "Major None defined" and substitute "Major: AQL 0.40%
101. Baffle missing (when applicable).....Visual 05003"

PAGE 16

4.3.2.13: Add the following:

"4.3.2.13 Baffle (see dwg. 9313654 covering a detail of dwg. 9278328) (when applicable).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
	101 Small hole(s) missing	Visual	13005

FSC: 1370

Source: https://assist.dla.mil -- Downloaded: 202610-22T19:19Z
Check the source to verify that this is the current version before use.

Minor:		AQL 1.50 percent		
201.	Diameter of baffle	Gage		13006
202.	Thickness	Gage		13007
203.	Evidence of poor workmanship (see 3.8)	Visual		13008"

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1370-A-054

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:19Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:19Z
Check the source to verify that this is the current version before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:19Z
Check the source to verify that this is the current version before use.