INCH-POUND

MIL-C-60943A(AR)
AMENDMENT 3
28 July 1991
SUPERSEDING
AMENDMENT 2
19 February 1985

MILITARY SPECIFICATION

CARTRIDGE, 40mm, HE, M384
LOADING, ASSEMBLING AND PACKAGING

This Amendment forms a part of Military Specification MIL-C-60943A (MU), dated 9 March 1970 and is approved for use by the U.S. Army Armament, Munitions, and Chemical command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Add the following preamble underneath the title:

"This specification is approved for use by the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense."

PAGE 2

Drawings: Add

"9362543 -Packing and Marking of Shipment and storage Container M548 with linked 40mm Cartridges"

* Paragraph 2.1, under Drawings, Add:

"8796522 -Marking Diagram and Sealing for wood packing Boxes
9251995 -Box, Wirebound, Packing, Ammunition for Cartridge, 40mm Linked
9251996 -Box, Fiber, Packing, Ammunition for cartridge, 40mm, Linked
9325874 –Packing for Light Boxes
19-48-4116 -Basic Procedures Unitization Procedures for Boxed Ammunition and Components on 4-Way Entry Pallets
19-48-4138 -Basic Procedures Unitization Procedures for Boxed Ammunition and Components on Skidded Bases

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

PAGE 3

3.3, last line after "position": Add the following:

"or presence of the setback pin flange seated against bottom surface of the rotar plate (Dwg. 8876197) counterbore"

3.6.1, line 2: Delete "790 ± 15" and substitute "795 ± 20".

PAGE 4

Add new paragraph 3.9 as follows:

"3.9 X-ray examination of ballistic samples. Prior to forwarding the cartridges to the proving ground for ballistic testing, as specified in 4.3.3.13 and 4.3.3.14, they shall be subjected to x-ray examination when tested as specified in 4.4.16".

PAGE 6

4.3.1g: Delete in its entirety and substitute the following:

"g. Cartridge in less than full belt quantities shall be handled in the following manner:

(1) If remaining quantity exceeds 25 rounds, use rounds from next lot to complete belt.

(2) If remaining quantity is less than 25 rounds, include rounds in next lot produced.

(3) Packing box and data cards shall be annotated as to the mixture."

* 4.3.1g: Delete in its entirety and substitute the following:

"g. Cartridges in less than full belt quantities shall be handled as described in para 5.5."

4.3.2.8: Add Major defect 104 as follows:

"104. Support missing Visual 08004"

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

Under Drawing number add

"or 9362543"

Add majors 105 and 106:

"105.	Spacer missing (when applicable)	Visual	08005
106.	Top pad missing (when applicable)	Visual	08006".

* 4.3.2.8: Delete all Major categories and substitute:

"101.	Incorrect number or cartridges in full boxes	Visual	08001
102.	Cartridge inverted	Visual	08002
103.	Fillers missing	Visual	08003
104.	At the beginning and end of lot - more than one ammunition lot per box	Visual	08004"

4.3.2.11:

Under Drawing Number add "or 9362543"

Under Title add "or sealed shipping and storage container"

Change Major 101: "101. Box or container damaged Visual 11002:

* 4.3.2.11, Add under major category:

"102.	Light boxes prepared in improper-manner (see 4.3.1g)	Visual	

* Add the following examination subparagraphs:

4.3.2.12 Unsealed shipping and storage container M548 (see dwg 9362543).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Incorrect number of cartridges in full. boxes	Visual	12001

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

102.	Fillers, supports and spacers not positioned properly or missing	Visual	12002
103.	Top pad not positioned properly or missing	Visual	12003
104.	Cartridge inverted	Visual	12004
105.	At beginning and end of lot - more than one ammunition lot per box	Visual	12005

Minor: None defined."

* 4.3.2.13 Sealed shipping and storage container M548 (see dwg. 9362543).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Light boxes prepared in improper manner	Visual	13001
Minor:	AQL 1.50 percent		
201.	Marking misleading or unidentifiable	Visual	13002
202.	Contents loose	Manual	13003"

PAGE 11

4.3.3.4: After "assembly" add the following:

"beginning with the first group produced (a "group" is defined as a quantity consisting of four (4) hours production) and continuing until one-hundred (100) consecutive groups have been accepted under the criteria specified. Thereafter, ten (10) base plug and primer assemblies shall be randomly selected every four (4) hours from each automatic primer assembly machine."

PAGE 12

4.3.3.11, line 4: Delete "as M384 Cartridges" and substitute "to an M533 Fuze Test Vehicle (Dwg. 9206914)."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

PAGE 13

4.3.3.13:

Line 14: Delete "three-hundred (300)" and substitute "five-hundred (500)"

Last sentence: Delete in its entirety and substitute the following:

"The sample cartridges shall be selected at random prior to linking and then linked with the same lot of links to which its respective end item lot has been assembled."

4.3.3.13.1a: Delete "Thirteen (13)" and substitute "Twenty-two (22)".

PAGE 14

4.3.3.13.1.1: Delete in its entirety.

4.3.3.14: Delete in its entirety and substitute the following:

"4.3.3.14 Functioning (see para 3.6), Major defect, Regular Production, Code No. 22001. - After three (3) consecutive lots have met the criteria of 4.3.3.13, the Government inspector shall select three-hundred (300) cartridges from each lot and subjected to this test. The sample cartridges shall be selected at random prior to linking and then linked with the same lot of links to which its respective end item lot has been assembled."

4.3.3.14.1:

a: Delete "Seven (7)" and substitute "Twenty (20)".

h: Delete "300" and substitute "500".

PAGE 15

4.3.3.14.1.1:

Line 1: Delete "four (4) to six (6)" and substitute "thirteen (13) through nineteen (19)".

Line 2: Delete "one-hundred (100)" and substitute "three-hundred (300)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

Line 4: Delete "nine (9)" and substitute "twenty-seven (27)".

4.3.3.16: Delete the first sentence and substitute the following:

"Two (2) full boxes (100 linked cartridges) shall be randomly selected from a complete linked lot and subjected to this test."

Add new paragraphs 4.3.3.17, 4.3.3.18 and 4.3.3.19 as follows:

"4.3.3.17 Pot life of adhesive (see 6.11), (see Dwg. 9217500), Major defect, Code No. 25001. - Each batch of adhesive mixed for use in assembly of fuzes to bodies shall be subjected to this determination. If any batch fails to comply with the applicable requirements, it shall not be used for assembly of fuzes to bodies. Projectile assemblies which have been assembled with adhesive which exceeded the pot life requirement shall be disassembled, cleaned and new adhesive applied. The test shall be performed as specified in 4.4.14.

4.3.3.18 Disassembled torque of fuze (see Dwg. 8886398), Major defect, Code No. 26001. - One (1) cartridge shall be selected from each batch of adhesive and held for 24 hours, after which each of the selected cartridges shall be subjected to this test. If any cartridge fails to comply with the applicable requirement the lot shall be rejected. This test shall be performed as specified in 4.4.15 using equipment in accordance with 4.3.4.

4.3.3.19 X-ray examination of ballistic sample (see para 3.9), Code No. 27001. - Prior to forwarding the cartridges to the proving ground for ballistic testing, as specified in 4.3.3.13 and 4.3.3.14, they shall be subjected to x-ray examination. The cartridges shall be x-rayed for critical and major defects. If any critical defect is found, it shall be noted and the samples forwarded to the proving ground. There shall be no replacement of samples. This test shall be performed as specified in 4.4.16 using equipment in accordance with 4.3.4."

4.4.7: Add the following sentence:

"Side view shall show the flange of the setback pin seated against bottom surface of the rotar plate (Dwg. 8876197) counterbore."

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

Add new paragraphs 4.4.14, 4.4.15, and 4.4.16 as follows:

"4.4.14 Pot life of adhesive. - The time from preparation of the adhesive for use in assembly of fuzes to bodies, to its application shall be determined. Any method considered satisfactory to the Contracting Officer may be used in performing this determination. This is a non-destructive test. Adhesive so tested shall be returned to the lot.

4.4.15 Disassembly torque of fuze. - The projectile assembly shall be placed in a fixture as specified on the Equipment List and the torque specified on Dwg. 8886398 shall be applied. This is a destructive test, no cartridges so tested may be returned to the lot.

4.4.16 X-ray examination of ballistic samples. - The cartridge, prior to forwarding to the proving ground, shall be subjected to x-ray examination using the x-ray equipment specified on the Equipment List or any other method satisfactory to the Contracting Officer. This test is a non-destructive test. Parts so tested may be returned to the lot. This test shall be conducted in two places. From the top of the fuze assembly down and from the side."

5.1.1: Add "or 9362543 as applicable"

5.2.1: Add "or 9362543 as applicable"

* 5.3 Add the following to sentence:

"or drawing 9362543 as applicable"

* Add the following para 5.5:

"5.5 Cartridges in less than full belt quantities shall be handled in the following manner:

(1) An ammunition box (exterior pack, shipping and storage container, or fiber packing box) will not contain more than one lot of ammunition per box.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.

(2) Less-than-full-boxes (light boxes) of an ammunition item are limited to only one lot of ammunition per box (see Procedures 19-48-4116 and 19-48-4138) and shall be packed in accordance with dwg. 9325874.

(3) Light boxes shall be painted and marked in accordance with "MARKING INSTRUCTIONS FOR LESS THAN FULL BOXES" in drawing 8796522."

PAGE 22

Add new paragraph 6.11 as follows:

"6.11 The period of time during which an adhesive after mixing with catalyst, solvent or other compounding ingredients, remains suitable for use."

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity
Army-AR

(Project 1310-A481)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T01:06Z
Check the source to verify that this is the current version before use.