MIL-A-50292 (MU)
Amendment 1
15 March 1972

MILITARY SPECIFICATION

ADAPTER AND TEST PLUG ASSEMBLY: TRAINING

This amendment forms a part of Military Specification MIL-A-50292 (MU), dated 29 May 1970.

Page 1 STANDARDS, MILITARY: Add "MIL-STD-810-Environmental Test Methods".

Page 2 and 3 Delete paragraphs 3.6, 3.7, 3.8 and 3.9 and substitute:

"3.6 Environmental testing. The adapter and test plug assembly shall comply with MIL-STD-810, visual inspection and failure criteria, section 3. The adapter and test plug assembly shall also comply with 3.4 and 3.5 before and after each environmental test. Testing shall be as specified in 4.4.3. Tests shall be conducted in the order specified.

3.6.1 Low Temperature. The adapter and Test plug assembly shall withstand exposure to a storage temperature of -13±5 degrees fahrenheit (°F) for a duration of 48 hours, min and shall comply with 3.4 and 3.5 while at -13±5°F when tested as specified in 4.4.3.1.

3.6.2 High Temperature. The adapter and test plug assembly shall withstand exposure to a temperature of 125 ± 5°F and shall comply with 3.4 and 3.5 while at 125 ± 5°F when tested as specified in 4.4.3.2.

3.6.3 Transportation Vibration. The adapter and test plug assembly packed for shipment shall withstand vibration when tested as specified in 4.4.3.3.

3.6.4 Humidity. The adapter and test plug assembly shall withstand exposure to a humid atmosphere when tested as specified in 4.4.3.4.

Page 4 Table II Delete tests 4, 5, 6, and 7 and substitute:

Examination or Test	Contractor's Inspection Permissable Before Submission	Non Dest	Assemb	Sub Assemb	Part
4. Low temperature (see 3.6.1)	x	x	x		
5. High temperature (see 3.6.2)	x	x	x		
6. Transportation Vibration (see 3.6.3)	x	x	x		

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:20Z
Check the source to verify that this is the current version before use.

Examination or Test	Contractor's Inspection Permissable Before Submission	Non Dest	Assemb	Sub Assemb	Part
7. Humidity (see 3.6.4)	x	x	x		

Page 9 Delete 4.4.3, 4.4.4, 4.4.5, and 4.4.6 and substitute:

"4.4.3 Environmental Testing (see 3.6)

4.4.3.1 Low Temperature (see 3.6.1). The adapter and test plug assembly shall be tested in accordance with MIL-STD-810, Method 502.

4.4.3.2 High temperature (see 3.6.2). The adapter and test plug assembly shall be tested in accordance with MIL-STD-810, Method 501, procedure I.

4.4.3.3 Transportation vibration (see 3.6.3). The adapter and test plug assembly shall be tested in accordance with MIL-STD-810, Method 514, Table 514-I, Procedure X, curve AB, Fig 514-6. The equipment shall not be operated during the test.

Custodian
Army-MU

Preparing Activity
Army-MU
Project No 1195-A106

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:20Z
Check the source to verify that this is the current version before use.