MILITARY SPECIFICATION

FUZE, POINT DETONATING, M739

LESS BOOSTER PELLET

This Amendment forms a part of Military Specification MIL-F-48277B (AR), 24 August 1978

PAGE 2

Paragraph 3.5: Delete in its entirety and substitute the following:

3.5 Fuze Leak Test-The Fuze Assemblies, less Booster Pellet and Booster Cup, shall comply with MIL-STD-331, Test No. 108 except that the duration of immersion shall be five (5 plus or minus 0.5) minutes and the pressure shall be three (3 plus or minus 0.5) PSI gauge."

PAGE 5

Paragraph 4.3.1: Add subparagraph f. as follows:

f. Fifty (50) each (dwg. 9258606) Fuze Body Assemblies for the Leak Test (see 4.5.8).

PAGE 56

Paragraph 4.4.2.46: Add Special Defect as follows:

Special

a. Presence of spinlock springs, 100%, 3.2, Gage

PAGE 64

Paragraph 4.4.2.53: Change the sample size for Major 103, Leak Test, from 80 to 12.

PAGE 69

Paragraph 4.4.3.6: Add new paragraph as follows:

4.4.3.6 Fuze Leak Test

4.4.3.6.1: Beginning with the first lot produced and continuing until three consecutive lots have been found acceptable, a sample of fifty (50) fuzes shall be randomly selected from each lot for use in the leak test specified in 4.5.8. If two (2) or more assemblies are classed defective,

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.

the lot shall be rejected.

4.4.3.6.2 After three consecutive lots have complied with the criteria of 4.4.3.6.1, the sample size shall be as specified in 4.4.2.53. If two (2) or more assemblies are classed defective, the lot shall be rejected. If only one (1) assembly is classed defective, a second sample of thirty-eight (38) assemblies shall be tested and the lot rejected if any additional failures are found. In the event of lot rejection the sampling plan for the next lot shall revert to that of 4.4.3.6.1 and continue until three consecutive lots have again been accepted.

PAGE 71

Paragraph 4.5.8: Delete in its entirety and substitute the following:

4.5.8 Leak Test - The test shall be performed in accordance with the procedure specified in MIL-STD-331, Test No. 108, except as provided in 3.5 and herein. When immersing the test assemblies in the water solution, care should be taken to displace all externally entrapped air. The test assemblies should be submerged in a horizontal position for testing. After completion of the test and drying of the samples, the assemblies shall be sectioned to reveal all cavities internal to the various seals. Examine all external and internal surfaces of parts for evidence of water entry using ultra-violet light. Any assembly that does not comply with the requirements of 3.5 shall be classed defective. Assemblies subjected to this test shall not be returned to the lot.

PAGE 73

Paragraph 4.5.16: Delete in its entirety and substitute the following:

4.5.16 Push test on pallet shaft. - The Lower Plate and Shaft Assembly after staking or pressing shall be held in an appropriate test fixture and the required pushout force shall be applied axially to the pallet shaft from the staked or press-fit side of the plate. If two or more assemblies fail to withstand the two-pound pushout force, the lot shall be rejected. Assemblies subjected to this test may be returned to the lot.

Custodian:
Army-AR

Preparing Activity:
Army-AR

Project Number; 1390-A232

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:20Z
Check the source to verify that this is the current version before use.