MIL-C-48143C (PA)
26 March 1976
SUPERSEDING
MIL-C-48143B(PA)
23 September 1975

MILITARY SPECIFICATION

CHARGE, PROPELLING, 8 INCH, M188 LOADING, ASSEMBLING, AND PACKING

This specification is approved for use by Picatinny Arsenal, Department of the Army, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the loading, assembling and packing for one type of propelling charge designated as Charge, Propelling, M188, for 8 Inch Howitzer, M110A1.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids or request for proposals form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-P-223	-	Powder, Black
MIL-A-48078	-	Ammunition, Standard Quality Assurance Provisions, General Specification For

DRAWINGS

PICATINNY ARSENAL

PRODUCT AND PACKAGE DRAWINGS

9283094- Packing and Marking for Container, Ammo, Metal PA66 for Charge Propelling 8 in. M188 for, How. SP, M110A1

9277173- Charge, Propelling, 8 Inch, M188 for 8 Inch Howitzer, SP, M110A1

FSC: 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

3. REQUIREMENTS

3.1 Materials.-Materials shall be in accordance with applicable drawings and specifications.

3.2 Propelling Charge.-The propelling charge shall comply with all requirements specified on drawing 9277173 and with all requirements specified in applicable specifications.

3.3 Moisture Content of Black Powder.-The moisture content of the black powder at the loading station at the time of loading shall not exceed the amount specified in MIL-P-223.

3.4 Propellant Weight.-The propellant weight shall comply with the weight specified in the loading authorization within plus or minus 0.40 ounce. The propellant weight may also be determined by weighing 50 percent of the loading authorization twice, each weighing to a tolerance of 0.20 ounce.

3.4.1 Charge, Propelling Assembly Weight.-The charge, propelling assembly weight shall not differ by more than 1.0 ounce from the total of the amount specified in the loading authorization plus tare weight of the empty increment, flash reducer, lacing cord, lacing jacket, and loaded base igniter and tube assembly. (See 6.8).

3.4.2 Base Igniter Cap and Tube Assembly Weight.-(see 6.8).

3.4.2.1 Using Tare Weight of Tube.-The loaded base igniter cap and tube assembly weight shall not differ by more than 0.25 ounce from the nominal black powder weight plus the tare weight of the tube, tare weight or average weight of the base igniter assembly, and average weight of cap.

3.4.2.2 Using Nominal Weight of Tube.-The loaded base igniter cap and tube assembly weight shall not differ by more than 0.30 ounce from the nominal black powder and tube weight plus the tare weight or average weight of the base igniter assembly and average weight of the cap.

3.5 Dimensional Gage.

3.5.1 Maximum Length and Diameter.-The completed charge shall freely enter the prescribed gage. The gage shall be designed to inspect the maximum diameter and length. If the diameter feature is separate from the length feature, the diameter feature must extend approximately the full length of the charge.

3.5.2 Minimum Diameter.-The base end of the completed charge shall not freely enter the prescribed gage greater than two inches.

Source: https://assist.dla.mil -- Downloaded: 20261O-26T03:55Z
Check the source to verify that this is the current version before use.

3.6 Workmanship.-All components shall be free of dirt, grease and other foreign material. There shall be no discoloration or deterioration of cloth and no evidence of rips, tears, or other cloth defects. All work performed shall be performed in a thorough workmanlike manner.

3.7 Proving Ground.-The muzzle velocity, pressure, and velocity standard deviation shall be as specified in Table I. (See 6.12)

TABLE I

Zone	Proj.	Temp	Velocity (feet per second) Minimum	Velocity (feet per second) Maximum	Velocity Standard Deviation FPS	Individual Maximum Pressure PSI
Chg. 8	M106	70°F	2315	2345	6.5	34,500
Chg. 8	M106	145°F (Differential Pressure)				40,500

3.8 Assembly Torque.-The test plug shall be assembled to withstand subsequent reapplication of the minimum assembly torque specified on the applicable drawing, without moving.

3.9 Igniter Tubes.-All tubes shall be free of cracks, dents, creases, tears, flat areas, and softness greater than 0.25 inch.

3.10 First Article Inspection.-This specification contains technical provisions for the first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions.-Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspections.-The following types of inspection shall be conducted on this item:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

a. First Article Inspection

b. Quality Conformance Inspection

4.3 First Article Inspection

4.3.1 Submission.-The contractor shall submit a First Article Sample as designated by the Contracting Officer for evaluation in accordance with the provisions of 4.3.2. The first article sample shall consist of twenty-four (24) propelling charges packed in metal containers which have been produced by the contractor and selected randomly from the first week's regular production.

4.3.2 Inspection to be Performed.-See MIL-A-48078.

4.3.3 Rejection.-See MIL-A-48078.

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation.-Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, inspection lots of propelling charge assemblies shall contain:

a. Propellant from not more than one lot number from one manufacturer.

b. Black powder from not more than one interfix number from one manufacturer.

c. Tubes from not more than one interfix number from one manufacturer.

4.4.2 Examination.-See MIL-A-48078.

a. Sampling Plans.-Unless otherwise specified in the Classification of Defects and Test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 20261O-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Strap, Tying		9277188
			NEXT HIGHER ASSEMBLY 9277178

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Length		0.65%	3.2	Scale
202	Width		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4B1C

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277277
4.4.2.2	Bag, Charge				NEXT HIGHER ASSEMBLY 9277276
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length of cloth		0.40%	3.2	Scale
102	Width of cloth		0.40%	3.2	Scale
103	Cloth improper			3.1	4.5.5
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Charge Bag Assembly				9277276
					NEXT HIGHER ASSEMBLY
					9281791
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Tape missing, insecure or improperly located		100%	3.2	Gage - Manual
102	Cloth Improper (tape)			3.1	4.5.5
Minor					
201	Length of tape after tack		0.65%	3.2	Scale
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277169
4.4.2.4	End, Base Igniter Marking				NEXT HIGHER ASSEMBLY 9277167
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
102	Diameter of base igniter end		0.40%	3.2	Gage
Minor					
201	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA 1 FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	End, Base Igniter		9277171
			NEXT HIGHER ASSEMBLY 9281791

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth Improper			3.1	4.5.5
102	Diameter of base igniter end		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C(PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	End Base Igniter and Charge Bag Assembly	1 OF 1	9281791
			NEXT HIGHER ASSEMBLY 9277167

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Location of charge bag assembly (including location of seam)		100%	3.2	Gage
102	Distance from end base igniter to first tape		0.40%	3.2	Gage
103	Seam Improper		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277167
4.4.2.7	Base Igniter Assembly				NEXT HIGHER ASSEMBLY 9281794
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of seam circle		0.40%	3.2	Scale
102	Quilting missing or improper		0.40%	3.2	Visual-Manual
103	Quilting seam improper length		0.40%	3.2	Scale
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Base Igniter and Charge Bag Loading Assembly				9281794
					NEXT HIGHER ASSEMBLY
					9285356
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly incorrect or damaged to the extent that black powder can escape (including any seams or openings incompletely stitched or broken stitching)		100%	3.2	Visual-Manual
Major					
101	Weight of black powder			3.2	4.5.1
102	Moisture content of black powder	(a)		3.3	4.5.3
103	Minimum distance from tape to inner stitching at trimmed end		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Distance from trimmed end of charge bag to first seam		0.65%	3.2	Scale

NOTES: (a) See paragraph 4.4.3.2

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9289130
4.4.2.9	Cap				NEXT HIGHER ASSEMBLY 9285356
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thickness		0.40%	3.2	Gage
Minor					
201	Inside diameter		0.65%	3.2	Gage
202	Length		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9285356
4.4.2.10	Base Igniter and Tube Assembly				NEXT HIGHER ASSEMBLY 9277175
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Base igniter and charge bag loading assembly damaged or improper		100%	3.2	Visual
Major					
101	Base igniter and charge bag loading assembly improperly tied to tube, i.e., tie missing, loose or incorrect (excluding length of ties after tying)		100%	3.2	Visual
102	Base igniter and tube assembly weight		100%	3.4.2	4.5.9
103	Cap missing or insecure		100%	3.2	Visual-Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Charge bag twisted or folded in tube (to be checked prior to assembly of cap to tube)		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Body				9277179
					NEXT HIGHER ASSEMBLY
					9277176
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.12	Liner Assembly				9277174
					NEXT HIGHER ASSEMBLY
					9277176
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Established length		0.40%	3.2	Scale
102	Established width		0.40%	3.2	Scale
103	Area coverage of additive coating, minimum		0.40%	3.2	Visual-Scale
104	Weight of additive		0.40%	3.2	Balance
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277176
4.4.2.13	Body and Liner Assembly				NEXT HIGHER ASSEMBLY 9277178
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Liner assembly improper, improperly assembled, missing or improperly located		0.40%	3.2	Visual-Scale
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.2.2.14	End				9277183
					NEXT HIGHER ASSEMBLY
					9277182
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Cloth improper			3.1	4.5.5
Minor					
201	Established length		0.65%	3.2	Scale
202	Established width of straight section		0.65%	3.2	Scale

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	End Assembly				9277182
					NEXT HIGHER ASSEMBLY
					9277178
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Seam improper		0.40%	3.2	Visual-Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.16	Body Assembly				9277178
					NEXT HIGHER ASSEMBLY
					9277175
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	End assembly improperly assembled to body and liner assembly		0.40%	3.2	Visual
102	Any seam incompletely stitched		0.40%	3.2	Visual-Manual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9277175
4.4.2.17	Increment 8 Loading Assembly				NEXT HIGHER ASSEMBLY 9277172
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Base Igniter and Tube Assembly improperly assembled to body assembly		100%	3.2	Visual-Manual
102	Base Igniter and Tube Assembly improper or damaged (including condition of tube immediately prior to insertion into body and end assembly)		100%	3.2/3.9	Visual-Manual
103	Propellant weight			3.4	4.5.2
104	Any seam incompletely stitched		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Jacket, Lacing				9282014
					NEXT HIGHER ASSEMBLY
					9277173
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Distance between rows		0.40%	3.2	Scale
102	Cloth improper			3.1	4.5.5
103	Lacing cord missing or improperly assembled (2 locations)		0.40%	3.2	Visual-Manual
Minor					
201	Jacket of excessive length		0.65%	3.2	Scale
202	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
203	Evidence of poor workmanship		0.65%	3.6	Visual
204	Any seam improper or incompletely stitched		0.65%	3.2	Visual-Manual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9299190
4.4.2.19	Body				NEXT HIGHER ASSEMBLY 9299189
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor 201	Outer diameter		0.65%	3.2	Gage
202	Inner diameter		0.65%	3.2	Gage

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.20	Body Assembly				9299189
					NEXT HIGHER ASSEMBLY
					9299188
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any seam incompletely stitched		0.40%	3.2	Visual
102	Location of inner seam, minimum		0.40%	3.2	Gage
103	Location of outer seam, minimum		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9299188
4.4.2.21	Flash Reducer Assembly				NEXT HIGHER ASSEMBLY 9277173
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined.				
Major					
101	Any assembly damaged or improper to the extent black powder or potassium sulfate can escape.		100%	3.2	Visual-Manual
102	Weight of potassium sulfate prior to loading.		0.40%	3.2	Balance
103	Weight of black powder prior to loading.		0.40%	3.2	Balance
104	Any seam incompletely stitched.		0.40%	3.2	Visual
Minor					
201	Marking missing, misleading, or unidentifiable.		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.6	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.22	Charge, Propelling, 8 Inch, M188 for 8 Inch Howitzer, SP, M110A1				9277173
					NEXT HIGHER ASSEMBLY --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Assembly damaged or improper to the extent that black powder can escape		100%	3.2	Visual-Manual
2	Base pad not in true position with respect to outer diameter of charge (to be determined after straps are securely tied and charge is laced)		100%	3.2	Gage
3	Black powder missing in basepad		100%	3.2	Manual
	Proving Ground				
4	Pressure	(a)		3.7	4.5.6
Major					
101	Dimensional gage failure		100%	3.5	Gage
102	Lacing missing, improper or insecure		100%	3.2	Visual-Manual
103	Igniter protector cap missing or improperly attached		0.40%	3.2	Visual
104	Propelling charge assembly weight		100%	3.4.1	4.5.8

NOTES: (a) Pressure sampling will consist of monitoring pressure on differential pressure and muzzle velocity standard deviation samples.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 2 OF 2	DRAWING NUMBER
4.4.2.22	CONTINUATION SHEET		9277173
			NEXT HIGHER ASSEMBLY --

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
105	Assembly damaged to the extent that propellant or potassium sulfate can escape (includes any seams or openings incompletely stitched and broken stitches)		100%	3.2	Visual
106	Any component missing or improperly assembled (including flash reducer)		100%	3.2	Visual
107	Straps loose, broken or insecurely tied		0.40%	3.2	Visual-Manual
	Proving Ground				
108	Muzzle velocity and muzzle velocity standard deviation	(b)		3.7	4.5.6
109	Differential pressure	10	Info	3.7	4.5.6
Minor					
201	Evidence of poor workmanship		0.65%	3.6	Visual
202	Location of lacing jacket		0.65%	3.2	Visual

NOTES: (b) Sampling plan shall be in accordance with MIL-STD-414, Section B, Table B3, Code letter G, AQL of 2.50%.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298807
4.4.2.23	Spacer, Hex				NEXT HIGHER ASSEMBLY 9283094
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Spacer fails to freely enter gage		0.65%	3.2	Gage (Note 1)
202	Diameter of hole		0.65%	3.2	Gage

NOTES:
1. Ring gage same diameter as minimum diameter of PA66 container, dwg. 9275845.

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.24	Charge, Prior to Insertion into Container				9283094
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Middle cushion missing or insecurely assembled to hex spacer		100%	3.2	Visual
102	Tying strap missing, damaged or improperly assembled to hex spacer		100%	3.2	Visual
103	Hex spacer improperly assembled to charge		100%	3.2	Visual
104	Wrapper above top of charge		100%	3.2	Visual
Minor					
201	Marking missing, misleading, or unidentifiable on strap (4 straps)		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.25	Container, Prior to Insertion of Charge				9283094
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Foreign matter or rust in container		0.40%	3.2	Visual
102	Bottom cushion missing		100%	3.2	Visual
103	Charge not tightly wrapped immediately prior to insertion into container (i.e., all charge full diameter points should be in contact with the wrapper).		0.40%	3.2	Visual
Minor					
201	Damaged container (to include dents protruding greater than 1/4" into container)		0.65%	3.2	Visual-Gage (see 6.4)

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9283094
4.4.2.26	Container, Prior to Sealing				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Long filler above top of hex spacer (except for one allowable torn filler).		100%	3.2	Visual
102	Charge diametrically loose to the extent that a long filler may be completely inserted		100%	3.2	Manual
103	Any filler (if required) or top cushion missing or improper		100%	3.2	Visual
104	Dimension "X", minimum. (In lieu of measuring Dimension "X", the measurement of Dimension "Y" maximum may be taken)		100%	3.2	Gage
105	Filler inserted in container prior to inserting top cushion		0.40%	3.2	Visual
106	More than five long fillers present		0.40%	3.2	Visual
107	Overlap of one long filler with another at top of charge		0.40	3.2	Visual
108	Cover cannot be removed by hand (immediately prior to application of torque)		0.40%	3.2	Manual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.26	CONTINUATION SHEET				9283094
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
109 Minor	Charge cannot be removed by hand None defined	(a)		3.2	4.5.10

NOTES: (a) One sample from each eight (8) hours production.

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.27	Container, Sealed		9283094
			NEXT HIGHER ASSEMBLY

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Test plug missing		100%	3.2	Visual
102	DOD symbol missing, misleading or unidentifiable (if applicable)		0.40%	3.2	Visual
103	Test plug assembly torque		0.40%	3.8	Test (see 6.11)
104	Air pressure test		100%	3.2	4.5.4
Minor					
201	Test plug not greased (to be checked after air pressure test and prior to reassembly)		0.65%	3.2	Visual
202	Metallic seal missing or incorrectly applied		0.65%	3.2	Visual
203	Marking missing, misleading, or unidentifiable		0.65%	3.2	Visual
204	Cover incompletely engaged		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48143C (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.28	Containerized Charge				9283094
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
NOTE (a)	Tear down Inspection	(b)		(c)	4.5.7

NOTES:

(a) Category is critical or major dependent upon the category of the defect inspected.
(b) See paragraph 4.4.3.1.
(c) Requirement paragraph is dependent upon inspection performed.

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.4.3.1 Teardown Inspection

4.4.3.1.1. Initial Lot Sampling.-Three completely assembled charges shall be randomly selected from each days production of the first production lot until three consecutive days production is found acceptable. Subsequent sampling will be on completely assembled charge from each days production. If there is a lapse in production in excess of ninety (90) days, sampling will return to initial lot sampling.

4.4.3.1.2 Subsequent lot sampling.-One completely assembled charge shall be randomly selected from each days production.

4.4.3.2 Moisture Content of Black Powder.-At least one sample of black powder from each eight hours loading of base igniter assemblies will be tested for moisture content.

4.4.4 Inspection Equipment.-The inspection equipment required to perform the examinations and tests prescribed herein is described in the 'Paragraph Reference/Inspection Method' column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and paragraph 6.3 of this specification.

4.5 Test Methods and Procedures

4.5.1 Weight of Black Powder in Base Igniter and Charge Bag Loading Assembly.- The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. Any assembly which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.1.1. Method 1.- The weight of black powder in the base igniter and charge bag will be inspected 100 percent. The weight of the black powder in the basepad will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded basepad, empty charge bag assembly weight. The weight of the black powder in the charge bag will be determined by subtracting the average or actual weight of the loaded basepad, empty charge bag assembly from the loaded base igniter and charge bag assembly weight.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:55Z
Check the source to verify that this is the current version before use.

4.5.1.2 Method 2.- The weight of the black powder will be inspected 100 percent prior to loading the assembly on a different balance. The black powder weight of the loaded basepad will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the black powder will be determined by subtracting an average weight of the empty assembly or the actual weight as marked on the individual assembly from the loaded basepad assembly. The total weight of black powder (base igniter and charge bag content) will be inspected 100 percent. The total weight of black powder will be determined by subtracting an average weight of the empty assembly or actual weight as marked on the individual assembly from the loaded base igniter and charge bag assembly (the allowable tolerance for total weight shall be equivalent to the charge bag weight tolerance).

4.5.2 Propellant Weight.(see 3.4)-The inspections below are to be conducted by inspection personnel using equipment designated for inspection purposes and shall be clearly distinguished from production operations. Any increment which fails to comply with the applicable requirement shall be classed defective and removed from the lot. Inspection equipment shall be in accordance with 4.4.4.

4.5.2.1 Method 1.- The loaded increment will be inspected 100 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.2.2 Method 2.- The weight of the propellant will be inspected 100 percent prior to loading the increment on a different balance. In addition, the propellant weight of the loaded increment will be inspected using a sampling plan from MIL-STD-105 or MIL-STD-1235 with an AQL of 0.40 percent. The weight of the propellant will be determined by subtracting an average weight of the empty increment bag or the actual weight as marked on the individual increment bag from the loaded increment weight.

4.5.3 Moisture Content of Black Powder.-The moisture content of the black powder will be determined in accordance with MIL-P-223. If any sample fails to meet the specified requirement, the eight hours production represented by the sample shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.5.4 Air Pressure Test.-Each container shall be tested as specified on the appropriate drawing. A pressure drop equivalent to 3 inches of water or greater shall be cause for rejection and removal from the lot.

4.5.5 Cloth.-At the time cloth is introduced to the sewing or cutting operation, an identification will be made for each roll to verify that proper material is used. Any cloth failing to be identified as proper material in accordance with applicable drawings and specifications shall be rejected from the lot.

4.5.6 Proving Ground.-This test shall be conducted at a Government Proving Ground in accordance with the applicable acceptance test procedure using M106, HE projectiles inert loaded within 0.5 pound of an as fired weight of 200.0 pounds using Primer, M82 and fired in cannon M201 with 95 percent (minimum) remaining life. Firing shall be conducted with a spindle to charge base stand-off of 1 inch (plus or minus 1/4 inch). Prior to firing, all charges shall be temperature conditioned at the required temperature (±2°F) for a minimum of 16 hours and assurance will be made that, when fired, the charges are at the conditioning temperature. Copper crusher gages (2) shall be used to measure the maximum chamber pressure of each charge. Velocity coils will be used to measure the muzzle velocity of each charge.

4.5.6.1 Muzzle-Velocity and Muzzle Velocity Standard Deviation.-Determination of acceptance will be in accordance with MIL-STD-414, Section B, Table B3, AQL of 2.50%. All muzzle velocity and muzzle velocity standard deviation samples will be ballistic tested at 70°F. Fifteen (15) charges will be fired for muzzle velocity and muzzle velocity standard deviation. If the sample is determined unacceptable the lot will be rejected. In addition, if the velocity standard deviation of the sample multiplied by the factor 0.76 exceeds the applicable lot requirement, the lot shall be rejected. Fifteen (15) calibration charges will be fired alternately with the test samples and the muzzle velocity and pressure of all test charges will be corrected to standard conditions.

4.5.6.2 Pressure.- If any propelling charge individual corrected maximum pressure exceeds the applicable requirement, the lot shall be rejected.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.5.6.3 Differential Pressure.-Two pressure-time gages at different locations (one in the spindle and one at the projectile base) will be used to record pressure-time traces. Differential pressure traces will be obtained by subtracting the spindle gage output from the projectile gage output. The maximum differential pressure of any charge will be defined as the maximum positive amplitude of the first positive wave of the differential pressure trace. Any trace which contains no amplitude in the positive direction will be considered to have a maximum differential pressure of zero. Ten (10) charges will be conditioned to 145°F for differential pressure firings. Ignition delay will be recorded for information on all differential pressure firings. Five (5) calibration charges will be fired intermixed with the test samples and the muzzle velocity and pressure of all test samples will be corrected.

4.5.7 Teardown Inspection.-Each container and propelling charge will be subjected to each of the critical (except critical defect 2. and 4., paragraph 4.4.2.19) and 100 percent major (except major defect 101, paragraph 4.4.2.8; major defect 102, paragraph 4.4.2.10; major defect 103, paragraph 4.4.2.17; major defect 104, paragraph 4.4.2.22; major defect 104, paragraph 4.4.2.26) inspections defined in 4.4.2 of this specification. Samples may be accumulated for one week's production, if desired, prior to the actual inspection. The inspection will be performed by the contractor and witnessed by the Government. The detection of any one of the above defects shall be cause for rejection of the charges produced on the day represented by the sample.

4.5.8 Charge, Propelling, Assembly Weight.- The tare weights as marked on the individual assembled base igniter and tube assembly, and empty increment assembly plus average or actual weight of the flash reducer plus the average tare weight of the lacing cords and jacket together with the nominal propellant weights as specified in the loading authorization shall be subtracted from the assembled charge, propelling, assembly weight. If the resulting weight deviation is greater than the requirement, the propelling charge will be classified defective and removed from the lot. (see 6.9)

4.5.9 Base Igniter and Tube Assembly Weight

4.5.9.1 Method 1.-The tare weight of the tube along with the average tare weight of the empty base igniter assembly or the tare weight as marked on the individual empty base igniter

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:55Z
Check the source to verify that this is the current version before use.

assembly shall be recorded for each base igniter and tube assembly. These weights along with the nominal weights of black powder and average weight of the cap shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and tube assembly will be classified defective and removed from the lot. (See 6.10.1).

4.5.9.2 Method 2.-The average tare weight of the empty base igniter assembly or the tare weight as marked on the individual empty base igniter assembly shall be recorded for each base igniter and tube assembly. These weights along with the average weight of the cap and the nominal weight of the tube and black powder shall be subtracted from the assembled base igniter and tube assembly weight. If the resulting weight deviation is greater than the requirement, the base igniter and the tube assembly will be classified defective and removed from the lot. (See 6.10.2).

4.5.10 Charge Removal from Container.-Each sample shall be tested for removal of the propelling charge from the container by hand. The charge may be pulled out by the tying straps or the container may be inverted and the charge either pulled out or slid out. Each charge tested shall be checked for damage to the tying straps (looseness, tears, etc.) and the charge will be repaired (retie the tying straps and relace the charge, if necessary). Each charge tested shall be rewrapped (may use the same wrapper if the wrapper is not badly damaged) and re-packed in accordance with this specification and the applicable drawings. Any charge that cannot be removed from the container using the above method shall be cause for rejection of the production represented by the sample.

5. PREPARATION FOR DELIVERY

5.1 Packing and Marking.-The propelling charges shall be packed, sealed, tested and marked in accordance with the specified requirements of drawing 9283094.

6. NOTES

6.1 Intended Use.-The propelling charges covered by this specification are intended for use in M201 cannon.

6.2 Ordering Data.-See MIL-A-48078.

6.3 Submission of Designs for Approval.-See 6.2.3 of MIL-A-48078. Submit equipment designs, as required, to Commander, Picatinny Arsenal, Attn: SARPA-QA-T, Dover, New Jersey 07801.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

6.4 Visual Examination Qualification.-When compliance with the applicable requirement is in doubt as a result of visual examination the characteristic may be measured or gaged to determine acceptability.

6.5 Inspection Lot Size.-It is noted that the size of inspection lots of components, assemblies, or items of delivery may differ from the actual quantities contractually scheduled for delivery. However, in order to facilitate scheduling of tests or deliveries, inspection lots of items of delivery may be equivalent to such contract quantities provided all of the lot formation criteria and sampling provisions of this specification are maintained.

6.6 Proving Ground.-A copy of all proving ground data should be submitted to Commander, Picatinny Arsenal, ATTN: SARPA-QA-A-A and SARPA-ADEP-3, Dover, New Jersey 07801.

6.7 Teardown Inspection.-A list of all defects found during teardown inspection shall be submitted to Commander, Picatinny Arsenal, ATTN: SARPA-QA-A-A, Dover, New Jersey 07801.

6.8 Charge, Propelling Assembly Weight and Base Igniter and Tube Assembly Weight.-This requirement applies to the load plant at the time of loading only. Due to subsequent change in tare weight of the components because of variation in material and moisture content, this test cannot be repeated after initial manufacture to the degree of accuracy required.

6.9 Charge, Propelling, Assembly Weight.-

Weights To Be Determined		Assembly Drawing Number
Actual Weight of Base Igniter and Tube Assembly	-	9285356
Average/Actual Weight of Flash Assembly	-	9299188
Actual Weight of Body Assembly	-	9277178
Average Weight of Lacing Cord	-	9277173
Average Weight of Lacing Jacket	-	9282014
Nominal Propellant Weight	-	Loading Authorization
Component Weight (sum of above weights)		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

The propelling charge assembly weight minus the component weight equals the "Weight Deviation".

6.10 Base Igniter and Tube Assembly Weight.-

6.10.1 Method 1.-

Weights To Be Determined		Assembly Drawing Number
Actual Weight of Tube	-	9285248
Average/Actual Weight of Base Igniter Assembly	-	9277167
Average Weight of Cap	-	9289130
Nominal Weight of Black Powder	-	9281794

Component Weight (Sum of above weights)

The base igniter and the tube assembly weight minus the component weight equals the "Weight Deviation".

6.10.2 Method 2

Weights To Be Determined		Assembly Drawing Number
Nominal Weight of Tube	-	MIL-I-48252
Average/Actual Weight of Base Igniter Assembly	-	9277167
Average Weight of Cap	-	9281794
Nominal Weight of Black Powder	-	9281794

Component Weight (Sum of above weights)

The base igniter and tube assembly weight minus the component weight equals the "Weight Deviation".

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

6.11 Test Plug Assembly Torque.-This requirement applies to the load plant at the time of loading only. Due to creep of the mechanical properties of the test plug washer, this test cannot be repeated after initial manufacture.

6.12 Proving Ground Summary (See 4.5.6).-

Test	Sample Size	Number of Ref Rounds	Velocity	Maximum Individual Pressure	Differential Pressure
70°F	15	15	*	34,500	NA
145°F	10	5	INFO	40,500	INFO

*See 4.5.6.1 and 3.7

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number 1320-A-326

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/ vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?

A. GIVE PARAGRAPH NUMBER AND WORDING.

B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.