MILITARY SPECIFICATION

CRYOGENIC SYSTEM STORAGE ASSY

This specification is approved for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 This specification covers the fabrication of parts and the assembly of one type of cryogenic system for explosive ordnance disposal.

2. APPLICABLE DOCUMENTS

2.1 The following documents of the issue in effect on date of invitation for bids, or request for proposals, form a part of this specification to the extent specified herein.

SPECIFICATIONS

MILITARY

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification For

STANDARDS

MILITARY

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)

DRAWINGS

PICATINNY ARSENAL

T9282032 - Storage Assy, Cryogenic System

MANUALS

Navy Manual - EODB/TM/TO 60A Series Publication

FSC: 1385

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

3. REQUIREMENTS

3.1 Materials. - Materials shall be in accordance with the applicable drawings and specifications.

3.2 Components and Assemblies. - The components and assemblies shall comply with all requirements specified on drawing 9282032 and associated drawings and with all requirements specified in the applicable specifications.

3.3 Storage Container and Withdrawal Systems. - The items, when assembled, shall be functional.

3.4 Workmanship. - All parts and assemblies shall be fabricated and finished in a thorough workmanlike manner and all manufacturing, processing, and assembly operations shall be correctly performed. All required markings shall be neat, legible and sharply defined. Metal parts and assemblies shall be free of burrs, chips, sharp edges, cracks, crazes, unblended radii, porosity, warpage, burn marks, checks, chipped edges, blisters, excess flash, dirt, grease, rust, salt deposits, visible raised cement seams, solder splash, corrosion products, and other defects and foreign matter which would affect their serviceability the cleaning method used shall not be injurious to any part or assembly nor shall the parts be contaminated by the cleaning agent. Cloth assemblies shall be free from protruding frays, abrasions surplus thread ends, unitential holes and accidental cuts, trears or rips. Protective paint finishes shall be free from voids, blisters, runs and scratches which expose bare surfaces. Wood components shall be smoothly finished, sound, free of rough surfaces, knots and splinters.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for Inspection and Standard Quality Assurance Provisions. - Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of Inspection. - The following type of inspection shall be conducted on this item:

a. Quality Conformance Inspection

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

4.3 First Article Inspection. - Not required.

4.4 Quality Conformance Inspection

4.4.1 Inspection Lot Formation. - Inspection lots shall comply with the lot formation provisions of MIL-A-48078.

4.4.1.1 Submission of product. - At the time each completed lot of items deliverable under the contract is submitted to the Government for acceptance, the contractor shall supply the following information accompanied by a certificate which attests that the information provided is correct and applicable to the product being submitted:

a. A statement that the lot complies with all of the quality assurance provisions specified in this specification.

b. Drawing and specification number and date, together with identification and date of changes thereto.

c. A statement that all material purchased by one contractor meets requirements, when such material is controlled by Government or commercial specifications referenced in any of the contractual documents, and that certificates of conformance are on file and available for review.

d. Number of items in the lot.

e. Date submitted.

The certificate shall be signed by a responsible agent of the certifying organization. The initial certificate submitted shall be substantiated by evidence of the agent's authority to bind his principal. Substantiation of the agent's authority will not be required with subsequent certificates unless, during the course of the contract, this authority is vested in another agent of the certifying organization.

4.4.2 Examination. - (See MIL-A-48078) - Unless otherwise specified in the Classification of Defects and test tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II. Equipment necessary for the performance of the inspections listed shall be in accordance with 4.4.4.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.1	Storage Assy, Cryogenic System				9282032
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Wire Spool Assy missing		100%	3.2	Visual
102	Diking Kit missing		100%	3.2	Visual
103	Nitrogen container cover assy missing		100%	3.2	Visual
Major B					
131	Any component missing		0.40%	3.2	Visual
132	Tank holder strap missing		0.40%	3.2	Visual
133	System cryogenic cover assembly missing		0.40%	3.2	Visual
134	Stair cart missing		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Cart, Stair (Modified)				9272078
					NEXT HIGHER ASSEMBLY 9282032
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

5

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Cable Assembly				9276577
					NEXT HIGHER ASSEMBLY
					9272078
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Parts cannot be assembled		0.40%	3.2	Manual/Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.4	Explosive Ordnance Disposal Cryogenic System				9273742
					NEXT HIGHER ASSEMBLY
					9282032
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Parts or material improperly arranged		0.40%	3.2	Visual
133	Storage compartment(s) in shelves missing or inadequate		0.40%	3.2	Visual
Minor	None defined				

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.5	Tip		9260230
			NEXT HIGHER ASSEMBLY 9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Protective finish missing, incomplete or damaged		100%	3.2	Visual
102	Location of jet holes		100%	3.2	Gage
103	Dia. of jet holes		100%	3.2	Gage
104	Depth of bore		100%	3.2	Gage
105	Dia. of bore		100%	3.2	Gage
Major B					
131	Total length		0.40%	3.2	Gage
132	Length of fitting		0.40%	3.2	Gage
133	Lengths of tapers		0.40%	3.2	Gage
134	Diameter of shaft		0.40%	3.2	Gage
135	True position of shaft		0.40%	3.2	Gage
136	Depth of large ID		0.40%	3.2	Gage
137	Thread pitch dia, max		0.40%	3.2	Gage
138	Thread major dia, max		0.40%	3.2	Gage
139	Chamfer missing - Detail B		0.40%	3.2	Visual
140	Fillet radius, max - Detail B		0.40%	3.2	Gage
141	Fillet radius of shaft, min		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.6	Gun Assembly (Prior to Assembly)		9260232
			NEXT HIGHER ASSEMBLY
			9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
131	Any component missing or damaged		100%	3.2	Visual
132	Any component other than specified		100%	3.2	Visual/Certificate of Conformance
133	Wad misoriented		100%	3.2	Visual
134	Grease on shock absorber omitted		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.40%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.7	Gun Assembly (After Assembly)		9260232
			NEXT HIGHER ASSEMBLY
			9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
131	Noticeable drag or binding of piston along path of travel		100%	3.2	Manual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.8	Body, Gun (After Heat Treatment)				9260110
					NEXT HIGHER ASSEMBLY
					9260232
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Length of body		100%	3.2	Gage
102	Length of head		100%	3.2	Gage
103	Length of end		100%	3.2	Gage
104	Length of end thread, min		100%	3.2	Gage
105	End thread pitch dia, min		100%	3.2	Gage
106	End thread major dia, min		100%	3.2	Gage
107	Head thread pitch dia, min		100%	3.2	Gage
108	Head thread major dia, min		100%	3.2	Gage
109	Length of bore		100%	3.2	Gage
110	Bore dia		100%	3.2	Gage
111	Small ID dia		100%	3.2	Gage
112	True position of small ID		100%	3.2	Gage
113	True position of end OD		100%	3.2	Gage
114	Dia of knurled section		100%	3.2	Gage
Major B					
131	Chamfer or fillet missing		0.40%	3.2	Visual
132	Width of knurl, min		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Adapter, Liquid	1 OF 1	9260111
			NEXT HIGHER ASSEMBLY 9260232

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	True position of large-inside diameter (ID)		100%	3.2	Gage
102	Depth of thread for large aperture		100%	3.2	Gage
103	Pitch diameter, max-large, ID thread		100%	3.2	Gage
104	Major diameter max-large, ID thread		100%	3.2	Gage
105	Location of core diameter		100%	3.2	Gage
106	Depth of core diameter		100%	3.2	Gage
107	ID of small diameter		100%	3.2	Gage
108	True position of core		100%	3.2	Gage
109	Pitch diameter, max-Lateral tapped hole		100%	3.2	Gage
110	Major diameter, min-Lateral tapped hole		100%	3.2	Gage
111	Location of lateral tapped hole		100%	3.2	Gage
112	Perpendicularity of large ID		100%	3.2	Gage
113	Detail A - Chamfer or fillet missing		100%	3.2	Visual
114	Protective finish missing or damaged		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Head, Firing (After Heat Treatment)	1 OF 1	9260114
			NEXT HIGHER ASSEMBLY 9260232

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Outside diameter (OD)		100%	3.2	Gage
102	Length		100%	3.2	Gage
103	True position of small counterbore		100%	3.2	Gage
104	Diameter of small counterbore		100%	3.2	Gage
105	Width of small counterbore		100%	3.2	Gage
106	True position of large counterbores		100%	3.2	Gage
107	Diameter of large counterbores		100%	3.2	Gage
108	Thread pitch dia, max-small tapped hole		100%	3.2	Gage
109	Thread major dia, max-small tapped hole		100%	3.2	Gage
110	Width of large cavity		100%	3.2	Gage
111	Thread pitch dia, max-large tapped hole		100%	3.2	Gage
112	Thread major dia, max-large tapped hole		100%	3.2	Gage
113	Chamfer missing from large counterbores		100%	3.2	Visual
114	Fillet radius, max - Detail A		100%	3.2	Gage
115	Protective finish missing or damaged		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.11	Piston, (After Heat Treatment)		9260231
			NEXT HIGHER ASSEMBLY 9260232

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Total length		100%	3.2	Gage
102	Dia of shaft		100%	3.2	Gage
103	Dia of heat		100%	3.2	Gage
104	Width of head		100%	3.2	Gage
105	Location of slot		100%	3.2	Gage
106	Length of slot		100%	3.2	Gage
107	Width of slot		100%	3.2	Gage
108	Thread length, min		100%	3.2	Gage
109	Thread pitch dia, min		100%	3.2	Gage
110	Thread major dia, min		100%	3.2	Gage
111	Location of bore		100%	3.2	Gage
112	Perpendicularity of end face		100%	3.2	Gage
113	True position of head		100%	3.2	Gage
114	True position of shaft		100%	3.2	Gage
115	True position of bore		100%	3.2	Gage
116	Fillet, min		100%	3.2	Gage
Major B					
131	Chamfer missing		0.40%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.11 cont.	Piston, (After Heat Treatment)				9260231
					NEXT HIGHER ASSEMBLY 9260232
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.12	Elbow, Male (Modified)		9275065
			NEXT HIGHER ASSEMBLY 9260232

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Depth of hole, max		0.40%	3.2	Gage
132	Inside dia, max		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	Hammer, Stem				9271841
					NEXT HIGHER ASSEMBLY
					9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Diameter of hole		100%	3.2	Gage
102	Overall length, max		100%	3.2	Gage
Major B					
131	Diameter of body		0.40%	3.2	Gage
132	Length of knurl		0.40%	3.2	Gage
133	Any corner radius missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14	Container Cover Assembly	1 OF 1	9272208
			NEXT HIGHER ASSEMBLY 9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Assembly damaged		0.40%	3.2	Visual
132	Shelf "A" assy or cover assy missing		0.40%	3.2	Visual
133	Shelf "A" assy missing cord(s) nylon, solid braid		0.40%	3.2	Visual
134	Lock assemblies do not secure positively		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9272209
4.4.2.15	Body Assembly				NEXT HIGHER ASSEMBLY 9272208
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Shelf "B" assy missing or damaged		0.40%	3.2	Visual
132	Support shelf missing or damaged		0.40%	3.2	Visual
133	Lock assy(s) missing or damaged		0.40%	3.2	Visual
134	Handle, reinforcement(s) missing or damaged		0.40%	3.2	Visual
Minor					
201	Rivet(s) missing		0.65%	3.2	Visual
202	Finishing not applied		0.65%	3.2	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.16	Shelf "B" Assembly		9272212
			NEXT HIGHER ASSEMBLY 9272209

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Layers not bonded		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.17	Cover Assembly				9272211
					NEXT HIGHER ASSEMBLY
					9272208
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Part(s) or material missing		0.40%	3.2	Visual
132	Part(s) or material damaged		0.40%	3.2	Visual
133	Rivet(s) not flush		0.40%	3.2	Visual
134	I.D. does not provide a slide fit with body assembly		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Shelf "A" Assembly				9276767
					NEXT HIGHER ASSEMBLY 9272208
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Layers not bonded		0.40%	3.2	Manual
133	Cords not secure		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Liquid Nitrogen Storage and Pressure Delivery Assembly (Modified)				9275074
					NEXT HIGHER ASSEMBLY 9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Leakage at fittings		0.40%	3.2	Visual
133	Leakage at gasket		0.40%	3.2	Visual
Minor					
201	Protective finish improper		0.65%	3.2	Visual
202	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296717
4.4.2.20	Spool Valve (Modified)				NEXT HIGHER ASSEMBLY 9275074
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Part or all of the characters specified omitted or of the wrong configuration		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Ball and Socket Adapter Assembly				9275062
					NEXT HIGHER ASSEMBLY
					9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Ball not greased		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9275070
4.4.2.22	Hook Tube Assembly				NEXT HIGHER ASSEMBLY 9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.23	Firesleeve Hose Assy		9281688
			NEXT HIGHER ASSEMBLY
			9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Firesleeve missing		0.40%	3.2	Visual
132	Firesleeve torn or abraided		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C- 48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.24	Stem Assembly		9281697
			NEXT HIGHER ASSEMBLY 9273742

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	none defined				
Major B					
131	Screw missing		0.40%	3.2	Visual
Minor	none defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9271843
4.4.2.25	Screw, Cap (Modified)				NEXT HIGHER ASSEMBLY 9281697
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Chamfer width		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.26	Stem		9271842
			NEXT HIGHER ASSEMBLY 9281697

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Outside diameter		0.40%	3.2	Gage
132	ID thread pitch dia, max - short bore		0.40%	3.2	Gage
133	ID thread major dia, max - short bore		0.40%	3.2	Gage
134	ID thread length, min - short bore		0.40%	3.2	Gage
135	ID thread pitch dia, max - Detail A		0.40%	3.2	Gage
136	ID thread major dia, max - Detail A		0.40%	3.2	Gage
137	ID thread length, min - Detail A		0.40%	3.2	Gage
138	Slot missing		0.40%	3.2	Visual
139	Length of slot - Detail A				
140	Counter sink depth angle of taper - Detail A				
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.27	Gun Assembly Renovation Kit				9296591
					NEXT HIGHER ASSEMBLY
					9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9260113
4.4.2.28	Absorber, Shock				NEXT HIGHER ASSEMBLY 9296591
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296592
4.4.2.29	Spool Valve Renovation Kit				NEXT HIGHER ASSEMBLY 9273742
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET	DRAWING NUMBER
4.4.2.30	Nut, Adapter		1 OF 1	9275068
				NEXT HIGHER ASSEMBLY 9275062

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Center hole pitch diameter of thread, max		0.40%	3.2	Gage
132	Center hole major diameter of thread, max		0.40%	3.2	Gage
133	Depths of lateral holes		0.40%	3.2	Gage
134	Lateral holes pitch diameter of thread, max		0.40%	3.2	Gage
135	Lateral holes major diameter of thread, max		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.31	Ball and Socket Head (Prior to Assembly) (Modified)				9296529
					NEXT HIGHER ASSEMBLY
					9275062
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
101	Sealant omitted from insert		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9296529
4.4.2.32	Ball and Socket Head (After Assembly)				NEXT HIGHER ASSEMBLY 9275062
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major A					
102	Insert protrudes		0.40%	3.2	Visual
103	Spring Pin protrudes		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.33	Insert				9296528
					NEXT HIGHER ASSEMBLY 9296529
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Length		0.40%	3.2	Gage
132	Slot missing		0.40%	3.2	Visual
133	Thread pitch diameter, min		0.40%	3.2	Gage
134	Thread major diameter, min		0.40%	3.2	Gage
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.34	Strap, Tank Holder				9275063
					NEXT HIGHER ASSEMBLY 9282032
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER 9275071
4.4.2.35	Kit, Diking (Prior to Assembly)		NEXT HIGHER ASSEMBLY 9282032

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION
CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.36	Kit, Diking (After Assembly)				9275071
					NEXT HIGHER ASSEMBLY 9282032
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Tape broken		0.40%	3.2	Visual
132	Pull tab missing		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.37	Spool Assy, Wire				9281765
					NEXT HIGHER ASSEMBLY 9282032
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Any component missing or damaged		0.40%	3.2	Visual
132	Parts incorrectly assembled		0.40%	3.2	Visual
133	Reel does not turn freely		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.38	Cover Assembly, Cryogenic System	1 OF 1	9281819
			NEXT HIGHER ASSEMBLY 9282032

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Seams, folds or hems do not conform with instructions		0.40%	3.2	Visual
132	Thread type other than specified		0.40%	3.2	Visual/Certificate of Conformance
133	Cover cannot enclose system		0.40%	3.2	Manual
134	Slide fastener does not zip shut through entire length		0.40%	3.2	Manual
135	Sockets and buttons do not secure when engaged		0.40%	3.2	Manual
136	Any component missing or damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.39	Flap, Top				9281807
					NEXT HIGHER ASSEMBLY 9281808
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

44

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9281814
4.4.2.40	Cover, Rear				NEXT HIGHER ASSEMBLY 9281815
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9281818
4.4.2.41	Cover, Body Assembly (Inside View)				NEXT HIGHER ASSEMBLY 9281819
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Pocket(s) and/or strip missing		0.40%	3.2	Visual
132	Seams or hems do not conform to instructions		0.40%	3.2	Visual
133	Welting missing		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.42	Pocket, Gloves				9281802
					NEXT HIGHER ASSEMBLY
					9281803
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.43	Pocket, Twin, Cartridge Top				9281804
					NEXT HIGHER ASSEMBLY
					9281824
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9281805
4.4.2.44	Pocket, Twin, Cartridge Bottom				NEXT HIGHER ASSEMBLY 9281806
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4B10

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9281816
4.4.2.45	Cover, Body				NEXT HIGHER ASSEMBLY 918817
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor	None defined				

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 20260-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.46	Pocket, Caulking Gun				9281800
					NEXT HIGHER ASSEMBLY 9281801
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.47	Cover Assembly, Nitrogen Container		9281850
			NEXT HIGHER ASSEMBLY 9283032

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Parts or material missing		0.40%	3.2	Visual
132	Seams do not conform with instructions		0.40%	3.2	Visual
133	Cover cannot enclose container		0.40%	3.2	Manual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 20260-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.48	Cover, Body, Nitrogen Container				9281848
					NEXT HIGHER ASSEMBLY 9281849
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS MIL-C-48862 (PA)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.49	Cover, Top, Nitrogen Container				9281851
					NEXT HIGHER ASSEMBLY 9281850
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major B					
131	Component damaged		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.4	Visual

NOTES:

SARPA-QA FORM 2567 FEB 74 4810

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

4.4.3 Testing

4.4.3.1 Hardness Testing of Gun Body (see dwg. 9260110), Major Defect. - A sample of 15 bodies shall be selected from each heat treatment batch for this test. If two or more items fail to comply with the drawing requirement, the batch shall be rejected. The test shall be performed as specified in 4.5.2 using equipment in accordance with 4.4.4.

4.4.3.2 Hardness Testing of Firing Head (see dwg. 9260114), Major Defect. - A sample of 15 heads shall be selected from each heat treatment batch for this test. If two or more items fail to comply with the drawing requirement, the batch shall be rejected. The test shall be performed as specified in 4.5.3 using equipment in accordance with 4.4.4.

4.4.3.3 Hardness Testing of Piston (see dwg. 9260231), Major Defect. - A sample of 15 pistons shall be selected from each heat treatment batch for this test. If two or more items fail to comply with the drawing requirement, the batch shall be rejected. The test shall be performed as specified in 4.5.4 using equipment in accordance with 4.4.4.

4.4.3.4 Storage Container and Withdrawal System (see dwg. 9282032), Major Defect. - The criteria of paragraph 3.3 shall be met for each item assembled. Any assembly failing to comply with the specified requirement, shall be rejected. Procedures for compliance shall be as specified in 4.5.5 using equipment in accordance with 4.4.4.

4.4.4 Inspection Equipment. - The inspection equipment required to perform the examinations and tests prescribed herein is described in the tables starting with 'Paragraph Reference/Inspection Method' column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6 herein.

4.5 Test Method and Procedures

4.5.1 Materials, Components and Processes. - Compliance with all requirements of Section 3 of this specification shall be ascertained by current and continuing examination of

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

inspection and test data to determine that all components (parts, subassemblies, and materials) have been inspected and tested and found to comply with their respective drawing and specification requirements, and that all specified manufacturing processes have been followed.

4.5.1.1 Visual and Mechanical Inspections. - The visual, manual and mechanical inspections and tests shall verify compliance with the requirements of Section 3 of this specification in accordance with 4.4.2 herein.

4.5.2 Rockwell Hardness of Gun Body. - The gun body shall be tested as specified in Federal Test Standard No. 151, Method 243.1. Observation shall be made for compliance with the specified drawing requirement. (Non-destructive Test)

4.5.3 Rockwell Hardness of Firing Head. - The firing head shall be tested as specified in Federal Test Standard No. 151 Method 243.1. Observation shall be made for compliance with the specified drawing requirement. (Non-destructive test)

4.5.4 Rockwell Hardness of Piston. - The piston shall be tested as specified in Federal Test Standard No. 151, Method 243.1. Observation shall be made for compliance with the specified drawing requirement. (Non-destructive test)

4.5.5 Storage Container and Withdrawal Systems. - The storage container shall be partially filled with 30±5 lbs of liquid nitrogen and then connected with system components. Function gun and valve in accordance with Navy Manual EODB/TM/TO 60A series publication procedures. No target is necessary. When liquid flows from the tip, the withdrawal system valve shall be closed. Clean, refurbish and stow components in accordance with EODB/TM/TO 60A series publication procedures.

5. PREPARATION FOR DELIVERY. _ Not Applicable

6. NOTES

6.1 Intended Use. - The components covered by this specification are intended for use on the cryogenic system.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

6.2 Ordering Data. - See MIL-A-48078 (PA)

6.3 Submission of Inspection Equipment Designs For Approval. - See MIL-A-48078. Submit equipment designs, as required, to Commander, Picatinny Arsenal, ATTN: SARPA-QA-T, Dover, New Jersey 07801.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project Number: 1385-A001

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

OMB Approval
No. 22-R255

INSTRUCTIONS: The purpose of this form is to solicit beneficial comments which will help achieve procurement of suitable products at reasonable cost and minimum delay, or will otherwise enhance use of the document. DoD contractors, government activities, or manufacturers/vendors who are prospective suppliers of the product are invited to submit comments to the government. Fold on lines on reverse side, staple in corner, and send to preparing activity. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements. Attach any pertinent data which may be of use in improving this document. If there are additional papers, attach to form and place both in an envelope addressed to preparing activity.

DOCUMENT IDENTIFIER AND TITLE

NAME OF ORGANIZATION AND ADDRESS

CONTRACT NUMBER

MATERIAL PROCURED UNDER A

☐ DIRECT GOVERNMENT CONTRACT ☐ SUBCONTRACT

1. HAS ANY PART OF THE DOCUMENT CREATED PROBLEMS OR REQUIRED INTERPRETATION IN PROCUREMENT USE?
   A. GIVE PARAGRAPH NUMBER AND WORDING.

   B. RECOMMENDATIONS FOR CORRECTING THE DEFICIENCIES

2. COMMENTS ON ANY DOCUMENT REQUIREMENT CONSIDERED TOO RIGID

3. IS THE DOCUMENT RESTRICTIVE?

   ☐ YES ☐ NO *(If "Yes", in what way?)*

4. REMARKS

SUBMITTED BY *(Printed or typed name and address - Optional)*

TELEPHONE NO.

DATE

DD FORM 1 JAN 72 1426 REPLACES EDITION OF 1 JAN 66 WHICH MAY BE USED

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

FOLD

POSTAGE AND FEES PAID
DEPARTMENT OF THE ARMY
DOD – 314

U.S.MAIL

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

COMMANDER
Picatinny Arsenal
ATTN: SARPA-QA-A
Dover, New Jersey 07801

FOLD

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.