INCH-POUND

MIL-P-48187C(AR)
10 April 1992
SUPERSEDING
MIL-P-48187B(AR)
3 July 1986

MILITARY SPECIFICATION

PROJECTILE, 155MM, HE: M692 and M731, LOADING, ASSEMBLING AND PACKING

This specification is approved for use by the U. S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

1. SCOPE

1.1 Scope. This specification covers the loading, assembling and packing for Projectiles designated as Projectile, 155MM, HE: M692 and M731.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications, standards and handbooks. The following specifications, standards and handbooks form a part of this document to the extent specified herein. Unless otherwise specified, the issues of these documents are those listed in the issue of the Department of Defense Index of Specifications and Standards (DODISS) and supplement thereto, cited in the solicitation. (See 6.2)

SPECIFICATIONS

MILITARY

MIL-A-48078	-	Ammunition, Standard Quality Assurance Provisions, General Specification For.
MIL-M-48186	-	Munition for Projectile, 155MM, H.E.: M692/M731, Loading and Assembling of.
MIL-P-50345	-	Projectile, 155mm: M483A1-1-M (41-M6)

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document, should be addressed to: Commander U.S. Army ARDEC, ATTN: SMCAR-BAC-S, Picatinny Arsenal, New Jersey 07806-5000 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

AMSC N/A FSC 1320
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

STANDARDS

MILITARY

MIL-STD-453 - Inspection, Radiographic.

(Unless otherwise indicated, copies of federal and military specification, standards, and handbooks are available from the Standardization Documents Order Desk, Bldg. 4D, 700 Robbins Avenue, Philadelphia, PA 19111-5094.)

2.1.2 Other Government documents, drawings, and publications. The following other Government documents, drawings, and publications form a part of this document to the extent specified herein. Unless otherwise specified, the issues are those cited in the solicitation.

DRAWINGS (See 6.5)

US ARMY ARMAMENT RESEARCH, DEVELOPMENT AND ENGINEERING CENTER (ARDEC)

8837839	-	Pallet for Projectile, 155MM, HE & GB, Hollow Base Type.
9298315	-	Projectile, 155MM, HE, M692.
9298316	-	Projectile, 155MM, HE, M731.
9298714	-	Self-Destruct Time Requirements.

(Copies of other Government documents, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.)

2.2 Order of precedence. In the event of a conflict between the text of this document and the references cited herein the text of this document shall takes precedence. Nothing in this document, however, supersedes applicable laws and regulations unless a specific exemption has been obtained.

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with the applicable drawings, specifications and standards.

3.2 Projectile. The Projectile Assembly and Components shall comply with all requirements specified on Drawing (Dwg.) 9298315 or 9298316, as applicable, all associated drawings, and with all requirements specified in applicable specifications and standards.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

3.3 Pre-mature munition functioning.

3.3.1 Projectile in-flight. There shall be no munition functioning within the projectile prior to initiation of the nose fuze.

3.4 Controls in use of adhesive and sealants. The contractor shall develop a documented operational procedure for utilization of adhesives and sealants. This procedure shall provide for quality control of raw materials and process to be used, also details associated with intended use, such as proper handling, mixing, curing cycles, pot life, etc., cleaning agents, safety precautions, special ventilations, drying or other processes, and any other information of a similar nature that is considered necessary for the particular adhesive or sealant in use. This procedure shall be updated whenever a change is made such that the original assurance of product quality is affected.

3.5 Documentation of plan for safety in handling and processing of munitions. Prior to loading, the contractor shall document a detailed plan of the procedures to be employed during handling of the munition. This documentation shall describe, as a minimum, the procedures to be employed to assure that:

(1) The shorting bar is not deformed or broken.
(2) The battery is not activated.
(3) The liquid propellant does not leak from the overlays.
(4) The two types of housing and munitions remain segregated at all times.
(5) Clearly visible model markings on each projectile are consistent with the cargo it contains.
(6) The temperature of the housing, timing and fuzing, or the munition does not exceed 165°F at any time during processing or storage.
(7) HE munitions remain segregated from inert (special test) munitions at all times.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

3.6 Radiographic examination of projectile. The projectile shall have each layer of munitions properly positioned with respect to the keyway and shall have the column segments (in layers 1 through 4) aligned to form a straight column when the projectile is radiographically examined as specified in 4.5.5. Radiographs shall be taken in accordance with MIL-STD-453 and shall be of a quality which will permit proper evaluation as determined by the responsible Government Technical Agency.

3.7 Mine functioning.

3.7.1 High explosive loaded mines. The mine shall be capable of self destructing itself high order within the required time limits for either a Type I or a Type II device.

3.7.2 Early functioning. The mine shall not self destruct itself prior to the minimum self destruct time.

3.7.3 Low order functioning. The mine shall not self destruct itself low order, i.e., it shall be capable of firing the complete firing train high order.

3.8 Duds.

3.8.1 Safe dud. The mine, if not functioned by any external or internal mode, shall not function after the maximum self destruct time has elapsed.

3.8.2 Hazardous dud. All safe duds when tested as specified in 4.5.8, shall not be capable of functioning after the maximum self destruct time has elapsed.

3.9 Test temperatures and conditioning. The loaded projectiles, shall be temperature conditioned for a time period of twenty-four (24) hours to one hundred and sixty-eight (168) hours prior to firings. Temperature conditioning and firing temperature shall be seventy degrees Fahrenheit plus or minus ten degrees Fahrenheit ($70^{o}F \pm 10^{o}F$).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

3.10 Test zones. The projectiles, regardless of conditioning temperature, shall be fired either at zone seven (7) or zone three (3) as required per test sequence.

3.11 Data requirements. The contractor shall generate data in accordance with the requirements of the data item description cited in paragraphs 3.5, 3.6, 4.4.2.3, 4.4.2.5, 4.4.2.10 and 6.5.

3.12 First article inspection. This specification contains technical provisions for first article inspection. Requirements for the submission of first article samples by the contractor shall be as specified in the contract.

3.13 Workmanship. All parts and assemblies shall be fabricated, loaded and assembled in a thorough workmanlike manner. They shall be free of burrs, sharp edges, cracks, dirt, grease, rust, and other foreign matter that may impair proper functioning. The cleaning method used shall not be injurious to any part, nor shall the parts be contaminated by the cleaning agents. All required marking and stamping shall be neat and sharply defined.

4. QUALITY ASSURANCE PROVISIONS

4.1 Responsibility for inspection. Unless otherwise specified in the contract or purchase order, the contractor is responsible for the performance of all inspection requirements (examinations and tests) as specified herein. Except as otherwise specified in the contract or purchase order, the contractor may use his own or any other facilities suitable for the performance of the inspection requirements specified herein, unless disapproved by the Government. The Government reserves the right to perform any of the inspections set forth in this specification where such inspections are deemed necessary to ensure supplies and services conform to prescribed requirements.

4.1.1 Responsibility for compliance. All items shall meet all requirements of sections 3 and 5. The inspection set forth in this specification shall become a part of the contractor's overall inspection system or quality program. The absence of any inspection requirements in the specification shall not relieve the contractor of the responsibility of ensuring that all products or supplies submitted to the Government for acceptance comply with all requirements of the contract. Sampling inspection, as part of manufacturing operations, is an acceptable practice to ascertain conformance to requirements, however, this does not authorize submission of known defective material, either indicated or actual, nor does it commit the Government to accept defective material.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.2 Classification of inspections. The inspection requirements specified herein are classified as follows:

a. First article inspection (see 4.3).

b. Quality conformance inspection (see 4.4).

4.3 First article inspection.

4.3.1 Submission. The contractor shall submit a first article sample as designated by the Contracting Officer for evaluation in accordance with provisions of 4.3.2. The first article sample shall consist of the following items in sample quantities as indicated in Table I.

4.3.2 Inspections to be performed. See MIL-A-48078 and Table I specified herein.

4.3.3 Rejection. See MIL-A-48078 and following defect list.

a. Any separation of metal parts occurs prior to initiation of the nose fuze.

b. Any detonation of the projectile cargo occurs prior to initiation of the nose fuze.

c. The projectile fails to function satisfactorily (see 3.2).

d. Any munition functions or is capable of functioning after the maximum time has elasped (Hazardous dud).

e. Any premature burst occurs (see 6.7.1).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE Projectile and Components	SHEET 1 OF 5		DRAWING NUMBER See below
				NEXT HIGHER ASSEMBLY --
CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Projectile Metal Parts Assembly (Prior to insertion of battery) (Dwg. 10542902-3) Examination for Defects	10	3.2	4.4.2.1
	Battery Activation Assembly (Dwg. 9298390) Examination for defects	10	3.2	4.4.2.2
	Munition (Prior to assembly into stack-up) (Dwg. 9298400) Examination for defects	720	3.2	4.4.2.3
	Munition Stack-up (Layers 1 to 8 prior to assembly into projectile) Dwgs. 9298315 & 9298316) Examination for defects	720	3.2	4.4.2.4

NOTES:

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE Projectile and Components	SHEET 2 OF 5	DRAWING NUMBER See Below
			NEXT HIGHER ASSEMBLY --

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Projectile, (During and after assembly of munitions and prior to assembly of base plug) (Dwgs. 9298315 & 9298316) Examination for defects	10	3.2	4.4.2.5
	Base Plug (prior to assembly of body) (Dwg. 9298335) Examination for defects	10	3.2	4.4.2.6
	Projectile (after assembly of base and prior to assembly of ogive (Dwgs. 9298315 & 9298316) Examination for defects	10	3.2	4.4.2.7
	Shim, Ogive (prior to assembly to projectile (Dwg. 9298339) Examination for defects	10	3.2	4.4.2.8

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
	Projectile and Components	3 OF 5	See Below
			NEXT HIGHER ASSEMBLY --

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Ogive (prior to assembly to projectile (Dwg. 9298324)			
	Examination for defects	10	3.2	4.4.2.9
	Projectile (immediately after assembly of ogive and prior to assembly of charge and sleeve assembly). (Dwgs. 9298315 & 9298316)			
	Examination for defects	10	3.2	4.4.2.10
	Radiographic examination	10	3.6	4.5.5
	Process inspection	10	3.2	4.5.4
	Charge and sleeve assembly (prior to insertion of charge assembly) (Dwg. 9298360)			
	Examination for defects	10	3.2	4.4.2.11

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
	Projectile and Components	4 OF 5	See Below
			NEXT HIGHER ASSEMBLY
			--

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Expulsion charge assembly (prior to insertion into charge and sleeve assembly) (Dwg. 9378194)			
	Examination for defects	10	3.2	
	Charge and sleeve assembly (prior to insertion into projectile) (Dwg. 9298360)			
	Examination for defects	10	3.2	4.4.2.12
	Projectile (after assembly of charge and sleeve assembly and prior to assembly of lifting plug) (Dwgs. 9298315 & 9298316)			
	Examination for defects	10	3.2	4.4.2.13
	Projectile (prior to assembly of grommet) (Dwgs. 9298315 & 9298316)			
	Examination for defects	10	3.2	4.4.2.14
	Air pressure test	10	3.2	4.5.1

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE I. First article inspection.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
	Projectile and Components	5 OF 5	See Below
			NEXT HIGHER ASSEMBLY: --

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
	Projectile, 155MM, HE, M692/M731 (Dwgs. 9298315 & 9298316)			
	Projectile in-flight detonation	2	3.3.1	Visual
	Projectile temperature	2	3.10	4.4.2.15
	Firing zone and pressure	2	3.11	4.4.2.15
	Mine, Anti-personnel, Type I or Type II (Dwg. 9298400)			
	Self destruct time out function	72/(1)		4.4.2.16
	Early time out function	72/8/9		4.4.2.16
	Low order function	72/4/5		4.4.2.16
	Hazardous dud	72/0/1		4.5.7
	Safe duds	72/8/9		4.4.2.16

NOTES:

1. Type I mine only.

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.4 Quality conformance inspection.

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. In addition, each inspection lot of projectiles shall contain:

a. Projectile metal parts from one lot interfix number, from one manufacturer.
b. Charge assembly propellant from one lot only.
c. Projectiles of one model designation only.
d. Loaded munitions of one lot interfix number from one manufacturer (See NOTE), and containing Housing, Timing and Fuzing from one serial lot only.
e. Bases from one lot interfix number, from one manufacturer.

NOTE: Only those munitions lots which have successfully passed all tests indicated in MIL-M-48186 covering the loading and assembling of the munition shall be assembled into the projectile.

4.4.2 Examination and tests.

a. Classification of characteristics. Quality conformance examinations and tests are specified in the following Classification of Characteristics paragraphs. The contractor's quality program or detailed inspection plan shall provide assurance of compliance of all characteristics with the applicable drawing and specification requirements utilizing as a minimum the conformance criteria specified. Where specified herein, attributes sampling inspection shall be conducted in accordance with Table II below using the inspection levels stated in the Classification of Characteristics paragraphs.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

TABLE II Attributes sampling inspection

Lot Size	Inspection Level					
	I	II	III	IV	V	VI
2 to 8	*	*	*	*	5	3
9 to 15	*	*	*	13	5	3
16 to 25	*	*	*	13	5	3
26 to 50	*	*	32	13	5	3
51 to 90	*	*	32	13	13	5
91 to 150	*	125	32	13	13	5
151 to 280	*	125	32	32	20	8
281 to 500	*	125	32	32	20	8
501 to 1200	*	125	80	50	20	13
1201 to 3200	1250	125	80	50	32	13
3201 to 10000	1250	125	125	50	32	13
10001 to 35000	1250	315	125	80	50	13
35001 to 150000	1250	315	125	80	50	13

Numbers under inspection levels indicate sample size; asterisks indicate one hundred percent inspection. If sample size exceeds lot size, perform one hundred percent inspection. Accept on zero and reject on one or more for all inspection levels.

b. Alternative quality conformance provisions. Alternative quality conformance procedures, methods, or equipment, such as statistical process control, tool control, other types of sampling procedures, etc., may be used by contractor when they provide as a minimum, the level of quality assurance required by the provisions specified herein. Prior to applying such alternative procedures, methods, or equipment, the contractor shall describe them in a written proposal submitted to the Government for evaluation (see 6.4). When required, the contractor shall demonstrate that the effectiveness of each proposed alternative is equal to or better than the specified quality assurance provisions herein. In cases of dispute as to whether the contractor's proposed alternative(s) provides equal assurance, the provisions of this specification shall apply. All approved alternative provisions shall be specifically incorporated into the contractor's quality program or detailed inspection system, as applicable.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.1	Projectile metal parts assembly (prior to insertion of battery activation assembly)	OF 1 1	10542902-3
			NEXT HIGHER ASSEMBLY 9298315, 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Depth of cavity, min.	Level II	3.2	Gage
102	Rust or foreign matter on interior wall, threads or face at base end	Level II	3.2	Visual
103	Base or ogive thread damaged	Level II	3.2	Visual
104	Lubricant coating missing, incomplete, damaged or peeling	Level II	3.2	Visual
105	Lubricant coating on threads	Level II	3.2	Visual
106	Rotating band damaged	Level II	3.2	Visual
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.2	Battery activation assembly	1 OF 1	9298390
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Distance from top of piston to forward face of pusher plate, max.	Level II	3.2	Gage
102	Distance from top of piston to second shoulder on battery rod, max.	Level II	3.2	Gage
103	O-ring missing, damaged or not lubricated	Level II	3.2	Visual
104	Battery rod bent	Level II	3.2	Visual
Minor				
201	Adhesive missing from threads (prior to assembly)	Level IV	3.2	Visual
202	Excessive adhesive around threaded joints	Level IV	3.2	Visual
203	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.3	Munition (prior to assembly into stack-up)	1 OF 1	9298400
			NEXT HIGHER ASSEMBLY: 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Type 2 munition being assembled into stack-up for M731 projectile	100%	3.2/3.5	Gage
Major				
101	Type 1 munition being assembled into stack-up for M692 projectile	Level II	3.2/3.5	Visual
102	Shorting bar missing, broken or damaged	Level II	3.2	Visual
103	Any sensor deployed	Level II	3.2	Visual
104	Battery ball or shorting bar below min. height	Level II	3.2	Gage
105	Any sensor plug not removed	Level II	3.2	Visual
106	Munition damaged	Level II	3.2	Visual
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 — Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.4	Munition Stack-up (layers 1 to 8 prior to assembly into projectile)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Any munition improperly positioned (i.e. #7 sensor not facing base end of stack-up)	Level II	3.2	Visual
102	Segment column height to munition column height incorrect	Level II	3.2	Certification
103	Sizing ring for radial compressive load incorrect for projectile diameter	Level II	3.2	Visual
104	Disc pad missing from pusher plate	Level II	3.2	Visual
105	Any plate pad missing	Level II	3.2	Visual
106	Any munition missing or damaged	Level II	3.2	Visual
107	Any layer not properly aligned with keyway	Level II	3.2	Certification
108	Any layer not radially sized or failing to comply with the specified force	Level II	3.2	Certification
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.5	Projectile (during and after assembly of munitions and prior to assembly of base plug)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Exterior markings indicate M731 projectile, but projectile contain M692 munition	100%	3.2/3.5	Visual
Major				
101	Exterior markings indicate M692 projectile, but projectile contain M731 munition	Level II	3.2/3.5	Visual
102	Base pad missing	Level II	3.2	Visual
103	Base clearance inadequate	Level II	3.2	Gage
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.6	Base plug (prior to assembly to body)	1 OF 1	9298335
			NEXT HIGHER ASSEMBLY: See note

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Seal ring missing	Level II	3.2	Visual
Minor				
201	Sealing compound not applied to threads	Level IV	3.2	Visual
202	Threads damaged	Level IV	3.2	Visual
203	Nicks on shoulder adjacent to threads	Level IV	3.2	Visual
204	Seal ring not lubricated	Level IV	3.2	Visual
205	Poor workmanship	Level IV	3.13	Visual

NOTES: Base 10542904 may be used when manufactured and inspected in accordance with dwg. 9298335 and paragraph 4.4.2.3 of spec MIL-P-50345, CDS 115 and 116.

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.7	Projectile (after assembly of base and prior to assembly of ogive)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Base turns when specified disassembly torque is applied	Level II	3.2	Gage
102	Excessive gap between body and base	Level II	3.2	Gage/4.5.8
Minor				
201	Sealant on exterior surface	Level IV	3.2	Visual
202	Poor workmanship	Level IV	3.13	Visual
203	Sealant not present between projectile Body and Base (360° degrees)	Level IV	3.2	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH 4.4.2.8	TITLE Shim, Ogive (prior to assembly to projectile)	SHEET 1 OF 1	DRAWING NUMBER 9298339
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major 101	Thickness incorrect for required preload	100%	3.2	Gage
Minor	None defined			

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.9	Ogive (prior to assembly to projectile)	1 OF 1	9298324
			NEXT HIGHER ASSEMBLY: 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Seal ring missing	Level II	3.2	Visual
Minor				
201	Compound not applied to external threads	Level IV	3.2	Visual
202	External threads damaged	Level IV	3.2	Visual
203	Nicks on shoulder adjacent to external threads	Level IV	3.2	Visual
204	Seal ring not lubricated	Level IV	3.2	Visual
205	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.10	Projectile (immediately after assembly of ogive and prior to assembly of charge and sleeve assembly)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Radiographic examination (column segments not axially aligned)	100%	3.6	4.5.5
Major				
101	Gap between body and ogive beyond specified limits	100%	3.2	Gage
102	Concentricity of ogive to bourrelets (2 places)	100%	3.2	Gage
103	Process control inspection	Level II	3.2	4.5.4
Minor				
201	Poor workmanship	Level III	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.11	Charge and Sleeve Assembly (prior to insertion of charge assembly)	1 OF 1	9298360
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major 101	Spotting charge assembly not secure	Level II	3.2	Visual/Manual
Minor 201	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.12	Charge and sleeve assembly (prior to insertion into projectile)		9298360
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major 101	Cover damaged, dented or punctured (4)	Level II	3.2	Visual
Minor 201	Poor workmanship	Level III	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89

Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.13	Projectile (after assembly of charge and sleeve assembly and prior to ~~assembly of lifting plug~~)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Weight	100%	3.2	4.5.3
102	Fuze thread in ogive damaged, incomplete or containing foreign matter	100%	3.2	Visual
103	Retaining ring missing or improperly assembled	Level II	3.2	Visual
104	Foreign matter in fuze cavity	Level II	3.2	Visual
105	Lifting plug threads not greased	Level II	3.2	Visual
106	Threads damaged or containing foreign matter	Level II	3.2	Visual
107	Zone weight marking missing or incorrect	Level II	3.2	Visual
108	Lifting plug or gasket missing or damaged	Level II	3.2	Visual
Minor				
201	Poor workmanship	Level III	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.14	Projectile (prior to assembly of grommet)	1 OF 1	9298315 & 9298316
			NEXT HIGHER ASSEMBLY 9298315 & 9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Air pressure test	100%	3.2	4.5.1
102	Lifting plug turns when disassembly torque is applied	Level II	3.2	Test
103	Diameter of bourrelet, max (applicable after retouching paint)	Level II	3.2	Gage
104	Rotating band damaged	Level II	3.2	Visual
105	Obturator missing or damaged	Level II	3.2	Visual
106	Stamped letter "A" missing from ogive (indicating air pressure test failure)	Level II	3.2	Visual
107	Base metal of base plug exposed	100%	3.2	Visual
Minor				
201	Protective coating damaged (total of bare areas exceeds 1/4 square inch)	Level IV	3.2	Visual
202	Marking missing or unidentifiable	Level IV	3.2	Visual
203	Poor workmanship	Level IV	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.15	Projectile, 155MM, HE, M692/M731	1 OF 1	9298315/9298316
			NEXT HIGHER ASSEMBLY 9298315/9298316

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Projectile in flight detonation	2, Level I	3.3.1	Visual
Major				
101	Projectile temperature	2, Level II	3.9	4.4.3.1/Gage
102	Projectile firing zone and pressure	2, Level II	3.10	4.4.3.1/Visual
Minor	None defined			

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

MIL-P-48187C(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.16	Mine, Anti-Personnel, Type I and Type II	1 OF 1	9298400
			NEXT HIGHER ASSEMBLY 9898400

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical				
1	Hazardous dud	Level I	3.8.2	4.5.7
Major				
101	Self destruct time out function		3.7.1	4.4.3.2/4.5.6.5
102	Early time out function		3.7.2	4.4.3.2/4.5.6.5
103	Low order function		3.7.3	4.4.3.2/4.5.6.5
104	Safe duds		3.8.1	4.4.3.2/4.5.6.5
Minor	None defined			

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.17	Pallet (loaded)	1 OF 1	8837839
			NEXT HIGHER ASSEMBLY

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Projectile lifting plug missing, damaged, or wrong type (not fusible)	Level II	3.2	Visual
102	Projectile grommet assembly missing, damaged, or improperly assembled	Level II	3.2	Visual
103	Board broken or split	Level II	3.2	Visual
Minor				
201	Strap width incorrect	Level IV	3.2	Visual
202	Strapping improperly assembly	Level IV	3.2	Visual
203	Marking missing, incorrect or unidentifiable	Level IV	3.2	Visual
204	Poor workmanship	Level IV	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.18	Wood box (prior to closing) (Applicable when projectiles are not shipped on pallets)	1 OF 1	NEXT HIGHER ASSEMBLY

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Provisional pack warning sheet missing	100%	3.2	Visual
102	Projectile not secured	100%	3.2	Visual
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

AMSMC Form 1570b, 1 Jul 89 Replaces 1570, 1 Feb 85, which may not be used.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.19	Wooden box (after closing and sealing) (applicable when projectiles are not shipped on pallets)	1 OF 1	NEXT HIGHER ASSEMBLY

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Provisional pack warning missing	100%	3.2	Visual
102	Exterior markings missing, incorrect or unidentifiable	100%	3.2	Visual
103	Cover not secured	100%	3.2	Visual
Minor				
201	Box damaged	100%	3.2	Visual
202	Poor workmanship	Level III	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF CHARACTERISTICS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.20	Spotting Charge Assembly	1 OF 1	9298373
			NEXT HIGHER ASSEMBLY 9298360

CLASSIFICATION	EXAMINATION OR TEST	CONFORMANCE CRITERIA	REQUIREMENT PARAGRAPH	INSPECTION METHOD REFERENCE
Critical	None defined			
Major				
101	Cup not completely filled (settling permitted)	Level II	3.2	Visual
102	Tape missing, loose or overlapping outside diameter of cup	Level II	3.2	Visual
Minor				
201	Poor workmanship	Level IV	3.13	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.3.1 High explosive (HE) projectile firings. Two (2) HE projectiles per lot shall be randomly selected and fired for lot acceptance testing. The rounds shall be conditioned and fired as follows:

Zone	Temperature	Quantity
3	+70°F	1
7	+70°F	1

4.4.3.2 Self destruct functioning. The lot shall be rejected if any of the self destruct functions equal or exceed any of the defect quantities as follows for two HE rounds:

Early function: (Information only).
Low order function: Five (5) mines. See 4.4.3.2.1.
Safe duds: Five (5) mines.

4.4.3.2.1 Low order functioning. If low order functioning exceeds four (4) and the combination of low orders and safe duds does not exceed twelve (12), the lot is referred to higher headquarters product quality manager, for dispostion.

4.4.4 Inspection equipment. The inspection equipment required to perform the inspections and tests prescribed in this specification is identified in the "Paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1, and the test method paragraph (See 4.5). The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Method of inspection.

4.5.1 Air pressure test of projectile. The assembled projectile, with lifting plug, shall be placed in a chamber and a pre-determined volume of air shall be delivered to produce the specified pressure between the inside of the chamber and the outside of the projectile. If the specified pressure remains constant for the specified time interval, that projectile will be considered to have passed this test. However, if the indicated pressure at the end of the specified time interval is less than the specified pressure at the beginning of the time interval, that projectile shall be suitably identified and removed from the lot to prevent mixing with satisfactory projectiles. All equipment used in this test shall be capable of performing the test accurately and consistently. Equipment shall be calibrated at intervals to be

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

approved by the technical agency. If it is found that the gage is out of calibration in such a direction that the test pressure was actually lower than that specified on the drawing, projectiles tested since the last satisfactory calibration shall be retested after the error has been corrected. All test and calibration instructions, equipment and procedures shall be approved in accordance with 4.4.4.

4.5.2 Leakage test of charge assembly. The specified quantity of charge assemblies shall be subjected to the pressure specified on the applicable drawing using equipment as specified in 4.4.4. A water immersion test shall be used. Any assembly which emits bubbles shall be rejected. Charge assemblies so tested shall not be returned to any lot. (Destructive test)

4.5.3 Projectile weight determination. The projectile, without lifting plug, gasket and grommet assembly, shall be weighed using equipment of suitable range and accuracy. The weight shall be marked in the specified location on the projectile and this marking shall be verified as being the same as the weight indicated by the equipment.

4.5.4 Process control. At random, irregular intervals, the Government inspector shall monitor the contractor's assembly operations to assure compliance with the requirements specified on the applicable drawings and the approved loading and assembling procedures. As a minimum, the following shall be monitored:

a. Application of pads to munitions.
b. Equalization of column segment heights by selective assembly or use of column shims.
c. Radial compression of layers prior to assembly into stack-up.
d. Loading size ring diameter for projectile inside diameter.
e. Determination of ogive shim thickness including application of specified load.
f. Torquing of ogive.
g. Axial alignment of column segment wedges in layers 1 through 4.

4.5.5 Radiographic examination of projectile. Prior to assembly of the base plug, the location of the keyway shall be marked on the exterior of each projectile. The projectiles shall be radiographed after assembly of the ogive and prior to assembly of the charge and sleeve assembly. In all exposures, the radiographic beam shall be focused along the center axis of the projectile and parallel to the face of the shelf plate. The radiograph shall be taken 10° clockwise from the keyway position such that the column segments are in line with the source. The Radiograph shall show, as a minimum, the entire cargo pack including the base and forward plate. If necessary, more than one radiograph shall be taken as

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

required to avoid detrimental parallax effects. The radiograph shall be examined to assure compliance with the requirements specified in 3.7. All projectiles failing to conform to the requirements shall be suitably identified and removed from the lot. Projectiles and radiographs shall be identified to permit future reference. The radiograph for the ballistic sample shall be furnished with the projectile to the Government inspector.

NOTE: Radiograhic equipment, operations, procedures and personnel shall be qualified in accordance with MIL-STD-453. In addition, the photographic density of the film used shall be of quality which will produce a sharp definition of internal structure.

4.5.6 Ballistic functioning.

4.5.6.1 Preparation and firing. This test shall be conducted at a Government proving ground in accordance with acceptance test procedures approved by the Government. The round shall be fitted with a fuze which is standard for the projectile. The projectile fuze setting and the quadrant elevation of fifteen hundred (1500) and twenty-five hundred (2500) feet over a prepared impact area. A photograph shall be taken of the fuze setting for each round immediately prior to firing and each photograph shall be marked for future identification with the round. The sample projectile(s) shall be tested in the specified zone(s) using weapon, equipment, methods and procedures in accordance with the acceptance test procedures referenced above. Suitable equipment for safely monitoring cargo performance shall be provided at the impact area. The M109A3 weapon shall be used unless otherwise specified by the procuring agency.

4.5.6.2 Records of ballistic tests. A record shall be made for each round fired and shall include an accounting for the defects listed in 4.2 or below as applicable. In addition, the record shall include nose fuze duds or malfunctions, expulsion height, actual munition-functioning times, including early functions, and any other pertinent data. A copy of the ballistic test results for each projectile lot shall be forwarded to the address specified in 6.3.

4.5.6.3 Low altitude expulsion. If any projectile, except those tested at excess pressure, functions below fifteen hundred (1500) feet above ground level and the total number of defects does not exceed the specified acceptance criteria, no replacement for that projectile will be required. However, when the results of the low bursting projectile would cause the lot represented by the sample to be rejected, the results of that projectile shall be immediately transmitted to the technical agency for a determination as to whether a replacement projectile is necessary.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

4.5.6.4 Nose fuze malfunctions. Nose fuze malfunctions shall not be considered as cause for rejection of a projectile lot. When a fuze malfunction occurs, the proving ground shall notify the technical agency and request a determination as to the need for a replacement projectile.

4.5.6.5 High explosive mines. The mine field shall be audibly and visually monitored for the specified requirements of early functioning, low order function and self destruct functioning during the specified time priod and for hazardous dud functioning after the self destruct period has elapsed.

4.5.6.5.1 High explosive mines. (Alternate test method) The mines comprising the projectile payload that has been dispersed onto the test area shall be remotely tested by personnel utilizing an Armored Personnel Carrier (APC).

a. Observe the mine for successful tripline deployment and serialization number.

b. Disturb the mine for functioning in either the anti-disturbance or break wire mode.

c. Observe the mine for either high or low order functioning.

d. Note if the detonation was at ground level.

e. Mines that do not function high or low order (potential dud devices) shall be flagged and left for self destruct time out.

f. Mines that function low order shall be flagged and retrieved for analysis after all the mines on the field have been tested.

g. All data, including serialization snall be recorded.

h. Mines that have not functioned and have undergone self destruct time out shall then be subject to standard procedures for hazardous dud evaluation in accordance with 4.5.8 (Destructive test)

4.5.7 Hazardous dud evaluation procedure (HE mine). Any mine which has failed to fire the detonator when subjected to any predesignated tests for anti-disturbance, breakwire or self destruct shall be evaluated as follows:

a. Maximum self destruct time shall elapse prior to additional test inputs.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

b. One tripline shall be pulled from each breakwire circuit. If the mine fires in either attempt it shall be classed as a hazardous dud.

c. If the sample under test does not fire in the breakwire mode it shall be tested for anti-disturbance functioning by moving it twice to adjacent mine faces. If it fires in any attempt to fire anti-disturbance it shall be classed as a hazardous dud.

d. If the mine does not fire in the anti-disturbance mode, it shall be tested for self-destruct functioning by allowing to remain undisturbed for a time period equal to that of the self-destruct time. If it fires prior to reacting the maximum self destruct time it shall be classed as a hazardous dud.

e. If the mine fails to fire in the self destruct mode, it shall be classed as a safe dud.

4.5.8 Inspection of gap between projectile body and base. Gap shall be inspected using an approved feeler gage as specified on drawing 9215220. The feeler gage shall be cleaned with a clean dry rag immediately after each inspection such that the gage is free of any base/body gap sealant. No solvent or other substance other than a clean dry rag shall be used to clean the gage. The gap between the projectile body and base shall be inspected within fifteen (15) minutes after the sealant is applied to the shoulder of the base.

5. PACKAGING

5.1 Packing (level A). The projectiles shall be packed in accordance with Dwg. 8837839.

5.2 Marking. Marking shall be in accordance with Dwg. 8837839.

5.3 Shipping. When projectiles from more than one lot are shipped at one time, each lot shall be kept separate and the division between lots clearly indicated to prevent mixing of the lots in transit.

6. NOTES

(This section contains information of a general or explanatory nature that may be helpful, but is not mandatory.)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

6.1 Intended use. The loading, assembling, and packing operations covered by this document are intended for use in the munition for projectiles, HE, 155MM, M692 and M731.

6.2 Acquisition requirements. Acquisition documents must specify the following:

a. Title, number, and date of the specification.

b. Issue of DODISS to be cited in the solicitation, and if required, the specific issue of individual documents referenced (See 2.1).

6.3 Submission of inspection equipment designs for approval. (See MIL-A-48078). Equipment designs shall be submitted as required to: Commander, U. S. Army Armament Research and Development Center, ATTN: SMCAR-QAT-I(D), Dover, New Jersey 07801. Request letter of submittal should state contractor, contract number, specification number, item nomenclature, and classification of defects and tests paragraph number. This address will be specified on the Contract Data Requirements List, DD Form 1423 in the contract.

6.4 Submission of alternative quality conformance procedures. Unless otherwise specified in the contract, proposed alternative quality conformance provisions will be submitted by the contractor to the procuring contracting officer.

6.5 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research, Development and Engineering Center (ARDEC), may also include drawings prepared by, and identified as, US Army Armament Research and Development Command, Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal or Picatinny Arsenal drawings. Technical data originally prepared by these activities are now under the cognizance of ARDEC.

6.6 Data requirements. Deliverable data required by this specification are cited in the following paragraphs:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

Paragraph	Data Requirement	Applicable DID
3.5	Plan for controls in use of adhesives and sealants	DI-T-5372(Tailored)
3.6	Plan for Safety in handling and Processing of Munitions	DI-T-5372(Tailored)

6.7 Projectile functioning.

6.7.1 Premature burst. A premature burst is considered to have occurred if the projectile functions in the weapon or the time of flight is less than 1.9 seconds.

6.7.2 Functioning at all zones, excluding excess pressure. Satisfactory functioning of the projectile when fired at any zone, except excess pressure is defined as successfual delivery of the cargo to the target area with all projectile hardware remaining intact until initiation of the nose fuze at a pre-determined time after firing, and also includes removal of all shorting bars, depression of all battery balls, and expulsion of the entire cargo.

6.7.3 Functioning at excess pressure. Satisfactory functioning of the projectile when fired at excess pressure is defined as successful delivery of the cargo to the target area with all projectile hardware remaining intact until initiation by the nose fuze.

6.7.4 Excess pressure. Excess pressure in the M109A1 weapon system is herein considered to be a chamber pressure of approximately 43,000 psi.

6.8 Subject term (keyword) listing.
Propellant
Solid
Radiographic

6.9 Changes from previous issue. Asterisks are not used in this revision to identify changes with respect to the previous issue, due to the extensiveness of the changes.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-AC81)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

INSTRUCTIONS

1. The preparing activity must complete blocks 1, 2, 3, and 8. In block 1, both the document number and revision letter should be given.
2. The submitter of this form must complete blocks 4, 5, 6, and 7.
3. The preparing activity must provide a reply within 30 days from receipt of the form.

NOTE: This form may not be used to request copies of documents, nor to request waivers, or clarification of requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document(s) or to amend contractual requirements.

I RECOMMEND A CHANGE:	1. DOCUMENT NUMBER	2. DOCUMENT DATE (YYMMDD)
	MIL-P-48187C (AR)	10 APRIL 1992

3. DOCUMENT TITLE
PROJECTILE, 155MM, HE, M692 AND M731 LOADING, ASSEMBLING AND PACKING

4. NATURE OF CHANGE *(Identify paragraph number and include proposed rewrite, if possible. Attach extra sheets if needed.)*

5. REASON FOR RECOMMENDATION

6. SUBMITTER

a. NAME (Last, First, Middle Initial)	b. ORGANIZATION	
c. ADDRESS (Include Zip Code)	d. TELEPHONE (Include Area Code) (1) Commercial (2) AUTOVON (If applicable)	7. DATE SUBMITTED (YYMMDD)

8. PREPARING ACTIVITY

a. NAME	b. TELEPHONE (Include Area Code)	
US ARMY ARDEC STANDARDIZATION OFFICE	(1) Commercial (201) 724-6675	(2) AUTOVON 880-6675
c. ADDRESS (Include Zip Code) ATTN: SMCAR-BAC-S PICATINNY ARSENAL,NJ 07806-5000	IF YOU DO NOT RECEIVE A REPLY WITHIN 45 DAYS, CONTACT: Defense Quality and Standardization Office 5203 Leesburg Pike, Suite 1403, Falls Church, VA 22041-3466 Telephone (703) 756-2340 AUTOVON 289-2340	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:55Z
Check the source to verify that this is the current version before use.