MILITARY SPECIFICATION

SENSOR, TRIPLINE; EXTENDED RANGE

This specification is approved for use by the US Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies for the Department of Defense.

1. SCOPE

1.1 Scope. This specification contains requirements not covered by the drawings and provides quality assurance provisions for the fabrication of parts, assembly and packing of a tripline sensor assembly used in various Anti-Personnel Mines.

2. APPLICABLE DOCUMENTS

2.1 Government documents.

2.1.1 Specifications and standards. Unless otherwise specified (see 6.2), the following specifications and standards of the issue listed in that issue of the Department of Defense Index of Specifications and Standards (DoDISS) specified in the solicitation, form a part of this specification to the extent specified herein.

SPECIFICATIONS

FEDERAL

J-W-1177/2A	Wire, Magnet, Electric, Class 105, Type U, Polyurethane- coated, Round

MILITARY

MIL-B-117	Bags, Sleeves and Tubing Interior Packaging
MIL-P-14232	Parts, Equipment and Tools for Army Materiel, Packaging of

FSC 1345

Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: Commander, US Army Armament Research and Development Center, Attn. DRSMC-QA, Dover, New Jersey 07801 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

MIL-S-45743 - Soldering, Manual Type, High Reliability, Electrical and Electronic Equipment

MIL-A-48078 - Ammunition, Standard Quality Assurance Provisions, General Specification for

STANDARDS

MIL-STD-105 - Sampling Procedures and Tables for Inspection by Attributes (ABC-STD-105)

MIL-STD-1188 - Commercial Packaging of Supplies and Equipment

DRAWINGS (See 6.5)

U.S. Army Armament Research and Development Center (ARDC)

9292972 - Tripline Sensor, Extended Range,

(Copies of specifications, standards, handbooks, drawings, and publications required by manufacturers in connection with specific acquisition functions should be obtained from the contracting activity or as directed by the contracting officer.

2.2 Other publications. The following documents form a part of this specification to the extent specified herein. Unless otherwise indicated, the issue in effect on the date of invitation for bids or request for proposal shall apply.

AMERICAN SOCIETY FOR TESTING AND MATERIALS

ASTM D 2240 - Test Method for Rubber Property - Durometer Hardness

(Application for copies should be addressed to: American Socity for Testing and Materials, 1916 Race Street, Philadelphia, PA 19103).

2.3 Order of precedence. In the event of a conflict between the text of this specification and the references cited herein, the text of this specification shall take precedence.

3. REQUIREMENTS

3.1 Material. Materials shall be in accordance with the applicable drawings and specifications.

3.2 Components and assemblies. The components and assemblies shall comply with all requirements specified on Drawing (dwg.) 9292972, and associated drawings, and with all requirements specified in applicable specifications and standards.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

3.3 Sensor Non-release (for BLU-92/B mine only) The Tripline Sensor (Dwg. 9292972) shall not release when subjected to a half sine wave deceleration of 4200 +300-0 g's for a time duration of 300 ± 50 microseconds, in the direction of deployment, when tested in accordance with 4.5.1.1.

3.4 Sensor release

3.4.1 Ambient temperature (75°F ± 10°F). - When subjected to a gage pressure of 300 ± 25 pounds per square inch (psig) for a maximum (max.) time duration of 200 milliseconds (ms.), the sensor shall release satisfactorily, as evidenced by expelling the ejection spring, sleeve, bobbin, anchor, cap and a length of tripline while the bobbin post is retained in the sensor body and breakwire continuity is maintained.

3.4.2 Cold temperature (Minus 40°F - 5°F). When subjected to a gage pressure of 500 ± 25 psig. for a max. time duration of 200 ins., the sensor shall release satisfactorily as specified in 3.4.1.

3.5 Tripline deployment. When the tripline sensor functions in 3.4, the tripline shall deploy as a minimum (min.), the distance specified on Drawing 9292972 and remain continuous to the post.

3.6 Breakwire function. When the pressure is released and the tripline pulled, the breakwire shall break when tested as specified in 4.5.1.4. Prior to breakwire function, the bobbin post must be retained within the sensor case and the thread must not break.

3.7 Post retention and thread breaking strength. When a 540 grams min. pull force is applied as specified in 4.5.1.5, post retention and tripline integrity should be maintained. (For information only).

3.8 Breakwire continuity. The resistance between the leadwires (for Pt. No. 9292972-1) or between the breakwire terminals (for Pt. No. 9292972-2) shall not be greater than 0.1 ohms.

3.9 Embrittlement of springs. Ejection springs and booster springs shall not break when extended to the min. point of permanent distortion.

3.10 Process controls. The contractor shall define and document the process for each of the following operations and shall not change that process after successful completion of first article testing without prior consent and approval of the Government Technical Agency (Ref. Sec 6.4, DI-P-1604 (Mod) with Attachment I):

Assembly and crimp of Release Mechanism and Case Assembly, Dwg. 9292986.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

b. Bobbin Assembly taping, Dwg. 9292982.

c. Molding and assembly of Diaphragm and Diaphragm Assembly, Dwgs . 9298598 and 9292998.

d. Terminal Staking, Dwg. 9292991.

Assembly and crimp of Release Mechanism Assembly, Dwg. 9292991.

f. Molding and post cure of Ring, Ball Lock, Dwg. 9298586.

g. Soldering of breakwire and lead wires to terminals, Dwg. 9292972.

h. Drill of Bobbin depth, Dwg. 9292976.

3.11 Soldering. Soldering procedures and acceptance criteria for the soldered components shall be in accordance with MIL-S-45743, except as specified in Appendix herein.

3.12 Workmanship. All parts shall be fabricated and finished in a thorough workmanlike manner, and all manufacturing, processing, and assembly operations shall be correctly performed. They shall be clean and free of burrs, sharp edges, unblended radii, surface defects, chips, dirt, grease and oil, corrosion products and other foreign matter. The cleaning method used shall not be injurious to any part or assembly, nor shall they be contaminated by the cleaning agent. Exterior surface coatings shall be continuous except for a few light scratches not exposing base material. All required markings shall be neat, legible and sharply defined. Required packing shall be dry.

4. QUALITY ASSURANCE PREVISIONS

4.1 Responsibility for inspection and standard quality assurance provisions. Unless otherwise specified herein or in the contract, the provisions of MIL-A-48078 shall apply and are hereby made a part of this detail specification.

4.2 Classification of inspections. The following types of inspections shall be conducted on this item:

a. First Article Inspection.

b. Quality Conformance Inspection.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

4.3 First article inspection

4.3.1 Submission. The contractor shall submit a first article sample as designated by the contracting officer for evaluation in accordance with provisions of 4.3.2, The first article sample shall consist of eighty-two (82) Tripline Sensors (Dwg. 9292972).

4.3.2 Inspections to be performed. See MIL-A-48078 and the tests specified herein.

a. Fifty (50) Tripline Sensors from 4.3.1 shall be subjected to the tests specified in 4.5.1.1, 4.5.1.2.1, 4.5.1.3, 4.5.1.4, and 4.5.1.5.

b. Thirty-two (32) Tripline Sensors from 4.3.1 shall be subjected to the tests specified in 4.5.1.1, 4.5.1.2.2, 4.5.1.3, 4.5.1.4, and 4.5.1.5.

4.3.3 Rejection. - See MIL-A-48078.

4.4 Quality conformance inspection

4.4.1 Inspection lot formation. Inspection lots shall comply with the lot formation provisions of MIL-A-48078. Inspection lots of tripline sensors shall contain metal parts of one lot interfix number from one manufacturer.

4.4.2 Examination. - See MIL-A-48078.

a. Sampling plans. Unless otherwise specified in the Classification of Defects and Tests tables, sampling plans for major and minor defects shall be in accordance with MIL-STD-105, Inspection Level II.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.1	Diaphragm		9298598
			NEXT HIGHER ASSEMBLY 9292998

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diaphragm split or cracked after mandril test (See Dwg. Note 3)		0.40%	3.2	Visual
102	Large inside diameter, open end	1/	0.40%	3.2	Gage
103	Large dimeter of pressure channel	1/	0.40%	3.2	Gage
104	Small diameter of pressure channel	1/	0.40%	3.2	Gage
105	Length of center hole	1/	0.40%	3.2	Gage
106	Hardness of piece part (9298598-1 only)	2/	0.40%	3.2	Test ASTM D 2240
Minor					
201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ See paragraph 4.5.1.7 for alternate method of dimensional control.
2/ Certification.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.2	Diaphragm Assembly				9292998
					NEXT HIGHER ASSEMBLY
					9292991
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Any part split, pinched, damaged, or axially loose		0.40%	3.2	Visual/Manual
102	Diaphragm skirt not notched, or notch improperly oriented		0.40%	3.2	Visual
Minor					
201	Improper orientation of gasket tongue		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 2	DRAWING NUMBER
4.4.2.3	Plate, Diaphragm		9298597
			NEXT HIGHER ASSEMBLY 9292998

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter of nozzle	1/	0.40%	3.2	Gage
102	Diameter of center hole	1/	0.40%	3.2	Gage
103	Outer diameter of pressure groove on flat surface	1/	0.40%	3.2	Gage
104	Inner diameter of pressure groove on flat surface	1/	0.40%	3.2	Gage
105	Location of breakwire terminal flat(s) 2 places	1/	0.40%	3.2	Visual
106	Location of breakwire terminal alignment post(s), 4 places	1/	0.40%	3.2	Gage
107	Inlet port blocked		0.40%	3.2	Visual/Manual

NOTES: 1/ See paragraph 4.5.1.7 for alternate method of dimensional control.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9298597
4.4.2.3	Plate, Diaphragm (Cont'd)				NEXT HIGHER ASSEMBLY 9292998
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Width of tabs on outer diameter of plate, 4 places	1/	0.65%	3.2	Gage
202	Location of tabs on outer diameter of plate, 4 places	1/	0.65%	3.2	Gage
203	Height of breakwire terminal alignment post(s), 4 places	1/	0.65%	3.2	Gage
204	Outside diameter of diaphragm plate	1/	0.65%	3.2	Gage
205	Diameter of post cover recess	1/	0.65%	3.2	Gage
206	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES: 1/ See paragraph 4.5.1.7 for alternate method of dimensional control.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298588
4.4.2.4	Cup, Housing				NEXT HIGHER ASSEMBLY 9298587
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of transverse hole, 4 places	1/	0.40%	3.2	Gage
102	Location of transverse hole, 4 places	1/	0.40%	3.2	Gage
103	Flange outside diameter	1/	0.40%	3.2	Gage
104	Diameter of large hole, closed end	1/	0.40%	3.2	Gage
105	Protective finish			3.2	Certification
106	Outside diameter of housing	1/	0.40%	3.2	Gage
107	Flange thickness	1/	0.40%	3.2	Gage
108	Flange step diameter	1/	0.40%	3.2	Gage
109	Inside diameter of housing	1/	0.40%	3.2	Gage
Minor					
201	Location of tabs in large hole closed end, 2 places	1/	0.65%	3.2	Gsge
202	Width of tabs in large hole, closed end, 2 places	1/	0.65%	3.2	Gage
203	Inside depth of housing	1/	0.65%	3.2	Gage
204	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ See paragraph 4.5.1.8 for alternate method of dimensional control.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298589
4.4.2.5	Tube, Housing				NEXT HIGHER ASSEMBLY 9298587
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Large outside diameter		0.65%	3.2	Gage
202	Small inside diameter		0.65%	3.2	Gage
203	Small outside diameter		0.65%	3.2	Gage
204	Length of large outside diameter		0.65%	3.2	Gage
205	Diameter of transverse hole		0.65%	3.2	Gage
206	Location of transverse hole		0.65%	3.2	Gage
207	Width of slot		0.65%	3.2	Gage
208	Location of slot		0.65%	3.2	Gage
209	Improper surface finish		1.00%	3.2	Visual
210	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

DD FORM 6A (R) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298587
4.4.2.6	Housing Assembly				NEXT HIGHER ASSEMBLY 9292991
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Incomplete crimp		0.40%	3.2	Visual
102	Crimp integrity	1/		3.2	Test Set-Up
103	Min. ID to depth indicated (See Dwg. Note 4)		0.40%	3.2	Gage
104	Dry lubricant missing		0.40%	3.2	Visual/Manual
Minor					
201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES: 1/ Ten (10) samples to be tested at start and finish of each 8 hr. shift, Accept 0, Reject 1.

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.7	Release Mechanism Assembly				9292991
					NEXT HIGHER ASSEMBLY 9292986
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Presence and position of (2) spring washers	1/	0.40%	3.2	Radiographic
Minor 201	Evidence of poor workmanship		1.00%	3.12	Visual

Note 1/: Alternate for machine assembly - Sampling shall be two (2) magazines (approx 50 parts) randomly selected from each one hour of production. A maximum of 1 defect is permitted in the sample. The production qty. shall remain segregated for screening in the event of failure.

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9292988
4.4.2.8	Sleeve				NEXT HIGHER ASSEMBLY 9292986
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Diameter of transverse hole, 4 places	1/	0.40%	3.2	Gage
102	Location of transverse hole, 4 places	1/	0.40%	3.2	Gage
Minor					
201	Outside diameter (See Dwg. Note 5)	1/	0.65%	3.2	Gage
202	Location of tabs	1/	0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ See paragraph 4.5.1.8 for alternate method of dimensional control.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9292987
4.4.2.9	Case, Sensor				NEXT HIGHER ASSEMBLY 9292986
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Large inside diameter	1/	0.40%	3.2	Gage
102	Small inside diameter	1/	0.40%	3.2	Gage
103	End of case to bottom of notch	1/	0.40%	3.2	Gage
Minor					
201	Width of notch	1/	0.65%	3.2	Gage
202	Location of notch	1/	0.65%	3.2	Gage
203	Overall length	1/	0.65%	3.2	Gage
204	Presence of nickel plate		1.00%	3.2	Visual
205	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ See paragrpah 4.5.1.8 for alternate method of dimensional control.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.10	Terminal, Breakwire				9298601
					NEXT HIGHER ASSEMBLY 9292991
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Solderability		10-0-1	3.2	See Dwg. Note 8
Minor 201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.11	Release Mechanism & Case Assembly				9292986
					NEXT HIGHER ASSEMBLY 9292976
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Presence of four (4) locking balls		0.40%	3.2	Radiographic
102	Any other component missing, loose, or improperly assembled		0.40%	3.2	Visual/Manual
Minor					
201	Any component damaged		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER 9292985
4.4.2.12	Bobbin				NEXT HIGHER ASSEMBLY 9292982
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Length from post end to face of post end flange	1/	0.40%	3.2	Gage
102	Depth of post slot below ring retaining groove	1/	0.40%	3.2	Gage
103	Angle of post slot	1/	0.40%	3.2	Gage
104	Diameter of thread area of bobbin core	1/	0.40%	3.2	Gage
105	Width of slot between post end flange and bobbin core raised flange	1/	0.40%	3.2	Gage
106	Diameter of post	1/	0.40%	3.2	Gage
107	Diameter of ball locking groove on post	1/	0.40%	3.2	Gage
108	Length of ball locking groove on post	1/	0.40%	3.2	Gage
109	Width of ring retaining groove on post	1/	0.40%	3.2	Gage
110	Length of post from face of post end flange to end of ball locking groove	1/	0.40%	3.2	Gage
111	Parting line mismatched (See Dwg. Note 5)	1/	0.40%	3.2	Visual

NOTES: 1/ See paragraph 4.5.1.7 for alternate method of dimensional control.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER 9292985
4.4.2.12	Bobbin (Cont'd)				NEXT HIGHER ASSEMBLY 9292982
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Minor					
201	Diameter of bobbin weight hole	1/	0.65%	3.2	Gage
202	Thickness of spring ejection flange, 4 places	1/	0.65%	3.2	Gage
203	Diameter of spring ejection flange	1/	0.65%	3.2	Gage
204	Width of spring ejection flange, 4 places	1/	0.65%	3.2	Gage
205	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ See paragraph 4.5.1.7 for alternate method of dimensional control.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.13	Thread, Polyester				9298274
					NEXT HIGHER ASSEMBLY 9292982
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major 101	Breaking strength below minimum	1/		3.2	Test
Minor	None defined				

NOTES:

1/ Select one sample from the beginning of each spool. Failure of the sample shall reject the spool for use in production.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.14	Bobbin Assembly				9292982
					NEXT HIGHER ASSEMBLY 9292976
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Thread breaks at points of attachment upon application of a 1.2 lb. axial force		0.40%	3.2	Test
102	Thread not clockwise (when viewed from post end)		0.40%	3.2	Visual
103	Thread in contact with post between flanges		0.40%	3.2	Visual
104	Thread in area of center hole on weighted end (See Dwg. Note 6)		0.40%	3.2	Visual
Minor					
201	Any component missing, loose, or improperly assembled		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.15	Sensor Case & Bobbin Assembly				9292976
					NEXT HIGHER ASSEMBLY 9292972
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major	None defined				
Minor					
201	Any component missing, loose, or improperly assembled		0.65%	3.2	Visual
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9298576
4.4.2.16	Wire, Magnet, Electrical (Breakwire)				NEXT HIGHER ASSEMBLY 9292972
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Component requirements (Note 1 of Dwg.)	1/			Certification
102	Elongation under minimum	2/		3.2	Gage
Minor					
201	Diameter	2/		3.2	Gage
202	Evidence of poor workmanship		0.65%	3.12	Visual

NOTES:
1/ Certificate of conformance with applicable requirements of J-W-1177/2A.
2/ Select one sample from the beginning of each spool or coil. Failure of the sample shall reject the spool/coil for use in production.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.17	Spring, Washer	1 OF 1	9298582
			NEXT HIGHER ASSEMBLY 9292991

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter (Note a)	1/	0.40%	3.2	Gage
102	Inside diameter (Note b)	1/	0.40%	3.2	Gage
103	Compressed height under load		0.40%	3.2	Test
104	Heat Treat	2/		3.2	Certification
Minor					
201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:
a. Maximum width, 1 place
b. Maximum width, 1 place

NOTES:
1/ See paragraph 4.5.1.8 for alternate method of dimensional control.
2/ Certificate of compliance for heat treatment.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.18	Ring, Ball Lock				9298586
					NEXT HIGHER ASSEMBLY 9292991
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter		0.40%	3.2	Gage
102	Small inside diameter	1/	0.40%	3.2	Gage
103	Length of small inside diameter	1/	0.40%	3.2	Gage
104	Distance across slots flat end, 2 places	1/	0.40%	3.2	Gage
105	Distance across slots raised end, 2 places	1/	0.40%	3.2	Gage
106	Width of slot, 4 places	1/	0.40%	3.2	Gage
107	Surface finish improper		0.40%	3.2	Visual
108	Post cure	2/			Certification
109	Large inside diameter	1/	0.40%	3.2	Gage
Minor					
201	Inside diameter on raised surface	1/	0.65%	3.2	Gage
202	Overall length	1/	0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:
1/ See paragraph 4.5.1.7 for alternate method of dimensional control.
2/ Certificate of compliance for post cure

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check this source to verify that this is the correct version before use.

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.19	Spring, Ejection				9292977
					NEXT HIGHER ASSEMBLY 9292976
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	O.D. max.		0.40%	3.2	Gage
102	I.D. small end		0.40%	3.2	Gage
103	Load at compressed height		0.40%	3.2	SME
104	Protective finish improper, (base metal exposed)		0.40%	3.2	Visual
105	Embrittlement	1/		3.9	4.5.1.9
Minor					
201	Free length		0.65%	3.2	Gage
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ Thirty (30) springs shall be selected from each lot for this test. Accept 0, Reject 1. Springs so tested shall be discarded.

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER 9292990
4.4.2.20	Spring, Booster				NEXT HIGHER ASSEMBLY 9292976
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Outside diameter, max.		0.40%	3.2	Gage
102	Inside diameter, small end		0.40%	3.2	Gage
103	Load at compressed height		0.40%	3.2	SME
104	Protective finish improper (base metal exposed)		0.40%	3.2	Visual
105	Embrittlement	1/		3.9	4.5.1.9
Minor					
201	Free length		0.65%	3.2	Gage
202	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

1/ Thirty (30) springs shall be selected from each lot for this test. Accept 0, Reject 1. Springs so tested shall be discarded.

Source: https://assist.dla.mil -- Downloaded: 2020-10-20 16:05:37Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.21	Anchor		9292980
			NEXT HIGHER ASSEMBLY 9292976

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Inside diameter	1/	0.40%	3.2	Gage
102	Crotch diameter, 2 places	1/	0.40%	3.2	Gage
103	Flat distance between tines, 2 places (See Note 8)		0.40%	3.2	Gage
104	Hardness	2/		3.2	Test Set-Up
105	Protective finish incorrect, inadequate or damaged (base metal exposed)		0.40%	3.2	Visual
106	Presence of burrs on wrong side (See Note 5)		0.40%	3.2	Visual
107	Thickness		0.40%	3.2	Gage
Minor					
201	Angle of legs after bending	1/	0.65%	3.2	Gage
202	Radius at origin of bend, 4 places	1/	0.65%	3.2	Gage
203	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:
1/ See paragraph 4.5.1.8 for alternate method of dimensional control.
2/ MIL-STD-105, Level S-3, Accept 0, Reject 1.

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.22	Tripline Sensor, Extended Range (Prior to assembly of Cover, Post)				9292972
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Breakwire improperly installed		0.40%	3.2	Visual
102	Breakwire retaining ring missing, improperly assembled or not engaged on post		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2020-10-28T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 1 OF 2		DRAWING NUMBER
4.4.2.23	Tripline Sensor, Extended Range				9292972
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Breakwire continuity - resistance		100%	3.8	4.5.1.6
102	Tabs improperly crimped		0.40%	3.2	Visual
103	Breakwire Soldered improperly (Note 3)		0.40%	3.11	Visual
104	Adhesive above flush or outside max. envelope (Pt. No. 9292972-1 only)		0.40%	3.2	Visual
105	Lead wire(s) incorrect or soldered improperly (Pt. No. 9292972-1 only, Note 3)		0.40%	3.11	Visual
106	Center of nozzle to end of case length, max.		0.40%	3.2	Gage
	Functioning Tests (Note 1)				
	NOTE:				
	1. The tests shall be performed in the order listed. The sample units for each test shall have been tested on all preceeding tests in this sequence. However, acceptance or rejection on one test shall not constitute acceptance or rejection on the other test. The sample sizes specified are applicable to each test and shall not be amended by fallout from previous tests.				
	2. This test to be performed with completed assembly only).			(applies	for BLU 92/B Mine
	3. To be inspected prior to application of adhesive.				
NOTES:					

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202640-26T03:57Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE		SHEET 2 OF 2		DRAWING NUMBER
4.4.2.23	Tripline Sensor, Extended Range				9292972
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Major	Functioning Test (Cont'd)				
107	Non Release (Note 2)		82-2-3	3.3	4.5.1.1
108	Release:			3.4	4.5.1.2
	Ambient (75°F + 10°F)		50-1-2	3.4.1	4.5.1.2.1
	Cold (minus 40°F - 5°F)		32-1-2	3.4.2	4.5.1.2.2
109	Tripline deployment:			3.5	4.5.1.3
	Ambient (75° + 10°F)		50-3-4	3.5	4.5.1.3
	Cold (minus 40°F - 5°F)		32-2-3	3.5	4.5.1.3
110	Breakwire functioning, (Note 4)		82-5-6	3.6	4.5.1.4
Minor					
201	Evidence of poor workmanship		1.00%	3.12	Visual
	For Information Only:				
	Post retention & thread breaking strength		82	3.7	4.5.1.5

NOTES:

4. No more than two of the five allowable defectives shall exceed 1.2 lbs.

Source: https://assist.dla.mil -- Downloaded: 2026/0-26T03:37Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

MIL-S-48755A(AR)

PARAGRAPH	TITLE			SHEET 1 OF 1	DRAWING NUMBER
4.4.2.24	Miscellaneous Components				NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	9298618 Gasket Fibrous 9298599 Eyelet, Diaphragm 9292989 Washer, Case 9298581 Ball, Locking 9292983 Weight, Bobbin 9292981 Eyelet, Interface 9298579 Cap 9298577 Ring, Retaining, Breakwire 9298575 Cover, Post 9298591 Tape				
Critical	None defined				
Major	None defined				
Minor 201	Evidence of poor workmanship		1.00%	3.12	Visual

NOTES:

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

4.4.3 Testing. Testing is described in the First Article and Quality Conformance Inspection Tables.

4.4.4 Inspection equipment. The inspection equipment required to perform the examinations and tests prescribed herein is described in the "paragraph Reference/Inspection Method" column in the tables starting with paragraph 4.4.2.1. The contractor shall submit for approval inspection equipment designs in accordance with the terms of the contract. See Section 6 of MIL-A-48078 and 6.3 herein.

4.5 Test methods and procedures

4.5.1 Sensor assembly

4.5.1.1 Non-release of sensor assembly (For BLU-92/B mine only). The sensor assembly shall be mounted in a suitable fixture/shock machine that is capable of inducing the deceleration environment specified in 3.3 to the normally releaseable sensor components along the axis of a conventional sensor deployment. Any unit in which the sleeve completely separates or begins to separate from the case shall be classed defective. This test is non-destructive. Those units meeting the requirements of this test shall be used for the tests in 4.5.1.2, 4.5.1.3, and 4.5.1.4.

4.5.1.2 Release of sensor assembly

4.5.1.2.1 Ambient temperature (75°F + 10°F). The breakwire circuit shall be checked for continuity in accordance with 4.5.1.6. Units which have resistance greater than 0.1 ohms shall not be subjected to this test. Units to be tested shall be conditioned at the specified temperature, along with the clamp device of deployment fixture, until all parts being conditioned are stabilized at the specified temperature. The test units in the clamping device shall be placed in a suitable test fixture and the pressure specified in 3.4.1 shall be applied. Any unit which fails to release when pressurized as evidenced by the bobbin core being retained within the sensor case, or in which breakwire resistance is greater than 0.1 ohms across the breakwire circuit, shall be classed defective and shall not be repressurized. This test is destructive. Those units meeting the requirements of this test shall be used for the test in 4.5.1.3.

4.5.1.2.2 Cold temperature (Minus 40°F - 5°F). - The breakwire circuit shall be checked for continuity in accordance with 4.5.1.6. Units having resistance greater than 0.1 ohms shall not be subjected to this test. Units to be tested shall be conditioned at the specified temperature, along with the clamp device of deployment fixture, until all parts being conditioned are stabilized at the specified temperature. Within three (3) minutes after removal from the conditioning chamber, the test unit in the clamping device shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

be placed in a suitable test fixture and the pressure shall be applied in accordance with 3.4.2. Any unit which fails to release when pressurized as evidenced by the bobbin core being retained within the sensor case, or in which breakwire resistance is greater than 0.1 ohms across the breakwire circuit shall be classed defective and shall not be repressurized. This test is destructive. Those units meeting the requirements of this paragraph shall be used for the test in 4.5.1.3.

4.5.1.3 Tripline deployment. After the sensor assembly is tested in accordance with 4.5.1.2.1 or 4.5.1.2.2 and with the sensor remaining in the test fixture, observation shall be made to assure that the bobbin core, with tripline attached, and continuous to the post, is deployed over a vertical barrier oriented as follows:

a. The barrier location shall be, as a minimum, be the distance specified on Drawing 9292972, measured horizontally from the sensor.

b. Barrier height shall be, as a minimum, be the height specified on Drawing 9292972, above the top of the sensor.

c. The sensor assembly shall be oriented to provide an angle of inclination from the horizontal between 30° and 45°.

A bobbin core that impacts ground level before the barrier or impacts the barrier shall be considered defective. This test is destructive. Those units that are capable of meeting the requirements of the test specified in 4.5.1.4 shall be used for that test even if they failed to meet the requirements for this test.

4.5.1.4 Breakwire function. After the sensor assembly is tested in accordance with 4.5.1.1, 4.5.1.2.1 or 4.5.1.2.2, and 4.5.1.3 the clamp device of deployment fixture, with the unit remaining in place, shall be adjusted to position the deployed sensor in an approximate horizontal attitude and a suitable force gage attached to the tripline at a distance which is coincident with the barrier. A pull force shall be applied to the tripline along the axis of the bobbin post and the force required for breakwire function shall be noted. The required force is that force at which a clean break is indicated in the breakwire circuit as evidenced by a resistance of 1000 ohms minimum for a minimum of 100 microseconds. Any unit that fails to meet the specified drawing requirements shall be classed defective. The rate of pull shall be 3 ft. ±~ 1 ft)/sec (approximately a normal walking rate of a person). Those units that are capable of meeting the requirements of the test specified in 4.5.1.5 shall be used for that test even if they failed to meet the requirements of this test. (Destructive test)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

4.5.1.5 Post retention and thread breaking strength. After the sensor assembly is tested in accordance with 4.5.1.1, 4.5.1.2.1 or 4.5.1.2.2, 4.5.1.3, and 4.5.1.4 and with the unit remaining in the clamp device of deployment fixture, the specified force (See 3.7) shall be applied to the tripline along the axis of the bobbin post. Any unit that releases the bobbin post, or on which the tripline breaks shall be noted for informational purposes (the force level at which either event occurs shall be identified with the event and be recorded). This test is destructive. The rate of pull shall be 3 ft ± 1 ft\sec (approximately a normal walking rate of a person).

4.5.1.6 Breakwire continuity. Resistance of the breakwire circuit shall be measured between the leadwires for Pt. No. 9292972-1 or between the breakwire terminals for Pt. No. 9292972-2, using an approved ohmmeter. Any unit failing to conform to the applicable requirement shall be classed defective and removed from the lot (Non-destructive test).

4.5.1.7 Dimensional control of molded or plastic parts. In place of normal sampling and inspections associated with the Classification of Defects, and after a curing time for the parts has been approved (see Note 1) a sample of three (3) parts (as molded) from each cavity shall be fully inspected dimensionally to qualify a new or reworked cavity for use in production. The molded parts shall carry the individual cavity identification. As a control of each cavity during production, a sample of three (3) parts from each cavity shall be inspected for the defects listed in the respective Quality Conformance inspection paragraph after continuous production of each 5,000 parts (from a single cavity) or at the end of each week, whichever occurs first. Of the sample of three (3) parts, one (1) part shall be the last one produced. If any defective parts are found during qualification of the cavity, the cavity producing the defective part will not be used in production. If any defective parts are found when inspection is performed for the control of the cavity, the cavity producing the defective part shall be removed from production. Further, that portion of production since the last control check shall be returned to the contractor for inspection for each separate type of defect according to MIL-STD-105, using an AQL of 0.40 percent for each major defect and an AQL of 0.65 percent for each minor defect. All cavities removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the contracting officer to substantiate the request. Contractor design of gages and test equipment required to perform the inspections listed herein shall be forwarded to Commander, ARDC, ATTN: DRSMC-QAT-I (D), Dover, NJ 07801 for approval prior to manufacture of equipment.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

NOTE 1: In establishing a curing time, dimensionally check ten (10) parts from each cavity at periodic intervals (e.g. every 30, 60, etc. mins.) until dimensional stability is attained. The curing time will be from the time the part comes out of the mold until dimensional stability is attained. The inspection data used in determining the curing time shall be sent to Commander, ARDC, ATTN: DRSMC-QAA-Q (D), Dover, NJ 07801. If there is a change in material, in the cycle time, if a cavity is reworked, or a new cavity is used, a new curing time shall be established and approved.

4.5.1.8 Dimensional control of stamped or formed parts. In place of the normal sampling associated with the Classification of Defects, and with the approval of the Contracting officer, a sample of at least ten (10) parts shall be dimensionally inspected to qualify the tool used in the stamping process for use in production. In addition, a random sample of five (5) parts shall be selected from the last portion of each day's production for dimensional inspection as a control of the tool during production.

If any defective parts are found during qualification of the tool, the tool producing the defective part shall not be used in production.

If any defective parts are found when inspection is performed for control of the tool, the tool producing the defective part shall be removed from production. Further, that portion of production since the last tool control check shall be returned to the contractor for corrective action.

All tools removed from production because of some fault, may, after reworking, be returned to production providing they pass the qualification test above. The contractor may request a change of inspection frequency providing he presents objective evidence to the Contracting Officer.

4.5.1.9 Spring embrittlement. The spring shall be stretched (see 3.9) along its longitudinal axis until the spring no longer returns to its original position. When the spring no longer returns to its original length or profile, it shall be considered permanently distorted. Any spring that cracks or breaks prior to this point shall be classed defective. (Destructive Test).

5. PACKAGING

5.1 Preservation and packaging. The Tripline Sensor shall be packaged in accordance with level B of Specification MIL-P-14232 with the following mandatory requirements: A quantity of the sensors without tangled, overly stressed or kinked leads, packed in an interior box with separators shall be sealed in a barrier bag conforming to Type II, Class E, Style 1, Specification MIL-B-117.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

5.2 Packing and marking. The Tripline Sensor shall be packed and marked in accordance with MIL-STD-1188.

5.3 Shipping. When shipments of units from more than one lot are made at one time, each lot shall be kept separate, and the division between lots clearly indicated, to prevent mixing of the lots in transit.

6. NOTES

6.1 Intended Use. The components covered by this specification are intended for use on the:

a. M74 Anti-Personnel Mine (GEMSS).

b. XM131 Mine System (MOPMS).

c. BLU-92/B Anti-Personnel Mine (GATOR).

6.2 Ordering data. See MIL-A-48078.

6.3 Submission of inspection equipment designs for approval. (See MIL-A-48078). Submit equipment designs as required to Commander, ARDC, ATTN: DRSMC-QAT-I (D), Dover, NJ 07801.

6.4 Submission of process control document. Process control documents as specified in 3.10 shall be submitted in accordance with DI-P-1604 (Mod) with Attachment 1, listed on DD Form 1423 incorporated in the contract.

6.5 Drawings. Drawings listed in Section 2 of this specification under the heading US Army Armament Research and Development Center (ARDC) may also include drawings prepared by, and identified as US Army Armament Research and Development Command, , Edgewood Arsenal, Frankford Arsenal, Rock Island Arsenal, or Picatinny Arsenal drawings. Technical data originally prepared by these activities is now under the cognizance of ARDC.

6.6 Distribution of ammunition data cards, inspection and test results. Distribution of ammunition data cards, inspection, and test results shall include Commander: ARDC, Dover, NJ 07801, ATTN: DRSCM-QAT-M (D).

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-A294)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

APPENDIX

SUPPLEMENTAL SOLDERING PROVISIONS

10. SCOPE

10.1 Scope. This appendix details supplemental soldering provisions to MIL-S-45743 for hand soldering. This Appendix is a mandatory part of the specification. The information contained herein is intended for compliance.

20. APPLICABLE DOCUMENTS

This section is not applicable to this Appendix.

30. REQUIREMENTS

30.1 Exceptions/clarification to requirement of MIL-S-45743. The following exceptions/clarifications to reference MIL-S-45743 paragraph titles shall apply.

a. Control of airborne contaminants. Delete the sentence, "Positive pressure shall . . . between them."

b. Soldering irons and resistance soldering irons. Delete the sentence, "The soldering iron shall . . . or standby condition.", and substitute the sentence, "The soldering iron shall be a soldering iron approved by the technical agency or a soldering iron that attains a temperature no more than 10°F (5.6°C) above the control temperature when in an idling or standby condition."

c. Cleaning the soldered connections. Delete requirement.

d. Cleaning solder joints other than those on printed board assemblies. Delete requirement.

e. Resisitivity of solvent extract. Delete requirement.

40. QUALITY ASSURANCE PROVISIONS

a. One hundred percent inspection. Delete and substitute the following: "Level of inspection. Inspection of soldered connections and associated wiring and leads shall be performed to the level specified in the classification of defects in the product specification. Table II of MIL-S-45743 provides a list of defects with reference to the applicable requirements."

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T03:57Z
Check the source to verify that this is the current version before use.

b. Visual inspection. Change to read "... a clear incandescent or fluorescent light should be used for detection of uncovered copper."

50. PACKAGING

This section is not applicable to this Appendix.

60. NOTES

This section is not applicable to this Appendix.

Source: https://assist.dla.mil -- Downloaded: 2026-04-26T03:57Z
Check the source to verify that this is the current version before use.

INSTRUCTIONS: In a continuing effort to make our standardization documents better, the DoD provides this form for use in submitting comments and suggestions for improvements. All users of military standardization documents are invited to provide suggestions. This form may be detached, folded along the lines indicated, taped along the loose edge *(DO NOT STAPLE)*, and mailed. In block 5, be as specific as possible about particular problem areas such as wording which required interpretation, was too rigid, restrictive, loose, ambiguous, or was incompatible, and give proposed wording changes which would alleviate the problems. Enter in block 6 any remarks not related to a specific paragraph of the document. If block 7 is filled out, an acknowledgement will be mailed to you within 30 days to let you know that your comments were received and are being considered.

NOTE: This form may not be used to request copies of documents, nor to request waivers, deviations, or clarification of specification requirements on current contracts. Comments submitted on this form do not constitute or imply authorization to waive any portion of the referenced document*(s)* or to amend contractual requirements.

(Fold along this line)

(Fold along this line)

DEPARTMENT OF THE ARMY

NO POSTAGE NECESSARY IF MAILED IN THE UNITED STATES

OFFICIAL BUSINESS
PENALTY FOR PRIVATE USE $300

BUSINESS REPLY MAIL
FIRST CLASS PERMIT NO. 12062 WASHINGTON D C.
POSTAGE WILL BE PAID BY THE DEPARTMENT OF THE ARMY

COMMANDER
US ARMY ARMAMENT RESEARCH & DEVELOPMENT CENTER
ATTN: DRSMC-QA
DOVER, NJ 07801

Source: https://assist.dla.mil -- Downloaded: 202610-26T03:57Z
Check the source to verify that this is the current version before use.

STANDARDIZATION DOCUMENT IMPROVEMENT PROPOSAL

(See Instructions – Reverse Side)

1. DOCUMENT NUMBER	2. DOCUMENT TITLE
MIL-S-48755A	SENSOR, TRIPLINE: EXTENDED RANGE

3a. NAME OF SUBMITTING ORGANIZATION	4. TYPE OF ORGANIZATION *(Mark one)*
	☐ VENDOR
	☐ USER
b. ADDRESS *(Street, City, State, ZIP Code)*	☐ MANUFACTURER
	☐ OTHER *(Specify)*: _____

5. PROBLEM AREAS

a. Paragraph Number and Wording:

b. Recommended Wording:

c. Reason/Rationale for Recommendation:

6. REMARKS

7a. NAME OF SUBMITTER *(Last, First, MI)* – Optional	b. WORK TELEPHONE NUMBER *(Include Area Code)* – Optional
c. MAILING ADDRESS *(Street, City, State, ZIP Code)* – Optional	8. DATE OF SUBMISSION *(YYMMDD)*

Source: https://assist.dla.mil – Downloaded: 2026-10-26T06:57Z
Check the source to verify that this is the current version before use.