NOTICE OF VALIDATION

INCH-POUND

MIL-S-8805/85E
NOTICE 1
23 August 2011

DETAIL SPECIFICATION

Switch, Sensitive, Rotary (Non-Self Return), 4 Amperes, Resilient Seal

MIL-S-8805/85E, dated 21 July 2005, remains inactive for new design; however, the document is valid for use.

Custodians:
Navy - EC
Air Force - 85

Preparing Activity:
DLA - CC

NOTE: The activities above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.daps.dla.mil.

AMSC N/A **FSC 5930**

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T11:17Z
Check the source to verify that this is the current version before use.