INCH-POUND

MIL-P-12764G (AR)
AMENDMENT 6
08 May 1990
SUPERSEDING
AMENDMENT 5
28 February 1989

MILITARY SPECIFICATION

PROJECTILE, 4.2 INCH, ILLUMINATING, M335A2
LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-P-12764G (AR), dated 11 March 1981 and is approved for use within the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.4.2, Luminosity, Delete "703,000" and substitute "800,000"; also delete "670,000" and substitute "750,000."

PAGE 5

TABLE I: Correct typing error "illuminent" to "illuminant"

* TABLE I: Add "Canister body assembly
(dwg. 8885176)
Examination for defects...15...3.2...4.4.2.4.1
Salt spray test.....2...3.2...4.5.5"

* TABLE I, Under "Illuminating canister loading assembly..." Delete line "Salt spray test...2...3.2...4.5.5"

PAGE 7

TABLE I: Correct typing error "Asembly" to "Assembly"

PAGE 8

4.4.1.c, Delete "lot" and substitute "lot interfix."

PAGE 12

4.4.2.4, Under Major category, delete defect 102 and substitute the following:

"102 Inside diameter, min...40%...3.2...Gage"

* 4.4.2.4.1, Add new paragraph page 12A, included.

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:18Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET OF	DRAWING NUMBER
4.4.2.4.1	Canister Body Assembly		8885176
			NEXT HIGHER ASSEMBLY: 8886453

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Brake missing		0.40%	3.2	Visual
102	Spot or projection weld missing		0.40%	3.2	Visual
103	Brake flush		0.40%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.7	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-01-17T23:18Z
Check the source to verify that this is the current version before use.

PAGE 13

* 4.4.2.5, Delete Major 101, 102, 103 and 104 in their entirety and substitute the following:

"101 Liner composition present on open end of can between brakes...0.40%...3.2...Visual"

PAGE 14

4.4.2.6, Under Major category add the following:

"108 Lot number missing...0.40%...3.2...Visual"

PAGE 15

4.4.2.7, Under Major category add the following:

"106 Single row gathering stitch through felled seam missing when 2-segment canopy was used...0.40%...3.2... Visual

107 Reinforcing tapes on felted seam issing when 2-segment canopy was used...0.40%...3.2...Visual

108 Improper number of double row gathering stitches... 0.40%...3.2...Visual"

PAGE 17

* 4.4.2.9, Delete Major 106 in its entirety and substitute:

"Outer edges of vent tape not within ± 3/4 inches with hemline (step 1) while unfolding for inspection...0.40%...3.2 ...Gage"

4.4.2.9, Under Major category, add the following:

"108 Rubber band located at shroud sleeving missing...0.40% ...3.2...Visual"

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:18Z
Check the source to verify that this is the current version before use.

PAGE 27

4.5.2, Delete "703,000" and substitute "800,000" also delete "670,000" and substitute "750,000"

NOTE: The margins of this amendment are marked with an asterisk or vertical line to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1315-AC35)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T23:18Z
Check the source to verify that this is the current version before use.