INCH - POUND

MIL-F-50541A (AR)
AMENDMENT 3
09 February 1990
SUPERSEDING
AMENDMENT 2
17 June 1980

MILITARY SPECIFICATION

FUZE FOR FLECHETTE WARHEAD, WDU-4A/A (LESS EXPULSION CHARGE)

This amendment forms a part of Military Specification MIL-F-50541A (AR), dated 8 September 1978, and is approved for use within the U.S. Army Armament, Munitions, and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* 2.1, Delete "MIL-P-38633 - Primer, Stab, for WDU-4A/A Warhead."

and substitute "MIL-P-63297 - Primer, Stab, PA515."

PAGE 2

* 2.1, Delete "65C11051" and substitute "9298753".

PAGE 3

* 3.2, Delete "65C11051" and substitute "9298753".

3.4.2, Delete "1.15 seconds" and substitute "1.20 seconds".

Delete "31.0 g's" and substitute "35.00 g's".

PAGE 4

3.6.3, Line 2: Delete "and shall function as specified after".

PAGE 7

* 4.3.1, Delete "65B11049" and substitute "9298751".

Delete "65C11048" and substitute "9298750".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

Delete "65C11047" and substitute "9298742".

Delete "65B11037" and substitute "9298747".

Delete "65C11052" and substitute "9298754".

Delete "65C11053" and substitute "9298755".

Delete "65C11054" and substitute "9298756".

Delete "65C11055" and substitute "9298757".

Delete "65C11057" and substitute "9298759".

Delete "65B11058" and substitute "9298760".

Delete "65C11051" and substitute "9298753".

Delete "65C11056" and substitute "9298758".

Delete "65B10082" and substitute "8883713".

Delete "66B10066" and substitute "8883718".

Delete "8883719" and substitute "9298424".

Delete "9239418" and substitute "9298657".

Delete "9239407" and substitute "9327030".

Delete "8883706" and substitute "9260776".

Delete "8883693" and substitute "9260804".

Delete "8883719" and substitute "9239424".

Delete "8883692" and substitute "9260774".

Delete "9239418" and substitute "9327657".

PAGE 9

* Table I: Delete "65B11049" and substitute "9298751".

Delete "65C11048" and substitute "9298750".

Delete "65C11047" and substitute "9298742".

Delete "65B11037" and substitute "9298747".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

Delete "65C11052" and substitute "9298754".

Delete "65C11051" and substitute "9298753".

Delete "4.3.2.1" and substitute "4.4.2.1".

Delete "4.3.2.4" and substitute "4.4.2.4".

Delete "4.3.2.5" and substitute "4.4.2.5".

Delete "4.3.2.6" and substitute "4.4.2.6".

Delete "4.3.2.7" and substitute "4.4.2.7".

PAGE 10

* Table I: Delete "65C11053" and substitute "9298755".

Delete "65C11054" and substitute "9298756".

Delete "65C11056" and substitute "9298758".

Delete "66B11082" and substitute "8883713".

Delete "66B10066" and substitute "8883718".

Delete "65C11051" and substitute "9298753".

PAGE 11

* Table I: Delete "65B11055" and substitute "9298757".

Delete "65C11057" and substitute "9298759".

Delete "65B11058" and substitute "9298760".

Delete "65C11051" and substitute "9298753" in 2 places.

Delete "4.3.2.10" and substitute "4.4.2.10".

Delete "4.3.2.11" and substitute "4.4.2.11".

Delete "4.3.2.12" and substitute "4.4.2.12".

Delete "4.3.2.19" and substitute "4.4.2.15".

Delete "Class" and substitute "Less".

Delete "(Dwg 65811051)" and substitute "(Dwg 65C11051)".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 12

* Table I: Delete "65C11051" and substitute "9298753".

PAGE 13

* Table I: Delete "65C11051" and substitute "9298753".

Delete "8883706" and substitute "9260776".

Delete "8883698" and substitute "9260804".

PAGE 14

* Table I: Delete "65C11051" and substitute "9298753".

Delete "8883719" and substitute "9298424".

Delete "9239418" and substitute "9327657".

Delete "8883692" and substitute "9260774".

PAGE 15

* Table II: Delete "65C11048" and substitute "9298750".

Delete "65C11051" and substitute "9298753".

PAGE 16

* Table II: Delete "65C11047" and substitute "9298742".

Delete "65C11051" and substitute "9298753".

PAGE 18

* 4.4.2.1, Delete "65B11049" and substitute "9298751".

PAGE 19

* 4.4.2.2, Delete "65C11048" and substitute "9298750".

PAGE 20

* 4.4.2.3, Delete "65C11047" and substitute "9298742".

PAGE 21

* 4.4.2.4, Delete "65B11037" and substitute "9298747".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 22

* 4.4.2.5, Delete "9239407" and substitute "9327030".

PAGE 24

* 4.4.2.7, Delete "65C11052" and substitute "9298754".

Delete "65C11051" and substitute "9298753".

PAGE 25

* 4.4.2.2.8, Delete "65C11053" and substitute "9298755".

Delete "65C11051" and substitute "9298753".

Delete "Perpendicularity of locking ball holes to small outside diameter" and substitute "True position of locking ball holes to small inside diameter".

Add Major 109 as follows:

"109	True position of diameter of S&A cavity to small inside diameter	0.40%	3.2	Gage".

PAGE 26

* 4.4.2.9, Delete "65C11054" and substitute "9298756".

Delete "65C11051" and substitute "9298753".

Delete Major 103 in its entirety.

PAGE 27

* 4.4.2.10, Delete "65B11055" and substitute "9298757".

Delete "65C11051" and substitute "9298753".

PAGE 28

* 4.4.2.10, Delete "65C11057" and substitute "9298759".

Delete "65C11051" and substitute "9298753".

PAGE 29

* 4.4.2.10, Delete "65B11058" and substitute "9298760".

Delete "65C11051" and substitute "9298753".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 58

6.3, Last line: Delete "DRDAR-QAR-I" and substitute "AMSMC-QAF-I".

PAGE 59

6.6, Line 4: Delete "DRDAR-QAR-M" and substitute "AMSMC-QAF-A".

PAGE 60

Delete Appendix A in its entirety and substitute enclosed Figure 1.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1340-A823)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 39

* 4.4.2.22, Delete "8883706" and substitute "9260776".

Delete "8883692" and substitute "9260774".

PAGE 40

* 4.4.2.23, Delete "65C11046" and substitute "9239423".

Delete "4.5.7.6" and substitute "4.5.4.6".

Delete "4.5.7.7" and substitute "4.5.4.7".

PAGE 41

* 4.4.2.24, Delete "8883693" and substitute "9260804".

Delete "65C11046" and substitute "9260774".

PAGE 42

* 4.4.2.25, Delete "8883719" and substitute "9239424".

Delete "65C11046" and substitute "9239423".

PAGE 43

* 4.4.2.26, Delete "8883692" and substitute "9260774".

Delete "65C11056" and substitute "9239423".

PAGE 47

* 4.5.3.1, Delete "4.3.4" and substitute "4.4.4".

Last line: Delete "the".

PAGE 48

4.5.4.5, Line 5: Delete "the required force" and substitute "the required force, the height of the lever pallet above the lever shall be inspected".

PAGE 50

4.5.5.1, Delete "4.3.4" and substitute "4.4.4".

4.5.5.2, Delete "4.3.4" and substitute "4.4.4".

4.5.5.3, Delete "4.3.4" and substitute "4.4.4".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 30

* 4.4.2.13, Delete "65C11051" and substitute "9327657".

PAGE 31

* 4.4.2.14, Delete "9239418" and substitute "9327657".

Delete "65C11051" and substitute "9298753".

PAGE 32

* 4.4.2.15, Delete "65C11051" and substitute "9298753".

PAGE 33

* 4.4.2.16, Delete "65C11056" and substitute "9298758".

Delete "65C11051" and substitute "9298753".

PAGE 34

* 4.4.2.17, Delete "66B10082" and substitute "8883713".

Delete "65C11051" and substitute "9239423".

PAGE 35

* 4.4.2.18, Delete "65B11067" and substitute "8883718".

Delete "65C11051" and substitute "9239423".

PAGE 36

* 4.4.2.19, Delete "8883692" and substitute "9260774".

PAGE 37

* 4.4.2.20, Delete "8883692" and substitute "9260774".

Add Critical category "2" to "Maximum gap between gear and pinion".

PAGE 38

* 4.4.2.21, Delete "8883692" and substitute "9260774".

Add Critical category "2" to "Maximum gap between gear and pinion".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

PAGE 51

4.5.5.4, Delete "4.3.4" and substitute "4.4.4".

4.5.5.5, Delete "4.3.4" and substitute "4.4.4".

In line 4:

Delete "rte" and substitute "rate".

Delete "31.00 g's" and substitute "35.00 g's".

4.5.6.1, Delete "4.3.4" and substitute "4.4.4".

4.5.6.2, Delete "4.3.4" and substitute "4.4.4".

PAGE 52

4.5.7, Line 7: Delete "than" and substitute "then".

PAGE 53

4.5.10, Line 3: Delete "Temperture" and substitute "Temperature".

* 4.5.11, Add note as follows:

"Note: Removing the fuze from the cold temperature environment prior to performing the centrifuge test may cause frost to form on the metal parts. This may have an effect on the test results due to attenuation of the acoustic signal of the arming mechanism, thus making it difficult to distinguish the arm signal from the background noise. The contractor shall take the appropriate action to alleviate this potential problem. One effective method has been to seal each fuze in a plastic bag prior to temperature conditioning. Bagged fuzes are then subjected to the centrifuge test."

PAGE 54

4.5.13, Line 6: Delete "except that resonance shall not be done".

PAGE 56

4.5.16d, Line 3: Delete "testing".

PAGE 57

4.5.17, Delete "within 10 milliseconds" and substitute "within 20 milliseconds".

Delete "DRDAR-QAR-M and DRDAR-QAR-I" and substitute "AMSMC-QAF-A and AMSMC-QAF-I".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.

FIGURE 1. Helicopter vibration

One 15 minute sinusoidal sweep (5-500-5 Hz) shall be performed for each of three axes. No dwell time shall be spent on any one frequency. A search for resonance shall not be done.




Figure 1 Helicopter Vibration

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:28Z
Check the source to verify that this is the current version before use.