MILITARY SPECIFICATION

VOICEMITTER-OUTLET VALVE ASSEMBLY, C29R1

This amendment forms a part of MIL-V-00500660(MU), dated 14 July 1967, and is approved for use within the Chemical Research, Development and Engineering Center, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 3

Add new paragraph 3.3.4 as follows:

"3.3.4 Resistance to DS2. The assembled voicemitter diaphragm shall not break, crack, craze, or have pinholes after being immersed in DS2 (MIL-D-50030) for 3 minutes minimum when tested as specified in 4.3.4.6."

PAGE 5

Add new paragraph 4.3.2.2 as follows:

"4.3.2.2 For destructive tests. Sampling for resistance to DS2 shall be conducted in accordance with MIL-STD-105, level S-4."

PAGE 6

Add new paragraph 4.3.3.4 as follows:

"4.3.3.4 For destructive tests. The sample for resistance to DS2 shall be tested as specified in 4.3.4.6 and evaluated in accordance with MIL-STD-105 using an AQL of 0.25 percent defective."

Add new paragraph 4.3.4.6 as follows:

"4.3.4.6 Resistance to DS2. The resistance of the voicemitter to decontamination shall be determined by immersing the voicemitter diaphragm assembly in DS2 (MIL-D-50030). The diaphragm shall be agitated for at least 15 seconds upon immersion to remove air bubbles and insure all diaphragm surfaces are

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202640-22T20:15Z
Check the source to verify that this is the currentversion before use.

covered by DS2. After at least 3 minutes exposure the diaphragm assembly shall be removed from the DS2, thoroughly rinsed with distilled water, blown dry with filtered compressed air and the diaphragm examined for breaks, cracks, crazing, or pinholes. (The rear baffle shall be cut away to facilitate this examination, however, care shall be exercised to assure that the diaphragm is not damaged.)"

Custodian:

Army - EA

Preparing activity:

Army - EA

Project No. 4240-A395

Source: https://assist.dla.mil -- Downloaded: 20260-22T20:15Z
Check the source to verify that this is the current version before use.