MILITARY SPECIFICATION

RADOME CW-860/GPS( )

This amendment forms a part of Military Specification MIL-R-38522B(USAF) dated 8 September 1972, and is approved for use by the Department of the Air Force and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

*2.1 Under SPECIFICATIONS, Military, MIL-C-9084, delete the word "Polyester"

MIL-P-9400, delete and add:

"MIL-P-9400 Plastic Laminate and Sandwich Construction, Parts Aircraft Structural, Process Specification Requirements"

MIL-A-22152, delete and add:

"MIL-H-6088 Heat Treatment of Aluminum Alloys"

*2.1 Under SPECIFICATIONS, Military add:

"MIL-Q-9858 Quality program Requirements"

*2.1 Under STANDARDS, Federal, change, "FED-STD-406" to "FED-STD-405"

PAGE 5

3.3.1.1,j change to read:

"Wind Load 150 Knots (172 miles per hour)"

*3.3.1.3, line 2: Delete the word "polypropolene"

*3.3.1.5, line 3 through line 7: Delete the last three sentences. Add:

"The laminate shall be self extinguishing in accordance with ASTM D-635. Mechanical testing of laminates shall be conducted in accordance with FED-STD-405, Method 2021."

PAGE 6

*3.3.1.7, line 3: Delete "MIL-A-22152" and add MIL-H-6088"

*3.4.2, line 4 through line 5: Delete the last sentence. Add:

"The interior surface of the radome shall be left uncoated or coated with White Tedlar."

FSC 5985

(Project No. 5985-F509)

Source: https://assist.dla.mil -- Downloaded: 202610-21T15:06Z
Check the source to verify that this is the current version before use.

PAGE 7

*3.5.1.1.1, line 6, add:

"Polysulphide calking materials are expressly prohibited. Gasketing may be used in lieu of calking. The gasketing material must last the design life of the radome."

PAGE 8

*3.5.1.3, change to read:

"3.5.1.3 Access Doors. A total of three access doors shall be provided in the radome. Two shall be located at 180 degree ± 36° intervals from each other about the periphery of the radome base yielding access to the catwalk of the support structure platform on the exterior of the radome. The third door shall be located near the zenith of the radome to provide access from the interior of the radome for maintenance of the warning lights. Co-located with this door shall be a hand hold bar, such that personnel may hold on securely to this bar with one hand while opening the door with the other. The door shall be hinged outward and means shall be provided for securing the door in the open position. The doors of hatches near base level shall be as large as practicable except that he opening shall not exceed 36" (91.4 cm) x 60" (152.4 cm). Irregularly shaped doors are acceptable when dictated by panel contraints. The door or hatch located near the zenith shall be 20" (50.8 cm)x 24"(60.7 cm) minimum. All hatches and doors shall have a non-key operated locking device controllable from the interior of the radome."

*3.5.3.a, line 2: Delete the word "magnesium"

*3.5.3.a, line 3 add:

"The service ladder shall conform to the design requirements of OSHA Standard 1910.27 (AFOSH 127.6)"

*3.5.3.b, line 8, add:

"The ladders shall conform to the requirements of OSHA Standard 1910.26 (AFOSH 127-6)."

*3.5.3.1, line 5, delete and substitute:

"requirements of OSHA Standard 1910.2a (AFOSH 127-9)."

PAGE 10

*3.5.5, line 6, add between the sentences:

"It is permissible to have both lights operate simultaneously so long as the service-free time is not shortened."

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T15:06Z
Check the source to verify that this is the current version before use.

*4.1, line 1, after the first sentence, add:

"Suppliers which have not previously supplied this radome to the Government must actually perform the tests specificed in sections 4.4 and 4.6. All production Quality Assurance should be done is accordance with MIL-Q-9858 ."

*4.4.3a, line 5: Delete "FED-STD-406" and substitute "FED-STD-405"

NOTE: The margins of this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convience only and the Governmnet assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this docuemnt based on the entire content irrespective of the marginal notations and relationship to the last previous amandment.

Custodian:
Air Force - 99

Review activities:
DLA - ES
Air Force - 85

Preparing-activity:
Air Force - 80

Agent:
DLA - ES

(Project 5985-F509)

MILITARY PART NUMBER	TYPE DESIGNATION	MFG PART NUMBER	(FSCM)
M38522-01	CW860/GPS( )	904-1	15175

Source: https://assist.dla.mil -- Downloaded: 202640-21T15:06Z
Check the source to verify that this is the currentversion before use.

Source: https://assist.dla.mil -- Downloaded: 2026-10-21T15:06Z
Check the source to verify that this is the current version before use.