MIL-A-25081 (USAF)
AMENDMENT 2
26 December 1978
SUPERSEDING
AMENDMENT 1
9 October 1958

MILITARY SPECIFICATION

AMPLIFIER, ELECTRONIC CONTROL, 2 CHANNEL,
APPROACH AND NAVIGATIONAL, TYPE MB-4

This amendment forms a part of Military Specification MIL-A-25081 (USAF), dated 22 August 1955.

PAGE 1

2.1, under SPECIFICATIONS, Federal: Delete, "NN-B-591", "NN-B-621", "NN-B-631", "LLL-B-631", and "LLL-B-636", and add:

"PPP-B-636 Box, Shipping, Fiberboard".

2.1, under SPECIFICATIONS, Military: Delete "JAN-P-103", "JAN-P-106", "MIL-B-107", "JAN-P-108", "MIL-E-4682", "MIL-C-5900", "MIL-T-9107", and "MIL-B-10377" and add:

"MIL-F-9490 Flight Control Systems - Design, Installation and Test of, Piloted Aircraft, General Specification For"

Add boxed paragraph to bottom center of page.

"Beneficial comments (recommendations, additions, deletions) and any pertinent data which may be of use in improving this document should be addressed to: HQ AFLC CASO/LODS, Federal Center, Battle Creek, MI 49016 by using the self-addressed Standardization Document Improvement Proposal (DD Form 1426) appearing at the end of this document or by letter."

PAGE 2

2.1, under STANDARDS, Military: Add:

"MIL-STD-831 Test Reports, Preparation Of".

2.1, under PUBLICATIONS, Air Force-Navy Aeronautical Bulletin: Delete: "405 Storage Life-Aeronautical Articles".

2.1, under PUBLICATIONS, U.S. Air Force Bulletin: Delete:

"67 Current List of Strategic and Critical Materials".

FSC 6615

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T03:32Z
Check the source to verify that this is the current version before use.

3.2, line 2: Delete "MIL-C-5900" and substitute "MIL-F-9490".

3.3, Delete.

PAGE 3

4.1 and 4.1.1, line 2: Delete "MIL-C-5900" and substitute "MIL-F-9490".

PAGE 5

4.2.2.2, line 3: Delete "ratio of 2 and 8 mv" and substitute "rates of 2 and 8mv".

PAGE 7

4.3.2, line 4: Delete "MIL-T-9107" and substitute "MIL-STD-831".

4.3.3, line 2: Delete "MIL-C-5900" and substitute "MIL-F-9490".

PAGE 8

4.4.1.3.1.2, delete and substitute:

"4.4.1.3.1.2 BALANCE AND NULL OUPTUT. Set the localizer displacement tap switch to position 5 and the displacement input to zero. Apply 27.5V dc to J-69-10, J-69-8 and J-69-6. Allow the lateral servo to follow-up and then remove 27.5V dc from J-69-6. Adjust the lateral balance signal until the output reads a minimum value. The balance signal required to obtain this null shall not exceed ±8 mv. The minimum output (null) shall not exceed 0.12V. Set the localizer rate tap switch to position 5. The null output shall not exceed 0.22V.

NOTE: The balance signal shall remain at the value determined above throughout the remainder of all lateral channel tests."

4.4.1.3.1.3, delete and substitute:

"4.4.1.3.1.3 LATERAL BEAM SENSOR. Set the localizer rate tap switch to position zero and apply 27.5V dc to J-69-6. Apply 200 mv of lateral displacement input. The lateral output shall not exceed 0.05V. (The lateral follow-up servo or rate generator will rotate continuously. Allow 10 seconds for follow-up rotation to be completed). Remove 27.5V dc from J-69-6. The lateral output shall remain unchanged until the lateral input signal is

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T03:32Z
Check the source to verify that this is the current version before use.

reduced to 148 ±12 mv. When K-3111 (lateral beam sensor relay) is deenergized by decreasing the input to the specified value, the lateral output shall increase reaching 90 percent of its final output value (approximately 3.3V) in 7 ±2.5 seconds."

PAGE 9

4.4.1.3.1.8, line 2: Delete "168 ±12 mv" and substitute "160 ±12 mv".

PAGE 10

4.4.1.3.1.11, line 1: Delete "2mv" and substitute "8mv".

4.4.1.3.2.5, line 2: Delete "position 5" and substitute "position 3".

PAGE 11

4.4.1.3.3 In the note portion delete the second sentence and substitute "It will be necessary to momentarily reestablish the gyropilot configuration by applying 27V dc to J-69-6 and removing from J-69-8, then applying 27V dc to J-69-8 and removing from J-69-6 to return to the range bracket configuration.

4.4.1.3.3.1, line 8: Delete "4 ±1.5 seconds" and substitute "7 ±2.5 seconds".

4.4.1.3.3.2, line 3: Delete "0.04V" and substitute "0.045V".

PAGE 13

4.4.1.3.4.3, line 3: Delete "0.85V to 1.35V" and substitute "0.80V to 1.30V". Line 5: Delete "2.10-3.30V" and substitute "1.30 to 2.10".

PAGE 14

4.4.1.3.4.6, line 5: Delete "+35mv" and substitute "+20 mv". Line 7: Delete "1.2V" and substitute "0.6V".

4.4.1.3.4.7, line 6: Delete "3.0V" and substitute "1.5V". Line 9: Delete "4 seconds" and substitute "5 seconds". Line 11: Delete "6 seconds" and substitute "15 seconds".

PAGE 16

4.4.1.4.1.10, line 3: Delete "position 2" and substitute "position 3".

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T03:32Z
Check the source to verify that this is the current version before use.

Delete paragraph 5 through 5.3.3 and substitute the following new paragraphs:

"5. PACKAGING.

5.1 Preservation-packaging. Preservation-packaging shall be level A, B, or C as specified by procuring activity.

5.1.1 Level A.

5.1.1.1 Cleaning. Unit shall be cleaned in accordance with process C-1 of MIL-P-116.

5.1.1.2 Drying. Immediately after cleaning, the unit shall be dried following any one or combination of the drying procedures of MIL-P-116. The drying procedures employed shall not be injurious to the unit.

5.1.1.3 Preservation application. Not required.

5.1.1.4 Unit Packaging. Unless otherwise specified by the procuring activity, each unit shall be packaged in quantity unit packs of one each in accordance with Method III of MIL-P-116. Water-vaporproof caps applied to electrical connectors. Unit container to be PPP-B-636 weather-resistant fiberboard. Apply sufficient cushioning material between primary and unit container of a type, density, and thickness to insure shock transmission does not exceed peak values in Gs established for the unit, when completed packs are subjected to rough handling drop tests of MIL-P-116. Insofar as practical, exterior containers shall be of uniform shape, minimum tare and cube consistent with protection required.

5.1.2 Level B. Each unit shall be packaged as indicated for Level A except that a specification PPP-B-636 class domestic shall be used as the unit container.

5.1.3 Level C. Units shall be cleaned, dried, and individually packaged in a manner that will afford adequate protection against corrosion, deterioration, and physical damage during shipment from supply source to the first receiving activity.

5.2 Packing. Packing shall be level A, B, or C as specified by procuring activity.

5.2.1 Level A. Units packaged as specified in 5.1 shall be packed in shipping containers conforming to specification PPP-B-636 weather-resistant. Closure and reinforcing requirements shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T03:32Z
Check the source to verify that this is the current version before use.

be in accordance with the appendix of PPP-B-636. For the Army, the shipping containers shall conform to specification PPP-B-636 class weather resistant.

5.2.3 Level C. Packaged units shall be packed in shipping containers in a manner that will afford adequate protection against damage during direct domestic shipment from the supply source to the first receiving activity. These packs shall conform to applicable carrier rules and regulations."

PAGE 19

Add new paragraph 6.4

"6.4 Reclaimed materials. The use of reclaimed material will be encouraged to the maximum extent possible.

Custodian:
Air Force - 99

Preparing Activity:
Air Force - 99

Project Number:
6615-F046

Source: https://assist.dla.mil -- Downloaded: 2026-10-20T03:32Z
Check the source to verify that this is the current version before use.