MILITARY SPECIFICATION

MASK, PROTECTIVE, FIELD, M9A1

This amendment forms a part of MIL-M-12296(CmlC), dated 22 October 1952, and is approved for use within the Chemical Research, Development and Engineering Center, Department of the Army and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

2.1:

Under "SPECIFICATIONS" "FEDERAL" add the following:

"PPP-B-26 - Bags, Plastic (General Purpose)
PPP-B-636 - Boxes, Shipping, Fiberboard
PPP-F-320 - Fiberboard: Corrugated and Solid, Sheet Stock (Container Grade and Cut Shapes)
PPP-T-76 - Tape, Packaging Paper"

Under "STANDARDS" "MILITARY" add "MIL-STD-147 - Palletized Unit Loads".

Under "DRAWINGS":

Delete "D5-20-84" and "D5-20-256" and their titles.

Add the following:

"D5-22-47 - Faceform, Gas Mask, M5 (For Large and Medium Facepieces)
D5-22-52 - Faceform, Gas Mask, M5 (For Small Facepieces)
C5-41-11 - Packaging Canister (For Mil Canister)
B5-16-1 - Set, Anti-Dim Assembly)"

Delete reference to Publications in its entirety.

PAGE 2

Add the following paragraph:

"3.4 Lot marking. Lot number as specified by the procuring activity shall be "branded" on the facepiece as required by Drawing E5-2-759."

AMSC N/A FSC 4240

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 202610-17T22:40Z
Check the source to verify that this is the current version before use.

4.3.4.1: Delete categories and defects in their entirety and substitute the following:

"Categories Defects

Critical: None defined

Major: AQL 0.65 percent defective

101	Component missing
102	Facepiece lot numbering incorrect
103	Multiple marking on single tab
104	Marked characters superimposed (inadequate spacing)
105	Tackiness of rubber in lot marking area
106	Damage (facepiece)
107	Contamination (grease and oil)

Minor: AQL 1.0 percent defective

201	Anti-dim set missing
202	Damage (other than major defect 106)
203	Contamination (other than major defect 107)
204	Marking missing or illegible
205	Lot markings in wrong location"

4.3.4.2: Delete in its entirety and substitute the following:

"4.3.4.2 Facepiece, Combat, M9 (Drawing E5-2-759).

Categories Defects

Critical: None defined

Major: AQL 1.0 percent defective

101	Incorrect process parameters used"

Source: https://assist.dla.mil -- Downloaded: 202640-17T22:40Z
Check the source to verify that this is the current version before use.

Add new 4.3.4.3 as follows:

"4.3.4.3 Packaging inspection.

Categories		Defects
Critical:		None defined
Major:		None defined
Minor:	AQL	4.0 percent defective
201		Unit packing assembly incorrect (5.1.1.2)
202		Shipping container, construction and closure incorrect (5.2.1)
203		Marking missing, incorrect or illegible (5.3)
204		Unitization not as specified (5.2.2)

PAGE 4

4.4 and 4.4.1: Delete in their entirety.

Section 5: Delete in its entirety and substitute the following:

"5. PACKAGING

5.1 Preservation. Shall be specified.

5.1.1 Level A.

5.1.1.1 Preservation applications. No preservation compounds shall be applied to any portion of the mask or its components.

5.1.1.2 Unit packs. The faceform (D5-22-47 or D5-22-52) shall be positioned in the mask. The mask with appropriate size faceform shall be placed with the outlet valve of the mask facing down in a plastic bag conforming to type II, style 1, 0.003 inch material of PPP-B-26, having inside dimensions of 9 by 14 inches, width, and length, respectively. The excess closure material shall be tucked into the faceform cavity sufficiently to hold the mask onto the faceform. Each bagged mask shall then be placed in a M11 Carrier (D5-4-313), which contains one Anti-Dim Set (B5-16-1) installed in its holder in the bottom of the carrier, with the outlet valve facing the carrier opening and the forehead area of the mask adjacent to the grommet end of the carrier opening. The carrier flap shall be closed with fasteners provided. The carrier assembly and one M11 Canister (C5-41-11) shall be placed in a grade W5c, style RSC fiberboard box conforming to PPP-B-636, having inside dimensions of 12-1/2 by 4-3/4 by 7-3/4 inches (length, width, and height, respectively). The canister shall

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:40Z
Check the source to verify that this is the current version before use.

be placed in the box on its side in the left corner with the can ends facing the long sides of the box. The carrier assembly shall be positioned in the box with the straps located loosely beneath the carrier, opening facing up and the broad end (curved end) of the carrier resting against the canister. The box shall be closed in accordance with method IV closure requirement specified in the appendix to PPP-B-636, except that 2-inch wide pressure-sensitive tape conforming to PPP-T-76 shall be used.

5.2 Packing.

5.2.1 Level B. Ten masks of one size, unit packed as specified in 5.1.1.2, shall be packed together in a grade V3c, style RSC, fiberboard box, conforming to PPP-B-636, having inside dimensions of 26-3/4 by 13-1/8 by 17-1/4 inches, length, width, and height, respectively. The unit packed masks shall be placed in two layers of five each. Fiberboard filler pads conforming to PPP-F-320 shall be added, as required, to make a tight pack. The box shall be closed in accordance with method IV closure requirements as specified in the appendix to PPP-B-636, except that 2-inch wide tape conforming to PPP-T-76 shall be used.

5.2.2 Unitized loads. Masks packed in accordance with 5.2.1 shall be palletized in accordance with the applicable requirements of MIL-STD-147. Fiberboard boxes shall be placed in an upright position. Width, length, and height of the final unit load shall not exceed 43 by 52 by 54 inches, respectively. When specified to meet MILVAN/SEAVAN requirements, unit load width, length, and height shall not exceed applicable requirements of MIL-STD-147. When the quantity of packed masks (5.2.1) is insufficient to constitute a full pallet load, the packed masks shall not be palletized.

5.3 Marking. In addition to any special marking required by the contract or order, the unit packs shall be marked in accordance with MIL-STD-129. Level B shipping containers and pallet loads shall be marked in accordance with the applicable requirements of MIL-STD-129. Each shipping container shall be marked to show the corresponding lot number and cure date markings as shown on the unit pack container contained therein. When two or more unit packs bear different cure dates, the earliest date shall be shown on the shipping container. These markings shall be in conformance with the requirements of MIL-STD-129. Pallet loads containing more than one lot of masks shall be appropriately marked to maintain lot integrity. The lot number shall be identified on a label and placed as near to the address marking as possible. Maximum label size shall be 4 inches by 6 inches (102 mm by 152 mm) with lettering not less than 1/4 inches (6.5 mm) in height. The label requirement shall be in accordance with MIL-STD-129."

Source: https://assist.dla.mil -- Downloaded: 202640-17T22:40Z
Check the source to verify that this is the currentversion before use.

6.2(c): Delete in its entirety.

6.3: Delete in its entirety.

6.4:

Delete "Chemical Corps" from first sentence and Table I and substitute "National".

Delete Table I stock numbers in their entirety and substitute the following:

"4240-00-368-6093
4240-00-368-6094
4240-00-368-6095
4240-00-368-6096
4240-00-368-6097
4240-00-368-6098"

Custodian:

Army - EA

Preparing activity:

Army - EA

(Project No. 4240-A896)

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T22:40Z
Check the source to verify that this is the current version before use.