MILITARY SPECIFICATION

SIGNALS, SMOKE, GROUND, HAND HELD PARACHUTE, GREEN SMOKE, M128A1, RED SMOKE, M129A1, AND YELLOW SMOKE, M194 PARTS AND LOADING, ASSEMBLING AND PACKING

This Amendment forms a part of Military Specification MIL-S-13303G(AR), dated 14 September 1984, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 2

Delete paragraph 3.3 - add new paragraph 3.3

"3.3 Cracks. The tube casing shall be free of cracks under visual inspection after hydrostatic testing."

PAGE 13

Delete Major 102, add:

"Critical 1 Delay Charge Missing 100% 3.2 Visual"

Change Major 101 from "Igniter composition above flush" to "Delay Composition above flush or more than max. below flush,"

PAGE 19

Add:

"Critical 2 Overall Density Test 100% 3.2 4.5.5.1"

Notes: "a. Grain shall be assembled and loaded by same manufacturing methods as intended for production.
b. 25 samples to be tested: accept 0,reject 1.
c. 150 grains to be assembled and tested in 50 signals: accept 0, reject 1."

Delete Major 103

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:23Z
Check the source to verify that this is the current version before use.

PAGE 25

Add:

"Major 111 Weld peel strength (a) 3.2 4.5.10" test

"Major 112 Hardness test (see dwg 8797951) (b) 3.2 4.5.8"

PAGE 27

Delete Critical 2 in its entirety and substitute: Critical 2 Hydrostatic test 100% 3.2 4.5.6

Delete Major 105

PAGE 28

Add to Major 101

"or improperly attached to chain bead assembly, when applicable."

PAGE 31

4.4.2.21 Delete Major 101 in its entirety and substitute: "Major 101 Component missing or damaged to extent that function may be impaired or chain bead assembly improperly fastened to smoke assembly 0.40% 3.2 Visual"

PAGE 32

Add:

"Critical 2 Initiating Charge 100% 3.2 Visual Missing"

Major 103, delete in its entirety and substitute: "Major 103 Initiating Charge Over Max. (see note) 0.40% 3.2 Balance "

PAGE 36

Delete Major 103

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:23Z
Check the source to verify that this is the current version before use.

PAGE 39

4.4.3.1 change from "Fiberboard" to "Hardboard"

Change from "Delay Composition (see 3.3)" to "Delay Composition (9251412)"

PAGE 40

Add to Table III

"Cork sealing disc in end of barrel loose (see label dwgs. 8797931-2, -3 and -10)" Major

4.4.3.2.1.1, Line three Change from "twenty-five (25) to "fifty (50)"

4.4.3.2.1.2, Line three Change from "ten (10) to "twenty (20)"

4.4.3.2.2.1, Line four Change from "one hundred and twenty-five (125)" to "one hundred (100)"

Line seven Change from "eight (8)" to "six (6)"

PAGE 41

4.4.3.2.3.1.1, Line three Change from "thirty-two (32)" to "fifty (50)"

Line four Delete "The lot shall ....(see Table III)." and substitute "The lot shall be rejected if, during the test a critical defect occurs, the average angle from vertical exceeds the requirements, or if four (4) or more assemblies exhibit any of the remaining major defects listed in Table III. (See note after the following paragraph)".

4.4.3.2.3.1.2, Line three Change from "ten (10) to "thirty-two (32)"

Line four Delete in its entirety and substitute: "If any critical defect occurs, the lot shall be rejected." to "The lot shall be rejected if during the test, a critical defect occurs, the average angle from the vertical exceeds the requirement or if three (3) or more assemblies exhibit any of the remaining major defects listed in Table III. (See note).

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:23Z
Check the source to verify that this is the current version before use.

Note: "A smoke assembly which ignites and burns normally but subsequently fails to meet minimum burning time requirements due to ground impact, will not be classified defective. Firing records will be annotated accordingly."

4.4.3.2.3.2.1, Change from "one hundred and twenty-five (125)" to "fifty (50)"

Change from "eight (8)" to "four (4)"

Change from "twelve (12)" to "nine (9)"

Add "(See note after the following paragraph)"

4.4.3.2.3.2.2, Change from "fifty (50)" to "twenty-five (25)"

Change from "four (4)" to "three (3)"

Add to end of paragraph "(see note)."

Add "Note: A smoke assembly which ignites and burns normally but subsequently fails to meet minimum burning time requirements due to ground impact, will not be classified defective. Firing records will be annotated accordingly."

PAGE 42

Delete paragraphs 4.4.3.3, 4.4.3.3.1, 4.4.3.3.2 and 4.4.3.4

Add new paragraph

"4.4.3.3. Propellant Ballistic Test - Critical defect.

50 signals per propellant sub-lot of loose propellant composition are to be ballistically tested in fully loaded signals at hot temperature in accordance with 4.5.2.1 abd 4.5.11. Upon successfully meeting the requirements (see para. 3.4.1) the propellant composition used and the method of manufacture of the propellant assembly shall be considered adequate for production. All production will then utilize the spacer, propellant part no. 8797936 in the aft end and the slotted spacer propellant part no. 9328587 in the forward (delay assembly end) section of the tube, casing, part no. 8797921.

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:23Z
Check the source to verify that this is the current version before use.

PAGE 43

Add:

"4.5.1.5 Propellant Assembly, propellant grain. The moisture content of the propellant assembly shall be determined in accordance with the prcedure specified in MIL-P-223 or an approved alternate."

PAGE 44

Add the following note after paragraphs 4.5.2.1, 4.5.2.2, 4.5.2.3.1, and 4.5.2.3.2

"Note: "Samples must be fired within three (3) minutes of removal from the conditioning chamber."

PAGE 46

Delete 4.5.11 in its entirety and substitute:

"4.5.11 Propellant Ballistic Test. The signal shall use propellant spacer part no. 8797936, in the forward and aft end while following the test procedure of 4.5..2.1. Simulated or dummy payloads may be used."

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1370-A190)

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T00:23Z
Check the source to verify that this is the current version before use.