INCH-POUND
MIL-A-70608A(AR)
AMENDMENT 1
27 March 1998

MILITARY SPECIFICATION

ADAPTER & FUZE, ASSEMBLY: M624,
LOADING, ASSEMBLING AND PACKING

MIL-A-70608A was inactivated after 4 January 1997 for New Design.

This amendment forms a part of MIL-A-70608A (AR), dated 31 May 1988, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 7

4.4.2.1:

Critical 1: Delete in its entirety and substitute the following:

"1 Boxed end pin improperly assembled 100% 3.2 Manual (3)".

Delete Critical 3 in its entirety.

Delete Major 103 in its entirety.

Major 105, AQL OR 100%: Delete "0.40%" and substitute "One fuze shall be tested at the completion of each 1000 fuzes assembled. If the fuze fails to function properly as required, that group of 1000 fuzes shall be subjected to a 0.40% AQL, Level II of MIL-STD-105D. In addition, the contractor shall take corrective action on the cause of the fault before proceding to the next 1000 fuze assemblies."

AMSC N/A FSC 1345

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:47Z
Check the source to verify that this is the current version before use.

PAGE 8

4.4.2.1, Sheet 2 of 2, NOTES:

Delete note (1) in its entirety and substitute “(1) Samples which have the detonator firing during tests or have cracked collars at the completion of the test shall be classed as critical defects. Samples which fail for other causes shall be classed as major defects.”

Add new note (3) as follows: “(3) Grasp Boxed End Pin by it’s loop and lightly push in the direction indicated on the dwg. Failure of pin surface “B” to contact the Band shall be classes as a critical defect.”

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1345-0032)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:47Z
Check the source to verify that this is the current version before use.