NOTICE OF INACTIVE
FOR NEW DESIGN

INCH-POUND

MIL-DTL-15370/16C
NOTICE 1
1 November 2012

DETAIL SPECIFICATION SHEET

COUPLERS, DIRECTIONAL, (COAXIAL, SMA CONNECTORS) (2 TO 1000 MHZ)

MIL-DTL-15370/16C is inactive for new design and is no longer used, except for replacement purposes.

Custodians:
Army – CR
Navy – EC
Air Force – 85
DLA – CC

Review activities:
Army - MI
Navy - AS, CG, MC, OS, SH
Air Force – 99

Preparing activity:
DLA - CC

Project (5985-2012-038)

NOTE: The activities listed above were interested in this document as of the date of this document. Since organizations and responsibilities can change, you should verify the currency of the information above using the ASSIST Online database at https://assist.dla.mil/.

AMSC N/A

FSC 5985

Source: https://assist.dla.mil -- Downloaded: 2026-10-18T06:12Z
Check the source to verify that this is the current version before use.