MIL-P-63066(AR)
AMENDMENT 3
28 APRIL 1983

SUPERSEDING
AMENDMENT 2
14 December 1982

MILITARY SPECIFICATION

PROJECTILE, 155MM, SPECIAL TEST, FOR
M692 and M731 LOADING, ASSEMBLING AND PACKING OF

This amendment forms a part of Military Specification MIL-P-63066(PA), dated 1 June 1976, and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 4

3.10: Add the following paragraph:

"3.10: Radiographic examination for Kill Mechanism. The loaded projectile shall be radiographically examined to show the absence of a Kill Mechanism in all mines contained within the projectile as specified in 4.5.9."

PAGE 9

4.4.2.1: Delete paragraph 4.4.2.1 in its entirety.

PAGE 10

4.4.2.2: Delete paragraph 4.4.2.2 in its entirety.

PAGE 11

4.4.2.3: Remove this paragraph and insert new paragraph 4.4.2.3 (Page 11).

PAGE 13

4.4.2.5: Remove this paragraph and insert new paragraph 4.4.2.5 (Page 13).

PAGE 18

4.4.2.9: Add the following:

"108 - Marking missing or incorrect - 0.40% - 3.2 - Visual"

FSC 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

4.4.2.16: Remove this paragraph and insert new paragraph 4.4.2.16 (Page 25).

PAGE 30

4.4.2.21: Add the following:

"107 - Weight marking missing or incorrect - 0.40% - 3.2 - Visual"

PAGE 31

* 4.4.2.22: Remove this paragraph and insert new paragraph 4.4.2.22 (Page 31).

PAGE 41

4.5.9: Add the following paragraph:

"4.5.9: Radiographic Examination of Projectile for Kill Mechanism. The projectile shall be radiographically examined with multiple views as required to positively determine the absence of a Kill Mechanism in all mines within the test projectile. Any Projectile containing a Kill Mechanism shall not be used for firings and the results should be reported immediately to the technical agency listed in 6.6."

PAGE 42

6.7: Submission of plans for approval, delete "Picatinny Arsenal, ATTN: SARPA-QA-A-S" and substitute "US Army Armament Research and Development Command, ATTN: DRDAR-QAT-M".

Custodian: Delete "PA" and substitute "AR".

Preparing activity: Delete "PA" and substitute "AR".

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the previous amendment."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-A718)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.3	Housing, Timing and Fuzing (Prior to assembly of inert filler)		9298450
			NEXT HIGHER ASSEMBLY 9298399

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Special					
a.	Barrier assembly not present or not properly positioned in S&A		100%	3.2	X-Ray
Major					
101	Shorting bar broken or damaged		100%	3.2	Visual
102	Battery ball depressed below normal position		100%	3.2	Gage
103	Foreign material in kill mechanism cavity		0.40%	3.2	Visual
104	Largest diameter in kill mechanism cavity not prepared for bonding		0.40%	3.2	Visual
105	Sensor plug(s) missing or damaged		0.40%	3.2	Visual
Minor					
201	Poor workmanship		1.0%	3.8	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.5	Special Test Mine (prior to final assembly of the mine)	1	1	9298399
				NEXT HIGHER ASSEMBLY 9298399

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1.	Presence of Kill Mechanism and Overlay Assembly		100%	3.2	Visual
Major 101	Housing not marked to indicate inert filler		100%	3.2	Visual
Minor 201	Poor workmanship		1.0%	3.8	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.16	Projectile (immediately after assembly of ogive and prior to assembly of charge and sleeve assembly)	1 OF 1	9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Marking or paint color incorrect		100%	3.2	Visual
Major					
101	Gap between body and ogive beyond specified limits		100%	3.2	Gage
102	Concentricity of ogive to bourrelets (2 places)		100%	3.2	Gage
103	Radiographic Examination (Column segments not axially aligned)		100%	3.4	4.5.5
Minor					
201	Poor workmanship		1.0%	3.8	Visual

NOTES:

DRDAR-QA Form 160 Jul 77

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	OF	DRAWING NUMBER
4.4.2.22	Projectile (prior to assembly of grommet)	1	1	9298319
				NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Presence of Kill Mechanism		100%	3.10	X-Ray
Major					
101	Lifting plug turns when disassembly torque is applied		0.40%	3.2	Test
102	Diameter of bourrelet, max (applicable after retouching paint)		0.40%	3.2	Gage
103	Rotating band damaged		0.40%	3.2	Visual
104	Obturator missing or damaged		0.40%	3.2	Visual
105	Stamped letter "A" missing from ogive (indicating air pressure test failure)		0.40%	3.2	Visual
106	Ballistic functioning test (High Zone)	1 Rd		3.3	4.5.7
107	Base metal of base plug exposed		100%	3.2	Visual
Minor					
201	Protective coating with a total of bare areas in excess of 1/4 square inch		0.65%	3.2	Visual
202	Marking missing or unidentifiable		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.8	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.