MIL-F-60348B (PA)
AMENDMENT 3
14 July 1975
SUPERSEDING
AMENDMENT 2
6 MARCH 1972

MILITARY SPECIFICATION

FUZE, POINT DETONATING, M48A3
METAL PARTS FOR

This Amendment forms a part of Military Specification MIL-F-60348B, dated 1 February 1970, and is approved for use by all Departments and Agencies of the Department of Defense.

Page 3 - Add Paragraph 3.7:

"3.7 Firing Pin Assembly Load Test.- The firing pin assembly shall not chip, crack or break when subjected to a minimum tension load of 80 pounds (lbs.) when tested as specified in 4.4.7."

Page 3 - Add Paragraph 3.8:

"3.8 Marking. - Body assemblies accepted by the Hurletron Inspection Machine, when tested as specified in 4.4.4, shall be marked as specified in Paragraph 5.2, using automated equipment in accordance with 4.3.4."

Page 6, Paragraph 4.3.2.2 - Add Major Defect 108 as follows:

"108. Wall thickness between detonator cavity and crush cup seat, min. ..... Gage 02022"

Page 6, Para. 4.3.2.2

Delete Minor 213 in its entirety

Add the following inspections:

Minor 213 Distance centerline of wrench hole to flange ....gage 02020
Minor 215 Diameter of wrench hole, ...gage 02022
Minor 216 Ogive staking hole 180° out of phase to wrench hole .....gage 02023

Page 9, Para. 4.3.2.8 - Add Major 106 as follows:

"106. Contour of ogive .....Gage 09106"

FSC: 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:30Z
Check the source to verify that this is the current version before use.

Page 14, Para. 4.3.2.17 - Delete Major 113 and substitute Major 113 as follows:

"113. Diameter of interrupter cavity below min, as evidenced by failure of a .2242 + .0001 dia. pin to seat against the bottom of the interrupter cavity, using a flush pin gage in the .437 counterbore ..... Gage 18052"

Page 14, Para. 4.3.2.17 - Change Minor 218, Code No. 18032 to "Major 114, Code No. 18032".

Page 15, Para. 4.3.2.18 - Delete Critical 1 and substitute Critical 1

as follows:

"1. Interrupter in armed or partially armed position, as evidenced by visible edge of interrupter, or light visible (to be performed after staking of setting sleeve assembly) ..... Visual"

Page 15, Para. 4.3.2.18 - Add Major 104 as follows:

"104, Setting sleeve fails to reach positive stop.. Manual 19006"

Page 15, Paragraph 4.3.2.18 - Add Minor Defect 202 as follows:

"202. Marking incorrect, unidentifiable or incorrectly positioned ..... Visual 19006"

Page 16 - Add Paragraphs 4.3.20 and 4.3.2.21:

"4.3.2.20 Pin, Firing (see dwg. 8798759 covering a detail of dwg. 8798235).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined		
Major:	AQL 0.40 percent		
101.	Distance from point to flange ...	Gage	22001
102.	Diameter and profile of pin point	Gage	22002
Minor:	AQL 1.0 percent		
201.	Diameter of shaft	Gage	22003
202.	Evidence of poor workmanship (see 3.5)	Visual	22004

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:30Z
Check the source to verify that this is the current version before use.

4.3.2.21 Firing Pin Assembly (see dwg. 8798240 covering a detail of dwg. 8798235).

Categories	Defects	Method of Inspection	Code No.
Critical:	None defined.		
Major:	AQL 0.65 percent		
101.	Thickness of flange	Gage	23001
102.	Concentricity of flange with firing pin	Gage	23002
103.	Pin loose	Manual	23003
Minor:	AQL 1.0 percent		
201.	Diameter of flange	Gage	23004
202.	Evidence of poor workmanship (see 3.5)	Visual	23005"

Page 16, Paragraph 4.3.3.1 - Add:

Test	Classification	Sample Size	Rejection	Test Procedure	No.
"Firing Pin Assembly Load Test (see 3.7)	Major	40	1	4.4.7	23006"

Page 16, Paragraph 4.3.3.2 - Delete "4.4.6" - Add "4.4.4"

Page 17, Paragraph 4.3.3.3 - Delete "4.4.6" - Add "4.4.4"

Page 17 - Delete Paragraph 4.3.3.4

Page 18, Paragraph 4.4.4 Body Assembly Interrupter Arming and Non-Arming - Delete Test Procedure - Add new Procedure:

"The unarmed assembly shall be subjected to these tests by rotation in a Hurletron Fuze body Inspection Machine (see 4.3.4). Each body assembly shall be placed in the Hurletron with the flash tube thread end facing up. Rotation will be first at the arming speed, followed by rotation at the non-arming speed.

Assemblies rejected by the Hurletron, in either the arming or non-arming phase, shall be classified defective and not be returned to the lot.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:30Z
Check the source to verify that this is the current version before use.

Assemblies successfully completing these tests shall be marked in accordance with Paragraph 5.2, using automated equipment as specified in 4.3.4. These tests may be conducted before the setting sleeve assembly is staked to the body assembly."

Page 18 - Delete Paragraph 4.4.4.1.

Page 19 - Add Paragraph 4.4.7:

"4.4.7 Firing Pin Assembly Load Test. - The firing pin assembly shall be assembled in equipment that is in accordance with 4.3.4. The required load shall be applied without impact, and the assembly observed for compliance with the requirements. Assemblies subjected to this test shall be scrapped."

Page 19 - Add Paragraph 5.2:

"5.2 Automated Marking of Hurletron Tested Fuze Bodies. - The fuze bodies, upon exiting from the Hurletron, shall be marked with a 3/16 inch wide circular band, whose inside diameter shall be one inch, and centered with the flash tube hole. The marking shall be applied to the top of the tang. Quick drying material to be choice of contractor, with Picatinny Arsenal approval.

Page 21, Para. 6.3.5, Line 9 - Delete "SMUPA ND7" and substitute "SARPA-QA-T-T".

Page 21, Paragraph 6.4, Line 7 - Delete "SMUPA ND" and substitute "SARPA-QA-I-Q".

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project NO. 1390-A-090

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:30Z
Check the source to verify that this is the current version before use.