MIL-C-48294 (PA)
Amendment 2
9 June 1975
Superseding
Amendment 1
12 September 1974

MILITARY SPECIFICATION

CONTAINER, SHIPPING AND STORAGE,
MINE CANISTER: M602

This Amendment forms a part of Military Specification MIL-C-48294 (PA) dated 12 February 1974 and is approved for use by all Departments and Agencies of the Department of Defense.

Paragraph 1.1 - Change "test of the canister used" to read "test of the container used".

Paragraph 3.5.3 - Change "Edgewise" to read "Cornerwise".

Paragraph 3.5.4 - Change "Cornerwise" to read "Edgewise".

*Add new paragraph:

3.9 Functional cell size

3.9.1 Large cell. - Nine (9) cells shall be capable of accepting a plug 9.71 inches min. by 9.71 inches min. by 6.0 inches min. long with a 2.0 inch max. cube cutout on each of the four corners for the entire depth and a cutout to clear the bracket.

3.9.2 Small cell. - Three (3) cells shall be capable of accepting a plug 9.71 inches min. by 4.82 inches min. by 6.0 inches min. long with a 2.0 inch max. cube cutout on each of the four corners for the entire depth and a cutout to clear the bracket.

Paragraph 4.2.1 Delete "ten (10) sets of component parts and ten (10) of each sub-assembly and assembly". and substitute - "two (2) sets of component parts and two (2) of each sub-assembly and assembly".

FSC: 1345

Source: https://assist.dla.mil -- Downloaded: 20261O-22T19:21Z
Check the source to verify that this is the currentversion before use.

Paragraph 4.2.2 Delete "The ten (10) sets of components" and substitute: "The two (2) sets of components".

Paragraph 4.2.2 - Delete "and 4.3.3.3".

Paragraph 4.2.2.1 - Delete in its entirety and substitute the following:

"4.2.2.1 In addition, the following tests shall be performed on the two (2) containers after they have undergone the requirements of 4.3.2 and 4.3.3 as noted above.

a. Fork lifting (see 3.5.1)
b. Stacking (see 3.5.2)
c. Cornerwise drops (see 3.5.3)
d. Edgewise drops (see 3.5.4)
e. Vibration (see 3.5.5)".

Paragraph 4.2.2.2 - Delete in its entirety and substitute the following:

"4.2.2.2 The two (2) assemblies shall then be tested for the air pressure test of 4.4.2".

*Paragraph 4.3.2.1 delete,

"101 Partitions not properly positioned..... Gage 01001"

and substitute,

"101 Partitions incorrect size (see 3.9)..... Gage 01001"

Paragraph 4.3.2.1 add the following Major Defect:

"111. Bracket (6 each) welds missing or improper (see 3.4)..... Visual 01012"

Paragraph 4.3.2.2 Add the following Major Defect:

"103. All-around welds (alternate construction of z bar) missing or improper (see 3.4)..... Visual 02005".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.

Paragraph 4.3.3.3 - Delete in its entirety.

Paragraph 4.4.6 - Change "Edgewise Drops" to read "Cornerwise Drops".

Paragraph 4.4.7 - Change "Cornerwise Drops" to read "Edgewise Drops".

Paragraph 4.4.7 - Change the word "sill" to read "block".

Asterisks indicate latest changes accomplished by Amendment 2 dated 9 June 1975. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous issue.

Custodian:
Army-PA

Preparing Activity:
Army-PA

Project No. 1345-A-132

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T19:21Z
Check the source to verify that this is the current version before use.