DATA ITEM DESCRIPTION

Form Approved
OMB No. 0704-0188

1. TITLE	2. IDENTIFICATION NUMBER
Quality Engineering Planning List	DI-CMAN-80788

3. DESCRIPTION/PURPOSE

3.1 The Quality Engineering Planning List (QEPL) identifies the number of Quality Assurance Provisions (QAPs) documents, the associated hardware/software items, the special inspection equipments (SIE), and the type of document to be utilized, i.e., specification (SPEC), drawing (DWG), depot maintenance work requirements (DMWR), Storage Serviceability Standards (SSS) or special inspection equipment.

4. APPROVAL DATE (YYMMDD)	5. OFFICE OF PRIMARY RESPONSIBILITY (OPR)	6a. DTIC APPLICABLE	6b. GIDEP APPLICABLE
890308	MT		

7. APPLICATION/INTERRELATIONSHIP

7.1 This Data Item Description (DID) contains the format and content preparation instructions for that data resulting from the work task described by 3.4 of MIL-T-47500/6.

7.2 This DID supersedes DI-R-1764.

8. APPROVAL LIMITATION	9a. APPLICABLE FORMS	9b. AMSC NUMBER
		A4662

10. PREPARATION INSTRUCTIONS

10.1 Format. The QEPL shall be in contractor format. Figure I may be used as a guideline.

10.2 Content. The QEPL shall contain the data elements as follows:

a. Block 1 Nomenclature. Enter the nomenclature of the QEPL item as it appears on the drawing.

b. Block 2 QEPL Number. Enter the identifying end item number of the QEPL (same as Major Item Drawing Number).

c. Block 3 Installation. Enter appropriate Government contracting agency.

d. Block 4 Date. Enter date QEPL is approved by the Quality Engineer.

e. Block 5 Submitted By. Type in name of Quality Engineering Contractor or Government activity as applicable.

(Continued on page 2)

11. DISTRIBUTION STATEMENT

DISTRIBUTION STATEMENT A:
Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:39Z
Check the source to verify that this is the current version before use.

Block 10, Preparation Instructions (Continued)

f. Block 6 Approved By. Enter signature of Government Quality Engineering Technical Representative approving QEPL.

g. Block 7 Page. Enter page number.

h. Block 8 Number-of-Pages. Enter total number of pages of QEPL.

i. Block 9 Assembly. Enter letter "A" to flag assembly.

j. Block 10 Part Number.

(1) Starting with the number in block 2, enter the number and assembly numbers in generation breakdown order.

(2) When an assembly number is entered, the breakdown of that assembly shall be completed before proceeding to the next number.

k. Block 11 Nomenclature. Enter the noun description of the item.

l. Block 12 Repair Part. Enter an "X" if the item in block 10 is designated as a repair part.

m. Block 13 Quality Assurance Documentation. At the time of documentation preparation, if quality assurance provisions including special inspection equipment (SIE) are required, enter "R" in each appropriate column. When the quality assurance provisions have been prepared, the QEPL shall be updated to reflect the appropriate documentation number. When no quality assurance provisions or SIE are required to be prepared, enter "NR" in the appropriate columns.

n. Block 14 Other Information. Enter special information as required, including the reason for nonpreparation of quality assurance documentation for those items identified in block 13.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T10:39Z
Check the source to verify that this is the current version before use.

Quality Engineering Planning List (QEPL)		3. Installation:			4. Date:	
1. Nomenclature	2. QEPL Number:	5. Submitted By:	6. Approved By:		7. Page:	8. No. of:

9. Assy	10. Part Number	11. Nomenclature	12. Repair Part	13. Quality Assurance Documentation					14. Other Information
				Spec	DWG	DMWR	SSS	Special Inspection Equipment	

DI-CMAN-80788

Source: https://assistdaxml -- Downloaded: 2026-10-26T10:39Z
Check the source to verify that this is the current version before use.

FIGURE 1. Quality engineering planning list (QEPL) sample format.