INCH-POUND
MIL-P-64005 (AR)
AMENDMENT 1
3 November 1992

MILITARY SPECIFICATION

PROJECTILE, 155MM, GB2, M687,
METAL PARTS ASSEMBLY WITH LOADED OGIVE

This amendment forms a part of Military Specification MIL-P-64005 (AR), dated 29 November 1985, and is approved for use by the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 4

3.4.5 Delete in its entirety and substitute the following:

"3.4.5 Surface cavitation. Voids or cracks in segment C of Figure 1 shall not be cause for rejection. Cavities in the base of the fuzewell (top of segment B) shall not be cause for rejection provided the sum of the areas of the cavities is not greater than 80 percent of the top of segment B and no individual point extends more than 1/4 inch below the maximum depth of the fuzewell permitted by the drawing. No point may extend above the flat surface on which the liner will rest. Cavities having a maximum dimension of 1/32 inch or less shall be disregarded in surface cavitation computations."

PAGE 7

4.3.2 Delete in its entirety and substitute included 4.3.2.

PAGE 10

4.4.2.2 Classification of defects, add major 104

"104 Presence of Sealant. 100% 3.2 Visual/Gage"

PAGE 11

4.4.2.3 Delete in its entirety and substitute included 4.4.2.3.

PAGE 12

4.4.2.4 Classification of defects; add minor 206:

"206 Explosive batch notation,
and batch number missing,

Source: https://assist.dla.mil -- Downloaded: 202640-23T03:08Z
Check the source to verify that this is the current version before use.
AMSC N/A FSC 1320
DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

TABLE II.- First article inspection

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.3.2	Metal Parts Assembly with Loaded Ogive				See Below
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
	Loaded Ogives (Dwg. 9349367)				
	Base separation of loaded ogive	8	100%	3.4.4	4.4.3.1.1
	After the test for base separation, each sample shall be completely sectioned and each half color photographed for the purpose of retaining a permanent record of the explosive filler.	8	100%	3.4	Each photograph shall be an 8 x 10 inch, color close-up of the sectioned ogive clearly defining the oxamide fill. The necessary ogive/oxamide identification numbers shall be clearly displayed in the photo, but properly located so as to not blur or cover the internal view of the ogive.
	Metal parts assembly with loaded ogive (Dwg. 9349367)				
	Examination for defects	20	100%	3.2	4.4.2.2 to 4.4.2.4, 4.4.2.6 (NOTE 2)
	Ballistic tests:				
	A. Zone 3 (-40 + 5 F)	5	100%	3.7.2	4.5.2.2
	B. Excess Pressure (+70 F)	15	100%	3.7.2	4.5.2.3

NOTES: 1. With the exception of ballistic tests first article tests shall be done at the loading facility.
2. For these inspections rounds will not be disassembled -- only external tests will be done.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:08Z
Check the source to verify that this is the current version before use.

QUALITY CONFORMANCE INSPECTION

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Metal Parts Assy with Loaded Ogive (with liner)				9349367
					NEXT HIGHER ASSEMBLY
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Liner missing		100%	3.2	Visual
Major					
202	Depth to bottom of liner, min.		.40%	3.2	Gage
Minor					
201	Liner damaged		.65%	3.2	Visual
202	Explosive or foreign matter in or on top of liner cavity		.65%	3.2	Visual
203	Liner can be twisted or pulled out by hand		.65%	3.2	Manual
204	Security of liner in cavity and against nose threads		.65%	3.2	Manual
205	Evidence of poor workmanship		.65%	3.9	Visual

NOTES:

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:08Z
Check the source to verify that this is the current version before use.

misleading, or unidentifiable .65% 3.1/6.10 Visual"

PAGE 15

4.4.3.1.1.1 Delete in its entirety and substitute the following:

"4.4.3.1.1.1 Ogive sectioning. Ogives exhibiting base separation, as determined by radiographic examination, shall be selected for sectioning at the following rate:

a. From every group of 700 consecutively produced and radiographed ogives or portion thereof, one sectioning sample shall be selected from the ogives indicating base separation. This sample shall have the largest amount of base separation from the subject ogives. If the sample fails the requirement of 3.4.4, then all ogives in that group which show any indication of base separation by radiographic examination shall be rejected.

b. If radiographic examination of an entire group reveals no ogives with base separation, a sectioning sample shall be randomly selected. If the randomly selected sample fails to meet the requirement of 3.4.4, the entire group of ogives represented by that sample shall be rejected.

c. The sectioning samples shall be tested in accordance with 4.5.3."

PAGE 19

4.5.2 Delete last sentence, "An attempt will be ....."

4.5.2.1 Change last sentence to read:

"An attempt will be made to recover the projectiles fired for first article. During production acceptance tests, projectiles shall be recovered only if failure or suspected failure occurs."

PAGE 21

Add the following new paragraph:

"6.10 Explosive batch quantities. An explosive batch quantity is defined as the amount of explosive composition that is blended at any one time. No additional materials will be added to the batch quantity once the ogive loading process begins for that particular batch. Each batch of explosive will be assigned a different non-repeating four (4) digit batch

Source: https://assist.dla.mil -- Downloaded: 202640-23T03:08Z
Check the source to verify that this is the current version before use.

number by the manufacturer. Any break or stoppage in production during mid-batch loading that is greater than three (3) hours, shall require that, (a) a new batch number be assigned to the explosive quantity left in the melt kettle from when production stopped and be considered a new batch by itself, or (b) the remaining batch quantity be reblended with the needed materials to create a new fuller batch quantity and renumbered. The manufacturer will have the option of exercising either (a) or (b). Records of projectile lots noting the explosive batch numbers in each lot will be maintained by the manufacturer."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-AC91)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T03:08Z
Check the source to verify that this is the current version before use.