MILITARY SPECIFICATION

SHELTER, ELECTRICAL EQUIPMENT S-419( )/TCC-73(V)

This amendment forms a part of specification MIL-C-55307(EL) dated 10 May 1971.

Page 35, paragraph 4.7.3.1, add the following paragraph under paragraph 4.7.3.1p.

q. Connect tester between pin A (of connector MS-3314-E-22-55S) and solder connection of pin 1A of contact assembly MX-3227 of connector U-187( )/G for system SYS-1-8-1 in monitor alarm box. Circuit continuity shall exist and meet the requirements of 3.3.3.1 (See Drawing SC-D-606781)

r. Repeat procedures 4.7.3.1q for each remaining conductor (pin B through pin EE) to its corresponding solder connection of contact assembly MX-3227 of connector U-187( )/G.

s. Repeat procedure 4.7.3.1q and r above, for each conductor terminated in connectors for system SYS-1-8-2.

Page 37, paragraph 4.7.3.2, add the following paragraphs under paragraph 4.7.3.2m.

n. At monitor alarm box, connect pins 1A through 26B of connector (U-187( )/G) SYS-1-8-1 to facility ground.

o. Connect tester between the facility ground terminal and pin A of connector (MS-3114-E-22-55S) SYS-1-8-1. Remove ground connection from pin 1A of contact assembly MS-3227 for SYS-1-8-1. (See drawing SC-D-606781)

p. Repeat procedure 4.7.3.2d.

q. Repeat procedure 4.7.3.2n through p for each remaining

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T22:57Z
Check the source to verify that this is the current version before use.

conductor (Pins B through pin EE) of connector (MS-3114-E-22-55S) each time ungrounding the pin of contact assembly MX-3227 for SYS-1-8-1 correlating with the circuit being tested and reconnecting pin to facility ground terminal following completion of the test.

r. Repeat procedures 4.7.3.2n through q for system SYS-1-8-2.

Page 37, paragraph 4.7.3.3, delete paragraph 4.7.3.3a and substitute:

a. Repeat procedures 4.7.3.2a through i, and n through r, except 4.7.3.2d which shall be replaced by 4.7.3.3b below.

Page 38, table IV in both columns delete, "TD-660-SYS-1, ACT PCM OUT" and substitute, "TD-660SYS-1, ALT PCM OUT".

Page 38, below Table IV add: Table IV continued on page 39.

Page 39, above Table shown add: Table IV continued.

Page 39, below Table shown add: Table IV continued on page 40.

Page 40, above Tables shown add: Table IV continued.

Page 40, to top table, left hand column add:

TD-976-#1 from cable
TD-976-#1 to cable
Repeat above for TD-976-#2

To top table, right hand column add:

TD-976-#1 from cable
TD-976-#1 to cable
Repeat above for TD-976-#2

Page 41, paragraph 4.7.4.2c delete from first sentence: "terminal ground in video entrance box." and substitute "shield".

Page 41, paragraph 4.7.4.2i delete from first sentence the word "shield" and substitute "shell".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T22:57Z
Check the source to verify that this is the current version before use.

Page 44, paragraph 4.8.2d: delete colon after "CV-1548( )/G" and substitute "except paragraphs (5) and (6) when using CV-1548A/G:"

Page 48, paragraph 4.8.2k: delete "Multiplexer TD-204( )/U or TD-754( )/U." and substitute, "Multiplexer TD-660( )/U."

Page 50, paragraph 4.9 add: Tire pressures shall be as specified for the truck for cross-country travel.

Custodian:
Army - EL

Preparing Activity
Army - EL

Project No. 5805-A197

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T22:57Z
Check the source to verify that this is the current version before use.