MIL-F-50454A(AR)
AMENDMENT 5
6 June 1988
SUPERSEDING
AMENDMENT 4
4 August 1981

MILITARY SPECIFICATION

FUZE, GRENADE, M219E1 LOADING, ASSEMBLING, AND PACKING

This amendment forms a part of Military Specification MIL-F-50454A(AR), dated 19 March 1973, and is approved for use within the U.S. Army Armament, Munitions and Chemical Command, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

* Change item designation from "M219E1" to "M219A1 and M219A2" in title.

* Paragraph 1.1, Line 2: Delete "one type of fuze designated as Fuze, Grenade, M219E1" and substitute with "two types of fuzes designated as Fuze, Grenade, M219A1 and M219A2".

PAGE 2

Drawings, Change fuze designation from "M219E1" to "M219A1".

* Drawings, Include "9332611 - Fuze, Grenade M219A2".

PAGE 6

Paragraph 4.2.1.e: Delete "Five hundred seventy-four (574)" and substitute with "Six hundred eighty-seven (687)".

PAGE 8

Paragraph 4.2.5.1, Line 1: Delete "See 3.11)" and substitute with "(See 3.12)".

PAGE 10

* Page 10 (3 places) Change fuze designation from "M219E1" to "M219A1/ M219A2", and add "/9332611".

PAGE 11

* Paragraph 4.3.2.5: Change fuze designation from "M219E1" to "M219A1/ M219A2", and add "/9332611".

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:25Z
Check the source to verify that this is the current version before use.

Add:

* 4.3.2.12 Rotor, Detonator (See Dwg. 9223676 - applicable to M219A2 only)

Categories	Defects	Method of Inspection
Major	AQL 0.40 Percent	
101.	Lubricant missing	Visual
Minor	AQL 0.65 Percent	
201.	Evidence of poor workmanship	Visual

* 4.3.2.13 Spring, Rotor (See Dwg. 9229736 - applicable to M219A2 only)

Categories	Defects	Method of Inspection
Major	AQL 0.65 Percent	
101.	Loads at compressed lengths	Test
102.	O.D. at compressed length (max)	Gage
103.	End(s) not closed and squared	Visual
104.	End configuration improper (Note 12)	Visual
Minor	AQL 1.00 Percent	
201.	Solid height (max)	Gage
202.	Evidence of poor workmanship	Visual

* 4.3.2.14 Spring, Weight Centering (See Dwg. 9207969 - applicable to M219A2 only)

Categories	Defects	Method of Inspection
Major	AQL 0.65 Percent	
101.	Loads at compressed lengths	Test
102.	O.D. at compressed length (max)	Gage
103.	Ends not closed and ground	Visual
Minor	AQL 1.00 Percent	
201.	Solid height (max)	Gage
202.	Evidence of poor workmanship	Visual

PAGE 16

Paragraph 4.4.3, Line 9: Delete "...visible through the lead cup in the housing." and substitute with "...visible through the lead cup hole in the housing."

Source: https://assist.dla.mil -- Downloaded: 20260-22T20:25Z
Check the source to verify that this is the current version before use.

PAGE 18

* Paragraph 4.4.14

PAGE 20

Paragraph 6.3.5, Lines 7 and 8, Change address to "Commander, ARRADCOM, ATTN: DRDAR-QAT-I, Dover, New Jersey 07801".

PAGE 21

* Paragraph 6.5, Line 2: Change fuze designation from "M219E1" to "M219A1 or M219A2".

Paragraph 6.5 and 6.6: Change address to "Commander, ARRADCOM, ATTN: DRDAR-QAT-M, Dover, New Jersey 07801".

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing Activity:
Army-AR

(Project 1330-A174)

Source: https://assist.dla.mil -- Downloaded: 202610-22T20:25Z
Check the source to verify that this is the current version before use.