MIL-F-50983B (AR)
AMENDMENT 3
10 June 1982

MILITARY SPECIFICATION

FUZE, MT, SQ, M577
LOADING, ASSEMBLING, PACKING AND METAL PARTS
FUZE, MT, SQ, M582
METAL PARTS

This amendment forms a part of Military Specification MIL-F-50983B (AR), dated 30 June 1980, and is approved for use by the US Army Armament Research and Development Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 6

* 4.3.1, to the group entitled 15 each, delete: "9236518".

* 4.3.1, to the group entitled 15 each, add: "9236729, 9236730, 9236731".

PAGE 7

4.3.1, to the group entitled 50 each, add: "6236712, 6236733".

PAGE 45

4.4.2.36, to the block entitled Drawing Number, add: "9236712 and 9236733".

4.4.2.36, to the block entitled Next Higher Assembly, add: "9236711 and 9236732".

PAGE 46

4.4.2.37, to the block entitled Drawing Number, add: "9236732".

4.4.2.37, to Note b, add: "and 9236732".

4.4.2.37, to Note c, add: "and 9236732".

FSC 1390

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

PAGE 97

* 4.4.2.87, to the block entitled Title, delete in its entirety and add: "Plug, Retainer".

* 4.4.2.87, to the block entitled Drawing Number, delete: "9236518" and add: "9236731".

* 4.4.2.87, to the block entitled Next Higher Assembly, delete "9236516" and add: "9236729".

* 4.4.2.87, Major 101, delete "Static Load Test" and add: "Outside Diameter".

* 4.4.2.87, to the block entitled No. of Sample Units, delete: "40a".

* 4.4.2.87, to the block entitled AQL or 100%, delete: "b" and add: "0.40%."

* 4.4.2.87, to the block entitled Paragraph Reference/Inspection Method, delete: "4.5.1.f" and add: "Gage."

* 4.4.2.87, to the block entitled Notes, delete: note a. and note b. in their entirety.

PAGE 98

* 4.4.2.88, to the block entitled Drawing Number, delete: "9236516" and add: "9236729".

* 4.4.2.88, Major 101, delete: "Crush retainer missing" and add: "Plug Retainer missing".

* 4.4.2.88, Major 102, delete: "Crush element missing" and add: "Axial static load test".

* 4.4.2.88, Major 102, to the block entitled No. of Sample Units, add: "40a".

* 4.4.2.88, Major 102, to the block entitled AQL or 100%, delete: "0.40%" and add: "b".

* 4.4.2.88, Major 102, to the block entitled Paragraph Reference/Inspection Method, delete: "Manual" and add: "4.5.1.f".

* 4.4.2.88, to the block entitled Notes, add: "b. Destructive".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.

* 4.4.2.88, to the block entitled Notes, add: "b. Reject the lot if one (1) or more defective units are found.".

PAGE 114

* 4.5.1, Table I, subparagraph f, delete: "Crush Element (dwg. 9236518)" and add: "Setting Key Assembly (dwg. 9236729)".

PAGE 117

4.5.1, Table I, subparagraph ab, add: "9236733".

4.5.1, Table I, subparagraph ac, add: "9236733".

4.5.1, Table I, subparagraph ad, add: "9236733".

4.5.1, Table I, subparagraph ae, add: "9236733".

PAGE 121

4.5.2, Table II, subparagraph d, add: "9236733".

PAGE 131

4.5.21.3.4, second and third line, delete: "and the suspect value falls outside the function time limits,."

The margins oif this amendment are marked with an asterisk to indicate where changes from the previous amendment were made. This was done as a convenience only and the government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army - AR

Preparing activity:
Army - AR

(Project 1390-A265)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:46Z
Check the source to verify that this is the current version before use.