MILITARY SPECIFICATION

FUZE, BASE DETONATING, M578
PARTS - WITH DETONATOR

This amendment forms a part of Military Specification MIL-F-60042B (PA), dated 14 March 1975 and is approved for use by the U.S. Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 16

4.4.2.2 Delete in its entirety and substitute:

"4.4.2.2 Booster lead cup (see dwg. 9323863 covering a detail of dwg. 8886433)

Categories	Defects	AQL	Method of Inspection
Critical	None defined		
Major:			
101	Thickness of bottom of lead cavity	0.40%	Gage
Minor:			
201	Pitch diameter of thread	0.65%	Gage
202	Major diameter of thread	0.65%	Gage
203	Length of thread engagement, min.	0.65%	Gage
204	Diameter of lead charge cavity	0.65%	Gage
205	Concentricity of lead charge cavity with thread	0.65%	Gage
206	Depth of pellet cavity	0.65%	Gage
207	Diameter of pellet cavity	0.65%	Gage
208	Concentricity of pellet cavity with thread	0.65%	Gage

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:05Z
Check the source to verify that this is the current version before use.

Categories	Defects	AQL	Method of Inspection
Minor (Continued):			
209	Concentricity of thread pilot at base end	0.65%	Gage
210	Concentricity of thread pilot at open end	0.65%	Gage
211	Diameter of thread pilot at base end	0.65%	Gage
212	Diameter of thread pilot at open end	0.65%	Gage
213	Length of thread pilot at base end	0.65%	Gage
214	Length of thread pilot at open end	0.65%	Gage
215	Width across wrench flats including location	0.65%	Gage
216	Chamfer missing or incorrect	0.65%	Visual
217	Surface finish	0.65%	Visual/ Gage
218	Radii	0.65%	Visual
219	Flatness of base	0.65%	Gage
220	Perpendicularity of base	0.65%	Gage
221	Protective finish missing or damaged	0.65%	Visual
222	Evidence of poor workmanship	0.65%	Visual"

4.4.2.3 Delete in its entirety and substitute:

"4.4.2.3 Cap (see dwg. 9323865 covering a detail of dwg. 8886433)

Categories	Defects	AQL	Method of Inspection
Critical: None defined.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:05Z
Check the source to verify that this is the current version before use.

Categories	Defects	AQL	Method of Inspection
Major: None defined			
Minor:			
201	Pitch diameter	0.65%	Gage
202	Major diameter	0.65%	Gage
203	Concentricity of thread with outside diameter	0.65%	Gage
204	Outside diameter	0.65%	Gage
205	Length	0.65%	Gage
206	Diameter of thread relief	0.65%	Gage
207	Width of thread relief	0.65%	Gage
208	Inside depth	0.65%	Gage
209	Diameter of step	0.65%	Gage
210	Width of step	0.65%	Gage
211	Chamfer missing	0.65%	Visual
212	Radii missing	0.65%	Visual
213	Length of engagement, min	0.65%	Gage
214	Surface finish	0.65%	Visual/ Gage
215	Protective coating missing or damaged	0.65%	Visual
216	Evidence of poor workmanship	0.65%	Visual"

PAGE 73

4.4.2.53 Delete in its entirety and substitute:

"4.4.2.53 Locking ring (see dwg. 9323864 covering a detail of dwg. 8886433)

Categories	Defects	AQL	Method of Inspection
Critical: None defined			
Major: None defined.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:05Z
Check the source to verify that this is the current version before use.

Categories	Defects	AQL	Method of Inspection
Minor:			
201	Pitch diameter of thread	0.65%	Gage
202	Minor diameter of thread	0.65%	Gage
203	Length of engagement, min	0.65%	Gage
204	Outside diameter	0.65%	Gage
205	Concentricity of outside diameter with pitch diameter of thread	0.65%	Gage"

Custodian:
Army-AR

Preparing Activity:
Army-AR

(Project 1390-A462)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T00:05Z
Check the source to verify that this is the current version before use.