QUALIFICATIONS CERTIFIED
August 1987

QPL-25027-14
16 September 1987
SUPERSEDING
QPL-25027-13
31 October 1985

QUALIFIED PRODUCTS LIST

OF FSC 5310

PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION

MIL-N-25027

NUT, SELF-LOCKING, 250°F, 450°F, AND 800°F

This list has been prepared for use by or for the Government in the acquisition of products covered by the subject specification and such listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified In the latest effective Issue of the applicable specification. This list Is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

THE ACTIVITY RESPONSIBLE FOR THIS QUALIFIED PRODUCTS LIST IS THE NAVAL AIR SYSTEMS (COMMAND (ATTENTION: COMMANDING OFFICER, NAVAL AIR ENGINEERING CENTER " (SESD), (CODE 53), LAKEHURST, NJ 08733-5100)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS14144 NUT, SELF-LOCKING, LIGHTWEIGHT, CASTELLATED, 450°F			
MS14144L3	RME9868-3	NADC Report No. 305Q7051 of 18 Jun 1979	Elastic Stop Nut A Divison of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083
MS14144L4	RME9868-4		
MS14144L5	RME9868-5		
MS14144L6	RME9868-6		
M1S14144L7	RME9868-7		
MS14144L8	RME9868-8		
MS14144L9	RME9868-9		Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS14144L1O	RME9868-10		
MS14144L12	RME9868-12		
MS14144L14	RME9868-14		
MS14144L16	RME9868-16		
MS14144L18	RME9868-18		

NOTE : "RM" designates Molybdenum Disulphide Lubricant Coating.

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:1[illegible]
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QALIFICATION REFERENCE	MANUFACTRRER'S NAME AND ADDRESS
MS14144-3	PH CR-353	NADC **Report** 60108414 of 26 Sep 1984	Simmonds Fastener Technologies, Inc. 181-A West Orangethorpe Placentia, CA 92670
MS14144-4	PH CR-354		
MS14144-5	PH CR-355		
MS14144-6	PH CR-336		
MS14144-7	PH CR-357		
MS14144-8	PH CR-358	"	Plant: **Shmmonds** **5, rue** Michelet, B.P. 52 F, 92152 Suresnes Cedex France
MS14144-9	PH CR-359		
MS14144-10	PH **CR-35**		
MS14144-12	PH CR-3512		
MS14144L3	PH CR-353M		
MS14144L4	PH CR-354M		
MS14144L5	PH CR-355M		
MS14144L6	PH CR-356H		
MS14144L7	PH CR-357M		
MS14144L8	PH CR-358M "		
MS14144L9	PH CR-359M		
MSS14144L10	PH CR-3510M		
MS14144L12	PH CR-3512M		

NOTE: (1) **MANUF** ACTURING **process: Cold formed**
(2) **Lubricant:** (For **Government Designation with-** "L') **QPL-8937:**
(3) Provisions Governing Procurement of **these self** locking **nuts shall be in accordance with FAR 52-225-3 (Buy American Act) and** DFARS 52.225-7012 **(Preference for Domestic Specialty Metals).** The contractor should include these provisions in every **subcontract and purchase order.**

MS14144-4	73781-428	" NADC **Report** 601Q8506 of 17 Jun 1985	SPS Technologies Highland Avenue Jenkintown; PA" 19046
MS14144L4.	73781M-428		

NOTE: Manufacturing process: Forged

MS14145 NUT SELF-LOCKING, LIGHYWEIGHT, THIN, **CASTELLATED: 450°F**

MS14145L3	RMTE9868-3	**NADC Report No. 305Q79051 of 18 Jun** 1979	**Elastic Stop Nut A Division of** Harvard Industries. Inc. 2330-Vauxhall Road **Union,** NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS14145L4	RMTE9868-4		
MS14145L5	RMTE9868-5		
MS14145L6	RMTE9868-6		
MS14145L7	RMTE9868-7		
MS14145L8	RMTE9868-8		
MS14145L9	RMTE9868-9		
MS14145L10	RMTE9868-10		
MS14145L12	RMTE9868-12		
MS14145L14	RMTE9868-14		
MS14145L16	RMTE9868-16		
MS14145L18	RMTE9868-18		
MS14145-3	TE9868-3		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER' S MAME AND ADDRESS
MS14145-4	TE9868-4	NADC Report No. 305079051 of 18 Jun 1979	Elastic Stop Nut A Division of Harvard Industries, Inc (Cent'd)
MS14145-5	TE9868-5		
MS14145-6	TE9868-6		
MS14145-7	TE9868-7		
MS141 **45-8**	**TE9868-8**		
MS14145-9	TE9868-9		

NOTE: "RM" designates Molybdenum Disulptide Lubricant Coating.

MS14145-3	THCR-353	NADC Report 601Q84150f 24 Sep 1984	Simmonds Fastener **Technologies, Inc.** 181-A West Orangethorpe Placentia, CA 92670 ,
MS14145-4	THCR-354		
MS14145-5	THCR-355		
MS14145-6	THCR-356		
MS14145-7	THCR-357		
MS14J45-8	THCR-358		Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes,Cedex, France
MS14145-9	THCR-359		
MS14145-10	THCR-3510		
MS14145-12	THCR-3512		
MS14145L3	THCR-353M		
MS14145L4	THCR-354M		
MS14145L5	THCR-355M		
MS14145L6	THCR-356M		
MS14145L7	THCR-357M		
MS14145L8	THCR-358M		
MS4145L9	THCR-359M		
MS14145L10	THCR-3510M		
MS14145L12	THCR-3512M		

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be,in accordance with FAR 52.225-3, (Buy American Act) and DFARS 52.225-7012 (preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order. . . .,

MS14145L14	THCR-3514M	NADC Report , . ", 601Q8516 of 12 Nov 1985	

NOTE : (1) Manufacturing process: Machined
(2) Lubricant: (For Government Designation with "L" QPL-8937
(3) Provisons Governing Procurement. Procurement of-these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012. (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS14145-14	THCR-3514	NADC **Report 601Q8606 of. 12 May 1986**	**Simmonds Fastener Technologies, Inc. (C o n t ' d)**

NOTE: (1) Manufacturing process: **Cold forging**

(2) Provisions Governing **Procurement.** Procurement of these self-locking **nuts shall be in accordance with FAR 52.225-3 (Buy** American **Act) and DFARS** 52.225-7012 **(Preference** for Domestic Specialty Metals). The contractor should include these provisions **In every subcontract and purchase order.**

MS14146 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, C-B0RED, 'CAPTIVE WASHER, 450°F.

MS14146-3 MS14146-4 MS14146-5 MS14146-6 MS14146-7 MS14146-8	E103613 E10361-4 E10361-5 E10361-6 E10361-7 E1036-8	Report No. **305Q81O66 of** 15 Oct 1981	Elastic Stop Nut.: A Division ofi . Harvard Industries Inc. 2330 Vauxhall Road Union, NJ 07083 **Plant: Same address**

NOTE: Manufacturing process: Forged

MS14146	**CR-5952-4**	**NADC Report 601Q8609** Of 8 **Aug 1986**	Simmonds **Fastener- . Technoiogies, Inc 181 A: West Orangethorpe Placentia, CA 92670** **Plant: S i m m o n d s** **5, rue** Michelet;, B.P. 52 F.92152.Suresnes Cedex France

NOTE: (1) Manufacturing process "Cold stamping

(2) Lubricant: (For Government Designation **with "L") QPL-8937**

(3) **Provisions Governing Procurement. Procurement of these self locking nuts shall be In -accordance With FAR. 52.225-3 (Buy American Act)** and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include **these provisions In every subcontract and** purchase order.

MS14200 **NUT, FLOATING,** SELF-LOCKING, ATTACHED RETENTION ELEMENT (A.R.E.), 450°F, STEEL, 125 ksi Ftu, REPLACEABLE NUT ELEMENT

MS14200L04 MS14200L06 MS14200L08 MS14200L3 MS14200L4	FF 6010(L)-(4) FF 6010(l)-(6) FF 6010(L)-(8) FF 6010(L)-(10), FF 6010(1)-(12)	NADC Report 601Q8607 of 9 **Jun 1986**	Deutsch Fastener Corp. 3969 Paramount Blvd- Lakewood, CA 90712-4193 Plant: Same address

NOTE : (1) Lubricant: QPL-8937 .

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION .	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS14210 NUT, FLOATING, SELF-LOCKING, ATTACHED RETENTION ELEMENT (A.R.E.), 450°F CRES (A-286), 125 kSi Ftu, REPUCEABLE NUT ELEMENT			
MS14210L04	GFP 6010(L)-(4)	NADC Report	Deutsch Fastener Corp.
MS14210L06	GFP 6010(L)-(6)	6010607 of	3969 Paramount Blvd.
MS14210L08	GFP 6010(L)-(8)	9 Jun 1986	Lakewood, CA 90712-4193
MS14210L3	GFP 6010(L)-(10)		
MS14210L4	GFP 6010(L)-(12)		Plant: Same address
NOTE: (1) Lubricant: QPL-8937.			
MSS16228 NUT, SELF-LOCKING, HEXAGON, THIN; UNC 3B, (NONMETALLIC INSERT), AUSTENITIC, CORROSION-RESISTANT STEEL, NONMAGNETIC, 250°F			
MS16228-4C	L79NTU-420	AMD Report No.	Greer-Smyrna
MS16228-5C	L79NTU-518	MA669027 of .	A Microdot Compahy
MS16228-6C	L79NTU-616	6 Mar 1969	P.O. Box 68
MS16228-8C	L79KTU-813		Smyrna, TN 37167
MS16228-12C	L79NTU-1210	NADC Report No.	Plant: . Mayfield Dr. . Smyrna, TN 37167
MS16228-16C	L79NTU-1608 .	305Q79055 of '24 Aug 1979	
MS16228-4C	79NTU-040	AMD Report No.	Elastic Stop Nut
MS16228-5C	79NTU-058	MA669026 of	A Division of
MS16228-6C	79NTU-066	6 Mar 1969	Harvard Industriesi Inc.
MS16228-7C	79NTU-074		2330 Vauxhall Road. . .
MS16228-8C	79NTU-083		Union, NJ 07083 . .
MS16228-10C	79NTU-101		
MS16228-12C	79NTU-120		Plant: Same address and
MS16228-16C	79NTU-168		3200 Country Club Road Pocahontas, AR 72455
MS17825 NUT, SELF-LOCKING CASTELIATED, HEXAGON, 250°F, NONMETALLIC INSERT			
MS17825-4	F12NE4753-048	Report No.	Elastic Stop Nut
MS17825-5	F12NE4753-054	NAMC-AML-1571	A Division of
		of Dec 1962	Harvard Industries, Inc.
			2330 Vauxhall Road
			Union, NJ 07083.
			Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
NOTE: Manufacturing process for all nuts listed: Machined			

Source: https://assist.dla.mil -- Downloaded: 202640-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17825-3 MS17825-6	F12NE4753-02 F12NE4753-064	Report No. NAEC-AML-1583 of 17 Dec 1962	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cont'd)
NOTE: Manufacturing process for all nuts listed: Machined			
MS17825-7	F12NE4753-070	Report No. NAEC-AML-1826 of 4 Dec 1963	
NOTE: Manufacturing process: Machined.			
MS17825-8	F12NE4753-080	Report No. NAEC-AML-2016 of 20 Aug 1964	
NOTE: Manufacuring process:~ Machined			
MS17825-9 MS17825-10 MS17825-12	F12NE4753-098 F12NE4753-108 F12NE4753-126	AMD Report No. MA770504A of 25 Nov 1969	
MS17825-14	F12NE4753-144 (Machined)		
MS17825-16	F12NE4753-162		
MS17825-18	F12NE4753-182		
MS17825-20	F12NE4753-202		
MS17825-4 MS17825-5 MS17825-6	F12NEC-428 F12NEC-524 F12NEC-624	AML Report No. 78608-67 of 9 Jun 1967	Microdot Inc ~ KAYNAR Div. P.O> Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS17825-3 MS17825-8	F12NMC-1032 F12NEC-820	AMD Report No. MA768758 of 30 Nov 1967	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrna, TN 37167 Plant: Mayfield Dr. Smyrna, TN 37167
MS17825-7	F12NEC-720	AMD Report No. MA768771 Of 29 Nov 1967,	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17825-4 MS17825-5 MS17825-6	F12NEC-428 F12NEC-524 F12NEC-624	AML Report No. 78608-67 of 9 Jun 1967	Greer-Smyrna (Cont'd)
MS17825-9 MS17825-10 MS17825-12	F12NEC-918 F12NEC-1018 F12NEC-1216	NADC Report No. 305Q78043 of 12 Apr 1978	
NOTES :- (1) Locking insert': Green, nylon-zytel 101 (z) Manufacturing process: Machined			
MS17826 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, 250°F, THIN NONMETALLIC INSERT			
MS17826-4 MS17826-5 MS17826-6	F12NE4717-048 F12NE4717-054 F12NE4717-064	Report No. NAMC-AML-1523 of 27 Nov 1962	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455.'
NOTE: Manufacturing process for all 'nuts listed: Machined			
MS17826-3	F12NE4717-02	Report No. NAEC-AML-1 579 of 14 Dec 1962	
NOTE : Manufacturing process: Machined			
MS17826-7 MS17826-8	F12NE4717-070 F12NE4717-080	Report No. NAEC-AML-1932 of 9 Apr 1964	
NOTE : Manufacturing..process: Machined			
MS17826-9 MS17826-10 MS17826-12 MS17826-14 MS17826-16 MS17826-18 MS17826-20	F12NE4717-098 F12NE4717-108 F12NE4717-126 F12NE4717-144 F12NE4717-162 F12NE4717-182 F12NE4717-202	AMD Report No. MA770504B of 8 Dec 1969	
NOTE : Manufacturing process: Machined			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17826-4	F12NTEC-428	AML Report No. 78608-67 of 9 Jun 1967	Microdot, Inc. -. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS17826-3 MS17826-7 MS17826-8	F12NTMC-1032 F12NTEC-720 F12NTEC-820	AMD Report MA768771 of 29 Nov 1967	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrna, TN 37167' plant: Mayfield Dr. Smyrna. TN 37167
MS17826-5 MS17826-6	F12NTEC-524 F12NTEC-624	AMD Report No. MA768758 of 30 Nov.1967	
MS17826-4	F12NTEC-428	AML Report No. 78608-67 of 9 Jun 1967	
MS17826-9 MS17826-10 MS17826-12	F12NTEC-918 F12NTEC-1018 F12NTEC-1216	NADC Report No. 305Q78043 Of 12 Apr 1978	

NOTES : (1) Locking Insert: **Green, nylon-zytel 101**
(2) Manufacturing process: Machined

MS17828 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, (NONMETALLIC INSERT) 250°F, NICKEL-COPPER ALLOY

MS17828-4C MS17828-5C MS17828-6C MS17828-8C MS17828-10C MS17828-12C	09NE-420 09NE-518 09NE-616 09NE-813 09NE-1011 09NE-1210	AMD Report No. MA669027 0f 6 Mar 1969	Greer-Smyrna A Microdot Company.T P.O. BOX 68 Smyrna, TN 37167 Plant: Mayfield Dr. Smyrna, TN 37167

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS,
MS17828-14C	09NE-1409	Report No. MA772020 of 2 Dec 1971	Greer-Smyrna (Cent'd}
NOTE: (1) Manufacturing process: Machined (2) Lubricant: Ferrocote #348			
MS17828-16C	09NE-1608	Report No. MA772005 of 26 Jan 1972	
MS17828-18C	09NE-1807		
MS17828-20C	09NE-2007		
MS17828-22C	09NE-2206		
MS17828-24C	09NE-2406		
NOTE: (1) Manufacturing process: Machined (2) Lubricant Ferrocote #348 .			
MS17828-3C	09NM-1024	NADC Report No. 305Q79055 of 24 Aug 1979	
MS17828-28C	09NU-2805		
MS17828-32C	09NU-3204.5		
MS17828-04C	09NM-40 (Monel)	AMD Report No. MA669026 of 6 Mar 1969	Elastic Stop Nut A Division Of. Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083. Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455,
MS17828-06C	09NM-62		
MS17828-08C	09NM-82		
MS17828-3C	09NM-04		
MS17828-3F	09NM-02		
MS17828-4C	09NE-040		
MS17828-4F	09NE-048		
MS17828-5C	09NE-058		
MS17828-5F	09NE-054		
MS17828-6C	09NE-066		
MS17828-6F	09NE-064		
MS17828-7C	09NE-074U		
MS17828-7F	09NE-070U		
MS17828-8C	09NE-083		
MS17828-8F	09NE-080		
MS17828-9C	09NE-092		
MS17828-9F	09NE-098		
MS17828-10C	09NE-101		
MS17828-10F	09NE-108		
MS17828-12C	09NE-120		
MSJ7828-12F	09NE-126		
MS17828-14C	09NE-149		
MS17828-14F	09NE-144		
MS17828-16C	09NE-168		
MS17828-16F	09NE-162		
MS17828-18C	09NE-187		
MS17828-18F	09NE-182		
MS17828-20C	09NE-207		
MS17828-20F	09NE-202		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17828-22C	09NE-226 (Monel M)	AMD Report No. MA669026 of 6 Mar 1969	Elastic Stop Nut...". A Division of Harvard Industries, Inc. (Cent'd)
MS17828-22F	09NE-222		
MS17828-24C	09NE-246		
MS17828-24F	09NE-242		
MS17828-28C	09NU-285		
MS17028_32C	09NU-324		
MS17828-36C	09NU-364		
MS17828-40C	09NU-404		

NOTE: Manufacturing process: Machined or Forged

MS17829 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250"F, (NONMETALLIC INSERT), NONCORROSION-RESISTANT STEEL

MS17829-3C	F52N1610-04	AMD Report No. MA669026 of 6 Mar 1969	Elastic Stop Nut " A Division of Harvard Industries, Inc. 233,0 Vauxhall Road Union, NJ 07083. Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS17829-4C	F52N1610-040		
MS17829-4F	F52NI610-048		
MS17829-5C	F52N1611-058		
MS17829-5F	F52N1610-054		
MS17829-6C	F52N1610-066		
MS17829-6F	F52N1610-064		
MS17829-7C	F52N1610-074U		
MS17829-7F	F52N1610-070U		
MS17829-8C	F52N610-083		
MS17829-8F	F52N1610-080		
MS17829-K	F52N1610-092		
MS17829-9F	F52N1630-098		
MS17829-10C	F52N1610-101		
MS17829-10F	F52N1610-108		
MS17829-12C	F52N1610-120		
MS17829-12F	F52N161-126		
MS17829-14C	F52N610-149		
MS17829-14F	F52N1610-144		
MS17829-16C	F52N1610-168		
MS17829-16F	F52N1610-162		
MS17829-18C	F52N1610-187		
MS17829-18N08	F52N1610-1808		
MS17829-18F	F52N1610-182		
MS17829-20C	F52N1610-207		
MS17829-20N08	F52N1610-2008		
MS17829-20F	F52N1610-202		
MS17829-22C	F52N1610-226		
MS17829-22N08	F52N1610-2208		
MS17829-2ZF	F52N1610-222		
MS17829-24C	F52N1610-246		
MS17829-24N08	F52N1610-2408		
MS17829-24F	F52N1610-242		
MS17829-28C	F52NU1610-285		
MS17829-28N08	F52NU1610-2808		
MS17829-32C	F52NU1610-324		
MS17829-32N08	F52NU1610-3208		
MS17829-36	F52NU1610-364		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17829-36N08 MS17829-40C MS17829-40N08	F52NU1610-3608 F52NU161-404 F52NU1610-4008	AMD Report No. MA669026 of 6 Mar 1969	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cont'd)
NOTE: Manufacturing process: Forged or machined for 1-12 size and smaller; machined for 11/8-7 size and larger.			
MS17829-5C MS17829-8C MS17829-4C MS17829-6C MS17829-7C MS17829-10C MS17829-12C MS17829-14C MS17829-16C MS17829-20C	F52N7582-518 F52N7582-813 F52N7582-420 F52N7582-616 F52N7582-714U F52N7582-1011 F52N7582-1210 F52N7582-1409 F52N7582-1608 F52N7582-2007	AMD Report No. MA669027 of 6 Mar 1969	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrna, TN 37167 Plant: Mayfield Dr; Smyrna, TN 37167
MS17829-22C MS17829-24C	F52N7582-2206 F52N7582-2406	Report No. MA772021 of 25 May 1972	
MS17829-18C	F52N7582-1807	Report No. MA772027 Of 30 Jun 1972	
MS17829-28C MS17829-32C MS17829-36C	F52N7582-2805 F52N7582-32045 F52N7582-36045	Report No. 305Q74017 of 3 Jan 1975	
NOTE : (1) Manufacturing process: Machined (2) Lubricant: Ferrocote #348			
MS17829-9C MS17829-40C	F52N7582-912 F52N7582-4004	NADC Report No. 305Q79055 of 24 Aug 1979	
MS17830 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250°F,, (NONMETALLIC INSERT), 300 SERIES CORROSION-RESISTANT STEEL			
MS17830-4C MS17830-5C MS17830-6C MS17830-8C MS17830-10C 14S17830-12C	L79NE-420 L79NE-518 L79NE-616 L79NE-813 L79NE-1011 L79NE-1210	AND Report No. MA669027 of 6 Mar 1969	Greer-Smyrna A Microdot Company Smyrna, TN 37167 Plant: Mayfield Dr. Smyrna, TN 37167
NOTE : (1) Manufacturing process: MS17830-4C,-5C,-6C machined or cold formed, all anothers machined. (2) Locking Insert: Green Nylon			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS17830-14C MS17830-16C	L79NE-1409 L79NE-1608	NADC Report No. 305Q79055 of 24 Aug 1979	Greer-Smyrna (Cont'd)

NOTE: (1), Manufacturing process; ,Machined ,
(2) Locking Insert:' Green nylon:;

MS17830-3C	**L79NM-1024**	NADC Report No. 305Q82084 of 22 Sep 1982	

NOTE: (1) Manufacturing process: Machined
(2) Locking Insert: Green Nylon

MS17830-04C MS17830-06C MS17830-08C	L79NM-440 L79NM-632 L79NM-832	NADC Report :- 601Q8605 of 14 Mar 1986	

NOTE: (1) Manufacturing process: Machined.
(2) Locking Insert: Green- Mylon

MS17830-04C MS17830-06C MS17830-08C MS17830-3C MS17830-4C MS17830-5C MS17830-6C MS17830-7C MS17830-8C MS17830-9C MS17830-10C MS17830-12C MS1730-14C MS17830-16C MS17830-18C **MS17830-20C** **MS17830-22C** **MS17830-22F** MS17830-24C MS17830-24F- MS17830-28C MS17830-32C MS17830-36C MS17830-40C ,	79NM-40 79NM-62 79NM-82 79NM-04 79NE-040 79NE-058 79NE-066 79NE-074U 79NE-083 79NE-092 79NE-101 79NE-120 79NE-149 79NE-168 79NE-187 **79NE-207** **79NE-226** **79NE-222** 79NE-246 79NE-242 79NU-285 79NU-324 79NU-364 79NU-404	AMD Report No. **MA669026 0f** 6 Mar 1969	Elastic Stop Nut **A Divisoion of.-** Harvard Industries, Inc. 2330 VauxhaLL Road , Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455

NOTE: Manufacturing process: Forged or machined for 9/16-12 size and smaller; machined for 5/8-11 size and larger.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS20365 NUT, SELF-LOCKING, 250°F			
NOTE : (1) MS20365 Canceled. (2) See interchangeability table on MS21042, MS21044 and MS21045 for substitute parts.			
MS21040 NUT, SELF-LOCKING, 500°F, HEXAGONAL, REDUCED HEIGHT			
NOTE: (1) MS21040 Canceled. (2) See interchangeability table on MS21042 for substitute parts.			
MS21042 NUT, SELF-LOCKING, 450°F, REDUCED HEXAGON, REDUCED HEIGHT, " RING BASE, NONCORROSION-RESISTANT STEEL			
MS21042L04	RM52LH3324-40	Report No. NAMC-AML-AE 6201.40, Part VIII of 8 Dec 1959	Elastic Stop Nut A **Division of.** Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant; Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21042-04	LF52LH3324-40		
MS21042-04	F52LH3324-40		
MS21042L06	RM52LH3324-62		
MS21042-06	LF52LH3324-62		
MS21042-06	F52LH3324-62		
MS21042L08	RM52LH332-82		
MS21042-08	LF52LH3324-82		
MS21042-08	F52LH3324-82		
MS1042L3	RM52LH3324-02		
MS21042-3	LF52LH3324-02		
MS21042-3	F52LH3324-02		
MS21042L4	RM52LH3324-048		
MS21042-4	LF52LH3324-048		
MS21042-4	F52LH3324-048		
MS21042L5	RM52LH3324-054		
MS2104Z-5	LF52LH3324-054		
MS21042-5	F52LH3324-054		
MS21042L6	RM52LH3324-064		
MS21042-6	LF52LH3324-064		
MS21042-6	F52LH3324-064		
NOTE : (1) Manufacturing process for all nuts listed: Forged (2) 'RM" designates molybdenum disulphide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9{1423) of July 1959. (3) Prefix "LF" designates cadmium-plated and lubricated with Ferrocote #348 (4) Prefix "F" designates cadmium-plated with no lubrication.			
MS21042L04	RM52 H3324-40	Report No. NAMC-AML-AE 6201.40, Part XI of 13 April 1960	
MS21042-04	LF52 H3324-40		
MS21042-04	F52L H3324-40		
MS21042L06	RM52 H3324-62		
MS21042-06	LF52 H3324-62		
MS21042-06	F52L H3324-62		
MS21042L08	RM52 H3324-82		
MS21042-08	LF52 H3324-82		
MS21042-08	F52L H3324-82		
MS21042L3	RM52 H3324-02		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042-3	LF52LH3324-02	Report No. NAMC-AML-AE 6201.40, Part XI of 13 April 1960	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cent'd)
MS21042-3	F52LH3324-02		
MS21042L4	RM52LH3324-048		
MS21042-4	LF52LH3324-048		
MS21042-4	F52LH3324-048		

NOTE: (1) Manufacturing process for all nuts listed: Stamped
(2) "RM" designates molybdenum disulphide dry film lubricant as approved by NAMATCEN letter XM-621-FTR:mlp J9(1423) of 20 July 1959.
(3) prefix "LF" designates cadmium-plated and lubricated with Ferrocote #348
(4) Prefix "F" designates cadmium-plated with no lubrication.

MS21042L5	RM52LH3324-054	Report No. NAMC-AML-1540 of 31 Ott 1962
MS21042-5	LF52LH3324-054	
MS21042-5	F52LH3324-054	

NOTE : (1) Manufacturing process: Stamped
(2) RM52LH3324-054 (with molybdenum disulphide dry film lubricant).
(3) LF52LH3324-054 (with Ferrocote #348 lubricant).
(4) F52LH3324-054 (no lubrication).

MS21042LO2	RM52LH3324-26	Report No. NAEC-AML-1851 -- of 20 Dec 1963
MS21042-02	LF52LH3324-26	

NOTE : (1) Manufacturing process: Stamped
(2) RM52LH3324-26 (with molybdenum disulphide dry film lubricant).
(3) LF52LH3324-26 (with Ferrocote #348 lubricant).

MS21042LO4	H14L04	Report No. NAMC-AML-AE 6201.40, Part XXI of 9 May 1961	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21042-04	H14L04CW		
MS21042-04	H14LX04		
MS21042LO6	H14L06		
MS21042-06	H14L06CW		
MS21042-O6	H14LX06		
MS21042LO8	H14L08		
MS21042-O8	H14L08CN		
MS21042-O8	H14LX08		

MS21042L3	H14-3	Report No. NAMC-AML-AE 6201.40, Part IX of 8 Dec 1959
MS21042-3	H14X3	
MS21042-3	H14-3CW	
MS21042L4	H14-4	
MS21042-4	H14X4	
MS21042-4	H14-4CW	
MS21042L5	H14-5	
MS21042-5	H14X5	

Source: https://assist.dla.mil -- Downloaded: 20240820T18:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042-5	H14-5CH	Report No. NAMC-AML-AE 6201.40, Part IX of 8 Dee 1959	Microdot, Inc. (Cent'd)
MS21042L6	H14-6		
HS21042-6	H14X6		
MS21042-6	H14-6CM		

NOTE : (1) Manufacturing process for all nuts listed: Forged
(2) Molybdenum disulphide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 Mar 1959.
(3) "CW" suffix in the Kaynar P/N designates lubricated with Kaywax which consists of a synthetic wax, corrosion inhibitor and an aromatic solvent.
(4) "X" designates cadmium-plated with no lubrication.

MS21042LO2	H14L02	Report No. NAEC AML-1743 of 29 Aug 1963	
MS21042-O2	H14L02CH		

NOTE : (1) Manufacturing process: Forged
(2) H14L02 (with molybdenum disulfide dry film lubricant).
(3) H14L02CW (with Kaywax lubricant).

MS21042LO4	EH14-L04	NADC Report No. 601Q8705 of 20 May 198?	Microdot Aerospace Limited Blackthorne Road Colnbrook, Slough SL3 OAG England
MS21042LO6	EH14-L06		
MS21042LO8	EH14-L08		
MS21042L3	EH14-3		
MS21042L4	EH14-4		
MS21042L5	EH14-5		Plant: Same Address

NOTE : (1) Manufacturing process: Forged
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement;. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference. for Domestic Specialty Metals). The contractor should Include these provisions In every subcontract and purchase order.

MS21042L04	FN12M-40	Report No. NAMC-AML-AE 6201.40, Part VII of 8 Dec 1959	SPS Technologies Highland Ave. Jenkintown, PA 19046
MS21042-O4	FN12A-40		
MS21042-04	FN12X-40		
MS21042L06	FN12M-62		
MS21042-O6	FN12A-62		Plant: Same address
MS21042-06	FN12X-62		
MS21042L08	FN12M-82		
MS21042-O8	FN12A-82		
MS21042-O8	FN12X-82		
MS21042L3	FN12M-02		
MS21042-3	FN12A-02		
MS21042-3	FN12X-02		
MS21042L4	FN12M-048		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042-4	FN12A-048	Report No. NAMC-AML-AE 6201.40, Part VII of 8 Dec 1959	SPS Technologies (Cent'd)
MS21042-4	FN12X-048		
MS21042L5	FN12M-054		
MS21042-5	FN12A-054		
MS21042-5	FN12X-054		
MS21042L6	FN12M-064		
MS21042-6	FN12A-064		
MS21042-6	FN12X-064		

NOTE: (1) Manufacturing process for all nuts listed: Forged
(2) Molybdenum disulphide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp (1428) of 29 July 1959.
(3) The FN12A series is cadmium-plated and lubricated with Carbo Wax.
(4) The FN12X series is cadmium-plated with no lubricant.
(5) The FN12M series is molybdenum disulphide lubricated.

MS21042L3	VN300-A-02	Report No. NAMC-AML-AE 620] .40, Part XV of 5 Aug 1960	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21042-3	VN300-C-02		
MS21042-3	VN300-CN-02		
MS21042L4	VN300-A-048		
MS21042-4	VN300-C-048		
MS21042-4	VN300-CN-048		

NOTE: (1) Manufacturing process for all nuts listed: Forged
(2) Molybdenum disulphide dry film lubricant designation "A" approved by NAMATCEN ltr XM-621:FTR:mlp J9(1421) of 20 July 1959.
(3) Cadmium-plated parts designated "C" are lubricated with Carbo Wax.
(4) "CN" designates cadmium-plated having no lubrication.

MS21042LO8	VN300-A-82	Report No. NAMC-AML-1348 of 2 Jan 1962
MS21042-O8	VN300-C-82	
MS21042-O8	VN300-CN-82	

NOTE : (1) Manufacturing process for all nuts: Forged
(2) Molybdenum disulphide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp 10410 (2510) of 9 February 1960.
(3) The "C" series is cadmium-plated, and lubricated with Carbo Wax.
(4) The "CN" series is cadmium-plated with no lubrication.

MS21042LO6	VN300-A-62	Report No. NAEC-AML-1686 of 29 May 1963
MS21042-O6	VN300-C-62	
MS21042-O6	VN300-CN-62	

NOTE : (1) Manufacturing process: Forged
(2) Molybdenum disulphide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp(2510) of 9 February 1960.
(3) The "C" series is cadmium-plated and lubricated with 11 Carbo Max.
(4) The "CR" series is cadmium-plated with no lubrication.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042L04	VN300-A-40	Report No.	VOI-SHAN
MS21042-O4	VN300-C-40	NAMC-AML-1569	(Cent'd)
MS21042-04	VN300-CN-40	of 7 Dec 1962	

NOTE : (1) Manufacturing process for all nuts: Forged
(2) The "A" series is cadmium-plated, and lubricated with molybdenum disulphide as approved by NAVAIRMATCEN ltr XM-621-FTR:mlp 10410(2510) of 9 February 1960-
(3) The "C" series is cadmiun-plated, and lubricated with Carbo Max.
(4) The "CN" series is cadmium-plated with no lubrication.

MS21042LO6	T97S632	Report No. NAMC-AML-AE 6201.40, Part XXII of 10 Aug 1961	Cherry, Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Warner Ave. Santa Ana, CA 92707-0157 Plant: Same address
MS21042-O6	T97S632 CPF		
MS21042-O6	T97S632 CPC		
MS21042LO8	T97S832		
MS21042-O8	T97S832 CPF		
MS21042-08	T97S832 CPC		
MS21042L3	T97S1032		
MS21042-3	T97S1032 CPF		
MS21042-3	T97S1032 CPC		
MS21042L4	797S428		
MS21042-4	T97S428 CPF		
MS21042-4	T97S428 CPC		
MS21042L5	T97S524		
MS21042-5	T97S524 CPF		
MS21042-5	T97S524 CPC		
MS21042L6	T97S624		
MS21042-6	T97S624 CPF		
MS21042-6	T97S624 CPC		

NOTE : (1) Manufacturing process forged for MS21042L04 and MS21042-O4.
(2) Manufacturing process for all other nuts: Machined
(3) Molybdenum disulphide dry film lubricant as approved by NAPVITCEN ltr XM-621-FTR:mlp 10410(2510) of 9 Feb 1960.
(4) The CPF series is cadmium-plated and lubricated with Ferrocote.
(5) The CPC series is cadmium-plated with no lubricant.

MS21042L04	T98S440	AML Report No.
MS21042-04	T98S440 CPF	78569-67 of
MS21042-O4	T98S440 CPC	17 Mar 1967

MS21042LO6	T98S632	Report No. NAMC-
MS21042-06	T98S632 CPF	AML-1313 of
MS21042-O6	T98S632 CPC	16 Nov 1961
MS21042L3	T98S1032	
MS21042-3	T98S1032 CPF	
MS21042-3	T98S1032 CPC	

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042L4 MS21042-4 MS21042-4	T98S428 T98S428 CPF T98S428 CPC	Report No. NAMC-AML-1313 of 16 Nov 1961	Cherry Textron, Cherry Aerospace Operation (Cont'd)
MS21042LO8 MS21042-O8 MS21042-O8	T98S832 T98S832 CPF T98S832 CPC	Report No. NAEC-AML-1554 of 7 Feb 1963	
MS21042-5 MS21042L5 MS21042L6 MS21042-6 MS21042-6	T98S524 CPF T98S524 T98S624 T98S624 CPF T98S624 CPC	AMD Report No. MA768806 of 30 Jan 1969	
MS21042LO2 MS21042-O2	T98S256 T98S256 CPC	NADC Report No. 305Q82074 of 29 Mar 1982	
MS21042-O6 MS21042LO6 MS21042-O8 MS21042LO8 MS21042-3 MS21042-4	MN16-06 MN16PJ-06 MN16-08 MN16PJ-08 MN16-3 MN16-4	NADC Report No. 305Q77035 of 30 March 1977	Hi-Shear Corp. 2600 Skypark Drive Torrance, CA 90509 Plant: Same address
MS21042-O6 MS21042LO6 MS21042-O8 MS21042LO8 MS21042-3 MS21042L3 MS21042-4	BH21042-O6 BH21042LO6 BH21042-O8 BH21042LO8 BH21042-3 BH21042L3 BH21042-4	NADC Report No. 305Q79052 of 30 Jul 1979	Bristol Industries 630 E. Lambert Road P.O. BOX 630 Brea, CA 92621 Plant: Same address

NOTE : (1) Manufacturing process for all nuts: Forged
(2) Molybdenum disulphide dry film lubricant as approved by NAMC ltr XF1-621-FTR:mlp 10410 0f 9 Feb 1960.
(3) The CPF series is cadmium-plated and lubricated with Ferrocote.
(4) The CPC series is cadmium-plated with no lubricant.

NOTE: (1) Manufacturing process: Forged
(2) T98S832 is cadmium-plated, and lubricated with molybdenum disulphide as approved by NAMATCEN ltr XM-621-FTR:mlp 10410(2510) of 9 February 1960.
(3) 198S832 CPF is cadmium-plated, and lubricated with Ferrocote.
(4) 198S832 CPC is cadmium-plated with no lubrication.

NOTE : Manufacturing process: Forged

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042L4 MS21042-5 MS21042L5 MS21042-6 MS21042L6	BH21042L4 BH21042-5 BH21042L5 BH21042-6 BH21042L6	NADC Report No. 305Q79052 of 30 Jul 1979	Bristol Industries (Cent'd)
MS21042-O4 MS21042LO4	BH21042-O4 BH21042LO4	NADC Report No. 305Q80061 Of 17 Nov 1980	
MS21042L3 MS21042L4	PLH-353M PLH-354M	Report No. 305Q8310l of 5 May 1983	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670
MS21042L04	PLH-3504M	Report No. 305Q83111 of 19 Ott 1983	Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152. Suresnes Cedex - France
MS21042L5	PLH-335M	Report No. 305Q83112 of 28 Nov 1983	
MS21042-O4 MS21042-O6 NS21042LO6 MS21042-O8 MS21042LO8 MS21042-3 MS21042-4 MS21042-5	PLH-3504 PLH-3506 PLH-3506M PLH-3508 PLH-3508M PLH-353 PLH-354 PLH-355	Report No. 601Q8401 of 24 Feb 1984	
MS21042-6 MS21042L6	PLH-356 PLH-356M	Report No. 601Q8407 of 20 Apr 1984	

NOTE: (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in' accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21042-02 MS21042L02	PLH-3502 PLH-3502M	NADC Report 601Q8505 of 30 May 1985	Simmonds Fastener

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Speciaity Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21042-08 MS21042-08 MS21042L08 MS21042-3 MS21042-3 MS21042L3 MS21042-4 MS21042-4 MS21042L4 MS21042-5 MS21042-5 MS21042L5 MS21042-6 MS21042-6 MS21042L6	RH30X08 RH30X08CW RH30A08 RH30X3 RH30X3CH RH30A3 RH30X4 RH30X4CW RH30A4 RH30X5 RH30X5CN RH30A5 RH30X6 RH30X6CN RH30XA6	NADC Report 601Q8503 of 8 Apr 1985	Republic Fastener Manufacturing Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address

NOTE : (1) Manufacturing process: Forged
(2) "CW" denotes CARBO WAX
(3) "X" denotes Cadmium Plating
(4) "'A" denotes Dry Film Lubricant

MS21043 NUT, SELF-LOCKING, 800°F, REDUCED HEXAGON, REDUCED HEIGHT, RING BASE, CORROSION-RESISTANT STEEL

MS21043-04 MS21043-06 MS21043-08 MS21043-3 MS21043-4 MS21043-5	T99C440 T99C632 T99C832 T99C1032 T99C428 T99C524	Report No. NAMC-ANL-AE 6201.40, Part XVII of 10 May 1961	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. BOX 2157 1224 East Warner Ave. Santa Ana, CA 92707-0157 Plant: Same address

NOTE: Manufacturing process for all nuts listed: Machined

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	NANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21043-06 MS21043-3 MS21043-4	T99C632 T99C1032 T99C428	Report No. NAMC-AML-1416 of 23 Apr 1962	Cherry Textron, Cherry Aerospace Operation, (Cent'd)
NOTE : Manufacturing process for all nuts listed: Forged			
MS21043-08	T99C832	Report No. NAMC-AML-1556 of 27 Nov 1962	
NOTE : Manufacturing process: Forged			
MS21043-04 MS21043-5	T99C440 T99C524	AMD Report No. MA768806 of 30 Jan 1969	
NOTE: Manufacturing process: Forged			
MS21043-6	T99C624	Report No. 305Q73008 of 29 Aug 1973	
NOTE : (1) Manufacturing process: Forged (2) Lubrication: None (3) Plating: Silver			
MS21043-04 MS21043-06 MS21043-08 MS21043-3 MS21043-4 MS21043-5 MS21043-6	LH3858-40 LH3858-62 LH3858-82 LH3858-02 LH3858-048 LH3858-054 LH3858-064	Report No. NAMC-AML-AE 6201.40, Part XVIII of 9 May 1961	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road. Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
NOTE : Manufacturing process for all nuts listed: Forged			
MS21043-04 MS21043-06 MS21043-08 MS21043-3	LH3858-40 LH3858-62 LH3858-82 LH3858-02	Report No. NAMC-AML-1412 of 19 Apr 1962	
NOTE : Manufacturing process for all nuts listed: Stamped			

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21043-04 MS21043-06 MS21043-08 MS21043-3 MS21043-4 MS21043-5 MS21043-6	FN1014-440 FN1014-632 FN1014-832 FN1014-1032 FN1014-428 FN1014-524 FN1014-624	Report No. NAMC-ANL-AE 6201.40, Part XIX of 9 May 1961	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address
NOTE: Manufacturing process for all nuts listed: Forged			
MS21043-04 MS21043-06 MS21043-08 MS21043-3 MS21043-5 MS21043-6	H41L-04 H41L-06 H41L-08 H41-3 H41-5 H41-6	Report No. NAMC-AML-AE 6201.40, Part XXIII of 29 Jun 1981	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
NOTE: Manufacturing process for all nuts listed: Forged			
MS21043-4	H41-4	Report No. NAMC-AML-AE 6201.40, Part XX of 10 May 1961	
NOTE : Manufacturing process for all nuts listed: Forged			
MS21043-06 MS21043-3	EH41-L06 EH14-3 EH14-L08	NAOC Report No. 601Q8705 of 20 May 1987	Microdot Aerospace Limited Blackthorn Road Colnbrook, Slough SL3 OAG England Plant: Same Address

NOTE : (1) Manufacturing process: Forged
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21043-3 MS21043-4	VN300-B-02 VN300-B-048	Report No. NAMC-AML-1408 of 26 Mar 1962	VOI-SHAN VSI Aerosp. Prod, Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
NOTE : Manufacturing process for both nuts listed: Forged			
MS21043-O8	VN300-B-82	Report No. NAEC-AML-1687 of 29 May 1963	
NOTE : Manufacturing process: Forged			
MS21043-O4 MS21043-06 MS21043-O8 MS21043-3	MN-19-04 MN-19-06 MN-19-08 MN-19-3	NADC Report No. 305Q76025 of 15 0ct 1976	Hi-Shear Corp. 2600 Skypark Dr. Torrance, CA 90509 Plant: Same address
NOTE : Nuts are forged.			
MS21043-O6 MS21043-O8 MS21043-3 MS21043-4 MS21043-5 MS21043-6	BH21043-O6 BH21043-O8 BH21043-3 BH21043-4 BH21043-5 BH21043-6	NADC Report No. 305Q79052 of 30 Jul 1979	Bristol Industries 630 E. Lambert Road P.O. B0X 630 Brea, CA 92621 Plant: Same address
MS21043-O4	BH21043-O4	NADC Report No. 305Q80061 of 17 Nov 1980	
MS21043-O8 MS21043-3 MS21043-4 MS21043-5 MS21043-6	RH30C08 RH30C3 RH30C4 RH30C5 RH30C6	NADC Report 601Q8503 of 8 Apr 1985	Republic Fastener Manufacturing Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
NOTE : (1) Manufacturing process: Forged			

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21043-04	PLH-504	NADC Report No. 305Q3111 of 19 Oct 1983	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France
MS21043-06	PLH-506		
MS21043-3	PLH-53		
MS21043-4	PLH-54		
MS21043-5	PLH-55	Report No. 305Q83112 of 28 Nov 1983	
MS21043-08	PLH-508	Report No. 601Q8401 of 24 Feb 1984	
MS21043-6	PLH-56	Report No. 601Q8417 of 25 Oct 1984	

NOTE : (1) Manufacturing **Process:** Cold formed
(2) Lubricant: (For Government Desgnation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and OFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every **subcontract** and purchase order.

MS21044 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 250°F, 125 ksi Ftu - AND 60 ksi Ftu

MS21044N04	F22NM-40	AMD Report No. MA769358 of 7 Feb 1969	Abbott Interfast Corp 190 Abbott Drive - Wheeling, IL 60090 Plant: Same address
MS21044N06	F22NM-62		
MS21044N08	F22NM-82		
MS21044N3	F22NM-02		
MS21044N4	F52NE-048		
MS21044N5	F52NE-054		
MS21044N6	FS2NE-064		
MS21044N7	F52NE-070U		
MS21044N8	F52NE-080		
MS21044N9	F52NE-098		
MS21044N10	F52NE-108		
MS21044N12	F52NE-126		
MS21044N14	F52NE-144		
MS21044N16	F52NE-162		

NOTE: (1) Manufacturing process: Machined or forged
(2) Material: Zytel 101 (yellow color).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044-NO4 MS21044-N06	F22NM-40 F22NM-62	Report No. NAEC-AML-2561 of 11 Jan 1967	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
NOTE: Manufacturing process: Machined			
MS21044-NO8 MS21044-N3 MS21044-N4 MS21044-N5 MS21044-N6	F22NM-82 F22NM-02 F42NE-048 F42NE-054 F52NE-064	Report No. NAEC-AML-2561 of 11 Jan 1967	
NOTE: Manufacturing process for all nuts listed: Forged or machined			
MS21044-N7 MS21044-N8 MS21044-N9 MS21044-N10 MS21044-N12 MS21044-N14 MS21044-N16 NOTE: Manufacturing process: Forged or machined MS21044-N18 MS21044-N20	F52 NE-070U F52 NE-080 F52 NE-098 F52 NE-108 F52 NE-126 F52 NE-144 F52 NE-162 F52 NE-182 F52 NE-202	Report No. NAMC-AML-1496 of 9 Aug 1962	
MS21044N1O	F52CE-108	Report No. 305Q81O67 of 25 Nov 1981	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083
NOTE: Manufacturing process: Forged			Plant: Same address
MS21044C4 MS21044C5 MS21044C6 MS21044C8	79CE-048 79CE-054 79CE-064 79CE-080	Report No. 305Q83100 of 1 Apr 1983	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083
NOTE : Manufacturing process: Formed			Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044-BO4	Y92NM-40	Report No. NAMC-AML-1496 of 9 Aug 1962	Elastic Stop Nut A Divisionof Harvard Industries, Inc. (Cent'd)
MS21044-BO6	Y92NM-62		
MS21044-BO8	Y92NM-82		
MS21044-B3	Y92NM-02		
MS21044-B4	Y92NE-048		
MS21044-B5	Y92NE-054		
MS21044-B6	Y92NE-064		
MS21044-B7	Y92NE-070U		
MS21044-B8	Y92NE-080		
MS21044-B9	Y92NE-098		
MS21O44-B1O	Y92NE-108		
MS21044-B12	Y92NE-126		
MS21044-B14	Y92NE-144		
MS21044-B16	Y92NE-162		
MS21044-B18	Y92NE-182		
MS21044-B2O	Y92NE-202		
MS21044-DO4	NMJ-40		
MS21044-DO6	NMJ-52		
MS21044-DO8	NMJ-82		
MS21044-D3	NMJ-02		
MS21044-D4	NMJ-048		
MS21044-D5	68NE-054		
MS21044-D6	68NE-064		
MS21044-D7	68NE-070U		
MS21044-D8	68NE-080		
MS21044-D9	68NE-098		
MS21044-D1O	68NE-108		
MS21044-D12	68NE-126		
MS21044-D14	68NE-144		
MS21044-D16	68NE-162		
MS21044-D18	68NE-182		
MS21044-D2O	68NE-202		
MS21044-EO8	1804-82		
MS21044-E3	1804-02		
MS21044-E4	1804-048		
MS21044-E5	1804-054		
MS21044-E6	1804-064		
MS21044-E7	1804-070U		
MS21044-E8	1804-080		

NOTE : Manufacturing process for all nuts listed: Machined

MS21044CO4	79NM-40	Report No. NAEC-AML-1860 of 10 Feb 1964	
MS21044CO6	79NM-62		
MS21044CO8	79NM-82		
MS21044C3	79NM-02		
MS21044C4	79NE-048		
MS21044C5	79NE-054		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044C6 MS21044C7 MS21044C8 MS21044C9	79NE-064 79NE-070U 79NE-080 79NE-098	Report No. NAMC-AML-1860 of 10 Feb 1964	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cent'd)

NOTE : (1) Manufacturing process: Forged or machined
(2) All parts are passivated plus Ferrocote #348.

MS2JO44C1O MS21044C12 MS21044C14 MS21044C16 MS21044CI8 MS21044C20	79NE-108 79NE-126 79NE-144 79NE-162 79NE-182 79NE-202	Report No. NAEC-ML-2075 of 12 Nov 1964	

NOTE: Manufacturing process: Machined

MS21044BO6 MS21044B6 MS21044B7	Y92NM-632 Y92NE-624 Y92NE-720U	Report No. NAEC-AML-1918 of 30 Mar 1964 and NAEC-AML ltr M-62-BRS 1041O(77O1) of 13 Apr 1966	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrnai TN 37167 Plant: Mayfield Dr. " Smyrna, TN 37167

NOTE: Manufacturing process: Machined

MS21044B8	Y92NE-820	Report No. NAEC-AML-2269 of 3 Sep 1965	

NOTE : Manufacturing process: Machined

MS21044-CO6 MS21044-BO8 MS21044-N7 MS21044-N8	L79NM-632 Y92NM-832 F52NE-720U F5ZNE-820	Report No. NAEC-AML-1935 of 24 Apr 1964	

NOTE : Manufacturing process: Machined

MS21044-NO8 MS21044-D4 MS21044-B5 MS21044-D5 MS21044-N5 MS21044-N6	F22NM-832 NMJ-428 Y92NE-524 68NE-524 F42NE-524 F52NE-624	Report No. NAEC-AML-1941 of 4 May 1964	

NOTE: Manufacturing process: Machined

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044-N12 MS21044-N1O MS21044-N9 MS21044-D6	F52NE-1216 F52NE-1OI8 F52NE-918 68NE-624	Report No. NAEC-AML-2086 of 25 Nov 1964	Greer-Smyrna (Cent 'd)
NOTE: Manufacturing process: Machined ,			
MS21044N3 MS21044N4 MS21044N5 MS21044N6	**F22NN-1032 F42NE-428 F42NE-524 F52NE-624**	**Report No". NAEC-AML-2480 of 5 Jul 1966**	
NOTE: Manufacturing process: Machined			
MS21044N14	F52NE-1414	AML Report No. 78496-67 of 15 Sep 1966	
MS210 44-N04 MS210 44-D04 MS210 44-B04 MS210 44-C04 MS210 44-N06 MS210 44-D06 MS210 44-N3 MS210 44-D3 MS210 44-B3 MS210 44-C3 MS210 44-N4 MS210 44-B4 MS210 44-C4	F22NM-440 NMJ-440 Y92NM-440 L79NM-440 F22NM-632 NMJ-632 F22NM-1032 NMJ-1032 Y92NM-1032 L79NM-1032 F42NE-428 Y92NE-428 L79NE-428	Report No.. NAEC-AML-1777 of 25 Oct 1963 and NAEC-AML ltr M-62-BRS 10410(7701) of 13 Apr 1966	
NOTE: Manufacturing process: Machined			
MS21044D08	NMJ-832	Report No. NAEC-ANL-2457 of 10 May 1966	
NOTE: Manufacturing process: Machined			
MS21044D8	68NE-820	Report No. NAEC-AML-1866 of 3 Feb 1964	
NOTE : Manufacturing process: Machined			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044C08	L79NM-832	Report No. NAEC-AML-1916 of 18 Mar 1964	Greer-Smyrna (Cont'd)
NOTE : Manufacturing process: Machined			
MS21044D7	68NE-720U	Report No. NAEC-AML-1908 of 18 Mar 1964	
NOTE: Manufacturing process: Machined			
MS2 1044G5 MS2 1044C6 MS2 1044C8 MS2 1044C1O MS2 1044C12 MS2 1044N16 MS2 1044N20	L79NE-524 L79NE-624 L79NE-820 L79NE-1018 L79NE-1216 F52NE-1612 F52NE-2012	NADC Report No. 305Q79055 of 24 Aug 1979	
MS21044D1O	68NE-1018	AML Report No. 78601-67 of 24 May 1967	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21044 H04 MS21044 H06 MS21044 H08 MS21044 H3 MS21044 H4 MS21044 H5 MS21044 H6 MS21044 H8 MS21044 H9 MS21044 H1O MS21044 H12 MS21044 H14	75FS-440 75FS-632 75FS-832 75FS-1032 75FS-428 75FS-524 75FS-624 75FS-820 75FS-918 75FS-1018 75FS-1216 75FS-1414	Report No. NAEC-AML-1774 of 31 Oct 1963	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address
NOTE : Manufacturing process: Machined			
MS21044N5 MS21044N6	PA0524-SCN3 PA0624-SCN3	AML Report No. 78373-66 of 1 July 1965	
NOTE: Manufacturing process: Machined			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21044-N04 MS21044-NO6 MS21044-NO8 MS21044-N3 MS21044-N4	PA0440-SCN3 PA0632-SCN3 PA0832-SCN3 PA1032-SCN3 PA0428-SCN3	Report No. NAEC-AML-1834 of 11 Dec 1963 and NAEC-AML ltr M-62-BRS:ma 10410(7052) of 25 May 1966	SPS Technologies (Cent'd)

NOTE : Manufacturing process: Machined

MS21045 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 450°F, 125 ksi Ftu

MS21045LO4 MS21045LO6 MS21045LO8	H55-04 H55-06 H55-08	Report No. NAEC-AML-1605 of 6 Feb 1963	Microdot, Inc. KAYNAR **Div.** P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21045L3 MS21045L4	H55-3 H55-4	Report No. NAEC-AML-1671 of 10 May 1963	

NOTE : **(1)** Manufacturing process for all nuts: Forged
(2) Molybdenum disulphide dry film lubricant as approved by **BUAER** ltr AER-AE-6337/25 of 2 March 1959.

MS21045CO8 MS21045C5	H57-08 H57-5	Report No. NAEC-AML-1892 of 24 Apr 1964
MS21045CO+ MS21045CO6	H57-04 H57-O6	Report No. NAEC-AML-1931 of 24 Apr 1964

NOTE : (1) Manufacturing process: Forged
(2) Lubricant: Molybdenum disulphide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 March 1959.

MS21045C3 MS21045C4	H57-3 H57-4	Report No. NAEC-AML-1990 of 6 Jul 1964

NOTE : (1) Manufacturing process: Forged
(2) Lubricant: Molybdenum disulphide dry film lubricant as approved by BUAER ltr AER-AE-6337/25 of 2 March 1959.

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045-04 MS21045-06 MS21045-08 MS21045-3 MS21045-4	H55-04CW H55-06CW H55-08CW H55-3CW H55-4CW	Report No. NAEC-AML-1998 of 3 Aug 1964	Microdot, Inc. KAYNAR Div. (Cent'd)
NOTE : (1) Manufacturing process: Forged (2) Lubricant: KayWax.			
MS21045-10	H55-10CW	AML Report No. 78601-67 of 24 May 1967	
MS21045-8	H55-8CW	AMD Report No. MA769434B of 4 Mar 1970	
NOTE : (1) Forged. (2) "CW" : Cad Plated and Kaywax added.			
MS21045L5(4)(2) MS21045-5(2)(3) MS21045L6(2)(4) MS21045-6(3)(2) MS21045L7(1)(4) MS21045C6(5)(1)	H55-5 H55-5CW H55-6 H55-6CW H55-7 H57-6	AMD Report No. MA769434A of 19 Feb 1970	
NOTE : (1) Machined. (2) Forged. (3) "CW" : Cad plated with Kaywax. (4) Cad plated with Kaylube. (5) Kaylube only.			
MS21045-04 MS21045-06 MS21045-08 MS21045-3 MS21045-4 MS21045-5 MS21045-6 MS21045-7 MS21045-8 MS21045-9 MS21045-10 MS21045-12 MS21045-14	27FH-440 27FH-632 27FH-832 27FH-1032 27FH-428 27FH-524 27FH-624 27FH-720UN 27FH-820 37FH-918 37FH-1018 37FH-1216 37FH-1414	Report No. NAMC-AML-1567 of 3 Dec 1962	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045-16	37FH-1612	Report No.	SPS Technologies
MS21045-18	37FH-1812	NAMC-AML-1567	(Cent'd)
MS21045-2O	37FH-2012	of 3 Dec 1962	
MS21045C04	58FH-440	Report No	
MS21045C06	58FH-632	NAEC-AML-2112	
MS21045C08	58FH-832	of 4 Jan 1965	
MS21045C3	58FH-1032		
MS21045C4	58FH-428		
MS21045C5	58FH-524		
MS21045C6	58FH-624		
MS21045L5	SPS28GH-524	AMD Report No. MA769379 of 7 Feb 1969	
MS21045L8	SPS28GH-820		
MS21045L4	SPS28GH-428	AMD Report No. MA669025 of 25 Feb 1969	
MS21045-O4	27GH-440	AMD Report No. MA796417 of 17 Jul 1969	
MS21045-O6	27GH-632		
MS21045-08	27G H-832		
MS21045-3	27GH-1032		
MS21045-4	27GH-428		
MS21045-5	27GH-524		
MS21045-6	27G H-624		
MS21045-7	27G H-720		
MS21045-8	27G H-820		

NOTE : Manufacturing process for all nuts listed: Machined

NOTE : (1) Manufacturing process: Machined
(2) Molybdenum disulphide dry film lubricant as previously approved by NAMATCEN ltr XM-621-FTR:mlp of 29 July 1959.

NOTE : (1) Manufacturing process: Machined
(2) Molybdenum disulfide dry film lubricant as approved by NAVMATCEN ltr XM-621-FTR:mlp.

NOTE : Manufacturing process: Machined or forged

NOTE : (1) Manufacturing process: Machined or forged
(2) Cadmium plated.

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045C12 MS21045L12	58FH-1216 38FH-1216	Report No. 305082073 of 18 Feb 1982	SPS Technologies (Cent'd)
NOTE: Manufacturing process: Forged for MS21045L12, machined for others			
MS21045L16	38FH-1612	Report No. 305Q831O7 of " 1 Sep 1983	
NOTE: Manufacturing process: Machined			
MS21045-O4 MS21045-O6 MS21045-O8 MS21045-3 MS21045-4 MS21045-5 MS21045-6 MS21045-I MS21045-8 MS21045-9 MS21045-10 MS21045-12 MS21045-14 MS21045-16	F 1801-40 F 1801-62 F 1801-82 F 1801-02 F 1801-048 F 1801-054 F 1801-064 F 1801-070U F 1801-080 F 1801-098 F 1801-108 F 1801-126 F 1801-144 F 1801-162	Report No. NAMC-AML-1514 of 3 Dec 1962	Elastic stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road " Pocahontas, AR 72455
NOTE : Manufacturing process for all nuts listed: Machined			
MS21045L04 MS21045LO6 MS21045L08 MS21045L3 MS21045L4 MS21045L5 MS21045L6 MS21045L7 MS21045L9 MS21045L1O MS21045L12 MS21045L14 MS21045L16	RM1801-40 RM1801-62 RM1801-82 RM1801-02 RM1801-048 RM1801-054 RM1801-064 RM1801-070U RM1801-098 RM1801-108 RM1801-126 RM1801-144 RM1801-162	Report No. NAEC-AML-2467 of 2 Jun 1966	

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045CO8 MS21045C3 MS21045C4 MS21045C5 MS21045C6	SM1813-82 SM1813-02 SM1813-048 SM1813-054 SM1813-064	Report No. NAEC-AML-1886 of 19 Feb 1964	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cent'd)

NOTE: (1) Manufacturing process: Machined
(2) All parts are passivated plus molybdenum disulphide (ESNALUBE 382).

MS21045-8 MS21045L8 MS21045C8	F52VE-080 RM52VE-080 RM79VE-080	AML Report No. 78468-67 of 4 Apr 1967	
MS21045C3 MS21045C4 MS21045C5	SMLH1813-02 SMLH1813-048 SMLH1813-054	AMD Report No. MA669013 of 21 Nov 1968	Elastic Stop Nut A **Division Of** Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant:- Same **address** "

NOTE: (1) Finish: Passivated plus Moly (ESNALUBE 382).
(z) Manufacturing process: Forged

MS21045C7 MS21045C8 MS21045C9[8] MS21045C1O	SM1813-07OU SM1813-080 SM1813-098 SM1813-108	AMD Report No. MA669030 of 21 **NOV** 1968	

NOTE : (1) Manufacturing process: Machined or forged
(2) Passivated plus molybdenum disulfide (ESNALUBE 382)

MS21045-08 MS21045-6 MS21045-7 MS21045LO8 MS21045L6 MS21045L7 MS21045CO8	LFLH 1801-82 (Machined) LFLH 1801-064 LFLH 1801-070U RMLH 1801-82 RMLH 1801-064 (Forged) RMLH 1801-070U SMLH 1813-82 (Forged)	AMD Report No. MA770504A of 25 Nov 1969	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045L3 MS21045L4 MS21045L5 MS21045-3 MS21045-4 MS21045-5	RMLH1801-02 RMLH1801-048 RMLH1801-054 LFLH1801-02 LFLH1801-048 LFLH1801-0S4	Report No. NAEC-AML-2060 of 3 Nov 1964	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Rd. Union, NJ 07083 Plant: Same address and 3200 Country Club Rd. Pocahontas, AR 72455
NOTE: (1) Manufacturing process: Forged or machined " (2) RM prefix designates molybdenum disulphide dry film lubricant. (3) LF prefix designates Carbowax.			
MS21045L8	RM1801-080	Report No. NAEC-AML-2203 of 24 May 1965	
NOTE: (1) Manufacturing process: Machined (2) "RM" designates molybdenum disulphide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1423) of 20 July 1959.			
MS21045-4 MS21045-5 MS21045-6 MS21045-7 MS21045-8	YE3180 YE3181 YE3182 YE3183 YE3184	Report No. NAEC-AML-1896 of 25 Feb 1964	RB&W Corporation 5970 Heisley Rd. Mentor, OH 44060 Plant: 800 Mogadore Rd. Kent, OH 44240
NOTE : (1) Manufacturing process: Machined (2) Lubricant: Ferrocote #348			
MS21045-4 MS21045-5 MS21045-6 MS21045-7 MS21045-8	YE3180 YE3181 YE3182 YE3183 YE3184	Report No. NAEC-ANL-78418-66 of 10 Oct 1966	
NOTE : (?) Manufacturing process: Cold forged (2) Lubrication: Ferrocote #348			
MS21045-9 MS21045-10 MS21045-12 MS21045-14	YE3185 YE3186 YE3187 YE3188	AML Report" No. 78397-66 of 24 Feb 1966	
NOTE : (1) Manufacturing process: MS21045-9 machined or cold forged. All others machined. (2) Lubrication: Ferrocote #348			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NANE AND ADDRESS
MS21045-3	YE3179	AMD Report No. MA768792 of 12 Dec 1967	RB&W Corporation (Cent'd)
NOTE: (1) Manufacturing process: Cold forged (2) Lubricant: Ferrocote #348			
MS21045C3	YE3219	AMD Report No. MA768848 of 19 Jun 1968	
MS21045C4	YE3220		
MS21045C5	YE3221		
MS21045C6	**YE3222**		
MS21045C7	**YE3223**		
MS21045C8	**YE3224**		
NOTE : (1) Manufacturing process: Machined (2) Lubricant: Dry Film- "VYDAX""AR"			
MS21045L3	YE3199	AMD Report No. MA770517 of 18 Dec 1970	
MS21045L4	YE3200		
MS21045L5	YE3201		
MS21045L6	YE3202		
MS21045L8	YE3204		
MS21045L1O	YE3206		
NOTE: (1) "L" denotes "VYDAX": "AR" dry film. (2) Ferrocote #348 Lubricant.			
MS21045LO8	YE3198	Report No. MA772002 of 27 Aug 1971	
MS21045L7	YE3203		
NOTE: (1) "L" denotes "VYDAX": "AR" dry film. (2) Lubricant: Ferrocote #348.			
MS21045L3	SL2374-3	NADC Report No. 305Q77036 of 5 May 1977	Shur-Lok Corp. P.O. Box 19584 2541 White Road Irvine, CA 92713 Plant: Same address
MS21045L4	SL2374-4		
MS21045L5	SL2374-5		
MS21045L6	SL2374-6		
MS21045L7	SL2374-7		
MS21045L8	SL2374-8		
NOTE : (1) Manufactured machined or forged (2) Dry Film, "TIO-LUBE 460." (3) "L" designates dry film.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	'TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045C3 MS21045C4 MS21045C5 MS21045C6	RH50C3M RH50C4M RH50C5M RH50C6M	NADC Report No. 305Q79048 of 15 Feb 1979	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Pk., CA 91320 Plant: Same address
NOTE : parts machined.			
MS21045-04 MS21045-06 MS21045-3 MS21045-4 MS21045-5 MS21045-6 MS21045-7 MS21045-8 MS21045-9 MS2145-10 MS21045-12 MS21045-14 MS21045-16 MS21045-18 MS21045-20	F22MXM-440 F22MXM-632 F22MXM-1032 F22MXE-428 F22 MXE-524 F22 MXE-624 F52 MXE-720U F52MXE-820 F52MXE-918 F52MXE-1018 F52 MXE-1216 F52MXE-1414 F52MXE-1612 F52MXE-1812 FS2MXE-2012	Report No. 305Q81068 of 9 Dec 1981	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrna, TN 37167 Plant: Same address
NOTE: (1) Manufactured process: Forged or machined for 3/4-16 size and smaller; machined for 7/8-14 size and larger. (2) C-1015 is an optional material used in cold-forming for MS21045-5, MS21045-6, and MS21045-8.			
MS21045-08	F22MXM-832	Report No. 305Q83094 of 10 Mar 1983	
NOTE : Manufacturing process: Forged or machined			
MS21045C06 MS21045C3 MS21045C4	PZ-506M PZ-53M PZ-54M	NADC Report 601Q8606 of 12 May 1986	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France
NOTE : (1) Manufacturing process: Screw cutting (2) Lubricant: QPL-8937 (3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFXRS 52.225-7012- (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	" MANUFACTURER' S - DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21045CO4	PZ-504M	Report No. 601Q8710 0f 22 **Jul** 1987	Simmonds Fastener Technologies, **Inc.** (Cent'd)

NOTE : (1) Manufacturing process: Machined
(2) Lubricant: QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21046 NUT, SELF-LOCKING, HEXAGON, REGULAR HEIGHT, 800°F, 125 ksi, Ftu

MS21046CO4 MS21046CO6 MS21046CO8 MS21046C6 MS21046C7 MS21046C8 **MS21046C9** **MS21046C10**	1803-40 1803-62 1803-82 1803-064 1803-070U 1803-080 **1803-098** **1803-108**	Report No. NAMC-AML-1423 of 15 June 1962 and XH-62-MJZ:jem 10410(8886) of 16 Aug **1963**	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21046C3 MS21046C4 MS21046C5	**LH1803-02** LH1803-048 LH1803-054	Report No. NAEC-AML-1922 of 7 Apr 1964	

NOTE : Manufacturing process forged for MS21046-C3, C4, C5.

MS21046CL2 MS21046C14	1803-126 1803-144	Report No. NAEC-AML-1942 of 29 Apr 1964

NOTE: Manufacturing process: Machined

MS21046C6 MS21046C7	**LH1803-064** LH1803-070U	**AMD** Report No. MA77050A of 21 Apr 1970
MS21046C3 MS21046C4 MS21046C5	1803-02 1803-048 1803-054	Report No. NAMC-AML-1423 of 15 Jun 1962 and XM-62-MJZ:jem 10410(8886)

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21046C06	H56-06	Report No. NAMC-AML-1575 of 12 Dec 1962	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
NOTE: Manufacturing process: Forged			
MS21046CO4 MS21046CO8	H56-04 H56-08	Report No. NAEC-AML-1611 of 29 Jan 1963	
NOTE : Manufacturing process: Forged			
MS21046C3	H56-3	Report No. NAMC-AML-1506 of 13 Sep 1962	
NOTE : Manufacturing process: Forged			
MS21046C4	H56-4	Report No. NAMC-ANL-1561 of 14 Nov 1962	
NOTE: Manufacturing process: Forged			
MS21046C5	H56-5	Report No. NAEC-AML-1744 of 30 Aug 1963	
NOTE : Manufacturing process: Forged			
MS21046C3 MS21046C4 MS21046C6 MS21046C7 MS21046C8	YE3702 YE3703 YE3705 YE3706 YE3707	AMD Report No. MA769406 of 27 May 1969	RB&W Corporation 5970 Heisley Rd. Mentor, OH 44060 Plant: 800 Mogadore Rd. Kent, OH 44240
NOTE: (1) Manufacturing process: Machined (2) Finish: Passivated-silver plated			
MS21046CO4 MS21046CO6 MS21046CO8 MS21046C3 MS21046C4 MS21046C5	59FH-440 59FH-632 59FH-832 59FH-1032 59FH-428 59FH-524	Report No. NAEC-AML-1486 of 22 Jan 1963	SPS Technologies Highland Ave. Jenkintown, PA 19046 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION .	TEST OR QUALIFY-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS , ,
MS21046C6	59FH-624	Report No.	SPS Technologies
MS21046C7	59FH-720	NAEC-AML-1656	(Cent'd)
MS21046C8	59FH-820	of 4 Apr 1963	
MS21046C9	59FH-918		
MS21046C1O	59FH-1018		
MS21046C12	59FH-1216	Report No.	
MS21046C14	59FH-1414	NAEC-AML-1656	
MS21046C16	59FH-1612	of 4 Apr 1963	
NOTE: **Manufacturing** process: Machined			
MS21046C3	RH40C3	NADC Report No.	Republic Fastener Mfg.
MS21046C4	RH40C4	305Q79048 of	Corp.
MS21046C5	RH40C5	15 Feb 1979	1300 Rancho Conejo Blvd.
MS21046C6	RH40C6		Newbury Pk., CA 91320
NOTE: Parts machined.			Plant: Same address
MS21046C4 - BH21046-4		Report No. 305Q82076 of **3 May 1982**	Bristol Industries 630 **E. Lambert Rd.** P.O. Box 630 Brea, CA 92621
NOTE: Manufacturing process: Forged			Plant: Same address
MS21047 NUT, SELF-LOCKING, PLATE, TWO LUG, LOW HEIGHT, STEEL, 125 ksi Ftu, 450°F			
MS21047-O4	T2S440CPC	Report No.	Cherry Textron, Cherry
MS21047-O6	T2S632CPC	NAEC-AML-2428	Aerospace Operations,
MS21047-O8	T2S832CPC	of 15 Mar 1966	Cherry Division of
MS21047-3	T2S1032CPC		Textron, Inc.
MS21047-4	T2S428CPC		P.O. Box 2157
MS21047-5	T2S524CPC		1224 East Harrier Ave.
MS21047-6	T2S624CPC		Santa Aria, CA 92707-0157
MS21047LO4	12S440		
MS21047L06	T2S632		Plant: Same address
MS21047LO8	T2S832		
MS21047L3	T2S1032		
MS21047L4	T2S428		
MS21047L5	T2S524		
MS21047L6	T2S624		
MS21047-O4K	T2S440BCCPC		
MS21047-O6K	T25632BCCPC		
MS21047-O8K	T2S832BCCPC		
MS21047-3K	T2S1032BCCPC		
MS21047-4K	T2S428BCCPC		
MS21047-5K	T2S524BCCPC		
MS21047LO4K	T2S440BC		
MS21047LO6K	T2S632BC		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION.	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21047LO8K	T2S832BC	Report No.	Cherry Textron, Cherry
MS21047L3K	T2S1032BC	NAEC-AML-2428	Aerospace operations,
MS21047L4K	T2S428BC	of 15 Mar 1966	(Cent'd)
MS21047L5K	T2S524BC		
MS21047-04	K1000-04CW	Report No.	Microdot, Inc.
MS21047-06	K1OOO-O6CW	NAEC-AML-2474	KAYNAR Div.
MS21047-O8	K1000-08CW	of 15 Jun 1966	P.O. Box 3001
MS21047-3	K1OOO-3CW		800 S. State College Blvd.
MS21047-4	K1OOO-4CW		Fullerton, CA 92634
MS21047-5	K1OOO-5CW		
MS21047-6	K1000-6CW		Plant: Same address
MS21047-O4K	K1OOO-O4BCCW		
MS21047-O6K	K1000-06BCCW		
MS21047-O8K	K1OOO-O8BCCW		
MS21047-3K	K1OOO-3BCCW		
MS21047-4K	K1OOO-4BCCW		
MS21047-5K	K1OOO-5BCCW		
MS21047L04	K1000-04		
MS21047LO6	K1OOO-O6		
MSO47LO8	K1000-08		
MS21047L3	K1OOO-3		
MS21047L4	K1OOO-4		
MS21047L5	K1000-5		
MS21047L6	K1000-6		
MS21047LO4K	K1OOO-O4BC		
MS21047L06K	K1OOO-06BC		
MS21047LO8K	K1OOO-O8BC		
MS21047L3K	K1OOO-3BC		
MS21047L4K	K1000-4BC		
MS21047L5K	K1OOO-5BC		
MS21047L7	K1000-7	Report No. 305Q83097 of 22 Mar 1983	

NOTE : Manufacturing process: Machined

MS21047L3	EK1000-3	NADC Report No. 601Q8706 of 22 May 1987	Microdot Aerospace Limited Blackthorne Road Colnbrook, Slough SL3 OAG England Plant: Same Address

NOTE : (1) Manufacturing process: Strip
(2) Lubrtcant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and QFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every-subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21047-O4	F52LHTA51-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and4 3200 Country Club Road Pocahontas, AR 72455
MS21047-O6	F52LHTA51-62		
MS21047-O8	F52LHTA51-A-82		
MS21047-3	F52LHTA51-A-02		
MS21047-4	F52LHTA51-A-048		
MS21047-5	F52LHTA51-054		
MS21047-6	F52LHTA51-B-06		
MS21047-6	F52LHTA51-064		
MS21047LO4	RM52LHTA51-40		
MS21047L06	RH52LNTA51-62		
MS21047L08	RM52LHTA51-A-82		
MS21047L3	RM52LHTA51-A-02		
MS21047L4	RM52LHTA51-A-048		
MS21047L5	RM52LHTA51-054		
MS21047L6	RM52LHTA51-B-064		
MS21047L6	RM52LHTA51-064		
MS21047-O4K	F52LHTA51-40BC		
MS21047-O6K	F52LHTA51-62BC		
MS21047-O8K	F52LHTA51-A-82BC		
MS21047-3K	F52LHTA51-A-02BC		
MS21047-4K	F52LHTA51-A-048BC		
MS21047-5K	F52LHTA51-054BC		
MS21047L04K	RM52LHTA51-40BC		
MS21047LO6K	RM52LHTA51-62BC		
MS21047LO8K	RM52LHTA51-A-82BC		
MS21047L3K	RM52LHTA51-A-02BC		
MS21047L4K	RM52LHTA51-A-048BC		
MS21047L5K	RM52LHTA51-054BC		
MS21047-O4	12600NM-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21047-O6	12600NM-62		
MS21047Z08	12600NM-82		
MS21047-3	12600NM-02		
MS21047-4	12600NM-048		
MS21047-5	12600NM-054		
MS21047-6	12600NM-064		
MS21047LO4	12600-40		
MS21047LO6	12600-62		
MS21047LO8	12600-82		
MS21047L3	12600-02		
MS21047L4	12600-048		
MS21047L5	12600-054		
MS21047L6	12600-064		
MS21047-O4K	12600NM-40BC		
MS21047-O6K	12600NM-62BC		
MS21047-08K	12600NM-82BC		
MS21047-3K	12600NM-02BC		
MS21047-4K	12600NM-048BC		
MS21047-5K	12600NM-054BC		
MS21047LO4K	12600-40BC		
MS21047L06K	12600-62BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21047L08K	12600-82BC	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies (Cont'd)
MS21047L3K	12600-02BC		
MS21047L4K	12600-048BC		
MS21047L5K	12600-054BC		
MS21047-04	VN102-C1-4O	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21047-O6	VN102-C1-62		
MS21047-O8	VN102-C1-82		
MS21047-3	VN102-C1-02		
MS21047-4	VN102-C1-048		
MS21047-5	VN102-C1-O54		
MS21047-6	VN102-C1-O64		
MS21047LO4	VN102-A1-4O		
MS21047LO6	VN102-A1-62		
MS21047LO8	VN102-A1-82		
MS21047L3	VN102-A1-O2		
MS21047L4	VN102-A1-O48		
MS21047L5	VN102-A1-O54		
MS21047L6	VN102-A1-O64		
MS21047-O4K	VN102-C2-40		
MS21047-O6K	VN102-C2-62		
MS21047-O8K	VN102-C2-82		
MS21047-3K	VN102-C2-O2		
MS21047-4K	VN102-C2-O48		
MS21047-5K	VN102-C2-054		
MS21047LO4K	VN102-A2-4O		
MS21047LO6K	VN102-A2-62		
MS21047LO8K	VN102-A2-82		
MS21047L3K	VN102-A2-O2		
MS21047L4K	VN102-A2-048		
MS21047L5K	VN102-A2-O54		
MS21047-O4	R2000X04	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21047L04	R2000A04		
MS21047-O4K	R2000X04K		
MS21047LO4K	R2000A04K		
MS21047-06	R2000X06		
MS21047LO6	R2000A06		
MS21047-O6K	R2000X06K		
MS21047LO6K	R2000A06K		
MS21047-O8	R2000X08		
MS21047L08	R2000A08		
MS21047-O8K	R2000X08K		
MS21047LO8K	R2000A08K		
MS21047-3	R2000X3		
MS21047L3	R2000A3		
MS21047-3K	R2000X3K		
MS21047L3K	R2000A3K		
MS21047-4	R2000X4		
MS21047L4	R2000A4		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21047-4K MS21047L4K MS21047-5 MS21047L5 MS21047-5K MS21047L5K	R2000X4K R2000A4K R2000X5 R2000A5 R2000X5K . R2000A5K	Report No. 305073001 of 6 Feb 1973	Republic Fastener Mfg. Corp. (Cent'd)
MS21047-6 MS21047L6	R2000X6 R2000A6	Report No. 305Q83088 of 26 Jan 1983	
MS21047L3 MS21047L3K MS21047L4 MS21047L4K	G-93M G-93MK G-94M G-94MK	NADC Report No. 305Q83112 of 28 NOV 1983	Simmonds Fastener Technologies Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21047LO8 MS21047LO8K	G-908M G-908MK	305Q83111 of ., 19 Oct 1983	Plant: Same address - Simmonds - -- 5, rue Michelet, B.P. 52
MS21047-3 MS21047-4	G-93 G-94	601Q8407 of 20 Apr 1984	F. 92152 Suresnes Cedex France
MS21047-O8 MS21047-O8K	G-908 G-908K "	NADC Report 601Q8502 of 11 Mar 1985	
MS21047-O6 MS21047-O6K MS21047LO6 MS21047LO6K	G-906 G-906K G-906M G-906MK	NADC Report 601Q851O of 10 Jun 1985	

NOTE: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124.

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals'). The contractor should include these provisions in every subcontract and purchase order.

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3. (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions In every subcontract and purchase order.

Source: https://assist.dla.mil - Downloaded: 202640-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048 NUT, SELF-LOCKING, PLATE, TWO LUG, LOW HEIGHT, CRES, 125 ksi Ftu, 450°F & 800°F			
MS21048-04	K1031-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21048-06	K1031-06		
MS21048-08	K1031-08		
MS21048-3	K1031-3		
MS21048-4	K1031-4		
MS21048-5	K1031-5		
MS21048-6	K1031-6		
MS21048-04K	K1031-04BC		
MS21048-06K	K1031-06BC		
MS21048-08K	K1031-08BC		
MS21048-3K	K1031-3BC		
MS21048-4K	K1031-4BC		
MS21048-5K	K1031-5BC		
MS21048-04N	K1031-04P		
MS21048-06N	K1031-06P		
MS21048-08N	K103I-08P		
MS21048-3W	K1031-3P		
MS21048-4W	K1031-4P		
MS21048-5W	K1031-5P		
MS21048-6W	K1031-6P		
MS21048LO4	K1OO1-04		
MS21048LO6	K1OO1-06		
MS2 1048L08	K1OO1-08		
MS2 1048L3	K1OO1-3		
MS2 1048L4	K1OO1-4		
MS2 1048L5	K1OO1-5		
MS2 1048L6	K1OO1-6		
MS2 1048L04K	K1OO1-04BC		
MS2 1048L06K	K1OO1-06BC		
MS2 1048L08K	K1OO1-08BC		
MS2 1048L3K	K1OO1-3BC		
MS2 1048LAK	K1OO1-4BC		
MS2 1048L5K	K1OO1-5BC		
MS2 1048L04W	K1OO1-04P		
MS2 1048L06W	K1OO1-06P		
MS2 1048L08W	K1001-08P		
MS2 1048L3W	K1OO1-3P		
MS2 1048L4W	K1OO1-4P		
MS2 1048L5W	K1OO1-5P		
MS2 1048L6W	K1OO1-6P		
MS21048-04	T2C440	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21048-06	T2C632		
MS2 1048-08	T2C832		
MS2 1048-3	T2C1032		
MS2 1048-4	T2C428		
MS2 1048-5	T2C524		
MS2 1048-6	T2C624		
MS2 1048-04K	T2C440BC		
MS2 1048-06K	T2C632BC		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	M A N U F A C T U R E R ' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048-O8K	T2C832BC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, (Cent'd)
MS21048-3K	T2C1032BC		
MS21048-4K	T2C428BC		
MS21048-5K	T2C524BC		
MS21048-O4W	T2C440P		
MS21048-06W	T2C632P		
MS21048-O8W	T2C832P		
MS21048-3M	T2C1032P		
MS21048-4W	T2C428P		
MS21048-5W	T2C524P		
MS21048-6W	T2C624P		
MS21048LO4	T2C440M		
MS21048LO6	T2C632M		
MS21048L08	T2C832M		
MS21048L3	T2C1032M		
MS21048L4	T2C428M		
MS21048L5	T2C524M		
MS21048L6	T2C624M		
MS21048LO4K	T2C440BCM		
MS21048LO6K	T2C632BCM		
MS21048LO8K	T2C832BCM		
MS21048L3K	T2C1032BCM		
MS21048L4K	T2C428BCM		
MS21048L5K	T2C524BCM		
MS21048LO4W	T2C440PM		
MS21048L06W	T2C632PM -		
MS21048LO8W	T2C832PM		
MS21048L3W	T2C1032PM		
MS21048L4W	T2C428PM		
MS21048L5W	T2C524PM		
MS21048L6W	T2C624PM		
MS210 48-04	12700-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies" 2701 S. Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MS210 48-06	12700-62		
MS210 48-08	12700-82		
MS210 48-3	12700-02		
MS210 48-4	12700-048		
MS210 48-5	12700-054		
MS21O 48-6	12700-064		
MS210 48-04K	12700-40BC		
MS210 48-06K	12700-62BC		
MS210 48-08K	12700-82BC		
MS210 48-3K	12700-02BC		
MS210 48-4K	12700-048BC		
MS210 48-SK	12700-054BC		
MS210 48-04W	12700-40PH		
MS210 48-06W	12700-62PW		
MS210 48-08W	12700-82PW		
MS210 48-3W	12700-02PW		
MS210 48-4W	12700-048PW		
MS210 48-5W	12700-054PW		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048-6W	12700-064PW	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies (Cent'd)
MS21048LO4	12700E-40		
MS21048L06	12700E-62		
MS21048LO8	12700E-82		
MS21048L3	12700E-02		
MS21048L4	12700E-048		
MS21048L5	12700E-054		
MS21048L6	12700E-064		
MS21048LO4K	12700E-40BC		
MS21048L06K	12700E-62BC		
MS21048LO8K	12700E-82BC		
MS21048L3K	12700E-02BC		
MS21048L4K	1Z700E-048BC		
MS21048L5K	12700E-0548C		
MS21048LO4N	12700E-40PW		
MS21048LO6W	12700E-62PW		
MS21048LO8H	12700E-82PW		
MS21048L3M	12700E-02PW		
MS21048L4W	12700E-048PW		
MS21048L5H	12700E-054PW		
MS21048L6H	12700E-064PW		
MS21048LO4	RMLHTA51-2860-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21048L06	RMLHTA51-2860-62		
MS21048LO8	RMLHTA51-2860-82		
MS21048L3	RMLHTA51-2860-02		
MS21048L4	RMLHTA51-2860-048		
MS21048L5	RMLHTA51-2860-054		
MS21048L6	RMLHTA51-2860-064		
MS21048LO4K	RMLHTA51-2860-40BC		
MS21048LO6K	RMLHTA51-2860-62BC		
MW521048LV8K	RMLHTA51-2860-82BC		
MS21048L3K	RMLHTA51-2860-02BC		
MS21048L4K	RMLHTA51-2860-048BC		
MS21048L5K	RMLHTA51-2860-054BC		
MS21048L04H	RMLHTA51-2860P-40		
MS21048L06W	RMLHTA51-2860P-62		
MS21048LO8W	RMLHTA51-2860P-82		
MS21048L3W	RMLHTA51-2860P-02		
MS21048L4W	RMLHTA51-2860P-048		
MS21048L5W	RMLHTA51-2860P-054		
MS21048L6W	RMLHTA51-2860P-064		
%21048-04	LH TA51-2860-40		
%21048-06	LH TA51-2860-62		
MS21048-O8	LH TA51-2860-82		
MS21048-3	LH TA51-2860-02		
MS21048-4	LH TA51-2860-048		
MS21048-5	LH TA51-2860-054		
MS21048-6	LH TA51-2860-064		
MS21048-04K	LH TA51-2860-40BC		
MS21048-06K	LH TA51-Z860-62BC		
MS21048-O8K	LH TA51-2860-82BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER 'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER 'S NAME AND ADDRESS
MS21048-3K	LH TA51-2860-02BC	Report No.	Elastic Stop Nut
MS21048-4K	LH TA51-2860-048BC	NAEC-AHL-2429 "	A Division of
MS21048-5K	LH TA51-2860-054BC	of 15 Mar 1966	Harvard Industries, Inc.
MS21048-04W	LH TA51-2860P-40		(Cent'd)
MS21048-06W	LH TA51-2860P-62		
MS21048-08W	LH TA51-2860P-82		
MS21048-3W	LH TA51-2860P-02		
MS21048-4W	LH TA51-2860P-048		
MS21048-5W	LH TA51-2860P-054		
MS21048-6W	LH TA51-2860P-064		
MS21048-O4	VN 102- B1-40	Report No.	VOX-WAN
MS21048-O6	VN 102- B1-62	NAEC-AML-2425	VSI Aerosp. Prod. Div.
MS21048-08	VN 102- B1-82	of 15 Mar 1966	8463 Higuera Street
MS21048-3	VN 102- B1-02		Culver City, CA 90230
MS21048-4	VN 102- B1-048		
MS21048-5	VN 102- B1-054		Plant:
MS21048-6	VN 102- B1-064		2700 Compton Blvd.
MS21048-04K	VN 102- B2-40		Redondo Beach, CA 90278
MS21048-O6K	VN 102- B2-62		
MS21048-08K	VN 102- B2-82		
MS21048-3K	VN 102- B2-02		
MS21048-4K	VN 102- B2-048		
MS21048-5K	VN 102- B2-054		
MS21048-O4W	VN 102- B3-40		
MS21048-O6W	VN 102- B3-62		
MS21048-O8W	VN 102- B3-82		
MS21048-3W	VN 102- B3-02		
MS21048-4W	VN 102- B3-048		
MS21048-5W	VN 102- B3-054		
MS21048-6W	VN 102- B3-064		
MS21048L04	VN 102- D1-40		
MS21048LO6	VN 102- D1-62		
MS21048LO8	VN 102- D1-82		
MS21048L3	VN 102- D1-02		
MS21048L4	VN 102- D1-048		
MS21048L5	VN 102- D1-054		
MS21048L6	VN 102- D1-064		
MS21048LO4K	VN 102- D2-40		
MS21048LO6K	VN 102- D2-62		
MS21048LO8K	VN 102- D2-82		
MS21048L3K	VN 102- D2-02		
MS21048L4K	VN 102- D2-048		
MS21048L5K	VN 102- D2-054		
MS21048LO4W	VN 102- D3-40		
MS21048LO6W	VN 102- D3-62		
MS21048LO8W	VN 102- D3-82		
MS21048L3W	VN 102- D3-02		
MS21048L4W	VN 102- D3-048		
MS21048L5W	VN 102- D3-054		
MS21048L6W	VN 102- D3-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048LO8	12000C08M	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21048L08K	12000C08MK		
MS21048LOW	12000C08MN		
MS21048-O8	12000C08		
MS21048-08K	R2000C08K		
MS21048-08W	R2000C08W		
MS21048L3	R2000C3M		
MS1048L3K	12000C3MK		
MS21048L3W	12000C3MW		
MS21048-3	R2000C3		
MS21048-3K	R2000C3K		
MS21048-3W	R2000C3W		
MS21048L4	R2000C4M		
MS21048L4K	R2000C4MK		
MS21048L4W	R2000C4MW		
MS21048-4	R2000C4		
MS21048-4K	R2000C4K		
MS21048-4W	R2000C4W		

NOTE: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21048-O4	R2000C04	Report No. 305Q76023 of 14 May 1976
MS21048L04	R2000C04M	
MS21048-04K	R2000C04K	
MS21048LO4K	R2000C04MK	
MS21048-04H	R2000C04W	
MS21048L04W	R2000C04MW	
MS21048-O6	R2000C06	
MS21048L06	R2000C06M	
MS21048-06K	R2000C06K	
MS21048LO6K	R2000C06MK	
MS21048-O6W	R2000C06W	
MS21048LO6W	R2000C06MW	
MS21048-5	R2000C5	
MS21048L5	R2000C5M	
MS21048-5K	R2000C5K	
MS21048L5K	R2000C5MK	
MS21048-5W	R2000C5W	
MS21048L5W	R2000C5MW	

MS21048-6	R2000C6	Report No. 305Q83088 of 26 Jan 1983
MS21048L6	R2000C6M	
MS21048-6W	R2000C6W	
MS21048L6W	R2000C6MW	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048-3 MS21048-3K	G-53 G53K	NADC Report No. 305Q83112 of 28 Nov 1983	Simmonds Fastener Technologies Inc. 181 A. blest Orangethorpe Placentia, CA 92670
MS21048-4 MS21048-4K	G-54 G-54K	305Q83111 of 19 Oct 1983	Plant: Simmonds
MS21048-O8 MS21048-O8K	G-508 G-508K	601Q8401 of 24 Feb 1984	5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France
MS21048L4	G-54M	601Q8612 of **6 Ott 1986**	

NOTE : (1) Manufacturing process: Cold formed (except MS21048L4 Cold Stamping)
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21049 NUT, SELF-LOCKING, PLATE, TWO LUG, 100° CSK, LOW HEIGHT, STEEL, 125 ksi Ftu, 450°F

MS21049-O8 MS21049-3 MS21049-4 MS21049-5 MS21049LO8 MS21049L3 MS21049L4 MS21049L5 MS21049-O8K MS21049-3K MS21049-4K MS21049-5K MS21049LO8K MS21049L3K MS21049L4K MS21049L5K	F52LHTA58-82 F52LHTA58-02 F52LHTA58-048 F52LHTA58-054 RM52LHTA58-82 RM52LHTA58-02 RM52LHTAS8-048 RM52LHTA58-054 F52LHTA58-82BC F52LHTA58-02BC F52LHTA58-048BC F52LHTA58-054BC RM52LHTA58-82BC RM52LHTA58-02BC RM52LHTA58-048BC RM52LHTA58-054BC	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455

MS21049-O8 MS21049-3 MS21049-4 MS21049-5 MS21049LO8 MS21049L3 MS21049L4 MS21049L5 MS21049-O8K MS21049-3K MS21049-4K	15600NM -82 15600NM -02 15600NM -048 15600NM -054 15600-8 2 15600-0 2 15600-0 48 15600-0 54 15600NM -82BC 15600NM -02BC 15600NM -048BC	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address

Source: https://assist.dla.mil Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21048-3	G-53	NADC Report No.	Simmonds Fastener
MS21048-3K	G-53K	305Q83112 of	Technologies Inc.
		28 Nov 1983	181 A. West Orangethorpe
			Placentia, CA 92670
MS21048-4	G-54	305Q83111 of	
MS21048-4K	G-54K	19 Oct 1983	Plant:
			Simmonds
MS21048-O8	G-508	601Q8401 of	5, rue Michelet, B.P. 52
MS21048-08K	G-508K	24 Feb 1984	F. 92152 Suresnes Cedex
			France
MS21048L4	G-54M	601Q8612 of	
		6 Oct 1986	

NOTE: (1) Manufacturing process: Cold formed (except MS21048L4 Cold Stamping)
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21049 NUT, SELF-LOCKING, 125 ksi PLATE. TWO LUG, 100° CSK, LOW HEIGHT, STEEL, Ftu, 450 °F			
MS21049-O8	F52LHTA58-82	Report No.	Elastic Stop Nut
MS21049-3	F52LHTA58-02	NAEC-AML-2429	A Division of
MS21049-4	F52LHTAS8-048	of 15 Mar 1966	Harvard Industries, Inc.
MS21049-5	F52LHTA58-054		2330 Vauxhall Road
MS21049LO8	RM52LHTA58-82		Union, NJ 07083
MS21049L3	RM52LHTA58-02		
MS21049L4	RMS2LHTA58-048		Plant: Same address and
MS21049L5	RM52LHTA58-054		3200 Country Club Road
MS21049-O8K	F52LHTA58-82BC		Pocahontas, AR 72455
MS21049-3K	F52LHTA58-02BC		
MS21049-4K	F52LHTA58-0488C		
MS21049-5K	F52LHTA58-054BC		
MS21049L08K	RM52LHTA58-82W		
MS21049L3K	RM52LHTA58-028C		
MS21049L4K	RM52LHTA58-048BC		
MS21049L5K	RM52LHTA58-0S4BC		
MS21049-08	15600N[illegible]M-82	Report No.	SPS Technologies
MS21049-3	15600N[illegible]M-02	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21049-4	15600N[illegible]M-048	of 15 Mar 1966	Santa Aria, CA 92702
MS21049-5	15600N[illegible]M-054		
MS21049LO8	15600-[illegible]82		Plant: Same address
MS21049L3	15600-[illegible]02		
MS21049L4	15600-[illegible]048		
MS21049L5	15600-[illegible]054		
MS21049-08K	15600N[illegible]M-82BC		
MS21049-3K	15600N[illegible]M-02BC		
MS21049-4K	15600N[illegible]M-048BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21049-4	R210OX4	Report No.	Republic Fastener Mfg.
MS21049L4	**R2100A4**	**305076023** of	Corp.
MS21049-4K	R210OX4K	14 May 1976	(Cent'd)
MS21049L4K	R2100A4K		
MS21049-5	R2100X5		
MS21049L5	R2100A5		
MS21049-5K	R2100X5K		
MS21049L5K	R2100A5K		
MS21049-08	**H - 9 0 8**	**NADC** Report	Simmonds **Fastener**
MS21049-08K	**H-908K**	**601Q8417 of**	**Technologies,** Inc.
MS21049LO8	**H-908M**	**Z5 Oct 1984**	**181 A.** Nest Orangethorpe
MS21049L08K	H-908MK		Placentia, CA 92670
MS21049-3	H-93	NAOC Report	Plant:
MS21049L3	H-93M	601Q8609 0f	Simmonds
		8 Aug 1986	5, rue Michelet, B.P. 52
			F. 92152 Suresnes Cedex
			France

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation With "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance **with FAR 52.225-3 (Buy** American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS2105O NUT, SELF-LOCKING, PLATE, TWO LUG, 100" CSK, LOW HEIGHT, CRES, 125 ksi Ftu, 450° AND 800°F

MS21050L08	RMLHTA58-2860-82	Report No.	Elastic Stop Nut
MS21050L3	RMLHTA58-2860-02	NAEC-AML-2429	A Division of
MS2105OL4	RMLHTA58-2860-048	of 15 Mar 1966	Harvard Industries, Inc.
MS2105OL5	RMLHTA58-2860-054		2330 Vauxhall Road
MS2105OLO8K	RMLHTA58-2860-82BC		Union, NJ 07083
MS2105OL3K	RMLHTA58-2860-02BC		
MS2105OL4K	RMLHTA58-2860-048BC		Plant: Same address and
MS2105OL5K	RMLHTA58-2860-054BC		3200 Country Club Road
MS21050L08bIJ	RMLHTA58-2860P-82		Pocahontas, AR 72455
MS2105OL3H	RMLHTA58-2860P-02		
MS2105OL4H	RMLHTA58-2860P-048		
MS21050L51i	RMLHTA58-2860P-054		
MS2105O-O8	LHTA58-2860-82		
MS21050-3	LHTA58-2860-02		
MS21050-4	LHHTA58-2860-048		
MS2105O-5	LHHTA58-2860-054		
MS2105O-O8K	LHHTA58-2860-82BC		
MS21050-3K	LHHTA58-2860-02BC		
MS2105O-4K	LHHTA58-2860-048BC		
MS2105O-5K	LHHTA58-2860-054BC		
MS2105O-O8H	LHHTA58-2860P-82		
MS2105O-3H	LHHTA58-2860P-02		
MS2105O-4H	LHHTA58-2860P-048		
MS2105O-5H	LHTA58-2860P-054		

Source: https://assist.dla.mil Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21050-08 MS21050-3 MS21050-4 MS21050-5 MS21050-08K MS21050-3K MS21050-4K MS21050-5K MS21050-08W MS21050-3W MS21050-4W MS21050-5W MS21050L08 MS21050L3 MS21050L4 MS21050L5 MS21050L08K MS21050L3K MS21050L4K MS21050L5K MS21050L08M MS21050L3W MS21050L4W MS21050L5W	15700-82 15700-02 15700-048 15700-054 15700-82BC 15700-02BC 15700-048BC 15700-054BC 15700-82PW 15700-02PW 15700-048PW 15700-054PW 15700E-82 15700E-02 15700E-048 15700E-054 15700E-82BC 15700E-02BC 15700E-048BC 15700E-054BC 15700E-82PW 15700E-02PW 15700E-048PW 15700E-054PW	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21050-08 MS21050-3 MS21050-4 MS21050-08K MS21050-3K MS21050-4K MS21050-08W MS21050-3W MS21050-4W MS21050L08 MS21050L3 MS21050L4 MS21050L08K MS21050L3K MS21050L4K MS21050L08W MS21050L3W MS21050L4W	K1131-08 K1131-3 K1131-4 K1131-08BC K1131-38C K1131-4BC K1131-08P K1131-3P K1131-4P K1101-08 K1101-3 K1101-4 K1101-08BC K1101-3BC K1101-4BC K1101-08P K1101-3P K1101-4P	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21050-08 MS21050-3 MS21050-4 MS21050-5 MS21050-08K MS21050-3K MS21050-4K MS2105-5K	T2CH832 T2CH1032 T2CH428 T2CH524 T2CH832BC T2CHI032BC T2CH428BC T2CH524BC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Divsion of Textron, Inc. P.O. BOX 2157 1224 East blamer Ave. Santa Aria, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MAMUFACTURER'S NAME AND ADDRESS
MS21050-08W	T2CH832P	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, (Cent'd)
MS2105O-3W	T2CH1032P		
MS2105O-4W	T2CH428P		
MS2105O-5W	T2CH524P		
MS2105OLO8	T2CH832M		
MS2105OL3	T2CH1032M		
MS2105OL4	T2CH428M		
MS2105OL5	T2CH524M		
MS21050L08K	T2CH832BCM		
MS105013K	T2CH1032BCM		
MS21050L4K	T2CH428BCM		
MS2105OL5K	T2CH524BCM		
MS2105OLO8W	T2CH832PM		
MS2105OL3W	T2CH1032PM		
MS2105OL4W	T2CH428PM		
MS2105OL5W	T2CH524PM		
MS210)5(0-08	R2100)C08	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener - - Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS210)5(0-08K	R2100)C08K		
MS210)5(0-08W	R2100)C08W		
MS210)5(0L08	R2100)C08M		
MS210)5(0L08K	R2100)C08MK		
MS210)5(0L08H	R210)C08MW		
MS210)5(0-3	R2100)C3		
MS210)5(0-3K	R2100)C3K		
MS210)5(0-3W	R2100)C3W		
MS210)5(0L3	R2100)C3M		
MS210)5(0L3K	R2100)C3MK		
MS210)5(0L3W	R21O)C3MW		

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21050-4	R2100C4	Report No. 305Q76023 0f 14 May 1976
MS21050L4	R2100C4M	
MS210S0-4K	R2100C4K	
MS21050L4K	R2100C4MK	
MS2105O-4W	R2100C4W	
MS21050L4W	R2100C4MN	
MS2105O-5	R2100C5	
MS21050L5	R2100C5M	
MS2105O-5K	R2100C5K	
MS2105OL5K	R2100C5MK	
MS21050-5W	R2100C5W	
MS2105OL5W	R21OOC5MW	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21051 NUT, SELF-LOCKING, PLATE, ONE LUG, LOW HEIGHT, ALLOY STEEL, 125 ksi Ftu, 450"F			
MS21051-O8	T12S832CPC	Report No. NAEC-AML-2428 of 16 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry **Division of Textron,** Inc. P.O. BOX 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21051-3	T12S1032CPC		
MS21051-4	T12S428CPC		
MS21051LO8	T12S832		
MS21051L3	T12S1032		
MS21051L4	T12S428		
MS21051-08K	T12S832BCCPC		
MS21051-3K	T12S1032BCCPC		
MS21051-4K	T12S428BCCPC		
MS21051L08K	T12S8328C		
MS2105IL3K	T12S1032BC		
MS21051L4K	T12S428BC		
MS21051-06	F52LHTA57-62	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS2105I-O8	F52LHTA57-82		
MS21051-3	F52LHTA57-02		
MS21051-4	F52LHTA57-048		
MS21051-5	F52LHTA57-054		
MS21051-6	F52LHTA57-064		
MS21051L06	RM52LHTA57-62		
MS21051LO8	RM52LHTA57-82		
MS21051L3	RM52LHTA57-02		
MS21051L4	RM52LHTA57-048		
MS21051L5	RM52LHTA57-054		
MS21051L6	RM52LHTA57-064		
MS21051-O6K	F52LHTA57-62BC		
MS21051-O8K	F52LHTA57-82BC		
MS21051-3K	F52LHTA57-02BC		
MS21051-4K	F52LHTA57-048BC		
MS21051-5K	F52LHTA57-054BC		
MS21051L06K	RM52LHTA57-62BC		
MS21051LO8K	RM52LHTA57-82BC		
MS21051L3K	RM52LHTA57-02BC		
MS21051L4K	RM52LHTA57-048BC		
MS21051L5K	RM52LHTA57-054BC		
MS21051-O6	VN101-C1-62	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21051-O8	VN101-C1-82		
MS21051-3	VN101-C1-O2		
MS21051-4	VN1O1-C1-O48		
MS21051-5	VN1O1-C1-054		
MS21051-6	VN101-C1-O64		
MS21051L06	VN101-A1-62		
MS21051LO8	VN1O1-A1-82		
MS21051L3	VN101-A1-O2		
MS21051L4	VN101-A1-O48		
MS21051L5	VN101-A1-O54		
MS21051L6	VN1O1-A1-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21051-06K	VN101-C2-62	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. (Cent'd)
MS21051-08K	VN101-C2-82		
MS21051-3K	VN10 1-C2-02		
MS21051-4K	VN101-C2-048		
MS21051-5K	VN101-C2-054		
MS21051L06K	VN10[illegible]-A2-62		
MS21051L08K	VN10[illegible]-A2-82		
MS21051L3K	VN101-A2-02		
MS21051L4K	VN101-A2-48		
MS21051L5K	VN101-A2-054		
MS21051-06	12610NM-62	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21051-08	12610NM-82		
MS21051-3	12610NM-02		
MS21051-4	12610NM-048		
MS21051-5	12610NM-054		
MS21051 -6	I2610NM-064		
MS21051LO6	12610-62		
MS21051L08	12610-82		
MS21051L3	12610-02		
MS21051L4	12610-048		
MS21051L5	12610-054		
MS21051L6	12610-064		
MS21051-O6K	12610NM-62BC		
MS21051-O8K	12610NM-82BC		
MS21051-3K	12610NM-O2BC		
MS21051-4K	12610NM-O48BC		
MS21051-5K	12610NM-O54BC		
MS21051LO6K	12610-62BC		
MS21051LO8K	12610-82BC		
MS21051L3K	12610-O2BC		
MS21051L4K	12610-048BC		
MS21051L5K	12610-O54BC		
MS21051-O6	K2000-06CW	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21051-08	K2000-08CW		
MS21051-3	K2000-3CW		
MS21051-4	K2000-4CW		
MS21051-5	K2000-5CW		
MS21051-6	K2000-6CW		
MS21051-06K	K2000-06BCCW		
MS21051-O8K	K2000-08BCCW		
MS21051-3K	K2000-3BCCW		
MS21051-4K	K2000-4BCCW		
MS21051-5K	K2000-5BCCW		
MS21051LO6	K2000-06		
MS21051L08	K2000-08		
MS21051L3	K2000-3		
MS21051L4	K2000-4		
MS21051L5	K2000-5		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21051L6	K2000-6	Report No.	Microdot, Inc.
MS21051LO6K	K2000-06BC	NAEC-AML-2474	KAYNAR Div.
MS21051LO8K	K2000-08BC	of 15 Jun 1966	(Cent'd)
MS21051L3K	K2000-3BC		
MS21051L4K	K2000-4BC		
W21051L5K	K2000-5BC		
MS21051-O8	R1000XQ8	Report No.	Republic Fastener Mfg.
MS21051L08	R1000A08	305Q76023 of	Corp.
MS21051-O8K	R1OOOX08K	14 May 1976	1300 Rancho Conejo Blvd.
MS21051LO8K	R1000A08K		Newbury Park, CA 91320
MS21051-3	R1OOOX3		
MS21051L3	R1OOOA3		Plant: Same address
MS21051-3K	R1000X3K		
MS21051L3K	R1OOOA3K		
MS21051-4	R1OOOX4		
MS21051L4	R1OOOA4		
MS21051-4K	R1OOOX4K		
MS21051L4K	R1OOOA4K		
MS21051-06	R1000X06	Report No.	
MS21051LO6	R1000A06	305Q83088 of	
MS21051-06K	R1OOOX06K	26 Jan 1983	
MS21051LO6K	R1OOOAO6K		
MS21051L3	AJ-93M	Report No.	Simmonds
MS21051L3K	AJ-93MK	305Q83104 of	Fastener Tech. Inc.
MS21051L4	AJ-94M	12 Aug 1983	181 A West Orangethorpe
MS21051L4K	AJ-94MK		Placentia, CA 92670
			Plant:
MS21051LO8	AJ-908M	601Q8401 of	Simmonds
MS21051L08K	AJ-908MK	24 Feb 1984	5, rue Michelet. B.P. 52 F. 92152 Suresnes Cedex France
MS21051-08	AJ-908	601Q8407 of	
MS21051-3	AJ-93	20 Apr 1984	

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST' OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21051-4 MS21051L4	AJ-94 AJ-94M	NADC Report 601Q8507 of 31 May 1985	Simmonds Fastener Technologies, Inc. (Cent'd)

NOTE: (1) Manufacturing process: **Cold** stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937.
(3) **Provisions** Governing Procurement. Procurement of these **self-locking nuts shall be In accordance with FAR 52.225-3 (Buy** American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21052 NUT, SELF-LOCKING, PLATE, ONE LUG, LOW HEIGHT, CRES, 125 ksi Ftu, 450"F AND 800"F

MS21052LO6	RMLHTA57-2860-62	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21052LO8	RMLHTA57-2860-82		
MS21052L3	RMLHTA57-2860-02		
MS21052L4	RMLHTA57-2860-048		
MS21052L5	RMLHTA57-2860-054		
MS21052L6	RMLHTA57-2860-064		
MS21052L06K	RMLHTA57-2860-628C		
MS21052LO8K	RMLHTA57-2860-82BC		
MS21052L3K	RMLHTA57-2860-02BC		
MS21052L4K	RMLHTA57-2860-048BC		
MS21052L5K	RMLHTA57-2860-054BC		
MS21052L06W	RMLHTA57-2860P-62		
MS21052LO8W	RMLHTA57-2860P-82		
MS21052L3W	RMLHTA57-2860P-02		
MS21052L4W	RMLHTA57-2860P-048		
MS21052L5W	RMLHTA57-2860P-054		
MS21052L6W	RMLHTA57-2860P-064		
MS21052-O6	LHTA57-2860-62		
MS21052-O8	LHTA57-2860-82		
MS21052-3	LHTA57-2860-02		
MS21052-4	LHTA57-2860-048		
MS21052-5	LHTA57-2860-054		
MS21052-6	LHTA57-2860-064		
MS21052-O6K	LHTA57-2860-62BC		
MS21052-O8K	LHTA57-2860-82BC		
MS21052-3K	LHTA57-2860-02BC		
MS21052-4K	LHTA57-2860-048BC		
MS21052-5K	LHTA57-2860-054BC		
MS21052-06W	LHTA57-2860P-62		
MS21052-O8W	LHTA57-2860P-82		
MS21052-3W	LHTA57-2860P-02		
MS21052-4W	LHTA57-2860P-048		
MS21052-5W	LHTA57-2860P-054		
MS21052-6W	LHTA57-2860P-064		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21052-06	VN101-B1-62	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 . Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21052-08	VN101-B1-82		
MS21052-3	VN101-B1-02		
MS21052-4	VN101-B1-048		
MS21052-5	VN101-B1-054		
MS21052-6	VN101-B1-064		
MS21052-06K	VN101-B2-62		
MS21052-08K	VN101-B2-82		
MS21052-3K	VN101-B2-02		
MS21052-4K	VN101-B2-048		
MS21052-5K	VN101-B2-054		
MS21052-06M	VN101-B3-62		
MS21052-08W	VN101-B3-82		
MS21052-3W	VN101-B3-02		
MS21052-4W	VN101-B3-048		
MS21052-5W	VN101- B3-054		
MS21052-6W	VN101-D3-064		
MS21052L06	VN101-D1-62		
MS21052L08	VN101-D1-82		
MS21052L3	VN101-D1-02		
MS21052L4	VN101-D1-048		
MS21052L5	VN101-D1-054		
MS21052L6	VN101-D1-064		
MS21052L06K	VN101-D2-62		
MS21052L08K	VN101-D2-82		
MS21052L3K	VN101-D2-02		
MS21052L4K	VN101-D2-048		
MS21052L5K	VN101-D2-054		
MS21052L06H	VN101-D3-62		
MS21052L08H	VN101-D3-82		
MS21052L3H	VN101-D3-02		
MS21052L4M	VN101-D3-048		
MS21052L5W	VN101- D3-054		
MS21052L6N	VN101-D3-064		
MS21052-06	12710-62	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21052-08	12710-82		
MS21052-3	12710-02		
MS21052-4	12710-048		
MS21052-5	12710-054		
MS21052-6	12710-064		
MS21052-06K	12710-62BC		
MS21052-08K	12710-82BC		
MS21052-3K	12710-02BC		
MS21052-4K	12710-048BC		
MS21052-5K	12710-054BC		
MS21052-06W	12710-62PW		
MS21052-08W	12710-82PW		
MS21052-3W	12710-02PW		
MS21052-4W	12710-048PW		
MS21052-5W	12710-054PW		
MS21052-6W	12710-064PW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS .
MS21052L06	1271OE-62	Report No.	SPS Technologies
MS21052L08	1271OE-82	NAEC-AML-2369	(Cent'd)
MS21052L3	1271OE-O2	of 15 Mar 1966	
MS21052L4	1271OE-O48		
MS21052L5	1271OE-O54		
MS21052L6	12710E-064		
MS21052LO6K	1271OE-62BC		
MS21052L08K	12710E-82BC		
MS21052L3K	12710E-028C		
MS21052L4K	1271OE-O488C		
MS21052L5K	1271OE-O54BC		
MS21052L06W	1271OE-62PW		
MS21052LO8W	1271OE-82PW		
MS21052L3W	1271OE-O2PW		
MS21052L4W	1271OE-O48PW		
MS21052L5W	1271OE-O54PW		
MS21052L6W	1271OE-O64PW		
MS21052-06	K2031-06	Report No.	Microdot, Inc.
MS21052-O8	K2031-08	NAEC-AML-2474	KAYNAR Div.
MS21052-3	K2031-3	of 15 Jun 1966	P.O. Box 3001
MS21052-4	K2031-4		800 S State College "-"
MS21052-5	K2031-5		
MS21052-6	K2031-6		Fullerton, CA. 92634
MS21052-06K	K2031-068C		
MS21052-O8K	K2031-08BC		Plant: Same address
MS21052-3K	K2031-3BC		
NS21052-4K	K2031-4BC		
MS21052-5K	K2031-5BC		
MS21052-06W	K2031-06P		
MS21052-08W	K2031-08P		
MS21052-3W	K2031-3P		
MS21052-4W`	K2031-4P		
MS21052-5W	K2031-5P		
MS21052-6W	K2031-6P		
MS21052LO6	K2001-06		
MS21052LO8	K2001-08		
MS21052L3	K2001-3		
MS21052L4	K2001-4		
MS21052L5	K2001-5		
MS21052L6	K2001-6		
MS21052LO6K	K2001-06BC		
NS21OS2LO8K	K2001-08BC		
MS21052L3K	K2001-3BC		
MS21052L4K	K2001-4BC		
MS21052L5K	K2001-5BC		
MS21052L06W	K2001-06P		
MS21052LO8W	K2001-08P		
MS21052L3W	K2001-3P		
MS21052L4W	K2001-4P		
MS21052L5W	K2001-5P		
MS21052L6W	K2001-6P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTRER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21052-08 MS21052-3 MS21052-4 MS21052-08K MS21052-3K MS21052-4K MS21052-08W MS21052-3W MS21052-4W MS21052L08 MS21OS2L3 MS21052L4 MS21052L08K MS21052L3K MS210S2L4K MS21052L08W MS21052L3W MS21052L4W	T12C832 T12C1032 T12C428 T12C832BC T12C1032BC T12C428BC T12C832P T12C1032P T12C428P T12C832M T12C1032M T12C428M T12C832BCM T12C1032BCM T12C428BCM T12C832PM T12C1032PM T12C428PM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations, Cherry Divsion of Textron, Inc. P.O. BOX 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21052-5	T98S524CP	AMD Report No. MA768806 of 30 Jan 1969	
MS21052-O8 MS21052L08 MS21052-O8K MS21052LO8K NS21052-O8W MS21052LO8M MS21052-3 MS21052L3 MS21052-3K MS21052L3K MS21052-3W MS21052L3W MS21052-4 MS21052L4 MS21052-4K MS21052L4K MS21052-4W MS21052L4W	R1000C08 R1000C08M R1OOOCO8K R1OOOCO8MK R1OOOCO8W R1OOOCO8MW R1OOOC3 R1OOOC3M R1000C3K R1OOOC3MK R1000C3W R1000C3MM R1000C4 R1000C4M R1000C4K R1OOOC4MK R1000C4M R1OOOC4MW	Report No. 305Q76023 of 14 May 1976	Republic Fasteners Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21052-O6 MS21052LO6 MS21052-06K MS21052LO6K MS21052-O6W MS21052LO6W	R1000C06 R1OOOC06M R1OOOCO6K R100OC06MK R1000C06W R1000C06MW	Report No. 305Q83088 of 26 Jan 1983	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21052-08 **MS21052-08K**	**AJ-508** **AJ-508K**	**Report No. 305Q83112 of** 28 **Nov** 1983	**Simmonds Fastener** Technologies, Inc. 181 A West Orangethorpe Placentia, CA 92670
MS21052-3 **MS21052-3K**	AJ-53 AJ-53K	601Q8401 of 24 Feb 1984	**Plant:** **S i m m o n d s** 5, rue Michelet, B.P. 52 F..92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: **Cold** formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21052-4 MS21052L4	AJ-54 AJ-54M	NADC Report 601QB507 of 31 May 1985	

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21053 NUT, SELF-LOCKING, PLATE, ONE LUG, 100° CSK, LOW HEIGHT, ALLOY **STEEL**, 125 ksi Ftu, 450°F

MS21053-O8 MS21053LO8 MS21053-O8K MS21053LO8K MS21053-3 MS210S3L3 MS21053-3K MS21053L3K MS21053-4 MS21053L4 MS21053-4K MS21053L4K	R1100X08 R11OOAO8 R11OOXO8K R11OOAO8K R1100X3 R1100A3 R1100X3K R1100A3K R1100X4 R1100A4 R11OOX4K R110OA4K	Report No. 305Q83088 of 26 Jan 1983	Republic Fastener Mfg. Corp 1300 Rancho Conejo Blvd Newbury Park, CA 91320 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS .
MS21053-08	T12S H832CPC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Divsion of Textron, Inc. P.O. 80X 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21053-3	T12S H1032CPC		
MS21053-4	T12S H428CPC		
MS21053LO8	T12S H832		
MS21053L3	T12S H1032		
M21053L4	T12S H428		
M21053-08K	T12S H832BCCPC		
M21053-3K	T12S H1032BCCPC		
MS21053-4K	T12S H428BCCPC		
MS21053L08K	T12S H832BC		
MS21053L3K	T12S H1032BC		
MS21053L4K	T12S H428BC		
MMS21053-08	F52L LHTA54-82	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
M MS21053-3	F52L LHTA54-02		
MMS21053-4	F52L LHTA54-048		
MMS21053-5	F52L LHTA54-054		
MMS21053L08	RM52 LHTA54-82		
MMS21053L3	RM52 LHTA54-02		
MMS2105314	RM52 LHTA54-048		
MMS21053L5	RM52 LHTA54-054		
MMS21053-08K	F52L HTA54-82BC		
MMS21053-3K	F52L HTA54-02BC		
MMS21053-4K	F52L HTA54-048BC		
MMS21053-5K	F52L HTA54-054BC		
MMS21053L08K	RM52 LHTA54-82BC		
MMS21053L3K	RM52 LHTA54-02BC		
M MS21053L4K	RM52 LHTA54-048BC		
M MS21053L5K	RM52 LHTA54-054BC		
MS21053-08	15610N M-82	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MS21053-3	15610N M-02		
MS21053-4	15610N M-048		
MS21053-5	15610N M-054		
MS21053LO8	15610- -B2		
MS21053L3	15610- -02		
MS21053L4	15610- -048		
MS21053L5	15610- -054		
MS21053-O8K	15610N M-828C		
MS21053-3K	15610N M-02BC		
MS21053-4K	15610N M-048BC		
MS21053-5K	15610N M-054BC		
MS21053LO8K	15610- 82BC		
MS21053L3K	15610- -02BC		
MS21053L4K	15610- -048BC		
MS21053L5K	15610- -054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21053-O8	K21(100-08CW	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same **address**
MS21053-3	K21(100-3CW		
MS21053-4	K21(100-4CW		
MS21053-O8K	K21(100-08BCCW		
MS21053-3K	K21(100-3BCCW		
MS21053-4K	K21(100-4BCCW		
MS21053LO8	K21(100-08		
MS21053L3	K21(100-3		
MS21OS3L4	K21(100-4		
MS21053LO8K	K21(100-08BC		
MS21053L3K	K21(100-3BC		
MS21053L4K	K21(100-4BC		
MS21053-O8	AK-908	NADC Report 601Q8710 of 22 Jul 1987	Simmonds Fastener Tech. Inc. 181 A West Orangethorpe Placentia, CA 92670 Plant: **Simmonds** 5, rue Michelet B .P 52 F. 92152 Suresnes Cedex France
MS21053LO8	AK-908M		

NOTE: (1) Manufacturing process: Cold stamping
(2) Lubricant: For Government Designation with "LM QPL-8937
(3) provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21054 NUT, SELF-LOCKING, PLATE, ONE LUG, 100° CSK, LOW HEIGHT, CRES, 125 ksi Ftu, 450" 800"F

MMS21054-O8	15710-82	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MMS21054-3	15710-02		
MMS21054-4	15710-048		
MMS21054-5	15710-054		
MMS21054-08K	1571O-82BC		
MMS21054-3K	1571O-O28C		
MMS21054-4K	1571O-O48BC		
MMS21054-5K	1571O-O54BC		
MMS21054-O8W	1571O-82PWB		
MMS21054-3N	15710-02PWB		
MMS21054-4W	I571O-O48PWB		
MMS21054-5W	1571O-O54PWB		
MMS21054LO8	1571OE-82		
MMS21054L3	1571OE-O2		
MMS21054L4	1571OE-O48		
MMS21054L5	15710E-054		
MMS21054LO8K	1571OE-82BC		

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21054L3K MS21054L4K MS21054L5K MS21054L08H MS21054L3W MS21054L4W MS21054L5W	15710E-02BC 1571OE-O48BC 1571OE-O54BC 1571OE-82PWB 15710E-02PWB 1571OE-O48PWB 1571OE-O54PWB	Report NO. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies (Cont'd)
MS21054-08 MS21054LO8 MS21054-08K MS21054LO8K MS21054-O8W MS21054L08W MS21054-3 MS21054L3 MS21054-3K MS21054L3K MS21054-3W MS21054L3W MS21054-4 MS21054L4 MS21054-4K MS21054L4K MS21054-4W MS21054L4W	R11OOC08 R11OOCO8M R11OOCO8K R11OOCO8MK R1100C8W R11OOCO8MW R1100C3 R11OOC3M R110OC3K R1100C3MK R11OOC3W R1100CMW R1100C4 R1100C4M R1100C4K R110OC4MK R1100C4W R1100C4MW	Report No. 305Q83088 of 26 Jan 1983	Republic Fastener Mfg. Corp 1300 Rancho Conejo Blvd Newbury Park, CA 91320 Plant: Same address
MS21054-O8 MS21054-3 MS21054-4 MS21054-O8K MS21054-3K MS21054-4K MS21054-O8W MS21054-3W MS21054-4W MS21054L08 MS21054L3 MS21054L4 MS21054LO8K MS21054L3K MS21054L4K MS21054L08W MS21054L3W MS21054L4W	T12CH832 T12CH1032 T12CH428 T12CH832BC T12CH1032BC T12CH428BC T12CH832PWB T12CH1032PWB T12CH428P T12CH832M T12CH1032M T12CH428M T12CH832BCM T12CH1032BCM T12CH428BCM T12CH832PM T12CH1032PM T12CH428PM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of, Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21054L08	RMLHTA54-2860-82	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21054L3	RMLHTA54-2860-02		
MS1054L4	RMLHTA54-2860-048		
MS21054L5	RMLHTA54-2860-054		
MS21054LO8K	RHLHTA54-2860-82BC		
MS21054L3K	RMLHTA54-2860-02BC		
MS21054L4K	RMLHTA54-2860-048BC		
MS21054L5K	RMLHTA54-2860-054BC		
MS21054L08W	RMLHTA54-2860P-82		
MS21054L3W	RMLHTA54-2860P-02		
MS21054L4W	RMLHTA54-2860P-048		
MS21054L5W	RMLHTA54-2860P-054		
MS21054-08	LHTA54-2860-82		
MS21054-3	LHTA54-2860-02		
MS21054-4	LHTA54-2860-048		
MS21054-5	LHTA54-2860-054		
MS21054-O8K	LHTA54-2860-82BC		
MS21054-3K	LHTA54-2860-02BC		
MS21054-4K	LHTA54-2860-048BC		
MS21054-5K	LHTA54-2860-054BC		
MS21054-O8W	LHTA54-2860P-82		
MS21054-3W	LHTA54-2860P-02		
MS21054-4W	LHTA54-2860P-048		
MS21054-5W	LHTA54-2860P-054		
MS21054-08	K2131-08	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21054-3	K2131-3		
MS21054-4	K2131-4		
MS21054-08K	K2131-08BC		
MS21054-3K	K2131-3BC		
MS21054-4K	K2131-4BC		
MS21054-O8W	K2131-08P		
MS21054-3W	K2131-3P		
MS21054-4W	K2131-4P		
MS21054LO8	K2101-O8		
MS21054L3	K2101-3		
MS21054L4	K2101-4		
MS21054L08K	K2101-O8BC		
MS21054L3K	K2101-3BC		
MS21054L4K	K2101-4BC		
MS21054L08W	K2101-O8P		
MS21054L3W	K2101-3P		
MS21054L4W	K2101-4P		

MS21055 NUT, SELF-LOCKING, PLATE, CORNER, LOW HEIGHT, ALLOY STEEL, 125 ksi Ftu, 450°F

MS21055-O6	12620NM-62	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21055-O8	12620NM-82		
MS21055-3	12620NM-02		
MS21055-4	12620NM-048		
MS21055-5	12620NM-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MSZ1055-6	12620NM-064	Report No.	SPS Technologies
MS21055L06	12620-62	NAEC-AML-2369	(Cont'd)
MS21055LO8	12620-82	of 15 Mar 1966	
MS21055L3	12620-02		
MS21055L4	12620-048		
MS21055L5	12620-054		
MS21055L6	12620-064		
MS21055-06K	12620NM-62BC		
MS21055-08K	12620NM-82BC		
MS21055-3K	12620NM-02BC		
MS21055-4K	12620NM-048BC		
MS21055-5K	12620NM-054BC		
MS21055LO6K	12620-62BC		
MS21055L08K	12620-82BC		
MS21055L3K	12620-02BC		
MS21055L4K	12620-048BC		
MS21055L5K	12620-054BC		
MS21055-O6	VN103-C1-62	Report No.	VOI-SHAN
MS21055-O8	VN103-C1-82	NAEC-AML-2425	VSI Aerosp. Prod. Div.
MS21055-3	VN103-C1-02	of 15 Mar 1966.	8463 Higuera Street. ... .
MS21055-4	VN103-C1-048		Culver City, CA 90230
MS21055-5	VN103-C1-054		
MS21055-6	VN103-C1-O64		Plant:
MS21055LO6	VN103-A1-62		2700 Compton Blvd.
MS21055LO8	VN103-A1-82		Redondo Beach, CA 90278
MS21055L3	VN103-A1-O2		
MS21055L4	VN103-A1-O48		
MS21055L5	VN103-A1-O54		
MS21055L6	VN103-A1-064		
MS21055-O6K	VN103-C2-62		
MS21055-O8K	VN103-C2-82		
MS21055-3K	VN103-C2-O2		
MS21055-4K	VN103-C2-048		
MS21055-5K	VN103-C2-O54		
MS21055LO6K	VN103-A2-62		
MS21055L08K	VN103-A2-82		
MS21055L3K	VN103-A2-O2		
MS21055L4K	VN103-A2-O48		
MS21055L5K	VN103-A2-054		
MS21055-06	T7S632CPC	Report No.	Cherry Textron, Cherry
MS21055-08	T7S832CPC	NAEC-AML-2428	Aerospace Operations,
MS21055-3	T7S1032CPC	of 15 Mar 1966	Cherry Division of
MS21055-4	T7S428CPC		Textron, Inc.
MS21055-5	T7S524CPC		P.O. **80X** 2157
MS21055-6	T7S624CPC		1224 East Warner Ave.
MS21055LO6	T7S632		Santa Aria, CA 92707-0157
MS21055LO8	T7S832		
NS21055L3	T7S1032		Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21055L4	T7S428	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations, (Cent'd)
MS21055L5	17S524		
MS21055L6	17S624		
MS21055-O6K	T7S632BCCPC		
MS21055-08K	T7S832BCCPC		
MS2105S-3K	T7S1032BCCPC		
MS21055-4K	T7S428BCCPC		
MS21055-5K	T7S5248CCPC		
MS21055LO6K	T7S632BC		
MS21055L08K	T7S8328C		
MS21055L3K	T7S1032BC		
MS210S5L4K	T7S428BC		
MS210S5LSK	T7S524BC		
MS21055-O6	F52LHTA55-62	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union NJ 07083 Plant:: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21055-08	F52LHTA55-82		
MS21055-3	F52LHTA55-02		
MS21055-4	F52LHTA55-048		
MS21055-5	F52LHTA55-054		
MS21055-6	F52LHTA55-064		
MS21055L06	RM52LHTA55-62		
MS21055LO8	RM52LHTA55-82		
MS21055L3	RM52LHTA55-02		
MS21055L4	RM52LHTA55-048		
MS21O55L5	RM52LHTA55-054		
MS21055L6	RM52LHTA55-064		
MS21055-O6K	F52LHTA55-62BC		
MS21055-O8K	F52LHTA55-82BC		
MS21O55-3K	F52LHTA55-02BC		
MS21055-4K	F52LHTA55-048BC		
MS21055-5K	F52LHTA55-054BC		
MS21055L06K	RM52LHTA55-62BC		
MS21O55LO8K	RM52LHTA55-82BC		
MS21055L3K	RM52LHTA55-02BC		
MS21055L4K	RM52LHTA55-0488C		
MS21055L5K	RM52LHTA55-054BC		
MS21055-06	K3000-06CW	Report No. NAEC-AML-2474 of 15 June 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21055-O8	K3000-08CW		
MS21055-3	K3000-3CW		
MS21055-4	K3000-4CW		
MS21055-5	K3000-5CW		
MS21055-6	K3000-6CW		
MS21055-O6K	K3000-06BCCW		
MS21055-O8K	K3000-08BCCW		
MS21055-3K	K3000-3BCCW		
MS21055-4K	K3000-4BCCW		
MS21055-5K	K3000-5BCCW		
MS21055LO6	K3000-06		
MS21055L08	K3000-08		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21055L3	K3000-3	Report No.	Microdot, Inc.
MS21055L4	K3000-4	NAEC-AML-2474	KAYNAR Div.
MS21055LS	K3000-5	of 15 June 1966	(Cent'd)
MS21055L6	K3000-6		
MS21055LO6K	K3000-06BC		
MS21055L08K	K3000-08BC		
MS21055L3K	K3000-3BC		
MS21055L4K	K3000-4BC		
MS21055L5K	K3000-58C		
MS21055L7	K3000-7	Report No. 305Q83097 of 22 Mar 1983	

NOTE : Manufacturing process: Machined

MS21055-08	R3000X08	Report No.	Republic Fastener
MS21055L08	R3000A08	305Q76023 of	Mfg. Corp.
MS21055-O8K	R3000X08K	14 May 1976	1300 Rancho Conejo Blvd.
MS21055L08K	R3000A08K		Newbury Park, CA 91320
MS21055-3	R3000X3		
MS21055L3	R3000A3		Plant: Same address
MS21055-3K	R3000X3K		
MS21055L3K	R3000A3K		
MS21055-4	R3000X4		
MS21055L4	R3000A4		
MS21055-4K	R3000X4K		
MS21055L4K	R3000A4K		
MS21055-O6	R3000X06	Report No.	
MS21055LO6	R3000A06	305Q83088 of	
MS21055-O6K	R3000X06K	26 Jan 1983	
MS21055LO6K	R3000A06K		

MS21056 NUT, SELF-LOCKING, PLATE, CORNER, LOW HEIGHT, CRES, 125 ksi Ftu, 450° & 800"F

MS21056-O6	12720-62	Report No.	SPS Technologies
MS21056-O8	12720-82	NAEC-AML-2369	2701 S. Harbor Blvd.
MS21056-3	12720-02	of 15 Mar 1966	Santa Ana, CA 92707
MS21056-4	12720-048		
MS21056-5	12720-054		Plant: Same address
MS21056-6	12720-064		
MS21056-O6K	12720-62BC		
MS21056-O8K	12720-82BC		
MS21056-3K	12720-02BC		
MS21056-4K	12720-048BC		
MS21056-5K	12720-054BC		
MS21056-O6W	12720-62PW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21056-08W	12720-82PW	Report No. NAEC-ANL-2369 of 15 Mar 1966	SPS Technologies (Cent'd)
MS21056-3W	12720-02PW		
MS21056-4W	12720-048PW		
MS21056-5W	12720-054PW		
MS21056-6W	12720-064PW		
MS21056L06	12720E-62		
MS21056L08	12720E-82		
MS21056L3	12720E-02		
MS21056L4	12720E-048		
MS21056L5	12720E-054		
MS21056L6	12720E-064		
MS21056L06K	12720E-62BC		
MS21056L08K	12720E-82BC		
MS21056L3K	12720E-02BC		
MS21056L4K	12720E-048BC		
MS21056L5K	12720E-054BC		
MS21056L06W	12720E-62PW		
MS21056&08W	12720E-82PW		
MS21056L3W	12720E-02PW		
MS21056L4W	12720E-048PW		
MS21056L5W	12720E-054PW		
MS21056L6W	12720E-064PW		
MS21056-06	VN103-B1-62	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. DIv. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21056-O8	VN103-B1-82		
MS21056-3	VN103-81-02		
MS21056-4	VN103-B1-O48		
MS21056-5	VN103-B1-O54		
MS21056-6	VN103-B1-O64		
MS21056-O6K	VN103-B2-62		
MS21056-O8K	VN103-B2-82		
MS21056-3K	VN103-B2-O2		
MS21056-4K	VN103-B2-O48		
MS21056-5K	VN103-B2-O54		
MS21056-O6W	VN103-B3-62		
MS21056-O8W	VN103-B3-82		
MS21056-3W	VN103-B3-02		
MS21056-4W	VN103-B3-048		
MS21056-5W	VN103-B3-O54		
MS21056-6W	VN103-B3-O64		
MS21056LO6	VN103-D1-62		
MS21056LO8	VN103-D1-82		
MS21056L3	VN103-D1-O2		
MS21056L4	VN103-D1-O48		
MS21056L5	VN103-D1-O54		
MS21056L6	VN103-D1-O64		
MS21056LO6K	VN103-D2-62		
MS21056LO8K	VN103-D2-82		
MS21056L3K	VN103-D2-O2		
MS21056L4K	VN103-D2-O48		
MS21056L5K	VN103-D2-O54		
MS21056L06W	VN103-D3-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21056LO8W	VN103-D3-82	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. (Cent'd)
MS21056L3W	VN103-D3-O2		
MS21056L4W	VN103-D3-048		
MS21056L5W	VN103-D3-O54		
MS21056L6W	VN103-O3-O64		
MS21056LO6	RMLHTA55-2860-62	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A **Division of** Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21056LO8	RMLHTA55-2860-82		
MS21056L3	RMLHTA55-2860-02		
MS21056L4	RMLHTA55-2860-048		
MS21056L5	RMLHTA55-2860-054		
MS21056L6	RMLHTA55-2860-064		
MS21056LO6K	RMLHTA55-2860-62BC		
MS21056LO8K	RMLHTA55-2860-82BC		
MS21056L3K	RMLHTA55-2860-02BC		
MS21056L4K	RMLHTA55-2860-048BC		
MS21056L5K	RMLHTA55-2860-054BC		
MS210S6L06W	RMLHTA55-2860P-62		
MS21056LO8W	RMLHTA55-2860P-82		
MS21056L3W	RMLHTA55-2860P-02		
MS21056L4W	RMLHTA55-2860P-048		
MS21056L5W	RMLHTA55-2860P-054		
MS21056L6W	RMLHTA55-2860P-064		
MS21056-06	LHTA55-2860-62		
MS21056-O8	LHTA55-2860-82		
MS21056-3	LHTA55-2860-02		
MS21056-4	LHTA55-2860-048		
MS21056-5 .	LHTA55-2860-054		
MS21056-6	LHTA55-2860-064		
MS21056-O6K	LHTA55-2860-62BC		
MS21056-O8K .	LHTA55-2860-82BC		
MS21056-3K	LHTA55-2860-028C		
MS21056-4K	LHTA55-2860-048BC		
MS21056-5K	LHTA55-2860-054BC		
MS21056-O6W	LHTA55-2860P-62		
MS21056-O8W	LHTA55-2860P-82		
MS21056-3W	LHTA55-2860P-02		
MS21056-4W	LHTA55-2860P-048		
MS21056-5W	LHTA55-2860P-054		
MS21056-6W	LHTA55-2860P-064		
MS21056-06	T7C632	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. BOX 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21056-08	T7C832		
MS21056-3	T7C1032		
MS21056-4	T7C428		
MS21056-5	T7C524		
M21056-6	T7C624		
MS21056-06K	T7C632BC		
MS21056-O8K	T7C832BC		
MS21056-3K	T7C10328C		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21056-4K	T7C428BC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, (Cent'd)
MS21056-5K	**T7C524BC**		
MS21056-06W	**T7C632PWB**		
MS21056-O8W	**T7C832PWB**		
MS21056-3W	**T7C1032PWB**		
MS210564W	**T7C428PWB**		
MS21056-5W	**T7C524PWB**		
MS21056-6W	**T7C624PWB**		
MS21056L06	**T7C632M**		
MS21056L08	**T7C832M**		
MS21056L3	**T7C1032M**		
MS21056L4	**T7C42BM**		
MS21056L5	**T7C524M**		
MS21056L6 -	**T7C624M**		
MS21056L06K	**T7C632BCM**		
MS21056L08K	**T7C832BCM**		
MS21056L3K	**T7C1032BCM**		
MS21056L4K	**T7C428BCM**		
MS21056L5K	**T7C524BCM**		
MS21056L06W	**T7C632PM**		
MS21056L08W	**T7C832PM**		
MS21056L3W	**T7C1032PM**		
MS21056L4W	**T7C428PM**		
MS21056L5W	**T7C524PM**		
MS21056L6W	**T7C624PM**		
MS21056-O6	K3031-06	Report No. NAEC-AML-2474 of 15 June 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College **Blvd.** ,Fullerton, CA 92634 Plant: Same address
MS21056-O8	K3031-08		
MS21056-3	K3031-3		
MS21056-4	K3031-4		
MS21056-5	K3031-5		
MS21056-6	K3031-6		
MS21056-O6K "	K3031-06BC		
MS21056-O8K	K3031-08BC		
MS21056-3K	K3031-3BC		
MS21056-4K	K3031-4BC		
MS21056-5K	K3031-5BC		
MS2105-06W	K3031-06P		
MS21056-O8W	K3031-08P		
MS21056-3W	K3031-3P		
MS21056-4W	K3031-4P		
MS21056-5W	K3031-5P		
MS21056-6W	K3031-6P		
MS21056LO6	K3001-06		
MS21056LO8	K3001-08		
MS21056L3	K3001-3		
MS21056L4	K3001-4		
MS21056L5	K3001-5		
MS21056L6	K3001-6		
MS21056LO6K	K3001-06BC		
MS21056LO8K	K3001-08BC		
MS21056L3K	K3001-3BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21056L4K	K3001-4BC	Report No.	Microdot, Inc.
MS21056L5K	K3001-5BC	NAEC-AML-2474	KAYNAR Div.
MS21056LO6W	K3001-06P	of 15 Jun 1966	(Cent'd)
MS21056LO8W	K3001-08P		
MS21056L3W	K3001-3P		
MS21056L4W	K3001-4P		
MS21056L5N	K3001-5P		
MS21056L6W	K3001-6P		
MS21056-O8	R3000C08	Report No.	Republic Fastener Mfg.
MS21056LO8	R3000C08M	305Q76023 of	Corp.
MS21056-O8K	R3000C08K	14 May 1976	1300 Rancho Conejo Blvd.
MS21056L08K	R3000C08MK		Newbury Park, CA 91320
MS21056-O8W	R3000C08W		
MS21056LO8W	R3000C08MW		Plant: Same address
MS21056-3	R3000C3		
MS21056L3	R3000C3M		
MS21056-3K	R3000C3K		
MS21056L3K	R3000C3MK		
MS21056-3W	R3000C3W		
MS21056L3W,	R30003MW		
MS21056-4	R3000C4		
MS21056L4	R3000C4M		
MS21056-4K	R3000C4K		
MS21056L4K	R3000C4MK		
MS21056-4W	R3000C4W		
MS21056L4W	R3000C4MW		
MS21056-O6	R3000C06	Report No.	
MS21056LO6	R3000C06M	305Q83088 of	
MS21056-06K	R3000C06K	26 Jan 1983	
MS21056L06K	R3000C06MK		
MS21056-06W	R3000C06W		
MS21056LO6W	R3000C06MW		

MS21057 NUT, SELF-LOCKING, PLATE, CORNER, 100° CSK, LOW HEIGHT, ALLOY STEEL, 125 ksi Ftu, 450°F

MS2 1057-08	R31OOXO8	Report No.	Republic Fastener
MS2 1057L08	R3100A08	305Q83088 of	Mfg. Corp
MS2 1057-08K	R31OOXO8K	26 Jan 1983	1300 Rancho Conejo Blvd
MS2 1057L08K	R31OOAO8K		Newbury Park, CA 91320
MS2 1057-3	R31OOX3		
MS2 1057L3	R3100A3		Plant: Same address
MS2 1057-3K	R3100X3K		
MS2 1057L3K	R3100A3K		
MS2 1057-4	R3100X4		
MS2 1057L4	R3100A4		
MS2 1057-4K	R31OOX4K		
MS2 1057L4K	R3100A4K		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S , DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21057-08	T7SH832CPC	Report No. NAEC-AML-2428 **of 15** Mar **1966**	Cherry Textron, Cherry Aerospace **Operation, Cherry Division of** Textron, Inc P.O. Box 2157 1224 East Warner Ave. Santa Aria, CA 927074)157 Plant: Same address"
MS21057-3	T7SH1032CPC		
MS21057-4	T7SH428CPC		
MS21057-5	T7SH524CPC		
HS21057-08K	T7SH832BCCPC		
MS21057-3K	T7SH1032BCCPC		
MS21057-4K	T7SH428BCCPC		
MS21057-5K	17SH524BCCPC		
MS21057L08	17SH832		
MS210S7L3	T7SH1032		
MS21057L4	T7SH428		
MS21057L5	T7SH524		
MS21057LO8K	17SH832BC		
MS21057L3K	17SH1032BC		
MS21057L4K	T7SH428BC		
MS21057L5K	T7SH524BC		
MS21(0157-08	F52LHTA35-82	Report No. NAEC-AML-2429 **of 15 Mar 1966**	Elastic Stop Nut **A Division of** Harvard Industries, Inc. 2330 Vauxhall Road.; . Union, NJ 07083 **Plant: Same** address **and** 3200 Country Club **Road** Pocahontas, AR 72455
MS21(1057-3	F52LHTA35-02		
MS21(1057-4	F52LHTA35-048		
MS21(1057-5	F52LHTA35-054		
MS21(1057L08	RMS2LHTA35-82		
MS21(1057L3	RM52LHTA35-02		
MS21(1057L4	RM52LHTA35-048		
MS21(1057L5	RM52LHTA35-054		
MS21(1057-08K	F52LHTA35-82BC		
MS21(1057-3K	F52LHTA35-02BC		
MS21(1057-4K	F52LHTA35-048BC		
MS21(1057-SK	F52LHTA35-054BC		
MS21(1057L08K	RM52LHTA35-82BC		
MS21(1057L3K	RM52LHTA35-02BC		
MS21(1057L4K	RM52LHTA35-048BC		
MS21(1057L5K	RM52LHTA35-054BC		
MS21057-08	K3100-08CW	Report No. NAEC-AML-2474 of 15 June 1966	Microdot. Inc. KAYHAR **Div.** P.O. Box. 3001 800 S. State College Fullerton, CA 92634 Plant: **Same address**
MS21057-3	K3100-3CW		
MS21057-4	K3100-4CW		
MS21057-5	K3100-5CW		
MS21057-08K	K3100-08BCCW		
MS21057-3K	K3100-3BCCW		
MS21057-4K	K3100-4BCCW		
MS21057-5K	K3100-5BCCW		
MS21057LO8	K3100-O8		
MS21057L3	K3100-3		
MS21057L4	K3100-4		
MS21057L5	K3100-5		
MS21057LO8K	K3100-08BC		
MS21057L3K	K3100-3BC		
MS21057L4K	K3100-4BC		
MS21057L5K	**K3100-5BC**		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21057-O8	15620NM-82	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21057-3	15620NM-02		
MS21057-4	15620NM-048		
MS21057-5	15620NM-054		
NS21057LO8	15620-82		
MS21057L3	15620-02		
MS21057L4	15620-048		
MS21057L5	15620-054		
MS21057-O8K	15620NM-82BC		
MS21057-3K	15620NM-028C		
MS21057-4K	15620NM-048BC		
MS21057-5K	15620NM-054BC		
MS21057LO8IC	15620-82BC		
MS21057L3K	15620-02BC		
MS21057L4K	15620-0488C		
MS21057L5K	15620-054BC		

MS21058 NUT, SELF-LOCKING, PLATE, CORNER, 100° CSK, LOW HEIGHT, CRES, 125 ksi Ftu, 450°F & 800°F

MS21058-08	R3 100C08	Report No. 305Q83088 of 26 Jan 1983"	Republic Fastener Mfg. Corp 1300:Rancho Conejo Blvd Newbury Park, CA 91320 Plant: Same address
MS21058L08	R3 100C08M		
MS21OS8-O8K	R3 100C08K		
MS21058LO8K	R3 **100C08MK**		
MS21058-O8W	R3 100C08W		
MS1058LO8W	R3 100C08MW		
MS21058-3	R3 100C3		
MS21058L3	R3 100C3M		
MS21058-3K	R3 100C3K		
MS21058L3K	R3 100C3MK		
MS21058-3W	R3 100C3W		
MS21058L3W	R3 100C3NW		
MS21058-4	R3 100C4		
MS21058L4	R3 100C4M		
MS21058-4K	R3 100C4K		
MS21058L4K	R3 100C4MK		
MS21058-4W	R31OOC4W		
MS21058L4W	R31OOC4MW		

MS21058-O8	T7CH832	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. **BOX** 2157 1224 East Namer Ave. Santa Ana, CA 92707-0157 Plant: Same address
MS21058-3	T7CH1032		
MS21058-4	T7CH428		
MS21058-5	T7CH524		
MS21058-O8K	T7CH832BC		
MS21058-3K	T7CH1032BC		
MS21058-4K	T7CH428BC		
MS21058-5K	T7CH524BC		
MS21058-O8W	T7CH832P		
MS21058-3W	T7CH1032P		
MS21058-4W	T7CH428P		
MS21058-5W	T7CH524P		
MS21058LO8	T7CH832M		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21058L3	T7CH1032M	Report No.	Cherry Textron, Cherry
MS21058L4	T7CH428M	NAEC-AML-2428	Aerospace Operation,
MS21058L5	T7CH524M	of 15 Mar 1966	(Cont'd)
MS21058L08K	T7CH832BCM		
MS21058L3K	T7CH10328CM		
MS21058L4K	T7CH4288CM		
MS21058L5K	T7CI15248CM		
MS21058L08W	T7CN832PM		
MS21058L3W	T7CH1032PM		
MS21058L4W	T7CH428PM		
MS21058L5W	T7CH524PM		
MS21058L08	**RMLHTA35-2860-82**	Report No.	Elastic Stop Nut
MS21058L3	RMLHTA35-2860-02	NAEC-AML-2429	A Division of
MS21058L4	RMLHTA35-2860-048	of 15 Mar 1966	Harvard Industries, Inc.
MS21058L5	RMLHTA35-2860-054		2330 Vauxhall Road
MS21058L08K	RMLHTA35-2860-82BC		Union, NJ 07083
MS21058L3K	RMLHTA35-2860-02BC		
MS21058L4K	RMLHTA35-2860-048BC		Plant: Same address and
MS21058L5K	RMLHTA35-2860-054BC		3200 Country Club Road
MS23058L08W	RMLHTA35-2860P-82		Pocahontas, AR 72455
MS21058L3W	RMLHTA35-2860P-02		
MS21058L4W	RMLHTA35-2860P-048		
MS21058L5W	RMLHTA35-2860P-054		
MS21058-O8	LHTA35-2860-82		
MS21058-3	LHTA35-2860-02		
MS21058-4	LHTA35-2860-048		
NS21058-5	LHTA35-2860-054		
MS21058-O8K	LHTA35-2860-82BC		
MS21058-3K	LHTA3S-2860-02BC		
MS21058-4K	LHTA35-2860-048BC		
MS21058-5K	LHTA35-2860-054BC		
MS21058-O8W	LHTA35-2860P-82		
MS21058-3W	LHTA35-2860P-02		
MS21058-4W	LHTA35-2860P-048		
MS21058-5W	LHTA35-2860P-054		
MS21058-08	15720-82	Report No.	SPS Technologies
MS21058-3	15720-02	NAEC-AML-2369	2701 S.Harbor Blvd.
MS21058-4	15720-048	of 15 Mar 1966	Santa Ana, CA 92702
MS21058-5	15720-054		
MS21058-O8K	15720-82BC		Plant: Same address
MS21058-3K	15720-02BC		
MS21058-4K	15720-048BC		
MS21058-5K	15720-054BC		
MS21058-O8W	15720-82PW		
MS21058-3W	15720-02PW		
MS21058-4W	15720-048PW		
MS21058-5W	15720-054PW		
MS21058L08	15720E-82		

Source: https://assist.dla.mil Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION -	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21058L3	15720E-02	Report No.	SPS Technologies
MS21058L4	15720E-048	NAEC-AML-2369	(Cont'd)
MS21058L5	15720E-054	of 15 Mar 1966	
MS21058L08K	15720E-82BC		
MS21058L3K	15720E-02BC		
MS21058L4K	15720E-048BC		
MS21058L5K	15720E-054BC		
MS21058L08W	15720E-82PW		
MS21058L3W	15720E-02PW		
MS21058L4W	.15720E-048PW		
MS21058L5W	15720E-054PW		
MS21058-08	K3131-08	Report No.	Microdot, Inc.
MS21058-3	K3131-3	NAEC-AML-2474	KAYNAR Div.
MS21058-4	K3131-4	of 15 Jun 1966	P.O. Box 3001
MS21058-5	K3131-5		800 S. State College Blvd.
MS21058-08K	K3131-08BC		Fullerton, CA 92634
MS21058-3K	K3131-3BC		
MS21058-4K	K3131-48C		
MS21058-5K .	K3131-5BC		Plant: Same address
MS21058-08W	K3131-08P		
MS210S8-3W	K3V31-3P		
MS21058-4W	K3131-4P		
MS21058-5W	K3131-5P		
MS21058L08	K3101-08		
MS21058L3	K3101-3		
MS21058L4	K3101-4		
MS21058L5	K3101-5		
MS21058L08K	K3101-08BC		
MS21058L3K	K3101-3BC		
MS21058L4K	K3101-4BC		
MS21058L5K	K3101-5BC		
MS21058L08W	K3101-08P		
MS21058L3W	K3101-3P		
MS21058L4W	K3101-4P		
MS21058L5W	K3101-5P		

MS21059 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, LOW HEIGHT, ALLOY STEEL, 125 ksi Ftu, 450"F

MS21059-04	T65S440SCPC	Report No.	Cherry Textron, Cherry Aerospace Operation,
MS21059-06	T65S632SCPC	NAEC-AML-2428	Cherry Division of Textron, Inc.
MS21059-08	T65S832SCPC	of 15 Mar 1966	P.O. **Box** 2157
MS21059-3	T65S1032SCPC		1224 East Warner Ave.
MS21059-4	T65S428SCPC		Santa Ana, CA 92707-0157
MS21059-5	T65S524SCPC		
MS21059-6	T65S624SCPC		Plant: Same address
MS21059L04	T65S440S		
MS21059L06	T65S632S		
MS21059L08	T65S832S		
MS21059L3	T65S1032S		

Source: https://assist.dla.mil -- Downloaded: 2026t0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21059L4	T65S428S	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace operation, (Cont'd)
MS21059L5	T65S524S		
MS21059L6	T65S624S		
MS21059-04K	T65S440SBCCPC		
MS21059-06K	T65S632SBCCPC		
MS21059-O8K	T65S832SBCCPC		
MS21059-3K	T65S103ZSBCCPC		
MS21059-4K	T65S428SBCCPC		
MS21059-5K	T65S524SBCCPC		
MS210S9L04K	T65S440SBC		
MS21059L06K	T65S632SBC		
MS21059L08K	T6SS832SBC		
MS21059L3K	T65S1032SBC		
MS21059L4K	T65S428SBC		
MS21059L5K	T 6 5 S 5 2 4 S B C		
MS21059-04	F52LHTA521-40	Report No. NAEC-AML-2429 of 15 Mar 1966	-Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083, Plant: Same address 3200 Country Club Road, Pocahontas, AR 72455
MS21059-06	F52LHTA521-62		
MS21059-O8	F52LHTA521-82		
MS21059-3	F52LHTA521-02		
MS21059-4	F52LHTA521-048		
MS21059-5	F52LHTA521-054		
MS21059-6	F52LHTA521-064		
MS21059LO4	RM52HTA521-40		
MS21059L06	RM52HTA521-62		
MS21059LO8	RM52HTA521-82		
MS21059L3	RM52HTA521-02		
MS21059L4	RM52HTA521-048		
MS21059L5	RM52 HTA521-054		
MS21059L6	RM52 HTA521-064		
MS21059-O4K	F52L HTA521-40BC		
MS21059-O6K	F52LHTA521-62BC		
MS21059-O8K	F52LHTA521-826C		
NS21059-3K *	F52LHTA521-02BC		
MS21059-4K	F52LHTA521-048BC		
MS21059-5K	F52LHTA521-054BC		
MS21059LO4K	RM52LHTA521-40BC		
MS21059L06K	RMS2LHTA521-62BC		
MS21059LO8K	RM52LHTA521-82BC		
MS21059L3K	RM52LHTA521-02BC		
MS21059L4K	RM52LHTA521-048BC		
MS21059L5K	RM52LHTA521-054BC		
MS21059-04	13605NM-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21059-06	13605NM-62		
MS21059-O8	13605NM-82		
MS21059-3	13605NM-02		
MS21059-4	13605NM-048		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21059-5	13605NM-054	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies (Cent'd)
MS21059-6	13605NM-064		
MS21059L04	13605-40		
MS21059LO6	13605-62		
MS21059L08	13605-82		
MS21059L3	13605-02		
MS21059L4	13605-048		
MS21059L5	13605-054		
MS21059L6	13605-064		
MS21059-O4K	13605NM-40BC		
MS21059-06K	13605NM-62BC		
MS21059-08K	13605NM-82BC		
MS21059-3K	13605NM-02BC		
MS21059-4K	13605NM-048BC		
MS21059-5K	13605NM-054BC		
MS21059LO4K	13605NM-40BC		
MS21059L06K	13605-62BC		
MS21059L08K	13605-82BC		
MS21059L3K	13605-02BC		
MS21059L4K	13605-048K		
MS21059L5K	13605-0548C		
MS21059-O4	VN152-C1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21059-O6	VN152-C1-62		
MS21059-O8	VN152-C1-82		
MS21059-3	VN152-C1-02		
MS21059-4	VN152-C1-048		
MS21059-5	VN152-C1-054		
MS21059-6	VN152-C1-064		
MS21059L04	VN152-A1-40		
MS21059LO6	VN152-A1-62		
MS21059LO8	VN152-A182		
MS21059L3	VN152-A1-02		
MS21059L4	VN152-A1-048		
MS21059L5	VN152-A1-054		
MS21059L6	VW152-A1-064		
MS21059-O4K	VN152-C2-40		
MS21059-O6K	VN152-C2-62		
MS21059-O8K	VN152-C2-82		
MS21059-3K	VN152-C2-02		
MS21059-4K	VN152-C2-048		
MS21059-5K	VN152-C2-054		
MS21059LO4K	VN152-A2-40		
MS21059L06K	VN152-A2-62		
MS21059L08K	VN152-A2-82		
MS21059L3K	VN152-A2-02		
MS21059L4K	VN152-A2-048		
MS21059L5K	VN152-A2-054		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME. AND ADDRESS
MS21059-04	F5000-04CW	Report No. NAEC-AML-2474 of 15 June 1966	Microdot, Inc. KAYMAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address .
MS21059-06	F5000-06CW		
MS21059-08	F5000-08CW		
MS21059-3	F5000-3CW		
MS21059-4	F5000-4CW		
MS21059-5	F5000-5CW		
MS21059-6	F5000-6CW		
MS21059-04K	F5000-4BCCW		
MS21059-06K	F5000-06BCCW		
MS21059-08K	F5000-08BCCW		
MS21059-3K	F5000-3BCCW		
MS21059-4K	F5000-4BCCW		
MS21059-5K	F5000-5BCCW		
MS21059L04	F5000-04		
MS21059L06	F5000-06		
MS21059L08	F5000-08		
MS21059L3	F5000-3		
MS21059L4	F5000-4		
MS21059L5	F5000-5		
MS21059L6	F5000-6		
MS21059L04K	F5000-048C		
MS21059L06K	F5000-06BC		
MS21059L08K	F5000-08BC		
MS21059L3K	.. F5000-3BC		
MS21059L4K	F5000-4BC		
MS21059L5K	F5000-5BC		
MS21059L3	EF5000-3	NADC Report No. 601Q8705 of 20 May 1987	Microdot Aerospace Limited Blackthorn Road Colnbrook, Slough SL3 0AG England Plant: Same Address

NOTE: (1) Manufacturing process: Strip
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Government Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions In every subcontract and purchase order.

MS21059-04	RF200X04	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21059L04	RF200A04		
MS21059-04K	RF200X04K		
MS21059L04K	RF200A04K		
MS21059-06	RF200X06		
MS21059L06	RF200A06		
MS21059-06K	RF200X06K		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21OS9LO6K MS21059-08 MS21059LO8 MS21059-08K MS21059L08K MS21059-3 MS21059L3 MS21059-3K MS21059-L3K MS21059-4 MS210591-4 MS21059-4K MS21059L4K	RF200A06K RF200X08 RF200A08 RF200X08K RF200A08K RF200X3 RF200A3 RF200X3K RF200A3K RF200X4 RF200A4 RF200X4K RF200A4K	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp . (Cent'd)

NOTE: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21059-S MS21059L5 MS21059-5K MS21059L5K	RF200X5 RF200A5 RF200X5K RF200A5K	Report No. 305Q76023 of 14 May 1976	
MS21059-6 MS21059L6	RF200X6 RF200A6	NADC Report No. 305Q76024 of 8 Oct 1976	
MS21059L3	LA-93M	Report No. 305Q83101 of 5 May 1983	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670
MS21059L3K	LA-93MK	305Q83104 of 12 Aug 1983	Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresenes Cedex France
MS21059LO8 MS21059L08K	LA-908M LA-908MK	305Q83112 of 28 Nov 1983	
MS21059-O8 MS21059-3	LA-908 LA-93	601Q8407 of 20 Apr 1984	

NOTE : (1) Manufacturing process: Cold formed with "L") QPL-8937
(2) Lubricant: (For Government Designation urement of these self-locking
(3) Provisions Governing Procurement. Proc .225-3 (Buy American Act) and
nuts shall be in accordance with FAR 52 tic Specialty Metals). The
DFARS 52.225-7012 (Preference for Domes ons in every subcontract and
contractor should Include these provisi
purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21059-4 **MS21059-4K** **MS21059L4** **MS21059L4K**	IA-94 LA-94K LA-94M LA-94MK	NADC Report 60108417 of 25 0ct 1984	Simmonds Fastener Technologies Inc. (Cent'd)
MS21059-O6 **MS21059-O6K** **MS21059LO6** **MS21059L06K**	LA-906 LA-9(I6K LA-906M LA-906MK	NADC Report 601Q8510 0f 10 Jun 1985	

NOTE: (i) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") **QPL-8937**
(3) **Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with 'FAR 52.225-3** (Buy American Act) and DFARS 52.22-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS2106O NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, LOW HEIGHT, CRES, 125 ksi Ftu, 450"F & 800°F

MS21**060-04**	137**05-40**	**Report No.**	**SPS** Technologies
MS21060-06	137(05-62	NAEC-AML-2369	2701 S. Harbor Blvd."
MS21060-08	137(05-82	of 15 Mar 1966	Santa Aria. CA 92702
MS21060-3	137(05-02		
MS21060-4	137(05-048		Plant: Same address-
MS21060-5	137(05-054		
MS21060-6	137(05-064		
MS21060-04K	137(05-40BC		
MS21060-06K	137(05-62BC		
MS21060-08K	137(05-82BC		
MS21060-3K	137(05-02BC		
MS21060-4K	137(05-048BC		
MS21060-5K	137(05-054BC		
MS21060-04W	137(05-40PW		
MS21060-06W	137(05-62PW		
MS21060-08W	137(05-82PW		
MS21060-3W	137(05-02PW		
MS21060-4W	137(05-048PW		
MS21060-5W	137(05-054PW		
MS21060-6W	137(05-064PW		
MS21060L04	137(05E-40		
MS21060L06	137(05E-62		
MS21060L08	137(05E-82		
MS21060L3	137(05E-02		
MS21060L4	137(05E-048		
MS21060L5	137(05E-054		
MS21060L6	137(05E-064		
MS21060L04K	137(05E-40BC		
MS21060L06K	137(05E-62BC		
MS21060L08K	137(05E-82BC		
MS21060L3K	137(05E-02BC		
MS21060L4K	137(05E-048BC		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21060L5K	13705E-054BC	**Report No.** NAEC-AML-2369 of 15 Mar 1966	**SPS** Technologies {Cent'd)
MS21060LO4W	13705E-40PW		
NS21060LO6W	13705E-62PW		
MS21060L08W	13705E-82PW		
MS21060L3W	13705E-02PW		
MS21060L4W	13705E-048PW		
MS21060L5W	13705E-054PW		
MS21060L6W	13705E-064PW		
MS21060-O4	T65C440C	**Report No.** NAEC-AML-2428 of 15 Mar 1966	**Cherry Textron,** Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Warner Ave. Santa Ana, CA .92707-0157 Plant: Same address
MS21060-06	T65C632C		
MS21060-08	T65C832C		
MS21060-3	T65C1032C		
MS21060-4	T65C428C		
MS21060-5	T65C524C		
MS21060-6	T65C624C		
MS21060-04K	T65C440CBC		
MS21060-06K	T65C632CBC		
MS21060-O8K	T65C832CBC		
MS21060-3K	T65C1032CBC		
MS21060-4K	T 6 5 C 4 2 S C B C		
MS21060-5K	T65C524CBX		
MS21060-O4W	T65C440CPWB		
MS21060-O6W	T65C632CPWB		
MS21060-O8W	T65C832CPWB		
MS21060-3W	T65C1032CPWB		
MS21060-4W	T65C428CPWB		
MS21060-5W	T65C524CPW6		
MS21060-6W	T65C624CPWB		
MS21060L04	T65C440CM	Report No. NAEC-AML-2428 of 15 Mar 1966	
MS21060L06	T65C632M		
MS2106OLO8	T65C832CM		
MS21060L3	T65C1032CM		
MS21060L4	T65C428CM		
MS2106OL5	T65C524CM		
MS2106OL6	T65C624CM		
MS2106OLO4K	T65C440CBCM		
MS21060L06K	T65C632CBCM		
MS2106OLO8K	T65C832CBCM		
MS2106OL3K	T65C1032CBCM		
MS21060L4K	T65C428CBCM		
MS21060L5K	T65C524CBCM		
MS2106OLO4W	T65C440CPM		
MS2106OLO6W	T65C632CPM		
MS2106OLO8W	T65C832CPM		
MS2106OL3W	T65C1032CPM		
MS2106OL4W	T65C428CPM		
MS2106OL5W	T65C524CPM		
MS2106OL6W	T65C624CPM		

Source: https://assist.dla.mil -- Downloaded: 202640-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21060L04	RMLHTA521-2860-40	Report No. NAEC-AML-2429 of 15 Mar 1966	**Elastic** Stop Nut A Division of Harvard Industries. Inc. 2330 Vauxhall Road **Union, NJ 07083** **Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455**
MS21060L06	RMLHTA521-2860-62		
MS21060L08	RMLHTA521-2860-82		
MS21060L3	RMLHTA521-2860-02		
MS21060L4	RMLHTA521-2860-048		
MS21060L5	RMLHTAS21-2860-054		
MS21060L6	RMLHTA521-2860-064		
MS21060L04K	RMLHTA521-2860-40BC		
- MS21060L06K	RMLHTA521-2860-62BC		
MS21060L08K	RMLHTA521-2860-828C		
MS21060L3K	RMLHTA521-2860-02BC		
MS21060L4K	RMLHTA521-2860-048BC		
MS21060L5K	RMLHTA521-2860-0548C		
MS21060L04W	RMLHTA521-2860P-40		
MS21060L06W	RMLHTA521-2860P-62		
MS21060L08W	RMLHTA521-2860P-82		
MS21060L3W	RMLHTA521-2860P-02		
MS21060L4W	RMLHTA521-2860P-048		
MS21060L5W	RMLHTA521-2860P-054		
MS21060L6W	RMLHTA521-2860P-064		
MS21060-04	LHTA521-2860-40		
MS21060-06	LHTA521-2860-62		
MS21060-08	LHTA521-286&82		
MS21060-3	LHTA521-2860-02		
MS21060-4	LHTA521-2860-048		
MS21060-5	LHTA521-286&054		
MS21060-6	LHTA521-2860-064		
MS21060-04K	LHTA521-2860-40BC		
MS21060-06K	LHTA521-2860-626C		
MS21060-08K	LHTA521-2860-82BC		
MS21060-3K	LHTA521-2860-02BC		
MS27060-4K	LHTA521-2860-048BC		
MS21060-5K	LHTA521-2860-054BC		
MS21060-04W	LHTA521-2860P-40		
MS21060-06W	LHTA521-286CP-62		
MS21060-08W	LHTA521-2860P-82		
MS21060-3W	LHTA521-2860P-02		
MS21060-4W	LHTA521-2860P-048		
MS21060-5W	LHTA521-2860P-054		
MS21060-6W	LHTA521-2860P-064		
MS21060-04	VN152-B1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21060-06	VN152-B1-62		
MS21060-08	VN152-BI-82		
MS21060-3	VN152-Bl-02		
MS21060-4	VN152-B1-048		
MS21060-5	VN152-B1-054		
MS21060-6	VN152-B1-064		
MS21060-04K	VN152-B2-40		
MS21060-06K	VN152-B2-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION -	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21060-08K	VN152-B2-82	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. (Cont'd)
MS21060-3K	VN152-B2-02		
MS21060-4K	VN152-B2-048		
MS21060-5K	VN152-B2-054		
MS21060-04W	VN152-B3-40		
MS21060-06W	VN152-B3-62		
MS21060-08M	VN152-B3-82		
MS21060-3W	VN152-B3-02		
MS21060-4W	VN152-B3-048		
MS21060-5W	VN152-B3-054		
MS21060-6W	VN152-B3-064		
MS21060L04	VN152-D1-40		
MS21060L06	VN152-D1-62		
MS21060L08	VN152-D1-82		
MS21060L3	VN152-D1-02		
MS21060L4	VN152-D1-048		
MS21060L5	VN152-D1-054		
MS21060L6	VN152-D1-064		
MS21060L04K	VN152-D2-40		
MS21060L06K	VN152-D2-62		
MS21060L08K	VN152-D2-82		
MS21060L3K	VN152-D2-02		
MS21060L4K	VN152-02-048		
MS21060L5K	VN152-D2-054		
MS21060L04W	VN152-D3-40		
MS21060L06M	VN152-D3-62		
MS21060L08W	VN152-D3-82		
MS21060L3W	VN152-D3-02		
MS21060L4W	VN152-D3-048		
MS21060L5W	VN152-D3-054		
MS21060L6W	VN152-D3-064		
MS21060L04	RF200C04M	Report No. 305Q73001 Of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21060L04K	RF200C04MK		
MS21060L04W	RF200C04MW		
MS21060-04	RF200C04		
MS21060-04K	RF200C04K		
MS21060-04W	RF200C04W		
MS21060L06	RF200C06M		
MS21060L06K	RF200C06MK		
MS21060L06W	RF200C06MW		
MS21060-06	RF200C06		
MS21060-06K	RF200C06K		
MS21060-06W	RF200C06W		
MS21060L08	RF200C08M		
MS21060L08K	RF200C08MK		
MS21060L08W	RF200C08MW		
MS21060-08	RF200C08		
MS21060-08K	RF200C08K		
MS21060-08W	RF200C08W		
MS21060L3	RF200C3M		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21060L3K	**RF200C3MK**	Report No. 305Q73001 of 6 Feb 1973 "	Republic Fastener Mfg. Corp. (Cont'd)
MS21060L3W	**RF200C31MW**		
MS2106O-3	**RF200C3**		
MS2106O-3K	**RF200C3K**		
MS21060-3W	**RF200C3W**		
MS2106OL4	**RF200C4M**		
MS21060L4K	**RF200C4MK**		
MS2106OL4W	**RF200C4MW**		
MS21060-4	**RF200C4**		
MS2106O-4K	**RF200C4K**		
MS21060-4W	**RF200C4W**		
MS21060-5	RF200C5	Report No. 305Q76023 of 14 May **1976**	
MS21060L5	RF200C5M		
MS2106O-5K	RF200C5K		
MS2106OL5K	RF200C5MK		
MS21060-5W	RF200C5W		
MS21O60L5W	RF200C5MW		
MS21060L6	RF200C6M		
MS2106OL6W	RF200C6MW		
MS21060-6	RF200C6		
MS2106O-6W	RF200C6W		
MS2106O-O4	F5031-04	Report No. , NAEC-AML-2474 of **15** Jun 1966	Microdot, Inc KAYNAR Div. P.O. Box **3001** **800 S. State College** Blvd Fullerton, CA 92634 Plant: Same address
MS2106O-O6	F5031-06		
MS21060-08	F5031-08		
MS21060-3	F5031-3		
MS21060-4	F50J1-4		
MS2106O-5	F5031-5		
MS21060-6	F5031-6		
MS2106O-O4K	F5031-04BC		
MS2106O-O6K	F5031-06BC		
MS2106-08K	F5031-08BC		
MS2106O-3K	F5031-3BC		
MS21060-4K	F5031-4BC		
MS2106O-5K	F5031-5BC		
MS21060-04M	F5031-04P		
MS21060-06W	F5031-06P		
MS21060-08W			
MS21060-3W			
MS2106O-4W			
MS2106O-5W			
MS21060-6W			
MS2106OLO1			
MS21060L06	F5001-06		
MS2106OLO8	F5001-08		
MS2106OL3	F5001-3		
MS21060L4	F5001-4		

NOTE : **"L"** designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21060L5	F5001-5	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. (Cent'd)
MS21060L6	F5001-6		
MS21060L04K	F5001-04BC		
MS21060L06K	F5001-06BC		
MS21060L08K	F5001-08BC		
MS21060L3K	F5001-3BC		
MS21060L4K	F5001-4BC		
MS21060L5K	F5001-5BC		
MS21060L04M	F5001-04P		
MS21060L06W	F5001-06P		
MS21060L08W	F5001-08P		
MS21060L3W	F5001-3P		
MS21060L4W	F5001-4P		
MS21060L5W	F5001-5P		
MS21060L6W	F5001-6P		
MS21060L3	EF5001-3	NADC Report No. 601Q8706 of 22 May 1987	Microdot Aerospace Limited Blackthorn Road Colnbrook, Slough SL3 OAG England . Plant: Same Address

NOTE : (1) Manufacturing process: Strip
(2) Lubricant: (For Government Designation with "L"), QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21060-08	LA-508	Report No. 601Q8401 of 24 Feb 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresenes Cedex France
MS21060-08K	LA-508K		
MS21060-3	LA-53		
MS21060-3K	LA-53K		

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS1060-4 MS21060-4K	LA-54 LA-54K	NADC Report 601Q8417 of 25 0ct 1984	Simmonds Fastener Technologies, Inc. (Cent'd)
MS2106O-O6 MS21060-06K	LA-506 LA-506K	NADC Report 601Q8510 of 10 Jun 1985	
MS21060L08 MS21060L3	LA-508M LA-S3M	NADC Report 601Q8517 of 16 Dec 1985	
MS21060-04 MS2106OLO4 MS2106OLO6 MS2106OL4	LA-504 LA-504M LA-506M LA-54M	NADC Report 601Q8609 of 8 Aug 1986	

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubrtcant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 **(Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals).** The **contractor should include these provisions in every subcontract and , purchase order.**

MS21061 NUT, SELF-LOCKING, PLATE, **ONE LUG, FLOATING, LOW HEIGHT,** ALLOY STEEL, 125 ksi Ftu, 450°F

MS21061-O4	**T66S440SCPC**	Report No. " NAEC-AML-2428 of 15 Mar 1966.	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. B0X 2157 1224 East Warner Ave. Santa Ana, CA 92707-0157 Plant: Same address
MS21061-O6	T66S632SCPC		
MS21061-O8	T66S832SCPC		
MS21061-3	T66S1032SCPC		
MS21061-4	T66S428SCPC		
MS21061-5	T66S524SCPC		
MS21061LO4	T66S440S		
MS21061LO6	T66S632S		
MS21061L08	T66S832S		
MS21061L3	T66S1032S		
MS21061L4	T66S428S		
MS21061L5	166S524S		
MS21061-O4K	T66S440SBCCPC		
MS21061-O6K	T66S632SBCCPC		
MS21061-O8K	T66S832SBCCPC		
MS21061-3K	T66S1032SBCCPC		
MS21061-4K	T66S428SBCCPC		
MS2106I-5K	T66S524SBCCPC		
MS2106ILO4K	T66S440SBC		
MS21061LO6K	T66S632SBC		
MS21061L08K	T66S832SBC		
MS21061L3K	T66S1032SBC		
MS21061L4K	T66S428SBC		
MS21061L5K	T66S524SBC .		

Source: https://assist.dla.mil Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21061-O4	F52LHTA517-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 **Plant:** Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21061-O6	F52LHTA517-62		
MS21061-O8	F52LHTA517-82		
MS21061-3	F52LHTA517-02		
MS21061-4	F52LHTA517-048		
MS21061-5	F52LHTA517-054		
MS21061L04	RM52LHTA517-40		
MS21061LO6	RM52LHTA517-62		
MS21061LO8	RM52LHTAS17-82		
MS21061L3	RM52LHTA517-02		
MS21061L4	RM52LHTA517-048		
MS21061L5	RM52LHTA517-054		
MS21061-O4K	F52LHTA517-40BC		
MS21061-O6K	F52LHTA517-62BC		
MS21061-O8K	F52LHTA517-82BC		
MS21061-3K	F52LHTA517-02BC		
MS21061-4K	F52LHTA517-048BC		
MS21061-5K	F52LHTA517-054BC		
MS21061L04K	RM52LHTA517-40BC		
MS21061L06K	RM52LHTA517-62BC		
MS21061LO8K	RM52LHTA517-82BC		
MS21061L3K	RM52LHTA517-02BC		
MS21061L4K	RM52LHTA517-048BC		
MS21061L5K	RM52LHTA517-054BC		
MS21061-04	13615NM-40	Report No. NAEC-ANL-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21061-O6	13615NM-62		
MS21061-08	13615NM-82		
MS21061-3	13615NM-02		
MS21061-4	13615NM-048		
MS21061-5	13615NM-054		
MS21061LO4	13615-40		
MS21061L06	13615-62		
MS21061LO8	13615-82		
MS21061L3	13615-02		
MS21061L4	13615-048		
MS21061L5	13615-054		
MS21061-04K	13615NM-40BC		
MS21061-06K	13615NM-62BC		
MS21061-08K	13615NM-82BC		
MS21061-3K	13615NM-02BC		
MS21061-4K	13615NM-04BC		
MS21061-5K	13615NM-054BC		
MS21061L04K	13615-40BC		
MS21061LO6K	13615-62BC		
MS21061LO8K	13615-82BC		
MS21061L3K	13615-02BC		
MS21061L4K	13615-048BC		
MS21061L5K	13615-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21061-04	VN151-C1-40	Report No. NAEC-AHL-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd Redondo Beach, CA 90278
MS21061-06	VN151-C1-62		
MS21061-08	VN151-C1-82		
MS21061-3	VN151-C1-02		
MS21061-4	VN151-C1-048		
MS21061-5	V151-C1-054		
MS21061LO4	VN151-A1-40		
MS21061L06	VN151-A1-62		
MS21061L08	VW151-A1-82		
MS21061L3	VH151-A1-02		
MS21061L4	VN151-A1-048		
MS21061LS	VN151-A1-054		
MS21061-04K	VN151-C2-40		
MS21061-06K	VN151-C2-62		
MS21061-08K	VN151-C2-82		
MS21061-3K	VN151-C2-02		
MS21061-4K	VN151-C2-048		
MS21061-5K	VN151-C2-054		
MS21061L04K	VN151-A2-40		
MS21061L06K	VN151-A2-62		
MS21061L08K	VN151-A2-82		
MS21061L3K	VN151-A2-Q2		
MS21061L4K	VN151-A2-048		
MS21061L5K	VN151-A2-054		
MS21061-O4	F2000-04CW	Report No. NAEC-ANL-2474 of 15 June 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21061-O6	F2000-06CW		
NS21061-O8	F2000-08CW		
MS21061-3	F2000-3CW		
MS21061-4	F2000-4CW		
MS21061-5	F2000-5CW		
MS21061-04K	F2000-04BCCW		
MS21061-06K	F2000-06BCCW		
MS2106I-O8K	F2000-08BCCW		
MS21061-3K	F2000-3BCCW		
MS21061-4K	F2000-4BCCW		
NS21061-5K	F2000-5BCCW		
MS21061LO4	F2000-04		
MS21061L06	F2000-06		
MS21061L08	F2000-08		
MS21061L3	F2000-3		
MS21061L4	F2000-4		
MS21061L5	F2000-5		
MS21061LO4K	F2000-04BC		
MS21061LO6K	F2000-06BC		
MS21061L08K	F2000-08BC		
MS21061L3K	F2000-3BC		
MS21061L4K	F2000-4BC		
MS21061L5K	F2000-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21061-04	RF100X04	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: . Same address
MS21061-04K	RF100X04K		
MS21061L04	RF100A04		
MS21061LO4K	RF100A04K		
MS21061-O6	RF1OOX06		
MS2106I-O6K	RF1OOX06K		
MS21061L06	RF1OOA06		
MS21061LO6K	RF1OOA06K		
MS21061-08	RF100X08		
MS21061-08K	RF100X08K		
MS21061L08	RF1OOA08		
MS21061L08K	RF1OOA08K		
MS21061-3	RF1OOX3		
MS21061-3K	RF1OOX3K		
MS21061L3	RF1OOA3		
MS21061L3K	RF1OOA3K		
MS21061-4	RF1OOX4		
MS21061-4K	RF100X4K		
MS21061L4	RF1OOA4		
MS21061L4K	RF100A4K		

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 0f 20 November 1970.

MS21061-5	RF1OOX5	Report No. 305Q83088 of 26 Jan 1983	
MS21061L5	RF1OOA5		
MS2106I-5K	RF100X5K		
MS21061L5K	RF100A5K		

MS21061LO8	AJF-908M	Report No. 305Q83112 of 28 Nov 1983	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet B.P. 52 F. 92152 Suresenes Cedex France
MS21061L08K	AJF-908MK		
MS21061L3	AJF-93M		
MS21061L3K	AJF-93MK		
MS21061-08	AJF-908	Report No. 601Q8407 of 20 Apr 1984	
MS21061-3	AJF-93		

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L'') QPL-8937
(3) Provisions Governing Procurement Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21061-4 MS21061-4K MS21061L4 MS21061L4K	AJF-94 AJF-94K AJF-94M AJF-94MK	NADC Report 601Q8502 of. 11 Mar 1985	Simmonds Fastener Technologies Inc. (cont'd)
MS21061-06 MS21061-06K MS21061LO6 MS21061L06K	**AJF-906** **AJF-906K** **AJF-906M** **AJF-906MK**	**NADC Report 601Q8510 of 10 Jun 1985**	
MS21061-04 **MS21061L04**	AJF-904 **AJF-904M**	NADC **Report 601Q8609 of 8 Aug 1986**	

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with **FAR 52.225-3 (Buy American Act)** and DFARS 52.225-7012 (Preference for Domestic **Specialty Metals). The contractor should include these** provisions in every **subcontract and purchase order. --**

MS21062 NUT. SELF-LOCKING, PLATE, ONE LUG, FLOATING, LOW HEIGHT, **CRES,** 125-ksi Ftu, 450° & 800°F

MS21062-O4	T66C440C	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron Inc. P.O. **80X** 2157 1224 East Warner Ave. Santa Ana, CA 92707 Plant: Same address
MS21062-06	T66C632C		
MS21062-O8	T66C832C		
MS21062-3	T66C1032C		
MS21062-4	T66C428C		
MS21062-S	T66C524C		
MS21062-04K	T66C440CBC		
MS21062-06K	T66C632CBC		
MS21062-O8K	T66C832CBC		
MS21062-3K	T66C1032CBC		
MS21062-4K	T66C428CBC		
MS21062-5K	T66C524CBC		
MS21062-O4W	T66C440CPWB		
MS21062-O6W	T66C632CPWB		
MS21062-08W	T66C832CPWB		
MS21062-3W	T66C1032CPWB		
MS21062-4W	T66C428CPWB		
MS21062-5W	T66C524CPWB		
MS21062L04	T66C440CM		
MS21062L06	T66C632CM		
M21062LO8	T66C832CM		
MS21062L3	T66C1032CM		
MS21062L4	T66C428CM		
MS21062L5	T66C524CM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21062LO4K	T66C440CBCM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, (Cent'd)
MS21062LO6K	T66C632CBCM		
MS21062LO8K	T66C832CBCM		
MS21062L3K	T66C1032CBCM		
MS21062L4K	T66C428CBCM		
MS21062L5K	T66C524CBCM		
MS21062LO4W	T66C440CPM		
MS21062L06W	T66C632CPM		
MS21062LO8W	T66C832CPM		
MS21062L3W	T66C1032CPM		
MS21062L4W	T66C428CPM		
MS21062L5W	T66C524CPM		
MS21062-O4	13715-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MS21062-O6	13715-62		
MS21062-O8	13715-82		
MS21062-3	13715-02		
MS21062-4	13715-048		
MS21062-5	13715-054		
MS21062-04K	13715-40BC		
MS21062-06K	13715-62BC		
MS21062-O8K	13715-82BC		
MS21062-3K	13715-02BC		
MS21062-4K	13715-048BC		
MS21062-5K	13715-054BC		
MS21062-O4W	13715-40PW		
MS21062-O6W	13715-62PW		
MS21062-O8W	13715-82PW		
MS21062-3W	13715-02PW		
MS21062-4W	13715-048PW		
MS21062-5W	13715-054PW		
MS21062LO4	13715E-40		
MS21062LO6	13715E-62		
MS21062LO8	13715E-82		
MS21062L3	13715E-02 .		
MS21062L4	13715E-048		
MS21062L5	13715E-054		
MS21062LO4K	13715E-40BC		
MS21062LO6K	13715E-62BC		
M21062L08K	13715E-82BC		
MS1062L3K	13715E-02BC		
M21062L4K	13715E-048BC		
MS21062L5K	13715E-054BC		
MS21062L04W	13715E-40PW		
MS21062L06W	13715E-62PW		
MS21062L08W	13715E-82PW		
MS21062L3W	13715E-02PW		
MS21062L4W	13715E-048PW		
MS21062L5W	13715E-054PW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21062-04	F2(031-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton , CA 92634 Plant: Same address
MS21062-06	F2(031 -06		
MS21062-08	F2(031-08		
MS21062-3	F2(031-3		
MS21062-4	F2(031-4		
MS21062-5	F2(031-5		
MS21062-O4K	F2(031-04BC		
MS21062-O6K	F2(031-06BC		
MS21062-O8K	F2(031-08BC		
MS21062-3K	F2(031-3BC		
MS21062-4K	F2(031-4BC		
MS21062-5K	F2(031-5BC		
MS21062-04W	F2(031-04P		
MS21062-06W	F2(031-06P		
MS21062-08W	F2(031-08P		
MS21062-3W	F2(031-3P		
MS21062-4W	F2(031-4P		
MS21062-5W	F2(031-5P		
MS21062LO4	F2(001-04		
MS21062L06	F2(001-06		
MS21062LO8	F2(001-08		
MS21062L3	F2(001-3		
MS21062L4	F2(003-4		
MS21062L5	F2(001-5		
MS21062L04K	F2(001-04BC		
MS21062L06K	F2(001-06BC		
MS21062LO8K	F2(001-08BC		
MS21062L3K	F2(001-3BC		
MS21062L4K	F2(001-4BC		
MS21062L5K	F2(001-5BC		
MS21062LO4W	F2(001-04P		
MS21062LO6W	F2(001-06P		
MS21062LO8W	F2(001-08P		
MS21062L3W	F2(001-3P		
MS21062L4W	F2(001-4P		
MS21062L5W	F2(001-5P		
MS21062LO4	RMLHTA517-286 0-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division Of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21062LO6	RMLHTA517-286 0-62		
MS21062LO8	RMLHTA517-286 0-82		
MS21062L3	RMLHTA517-286 (0-02		
MS21062L4	RMLHTA517-286 (0-048		
MS21062L5	RMLHTA517-286 (0-054		
MS21062LO4K	RMLHTA517-286 (0-40BC		
MS21062LO6K	RMLHTA517-286 (0-62BC		
MS21062LO8K	RMLHTA517-286 (0-82BC		
MS21062L3K	RMLHTA517-286 (0-02BC		
MS21062L4K	RMLHTA517-286 (0-048BC		
MS21062L5K	RMLHTA517-286 (0-054BC		
MS21062L04W	RMLHTA517-286 (0P-40		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21062LO6W	R MLHTA517-2860P-62	Report No.	Elastic Stop Nut
MS21062LO8W	R MLHTA517-2860P-82	NAEC-AML-2429	A Division of
MS21062L3W	R MLHTA517-2860P-02	of 15 Mar 1966	Harvard Industries, Inc.
MS21062L4W	R MLHTA517-2860P-048		(Cent'd)
MS21062L5W	R MLHTA517-.286OP-O54		
MS21062-O4	L HTA517-2860-40		
MS21062-06	L HTA517-2860-62		
MS21062-O8	L HTA517-2860-82		
MS21062-3	L HTA517-2860-02		
MS21062-4	L HTA517-2860-048		
MS21062-5	L HTA517-2860-054		
MS21062-O4K	L HTA517-2860-40BC		
MS21062-O6K	L HTA517-2860-62BC		
MS21062-O8K	L HTA517-2860-82BC		
MS21062-3K	L HTA517-2860-02BC		
MS21062-4K	L HTA517-2860-048BC		
MS21062-5K	L HTA517-2860-054BC		
MS21062-O4W	L HTA517-2860P-40		
MS21062-O6W	L HTA517-2860P-62		
MS21062-O8W	L HTA517-2860P-82		
MS21062-3W	L HTA517-2860P-02		
MS21062-4W	L HTA517-2860P-048		
MS21062-5W	L HTA517-2860P-054		
MS21062-04	VN151-B1-40	Report No.	VOI-SHAN
MS21062-O6	VN151-B1-62	NAEC-AML-2425	VSI Aerosp. Prod. Div.
MS21062-O8	VN151-B1-82	of 15 Mar 1966	8463 Higuera Street
MS21062-3	VN151-B1-02		Culver City, CA 90230
MS21062-4	VN151-B1-048		
MS21062-5	VN151-B1-054		Plant:
MS21062-O4K	VN151-B2-40		2700 Compton Blvd.
MS21062-06K	VN151-B2-62		Redondo Beach, CA 90278
MS21062-08K	VN151-B2-82		
NS21062-3K	VN151-B2-02		
MS21062-4K	VN151-B2-048		
MS21062-5K	VN151-B2-054		
MS21062-04W	VN151-B3-40		
MS21062-O6W	VN151-B3-62		
MS21062-O8W	VN151-B3-82		
MS21062-3W	VN151-B3-02.		
MS21062-4W	VN151-B3-048		
MS21062-5W	VN151-B3-054		
MS21062104	VN151-D1-40		
MS21062L06	VN151-D1-62		
MS21062LO8	VN151-D1-82		
MS21062L3	VN151-D1-02		
MS21062L4	VN151-D1-048		
MS21062L5	VN151-D1-054		
MS21062L04K	VN151-D2-40		
MS21062LO6K	VN151-D2-62		
MS21062L08K	VN151-D2-82		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21062L3K	**VN151-D2-02**	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. (Cent'd)
MS21062L4K	VN151-D2-048		
MS21062L5K	VN151-D2-054		
MS21062L04W	VN151-D3-40		
MS21062L06W	VN151-D3-62		
MS21062L08W	VN151-D3-82		
MS21062L3W	VN151-D3-02		
MS21062L4W	VN151-D3-048		
MS21062L5W	**VN151-D3-054**		
MS21062L04	**RF100C04M**	**Report No. 305Q73001 of 6 Feb 1973**	**Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320** Plant: Same address
MS21062L04K	**RF1OOCO4MK**		
MS21062L04W	**RF1OOCO4MW**		
MS21062-04	RF1OOC04		
MS21062-O4K	RF1OOCO4K		
MS21062-04W	RF1OOCO4W		
MS21062LO6	RF10 0C06M		
MS21062LO6K	**RF10** 0C06MK		
MS21062LO6W	**RF10** 0C06MW		
MS21062-06	**RF10** 0C06		
MS21062-06K	**RF10** 0C06K		
MS21062-06W	**RF10** 0C06W		
MS21062L08	**RF10** 0C08M		
MS21062L08K	**RF10** 0C08MK		
MS21062L08W	**RF10** 0C08MW		
MS21062-08	**RF1OOCO8**		
MS21062-08K	**RF1OOCO8K**		
MS21062-08W	**RF100C08W**		
MS21062L3	**RF100C3M**		
MS21062L3K	**RF100C3MK**		
MS21062L3W	**RF100C3MW**		
MS21062-3	**RF1OOC3**		
MS21062-3K	**RF100C3K**		
MS21062-3W	**RF1OOC3W**		
MS21062L4	**RF100C4M**		
MS21062L4K	**RF100C4MK**		
MS21062L4W	**RF100C4MW**		
MS21062-4	**RF100C4**		
MS21062-4K	**RF1OOC4K**		
MS21062-4W	**RF1OOC4W**		

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 0f 20 November 1970.

MS21062-5	RF1OOC5	Report No. 305Q83088 of 26 Jan 1983
MS21062L5	RF1OOC5M	
MS21062-5K	RF1OOC5K	
MS21062L5K	RF1OOC5MK	
MS21062-5W	RF1OOC5W	
MS21062L5W	RF100C5MW	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION .	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21062-4 MS21062-4K	AJF-54 AJF-54K	NADC Report 601Q8417 of 25 Ott 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21062-O8 MS21062-O8K MS21062-3 MS21062-3K	AJF-508 AJF-508K **AJF-53** **AJF-53K**	NADC Report 601Q8502 of **11** Mar **1985**	Plant: **Simmonds** **5,** rue Michelet, **B.P. 52** **F. 92152** Suresnes Cedex **France**
MS21062L08 MS21062L3 MS21062L4	**AJF-508M** AJF-53M AJF-54M	**NADC** Report 601Q8604 of 12 Mar 1986	

NOTE: (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21062-O6 MS21062LO6	AJF-506 AJF-506M	NADC Report 601Q8518 **of** 30 Dec 1985	

NOTE : (1) Manufacturing process: Cold forging
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Speciaity Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21063 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, STEEL, 125 ksi Ftu, 250°F

MS2 063-08-( ) MS2 063-3-( ) MS2 063-4-( ) MS2 063-5-( ) MS2 063L08-( ) MS2 063L3-( ) MS2 063L4-( ) MS21063L5-( )	T63S832-( )CPC T63S1032-( )CPC T63S428-( )CPC T63S524-( )CPC T63S832-( ) T63S1032-( ) T63S428-( ) T63S524-( )	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Divsison of Textron, Inc. P.O. **Box** 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER 'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21063-08-( )	F52LHTG51-82-( )	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 , ,
MS21063-3-( )	F52LHTG51-02-( )		
MS21063-4. ( )	F52LHTG51-048-( )		
MS21063-5-( )	F52LHTG51-054-( )		
MS21063-6-( )	F52LHTG51-064-( )		
MS21063L08-( )	RM52LHTG51-82-( )		
MS21063L3-( )	RN52LHTG51-02-( )		Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
HS21063L4-( )	RM52LHTG51-048-( )		
MS21063L5-( )	RM52LHTG51-054-( )		
MS21063L6-( )	RM52LHTG51-064-( )		
MS21063-O8-( )	G1OOO-O8CW-( )	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot Inc. KAYNAR Div. P.O. Box 3001 800 S.State College Blvd. Fullerton, CA 92634
MS21063-3-( )	G1OOO-3CW-( )		
MS21063-4-( )	G1OOO-4CW-( )		
MS21063-5-( )	G1OOO-5CW-( )		
MS21063-6-( )	G1OOO-6CW-( )		
MS21063LO8-( )	G1OOO-O8-( )		
MS21063L3-( )	G1OOO-3-( )		
MS21063L4-( )	G1OOO-4-( )		Plant: Same address
MS21063L5-( )	G1OOO-5-( )		
MS21063L6-( )	G1000-6-( )		
MS21063-08-( )	C182-82-( )NM	Report No. 601Q84U6 of 20 Mar 1984	**SPS Technologies .** 2701 South Harbor Blvd. Santa Ana, CA 92702
MS21063-3-( )	C182-3-( )NM		
MS21063-4-( )	C182-4-( )NM		
MS21063-5-( )	Cl 82-5-( )NM		
MS21063-6-( )	C182-6-( )NM		Plant: Same address
MS21063LO8-( )	C182-82-( )		
MS21063L3-( )	C182-3-( )		
MS21063L4-( )	C182-4-( )		
MS21063L5-( )	C182-5-( )		
MS21063L6-( )	C182-6-( )		
MS21063-O8-( )	937RS908-( )	NADC Report 60108418 of 26 Ott 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21063-3-( )	937RS93-( )		
MS21063-4-( )	937RS94-( )		
MS21063L08-( )	937RS908M-( )		
MS21063L3-( )	937RS93M-( ) .		Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France
MS21063L4-( )	937RS94M-( )		

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21063-08 MS21063-3 MS21063-4	BGC21063-08 BGC21063-3 BGC21063-4	NADC Report 601Q8419 of 9 Nov 1984	Bristol Industries 630 E. Lambert Rd. P.O. Box 630 Brea, CA 92621
MS21063LO8 - MS21063L3 MS21063L4	BGC21063LO8 BGC21063L3 BGC21063L4	NADC Report 601Q8703 of 3 Mar 1987	Plant: Same address
MS21064 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, STEEL, 125 ksi Ftu, 450°F			
MS21064-O8-( ) MS21064-3-( ) MS21064-4-( ) MS21064-5-( ) MS21064LO8-( ) MS21064L3-( ) MS21064L4-( ) MS21064L5-( )	TC63S832-( )CPC TC63S1032-( )CPC TC63S428-( )CPC TC63S524-( )CPC TC63S832-( ) TC63S1032-( ) TC63S428-( ) TC63S524-( )	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. Box 2157 Santa Ana, CA 92707-0157 Plant: Same address
MS21064-08-( ) MS21064-3-( ) MS21064-4-( ) MS21064-5-( ) MS21064LO8-( ) MS21064L3-( ) MS21064L4-( ) MS21064L5-( ) MS21064L6-( )	F52L HTG51-82-( ) F52L HTG51-02-( ) F52L HTG51-048-( ) F52L HTG51-054-( ) RM52 HTG51-82-( ) RM52 HTG51-02-( ) RM52 HTG51-048-( ) RM52 HTG51-054-( ) RM52 HTG51-064-( )	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21064-O8-( ) MS21064-3-( ) MS21064-4-( ) MS21064-5-( ) MS21064LO8-( ) MS21064L3-( ) MS21064L4-( ) MS21064L5-( )	G1981-08CW-( ) G1981-3CW-( ) G1981-4CW-( ) G1981-5CW-( ) G1981-08-( ) G1981-3-( ) G1981-4-( ) G1981-5-( )	Report No. NAEC-AHL-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21064-O8-( ) MS21064-3-( ) MS21064-4-( ) MS21064-5-( ) MS21064-6-( ) MS21064LO8-( ) MS21064L3-( ) MS21064L4-( ) MS21064L5-( ) MS21064L6-( )	C184-82-( )NM C184-3-( )NM C184-4-( )NM C184-5-( )NM C184-6-( )NM C184-82-( ) C184-3-( ) C184-4-( ) C184-5-( ) C184-6-( )	Report No. 601Q8406 of 20 Mar 1984	SPS Technologies 2701 South Harbor Blvd. Santa Aria, CA 92702 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21064-08-( )	95RS908-( )	NADC Report 601Q8418 of 26 Oct 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21064-3-( )	95RS93-( )		
MS21064-4-( )	95RS94-( )		
MS21064LO8-( )	95RS908M-( )		
MS21064L3-( )	95RS93M-( )		Plant: Simmonds 5, rue Michelet. B.P. 52 F. 92152 Suresnes Cedex France
MS21064L4-( )	95RS94M-( )		

NOTE: (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21064-08	BGC21064-O8	NADC Report 601Q8419 of 9 Nov 1984	Bristol Industries 630 E. Lambert Rd. P.O. BOX 630 Brea, CA 92621
MS21064-3	BGC21064-3 "		
MS21064-4 . . .	BGC2106-4		
MS21064LO8	BGC21064L08	NADC Report 601Q8703 of 3 Mar 1987	Plant: Same address
MS21064L3	BGC21064L3		
MS21064L4	BGC21064L4		

MS21065 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, CRES, 125 ksi Ftu, 450° & 800'F

MS21065LO8-( )	TC63C832-( )M	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. BOX 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21065L3-( )	TC63C1032-( )M		
MS21065L4-( )	TC63C428-( )M		
MS21065L5-( )	TC63C524-( )M		
MS21065-08-( )	TC63C832-( )		
MS2106S-3-( )	TC63C1032-( )		
MS21065-4-( )	TC63C428-( )		
MS21065-5-( )	TC63C524-( )		

MS21065LO8-( )	RM LHTG51-2860-82-( )	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21065L3-( )	RM LHTG51-2860-02-( )		
MS21065L4-( )	RM LHTG51-2860-048-( )		
MS2106SL5-( )	RM LHTG51-2860-054-( )		
MS21065L6-( )	RM LHTG51-2860-064-( )		
MS21065-O8-( )	LH TG51-2860-82-( )		
MS21065-3-( )	LH TG51-2860-02-( )		
MS21065-4-( )	LH TG51-2860-048-( )		
MS21065-5-( )	LH TG51-2860-054-( )		
MS21065-6-( )	LH TG51-2860-064-( )		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21065-08-( )	G1031-08-( )	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634
MS21065-3-( )	G1031-3-( )		
MS21065-4-( )	G1031-4-( )		
MS21065-5-( )	G1031-5-( )		
MS21065LO8-( )	G1OO1-O8-( )		
MS21065L3-( )	G1OO1-3-( )		
MS21065L4-( )	G1OO1-4-( )		
MS21065L5-( )	G1OO1-5-( )		Plant: Same address
MS21065-08-( )	C185-82-( )	Report No. 601Q8406 of 20 Mar 1984	SPS Technologies 2701 South Harbor Blvd. Santa Ana, CA 92702
MS21065-3-( )	C185-3-( )		
MS21065-4-( )	C185-4-( )		
MS21065-5-( )	C185-5-( )		
M21065-6-( )	C185-6-( )		Plant: Same address
MS21065L08-( )	C185E82-( )		
MS21065L3-( )	C185E3-( )		
MS21065L4-( )	C185E4-( )		
MS21065L5-( )	C185E5-( )		
MS21065L6-( )	C185E6-( )		
MS21065-O8-( )	55RS508-( )	NADC Report 601Q8418 of 26 Oct 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21065-3-( )	55RS53-( )		
MS21065-4-( )	55RS54-( )		Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France
MS21065-08	BGC21065-08	NADC Report 601Q8419 of 9 Nov 1984	Bristol Industries 630 E. Lambert Rd. P.O. BOX 630 Brea, CA 92621
MS21065-3	BGC21065-3		
MS21065-4	BGC21065-4		
MS21065LO8	BGC2106SLO8	NADC Report 601Q8703 of 3 Mar 1987	Plant: Same address
MS21065L3	BGC21065L3		
MS21065L4	BGC21065L4		

NOTE : (1) Nanufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21066 NUT, SELF-LOCKING, CHANNEL, 100° CSK, FLOATING, LOW HEIGHT, STEEL, 125 ksi Ftu, 250°F			
MS21066L08-( ) MS21066L3-( ) MS21066L4-( ) **MS21066-08-( )** **MS21066-3-( )** **MS21066-4-( )**	T64SH832-( ) **T64SH1032-( )** T64SH428-( ) **T64SH832-( )CPC** **T64SH1032-( )CPC** **T64SH428-( )CPC**	Report No. **NAEC-AML-2428** of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, **Cherry Division of Textron, Inc.** **P.O. Box 2157** **1224 East Warner Ave.** **Santa Ana, CA 92707-0157** Plant: Same address
MS21066-08-( ) MS21066-3-( ) MS21066-4-( ) MS21066LO8-( ) MS21066L3-( ) MS21066L4-( )	F52LHTG55-82-( ) F52LHTG55-02-( ) F52LHTG55-048-( ) RM52LHTG55-82-( ) RH52LHTG55-02-( ) RM52LHTG5S-048-( )	Report No. NAEC-AML-2429. of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, **Inc.** **2330 Vauxhall Road** **Union,** NJ 07083 **Plant: Same address and 3200 Country Club Road Pocahontas,** AR 72455
MS21066-08-( ) MS21066-3-( ) MS21066-4-( ) MS21066LO8-( ) MS21066L3-( ) MS21066L4-( )	G1 100-08-( ) G1 100-3-( ) G1 100-4-( ) G1 100-08-( ) G1 100-3-( ) G1 100-4-( )	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. . KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21067 NUT, SELF-LOCKING, CHANNEL, 100' CSK, FLOATING, LOW HEIGHT, STEEL, 125 ksi **Ftu, 450°F**			
MS21067-O8-( ) MS21067-3-( ) MS21067-4-( ) MS21067LO8-( ) MS21067L3-( ) MS21067L4-( )	TC64SH832-( ) TC64SH1032-( ) TC64SH428-( ) TC64SH832-( ) TC64SH1032-( ) TC64SH428-( )	Report No. NAEC-AHL-2428 of 15 **Mar 1966**	Cherry Textron, Cherry Aerospace operation, **Cherry Division of** Textron, Inc. P.O. Box 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21067-O8-( ) F52LHTG55-82-( ) MS21067-3-( ) F52LHTG55-02-( ) MS21067-4-( ) F52LHTG55-048-( ) MS21067LO8-( ) RM52LHTG55-82-( ) MS21067L3-( ) RM52LHTG55-02-( ) MS21067L4-( ) RH52LHTG55-048-( )		Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21067-O8-( ) G1982-08-( ) MS21067-3-( ) G1982-3-( ) MS21067-4-( ) G1982-4-( ) MS21067LO8-( ) G1982-08-( ) MS21067L3-( ) G1982-3-( ) MS21067L4-( ) G1982-4-( )		Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21067-O8-( ) 95RSF908-( ) MS21067LO8-( ) 95RSF908M-( )		NADC Report 601Q8505 of 30 May 1985	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21068 NUT, SELF-LOCKING, CHANNEL, 100" CSK, FLOATING, LOU HEIGHT, CRES, 125 ksi Ftu, 450° & 800°F

MS21068-O8-( ) TC64CH832-( ) MS21068-3-( ) TC64CH1032-( ) MS21068-4-( ) TC64CH428-( ) MS21068LO8-( ) TC64CH832-( )M MS21068L3-( ) TC64CH1032-( )M MS21068L4-( ) TC64CH428-( )M		Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operation, Cherry Division of Textron, Inc. P.O. BOX 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21068L08-( ) RMLHTG55-2860-82-( ) MS21068L3-( ) RMLHTG55-2860-02-( ) MS21068L4-( ) RMLHTG55-2860-048-( ) **MS21068-O8-( ) LHTG55-2860-82-( )** **MS21068-3-( ) LHTG55-2860-02-( )** **MS21068-4-( ) LHTG55-2860-048-( )**		**Report No.** NAEC-AUL-2429 of 15 Mar **1966**	**Elastic Stop** Nut A Division of **Harvard Industries, Inc.** **2330 Vauxhall Road** **Union; NJ 07083** **Plant: Same** address and 3200 **Country Club Road** **Pocahontas,** AR 72455
MS21068-08-( ) G1131-08-( ) MS21068-3-( ) G1131-3-( ) MS21068-4-( ) G1131-4-( ) MS21068LO8-( ) G11O1-08-( ) MS21068L3-( ) G11O1-3-( ) MS21068L4-( ) G11O1-4-( )		**Report No.** NAEC-AML-2474 of 15 Jun 1966	**Microdot,** Inc. KAYNAR Div. P.0. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21069 NUT, SELF-LOCKING, PLATE, TWO LUG, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 125 ksi Ftu, 450°F			
MS21069-04	**MTL2S440CPC**	Report No. NAEC-AML-2428 **of 15 Mar 1966**	Cherry **Textron, Cherry** Aerbspace **Operations** **Cherry** Division of **Textron, Inc.** P.O. **BOX** 2157 1224 East Warner Ave. Santa Ana, CA 92707-0157 **Plant: Same address**
MS21069-O6	MTL25632CPC		
MS21069-08	MT2S832CPC		
MS21069-3	MT2S1032CPC		
MS21069-4	MT2S428CPC		
MS21069-5	MT2S524CPC		
MS21069-6	MT2S624CPC		
MS21069L04	MTL2S440		
MS21069LO6	MTL2S632		
MS21069LO8	MT2S832		
MS21069L3	MT2S1032		
MS21069L4	MT2S428		
MS21069L5	MT2S524		
MS21069L6	MT2S624		
MS21069-04K	MTL2S440BCCPC		
MS21069-06K	MTL2S632BCCPC		
MS21069-08K	MT2S8328CCPC		
MS21069-3K	MT2S1032BCCPC		
MS21069-4K	MT2S428BCCPC		
MS21069-5K	MT2S524BCCPC		
MS21069LO4K	MTL2S440BC		
MS21069LO6K	MTL2S632BC		
MS21069L08K	MT2S832BC		
MS21069L3K	MT2S1032BC		
MS21069L4K	MT2S428BC		
MS21069L5K	MT2S524BC		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21069-04	F12L HTA1M-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21069-O6	F12L HTA1M-62		
MS21069-O2	F52L HTA51M-26		
MS21069-08	F52L HTA51M-82		
MS21069-3	F52L HTA51M-02		
MS21069-4	F52L HTA51M-048		
MS21069-5	F52L HTA51M-054		
MS21069-6	F52L HTA51M-064		
MS21069LO4	RM12LHTA1M-40		
MS21069LO6	RM12 LHTA1M-62		
MS21069LO2	RM52 LHTA51M-26		
MS21069L08	RM52 LHTA51M-82		
NS21069L3	RM52 LHTA51M-02		
MS21069L4	RM52 LHTA51M-048		
MS21069L5	RM52 LHTA51M-054		
MS21069L6	RM52 LHTA51M-064		
MS21069-O4K	F12L HTA1M-40BC		
MS21069-O6K	F12L HTA1M-62BC		
MS21069-O8K	F52L HTA51M-82BC		
MS21069-3K	F52L HTA51M-02BC		
MS21069-4K	F52L HTA51M-048BC		
NS21069-5K	F52L HTA51M-054Bc		
MS21069LO4K	RM12LHTA1M-40BC		
MS21069LO6K	RM12LHTA1M-62BC		
,S21069LO8K	RM52LHTA51M-82BC		
MS21069L3K	RM52 LHTA51M-02BC		
MS21069L4K	RM52LHTA51M-048BC		
MS21069L5K	RM52LHTA51M-054BC		
MS21069-O4	VN202-C1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21069-O6	VN202-C1-62		
MS21069-08	VN202-C1-82		
MS21069-3	VN202-C1-02		
MS21069-4	VN202-C1-048		
MS21069-5	VN202-C1-054		
MS21069-6	VN202-C1-064		
MS21069LO4	VN202-A1-40		
MS21069L06	VN202-A1-62		
MS21069L08	VN202-A1-82		
MS21069L3	VN202-A1-02		
MS21069L4	VN202-A1-048		
MS21069L5	VN202-A1-054		
MS21069L6	VN202-A1-064		
MS21069-04K	VN202-C2-40		
MS21069-06K	VN202-C2-62		
MS21069-08K	VN202-C2-82		
MS21069-3K	VN202-C2-02		
MS21069-4K	VN202-C2-048		
MS21069-5K	VN202-C2-054		
MS21069L04K	VN202-A2-40		
MS21069LO6K	VN202-A2-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21069LO8K	VN202-A2-82	Report No.	VOI-SHAN
MS21069L3K	VN202-A2-02	NAEC-AML-2425	VSI Aerosp. Prod. Div.
MS21069L4K	VN202-A2-048	of 15 Mar 1966	(Cent'd)
MS21069L5K	VN202-A2-054		
MS21069-04	M12600NM-40	**Report No. NAEC-AML-2369 of 15 Mar 1966**	**SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702**
MS21069-06	M12600NM-62		
MS21069-O8	M12600NM-82		
MS21069-3	M12600NM-02		Plant: Same **address** .
MS21069-4	M12600NM-048		
MS21069-5	M12600NM-054		
MS21069-6	M12600NM-064		
MS21069L04	M12600-40		
MS21069LO6	M12600-62		
MS21069LO8	M12600-82		
MS21069L3	M12600-02		
MS21069L4	M12600-048		
MS21069L5	M12600-054		
MS21069L6	M12600-064		
MS21069-O4K	M12600NM-4BC		
MS2106906K	M12600NM-62BC		
MS21069-08K	M12600NM-82BC		
MS21069-3K	M12600NM-02BC		
MS21069-4K	M12600NM-048BC		
MS21069-5K	M12600NM-054BC		
MS21069LO4K	M12600NM-40BC		
MS21069LO6K	M12600-62BC		
MS21069L08K	M12600-82BC		
MS21069L3K	M12600-02BC		
MS21069L4K	M12600-048BC		
MS21069L5K	MA12600-054BC		
MS21069-O2	MK1300-02CW	Report No.	Microdot, Inc.
MS21069-O4	MK1000-04CW	NAEC-AML-2474	KAYNAR Div.
MS21069-06	**MK1000-06CW**	of 15 Jun 1966	P.O. Box 3001
MS21069-O8	MK1000-08CW		800 S. State College Blvd.
MS21069-3	MK1OOO-3CW "		Fullerton, CA 92634
MS21069-4	MK1000-4CW		
MS21069-5	MK1300-5CW		Plant: Same address
MS21069-6	MK1300-6CW		
MS21069-02K	MK1300-02BCCW		
MS21069-04K	MK1OOO-O4BCCW		
MS21069-06K	MK1OOO-O6BCCW		
MS21069-O8K	MK1OOO-O8BCCW		
MS21069-3K	MK1OOO-3BCCW		
MS21069-4K	MK1OOO-4BCCW		
MS21069-5K	MK1300-5BCCW		
MS21069LO2	MK1300-02		
MS21069LO4	MK1000-04		
MS21069LO6	MK1000-06		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21069L08	MK1000-08	Report No. NAEC-AHL-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. (Cent'd)
MS21069L3	MK1000-3		
MS21069L4	MK1000-4		
MS21069L5	MK1300-5		
MS21069L6	MK1300-6		
MS21069L02K	MK1300-02K		
MS21069L04K	MK1000-04BC		
MS21069LO6K	MK1000-068C		
MS21069L08K	MK1000-08BC		
MS21069L3K	MK1000-3BC		
MS21069L4K	MK1000-4BC		
MS21069L5K	MK1300-58C		
MS21069L06	EFK1000-06	NADC Report No. 601Q8705 of 20 May 1987	Microdot Aerospace Limited Blackthorn Road Colnbrook, Slough SL3 OAG England Plant: Same Address
MS21069LO8	EFK1000-08		
MS21069L3	EMK1000-3	601Q8706 of 22 May 1987	

NOTE: (1) Manufacturing process Strip
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement; Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21069-O4	RM200X04L	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21069-04K	RM200X04LK		
MS21069LO4	RM200A04L		
MS21069LO4K	RM200A04LK		
MS21069-O6	RM200X06L		
MS21069-O6K	RM200X06LK		
MS21069L06	RM200A06L		
MS21069L06K	RM200A06LK		
MS21069-O8	RM200X08		
MS21069-O8K	RM200X08K		
MS21069LO8	RM200A08		
MS21069L08K	RM200A08K		
MS21069-3	RM200X3		
MS21069-3K	RM200X3K		
MS21069L3	RM200A3		
MS21069L3K	RM200A3K		
MS21069-4	RM200X4		
MS21069-4K	RM200X4K		
MS21069L4	RM200A4		
MS21069L4K	RM200A4K		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21069-5 MS21069L5 MS21069-5K MS21069L5K	RM200X5 RM200A5 RM200X5K RM200A5K	Report No. 305Q76023 of 14 May 1976	Republic Fastener Mfg. Corp. (Cont'd) -
NOTE: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 0f 20 November 1970.			
MS21069-6 MS21069L6	RM200X6 RM200A6	Report No. 305Q83088 0f 26 Jan 1983	
MS21069L3 MS21069L3K MS21069L4 MS21069L4K MS21069LO4 MS21069LO4K MS21069LOR NS21069LO8K MS21069-O8 MS21069-3 MS21069-4	GM-93M GM-93MK GM-94M GM-94MK GM-904M GM-904MK GM-908M GM-908MK GM-908 GM-93 GM-94	Report No. 305Q83101 of 5 May 1983 305Q83104 of 12 Aug 1983 305Q83142 **Of** 28 **Nov** 1983 601Q8401 of 24 Feb 1984 601Q8407 of 20 Apr 1984	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 - f. 92152 Suresnes Cedex **France**
NOTE : (1) Manufacturing process: **Cold** formed (2) Lubricant: (For Government Designation with "L") QPL-8937 (3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.			
MS21069-O4 MS21069-O4K	GM-904 GM-904K	NADC Report 601Q8502 of 11 Mar 1985	
NOTE : (1) Manufacturing process: Cold stamping. (2) Lubricant: (For Government Designation with "L") QPL-8937 (3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in **every** subcontract and purchase order.			

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21069-06	GSM-906	NADC Report 601Q8518 of 30 Dec 1985	Simmonds Fastener Technologies Inc. (Cent'd)
MS21069LO6	GSM-906M		

NOTE : (1) Manufacturing process: Cold forging
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy **American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The** contractor should include these provisions in every subcontract and purchase order.

MS21070 NUT, SELF-LOCKING, PLATE, TWO LUG, REDUCED RIVET SPACING, LOW HEIGHT. CRES, 125 ksi Ftu, 450° & 800°F

MS2107OLO4	MTL2C440M	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Namer Ave. Santa Ana, CA 92707-0157 . Plant: Same address -
MS2107OLO6	MTL2C632M		
MS21070L08	MT2C832M		
MS2107OL3	MT2C1032M		
MS2107OL4	MT2C428M		
MS21070L5	MT2C524M		
MS2107OL6	MT2C624M		
MS2107OLO4K	MTL2C440BCM		
MS2107OLO6K	MTL2C632BCM		
MS2107OLO8K	MT2C832BCM		
MS21070L3K	MT2C1032BCM		
MS2107OL4K	MT2C428BCM		
MS2107OL5K	MT2C524BCM		
MS2107O-O4	MTL2C440		
MS21070-06	MTL2C632		
MS2107O-O8	MT2C832		
MS2107O-3	MT2C1032		
MS2107O-4	MT2C428		
MS2107O-5	MT2C524		
MS21070-6	MT2C624		
MS2107O-O4K	MTL2C440BC		
MS2107O-O6K	MTL2C632BC		
MS21070-08K	MT2C832BC		
MS2107O-3K	MT2C1032BC		
MS2107O-4K	MT2C428BC		
MS2107O-5K	MT2C524BC		
MS2107O-O4W	MTL2C440PWB		
MS2107O-O6W	MTL2C632PWB		
MS21070-08W	MT2C832PWB		
MS21070-3W	MT2C1032PWB		
MS2107O-4W	MT2C428PWB		
MS2107O-5W	MT2C524PWB		
MS21070-6W	MT2C624PWB		
MS2107OLO4W	MTL2C440PM		
MS21070L06W	MTL2C632PM		
MS2107OLO8W	MT2C832PM		
MS21070L3W	MT2C1032PM		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21070L4W	MT2C428PM	**Report No.** NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations (Cent'd)
MS21070L5W	MT2C524PM		
MS21070L6W	MT2C624PM		
MS21070LO4	RMLHTA1M2860-40	Report No. NAEC-AML-2429 of 15 Mar 1966	**Elastic Stop** Nut **A Division of Harvard Industries,** Inc. **2330 Vauxhall Road** Union, NJ 07083 **Plant: Same address and 3200 Country Club** Road Pocahontas, AR 72455
MS21070L06	RMLHTA1M2860-62		
MS21070L02	RMLHTA51M2860-26		
MS21070LO8	RMLHTA51M2860-82		
MS21070L3	RMLHTA51M2860-02		
MS21070L4	RMLHTA51H2860-048		
MS21070L5	RMLHTA51M2860-054		
MS21070L6	RMLHTA51M2860-064		
MS21070LO4K	RMLHTA1M2860-40BC		
MS21070LO6K	RMLHTA1M2860-62BC		
MS21070LO8K	RMLHTA51M2860-82BC		
MS21070L3K	RMLHTA51M2860-02BC		
MS21070L4K	RMLHTA51M2860-048BC		
MS21070L5K	RMLHTA51M2860-054BC		
MS21070LO4W	RMLHTA1M2860P-40		
MS21070L06W	RMLHTA1M2860P-62		
MS21070LO2W	RMLHTA51M2860P-26		
MS21070LO8W	RMLHTA51M2860P-82		
MS21070L3W	RMLHTA51M2860P-02		
MS21070L4W	RMLHTA51M2860P-048		
MS21070L5W	RMLHTA51M2860P-054		
MS21070L6W	RMLHTA51M2860P-064		
MS21070-O4	LHHTA1M42860-40		
MS21070-O6	LHHTA1M2860-62		
MS21070-O2	LHHTA51M2860-26		
MS21070-O8	LHHTA51M2860-82		
MS21070-3	LHHTA51M2860-02		
MS21070-4	L HTA51M2860-048		
MS21070-5	LHHTA51M2860-054		
MS21070-6	LHHTA51M2860-064		
MS21070-O4K	LHHITA1M2860-40BC		
MS21070-O6K	LHHTA1M2860-62BC		
MS21070-O8K	LHHTA51M2860-82BC		
MS21070-3K	LHHTA51M2860-02BC		
MS21070-4K	LHHTA51M2860-048BC		
MS21070-5K	LHHTA51M2860-054BC		
MS21070-04W	LHHTA1M2860P-40		
MS21070-O6W	LHHTA1M2860P-62		
MS21070-O2W	LHHTA51M2860P-26		
MS21070-O8W	LHHTA51M2860P-82		
MS21070-3W	LHHTA51M2860P-02		
MS21070-4W	LHHTA51M2860P-048		
MS21070-5W	LHHTA51M2860P-054		
MS21070-6W	L HTA51M2860P-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21070-04	VN202-B1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21070-06	VN202-B1-62		
MS21070-08	VN202-B1-82		
MS21070-3	VN202-B1-02		
MS21070-4	VN202-B1-048		
MS21070-5	VN202-B1-054		
MS21070-6	VN202-B1-064		
MS21070-04K	VN202-B2-40		
MS21070-06K	VN202-B2-62		
MS21070-08K	VN202-B2-82		
MS21070-3K	VN202-B2-02		
MSZI070-4K	VN202-B2-048		
MS21070-5K	VN202-B2-054		
MS21070-04W	VN202-B3-40		
MS21070-06W	VN202-B3-62		
MS21070-08W	VN202-B3-82		
MS21070-3W	VN202-B3-02		
MS21070-4W	VN202-B3-048		
MS21070-5W	VN202-B3-054		
MS21070-6W	VN202-B3-064		
MS2107OLO4	VN202-D1-40		
MS21070L06	VN202-D1-62		
MS21070108	VN202-D1-82		
MS2107OL3	VN202-D1-02		
MS2107OL4	VN202-D1-048		
MS21070L5	VN202-D1-054		
MS2107OL6	VN202-D1-064		
MS21070L04K	VN202-D2-40		
MS2107OLO6K	VN202-D2-62		
MS21070L08K	VN202-D2-82		
MS21070L3K	VN202-D2-02		
MS2107OL4K	VN202-D2-048		
MS2107OL5K	VN202-D2-054		
MS2107OLO4W	VN202-D3-40		
MS2107OLO6W	VN202-D3-62		
MS2107OLO8W	VN202-D3-82		
MS2107OL3W	VN202-D3-02		
MS21070L4W	VN202-D3-048		
MS21070L5W	VN202-D3-054		
MS2107OL6W	VN202-D3-064		
MS2107O-O4	M12700-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS2107O-O6	M12700-62		
MS2107O-O8	M12700-82		
MS2107O-3	M12700-02		
MS21070-4	M12700-048		
MS21070-5	M12700-054		
MS2107O-6	M12700-064		
MS2107O-O4K	M12700-40BC		
MS2107O-O6K	M12700-62BC		
MS2107O-O8K	M12700-82BC		
MS2107O-3K	M12700-02BC		
MS2107O-4K	M12700-048BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21070-5K	MA12700-054BC	Report No. **NAEC-AML-2369 of 15 Mar 1966**	SPS **Technologies (Cent'd)**
MS21070-04W	M12700-40PW		
MS21070-06W	M12700-62PW		
MS21070-08W	M12700-82PW		
MS21070-3W	M12700-02PW		
MS21070-4W	M12700-048PW		
MS21070-5W	MA12700-054PW		
MS21070-6W	MA12700-064PW		
MS21070L04	M12700E-40		
MS21070L06	M12700E-62		
MS21070L08	M12700E-82		
MS21070L3	M12700E-02		
MS21070L4	M12700E-048		
MS21070L5	MA12700E-054		
MS21070L6	MA12700E-064		
MS21070L04K	MA12700E-40BC		
MS21070L06K	MA12700E-62BC		
MS21070L08K	MA12700E-82BC		
MS21070L3K	MA12700E-02BC		
MS21070L4K	MA12700E-048BC		
MS21070L5K	MA12700E-054BC		
MS21070L04W	M12700E-40PW		
MS21070L06W	M12700E-62PW		
MS21070L08W	M12700E-82PW		
MS21070L3W	M12700E-02PW		
MS21070L4W	M12700E-048PW		
MS21070L5W	MA12700E-054PW		
MS21070L6W	MA12700E-064PW		
MS21070-02	MK1331-02	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21070-04	MK1031-04		
MS21070-06	MK1031-06		
MS21070-08	MK1031-08		
MS21070-3	MK1031-3		
MS21070-4	MK1031-4		
MS21070-5	MK1331-5		
MS21070-6	MK1331-6		
MS21070-04K	MK1031-04BC		
MS21070-06K	MK1031-06BC		
MS21070-08K	MK1031-08BC		
MS21070-3K	MK1031-3BC		
MS21070-4K	MK1031-4BC		
MS21070-5K	MK1331-5BC		
MS21070-02W	MK1331-02P		
MS21070-04W	MK1031-04P		
MS21070-06W	MK1031-06P		
MS21070-08W	MK1031-08P		
MS21070-3W	MK1031-3P		
MS21070-4W	MK1031-4P		
MS21070-5W	MK1331-5P		
MS21070-6W	MK1331-6P		
MS21070L02	MK1301-02		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION.	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21070L04	MK1001-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. (Cont'd)
MS21070L06	MK1001-06		
MS21070L08	MK1001-08		
MS21070L3	MK1001-3		
MS21070L4	MK1001-4		
MS21070L5	MK1301-5		
MS21070L6	MK1301-6		
MS21070L04K	MK1001-04BC		
MS21070L06K	MK1001-06BC		
MS21070L0BK	MK1001-08BC		
MS21070L3K	MK1001-3BC		
MS21070L4K	MK1001-4BC		
MS21070L5K	MK1301-5BC		
MS21070L02W	MK1301-02P		
MS21070L04W	MK1001-04P		
MS21070L06W	NK1001-06P		
MS21070L08W	MK1001-08P		
MS21070L3W	MK1001-3P		
MS21070L4W	MK1001-4P		
MS21070L5W	MK1301-5P		
MS21070L6W	MK1301-6P		
MS21070-04	RM200C04L	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21070-04K	RM200C04LK		
MS21070-04W	RM2001C04LW		
MS21070L04	RM200C04LM		
MS21070L04K	RM200C04LMK		
MS21070L04W	RM200C04LMW		
MS21070-06	RM200C06L		
MS21070-06K	RM200C06LK		
MS21070-06W	RM200C06LW		
MS21070L06	RM200C06LM		
MS21070L06K	RM200C06LMK		
MS21070L06W	RM200C06LMW		
MS21070-08	RM200C08		
MS21070-08K	RM200C08K		
HS21070-08W	RM200C08W		
MS21070L08	RM200C08M		
MS21070L08K	RM200C08MK		
MS21070L08W	RM200C08MW		
MS21070-3	RM200C3		
MS21070-3K	RM200C3K		
MS21070-3W	RM200C3W		
MS21070L3	RM200C3M		
MS21070L3K	RM200C3MK		
MS21070L3W	RM200C3MW		
MS21070-4	RM200C4		
MS21070-4K	RM200C4K		
MS21070-4W	RM200C4W		
MS21070L4	RM200C4M		
MS21070L4K	RM200C4MK		
MS21070L4W	RM200C4W		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION
MS21070-5
MS21070-5K
MS21070-5W
MS21070L5
MS21070L5K
MS21070L5W
MS21070-6
MS21070-6W
MS21070L6
MS21070L6W
MS21070-3
MS21070-3K
MS21070-08
MS21070-08K
MS21070-4
MS21070-4K
NOTE : Provis Procure be in i 52.225- should
MS21070L08
MS21070L3
NOTE : (1) Mi (2) Lu (3) p N Co P
MS21070-06
MS21070L06
NOTE: (1) Ma (2) Lu (3) Pr nu Dl co pu

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21071 NUT, SELF-LOCKING, PLATE, ONE LUG, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 125 ksi Ftu, 450"F			
MS21071-O4	MTL12S440CPC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Divisionof Textron, Inc. **P.O. Box 2157** **1224 East** Warner **Ave.** **Santa Ana, CA 92707-0157** Plant: Same address
MS21071-06	MTL12S632CPC		
MS21071-08	MT12S832CPC		
MS21071-3	MT12SI032CPC		
MS21071-4	MT12S42BCPC		
MS2107I-5	MT12S524CPC		
MS21071-6	MT12S624CPC		
MS21071L04	MTL12S440		
MS21071L06	MTL12S632		
MS21071LO8	MT12S832		
MS21071L3	MT12SI032		
MS21071L4	MT12S428		
MS2107IL5	MT12S524		
MS21071L6	MT12S624		
MS21071-O4K	MTL12S440BCCPC		
MS21071-O6K	MTL12S632BCCPC		
MS21071-O8K	MT12S832BCCPC		
MS21071-3K	MT12S1032BCCPC		
MS21071-4K	MT12S428BCCPC		
MS21071-5K	MT12S524BCCPC		
MS21071L04K	MTL12S440BC		
MS21071LO6K	MTL12S632BC		
MS21071L08K	MT12S832BC		
MS21071L3K	MT12S1032BC		
MS21071L4K	MT12S428BC		
MS21071L5K	MT12S524BC		
MS21071-O4	MK2000-04CW	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21071-O6	MK2000-06CW		
M521071-O8	MK2000-08CW		
MS2107I-3	MK2000-3CW		
MS21071-4	MK2000-4CW		
MS21071-O4K	MK2000-04BCCW		
MS21071-O6K	MK2000-06BCCW		
MS21071-08K	MK20O0-08BCCW		
MS21071-3K	MK2000-3BCCW		
MS2107I-4K	MK2000-4BCCW		
MS21071LO4	MK2000-04		
MS21071LO6	MK2000-06		
MS21071LO8	MK2000-08		
MS21071L3	MK2000-3		
MS21071L4	MK2000-4		
MS21071L04K	MK2000-04BC		
MS21071LO6K	MK2000-06BC		
MS21071LO8K	MK2000-08BC		
MS21071L3K	MK2000-3BC		
MS21071L4K	MK2000-4BC		

Source: https://assist.dla.mil -- Downloaded: 2026t0-26T13:17Z
Check the source to verify that this is the currentversion before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S - NAME AND ADDRESS
MS21071-04	VN201-C1-40	Report No. NAEC-AML-2425 **of 15 Mar** 1966	VOI-SHAN VSI Aerosp. **Prod. Div.** 8463 Higuera Street Culver City, CA **90230** **Plant: 2700 Compton Blvd. Redondo Beach, CA 90278**
MS21071-06	VN201-C1-62		
MS21071-08	VN201-C1-82		
MS21071-3	VN201-C1-02		
MS21071-4	VN201-C1-048		
MS21071-5	VN201-C1-054		
MS21071-6	VN201-C1-064		
MS21071L04	VN201-A1-40		
MS21071L06	VN201-A1-62		
MS21071L08	VN201-A1-82		
MS21071L3	VN201-A1-02		
MS21071L4	VN201-A1-048		
MS21071L5	VN201-A1-054		
MS21071L6	VN201-A1-064		
MS21071-04K	VN201-C2-40		
MS21071-06K	VN201-C2-62		
MS21071-08K	VN201-C2-82		
MS21071-3K	VN201-C2-02		
MS21071-4K	VN201-C2-048		
MS21071-5K	VN201-C2-054		
MS21071L04K	VN201-A2-40		
MS21071L06K	VN201-A2-62		
MS21071L08K	VN201-A2-82		
MS21071L3K	VN201-A2-02		
MS21071L4K	VN201-A2-048		
MS21071L5K	VN201-A2-054		
MS21071-04	F12LHTA17M-40	Report No. NAEC-AML-2429 of 15 **Mar** 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall **Road** Union, NJ 07083 **Plant:** Same address and 3200 Country **Club Road Pocahontas,** AR 72455
MS21071-06	F12LHTA17M-62		
MS21071-02	F52LHTA57M-26		
MS21071-08	F52LHTA57M-82		
MS21071-3	F52LHTA57M-02		
MS21071-4	F52LHTA57M-048		
MS21071-5	F52LHTA57M-054		
MS21071-6	F52LHTA57M-064		
MS21071L04	RM12LHTA17N-40		
MS21071L06	RM12LHTA17M-62		
MS21071L02	RM52LHTA57M-26		
MS21071L08	RM52LHTA57M-82		
MS21071L3	RM52LHTA57M-02		
MS21071L4	RM52LHTA57M-048		
MS21071L5	RM52LHTA57M-054		
MS21071L6	RM52LHTA57M-064		
MS21071-04K	F12LHTA17M-40BC		
MS21071-06K	F12LHTA17M-62BC		
MS21071-08K	F52LHTA57M-82BC		
MS21071-3K	F52LHTA57M-02BC		
MS21071-4K	F52LHTA57M-048BC		
MS21071-5K	F52LHTA57M-054BC		
MS21071L04K	RM12LHTA17M-40BC		
MS21071L06K	RM12LHTA17M-62BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21071L08K	RM52LHTA57M-82BC	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. (Cont'd)
MS21071L3K	RM52LHTA57M-02BC		
MS21071L4K	RM52LHTA57M-048BC		
MS2107?L5K	RH52LHTA57M-054BC		
MS21071-04	M12610NM-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MS2107I-O6	M1261ONM-62		
MS21071-O8	M1261ONM-82		
MS21071-3	M1261ONM-O2		
MS21071-4	M1261ONM-O48		
MS21071-5	MA1261ONM-O54		
M4S21071-6	MA1261ONM-O64		
MS21071LO4	M12610-40		
MS21071L06	M12610-62		
MS21071L08	M12610-82		
MS21071L3	M1261O-O2		
MS21071L4	M1261O-O48		
MS21071L5	MA1261O-O54		
MS21071L6	MA12610-064		
MS21071-04K	M1261ONM-4OBC		
MS21071-06K	M12610NM-62BC		
MS21071-08K	M12610NM-828C		
MS21071-3K	M12610NM-02BC		
MS121071-4K	M12610NM-048BC		
MS21071-5K	MA12610NM-054BC		
MS21071L04K	M1261O-4OBC		
MS21071LO6K	M12610-628C		
MS21071LO8K	M1261O-82BC		
MS21071L3K	M12610-02BC		
MS21071L4K	M12610-048BC		
MS21071L5K	MA1261O-O54BC		
MS21071-08	RM1OOXO8	Report No. 305Q76023 of 14 May 1976	Republic Fastener Mfg. co. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21071LO8	RM1OOAO8		
MS21071-O8K	RM100X08K		
MS21071L08K	RM100A08K		
MS21071-3	RM1OOX3		
MS21071L3	RM100A3		
MS21071-3K	RM1OOX3K		
MS21071L3K	RM1OOA3K		
MS21071-4	RM100X4		
MS21071L4	RM1OOA4		
MS21071-4K	RM100X4K		
MS21071L4K	RM1OOA4K		

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21071-O4	RM100X04L	Report No.	Republic Fastener Mfg. co. (Cont'd)
MS21071L04	RM100A04L	305Q76023 0f 14 May 1976	
MS21071-04K	RM100X04LK		
MS21071L04K	RM100A04LK		
MS21071-06	RM100X06L		
MS21071L06	RM100A06L		
MS21171-06K	RM100X06LK		
MS21071L06K	RM100A06LK		
MS21071-5	RM100X5		
MS21071L5	RM100A5		
MS21071-5K	RM100X5K		
MS21071L5K	RM100A5K		
MS21071-6	RM100X6	Report No.	
MS21071L6	RM100A6	305Q83088 of 26 Jan 1983	
MS21071L3	AJM-93M	Report No.	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670
MS21071L3K	AJM-93MK	305Q83104 of 12 Aug 1983	
MS21071L4	AJM-94M		
MS21071L4K	AJM-94MK		
MS2107IL08	AJM-908M	601Q8401 of 24 Feb 1984	Plant: Simmonds 5, rue Michele, B.P. 52 F. 92152 Suresnes Cedex France
MS21071LO8K	AJM-908MK		
MS21071-3	AJH-93	601Q84070f 20 Apr 1984	

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21071-08	AJM-908	NADC Report 601Q8417 0f 25 Ott 1984
1621071-08K	AJM-908K	
MS21071-4	AJM-94	601Q8517 of 16 Dec 1985
MS21071LO4	AJSM-904M	601Q8612 of 6 Ott 1986

NOTE: (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTRER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21071-06 MS21071L06	AJSM-906 AJSM-906M	NADC Report 601Q8518 of 30 Dec 1985	Simmonds Fastener Technologies Inc. (Cont'd)

NOTE: (1) Manufacturing process: Cold forging
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic **Specialty Metals). The** contractor should include these provisions in every subcontract and purchase order.

MS21072 NUT, SELF-LOCKING, PLATE, ONE LUG, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 **ksi** Ftu, 450° & 800°F

MS21072-04 MS21072-06 MS21072-08 MS21072-3 MS21072-4 MS21072-5 MS21072-6 MS21072-O4K MS21072-O6K MS21072-O8K MS21072-3K MS21072-4K MS21072-5K MS21072-O4W MS21072-06W MS21072-O8W MS21072-3W MS21072-4W MS21072-5W MS21072-6W MS21072LO4 MS21072L06 MS21072L08 MS21072L3 MS21072L4 MS21072L5 MS21072L6 MS21072LO4K MS21072LO6K MS21072L08K MS21072L3K MS21072L4K MS21072L5K MS21072L04W MS21072L06W MS21072L08W	MTL12C440 MTL12C632 MT12C832 MT12C1032 MT12C428 MT12C524 MT12C624 MTL12C440BC MTL12C632BC MT12C832BC MT12C1032BC MT12C428BC MT12C524BC MTL12C440P MTL12C632P MT12C832P MT12C1032P MT12C428P MT12C524P MT12C624P MTL12C440M MTL12C632M MT12C832M MT12C1032M MT12C428M MT12C524M MT12C624M MTL12C440BCM MTL12C632BCM MT12C832BCM MT12C1032BCM MT12C428BCM MT12C524BCM MTL12C440PM MTL12C632PM ML12C832PM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave Santa Aria, CA 92707-0157 **Plant: Same address**

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21072L3W MS21072L4W MS21072L5W MS21072L6W	ML12C1032PM ML12C428PM ML12C524PM ML12C624PM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations (Cont'd)
MS21072L04	RMLHTA17M2860-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21072L06	RMLHTA17M2860-62		
MS21072L02	RMLHTA57M2860-26		
MS21072L08	EMLHTA57M2860-82		
MS21072L3	EMLHTA57M2860-02		
MS21072L4	RMLHTA57M2860-048		
MS21072L5	RMLHTA57M2860-054		
MS21072L6	RMLHTA57M2860-064		
MS21072L04K	RMLHTA17M2860-40BC		
MS21072L06K	RMLHTA17M2860-62BC		
MS21072L08K	RMLHTA57M2860-82BC		
MS21072L3K	RMLHTA57M2860-02BC		
MS21072L4K	RMLHTA57M2860-048BC		
MS21072L5K	RMLHTA57M2860-054BC		
MS21072L04W	RMLHTA17M2860P-40		
MS21072L06W	RMLHTA17M2860P-62		
MS21072L02W	RMLHTA57M2860P-26		
MS21072L08W	RMLHTA57M2860P-82		
MS21072L3W	RMLHTA57M2860P-02		
MS21072L4W	RMLHTA57M2860P-048		
MS21072L5W	RMLHTA57M2860P-054		
MS21072L6W	RMLHTA57M2860P-064		
MS21072-04	LHTA17M2860-40		
MS21072-06	LHTA17M2860-62		
MS21072-02	LHTA57M2860-26		
MS21072-08	LHTA57M2860-82		
MS21072-3	LHTA57M2860-02		
MS21072-4	LHTA57M2860-048		
MS21072-5	LHTA57M2860-054		
MS21072-6	LHTA57M2860-064		
MS21072-04K	LHTA17M2860-40BC		
MS21072-06K	LHTA17M2860-62BC		
MS21072-08K	LHTA57M2860-82BC		
MS21072-3K	LHTA57M2860-02BC		
MS21072-4K	LHTA57M2860-048BC		
MS21072-5K	LHTA57M2860-054BC		
MS21072-04W	LHTA17M2860P-40		
MS21072-06W	LHTA17M2860P-62		
MS21072-02W	LHTA57M2860P-26		
MS21072-08W	LHTA57M2860P-82		
MS21072-3W	LHTA57M2860P-02		
MS21072-4W	LHTA57M2860P-048		
MS21072-5W	LHTA57M2860P-054		
MS21072-6W	LHTA57M2860P-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21072-O4	M12710-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 South Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21072-O6	M12710-62		
MS21072-O8	M12710-82		
MS21072-3	M12710-02		
MS21072-4	M1271O-O48		
MS21072-5	MA12710-054		
MS21072-6	MA1271O-O64		
MS21072-04K	M12710-40BC		
MS21072-06K	M1271O-62BC		
MS21072-O8K	M1271O-82BC		
MS21072-3K	M12710-02BC		
MS21072-4K	M1271O-O48BC		
MS21072-5K	MA1271O-O54BC		
MS21072-O4W	M1271O-4OPW		
MS21072-06W	M12710-62PW		
MS21072-08W	M1271O-82PW		
MS21072-3W	M1271O-O2PW		
MS21072-4W	M12710-048PW		
MS21072-5W	MA12710-054PW		
MS21072-6W	MA1271O-O64PW		
MS21072L04	M1271OE-4O		
MS21072L06	M12710E-62		
MS21072L08	M1271OE-82		
MS21072L3	M1271OE-O2		
MS21072L4	M12710E-048		
MS21072L5	MA12710E-054		
MS21072L6	MA12710E-064		
MS21072L04K	M12710E-40BC		
MS21072LO6K	M12710E-62BC		
MS21072LO8K	M1271OE-82BC		
MS21072L3K	M1271OE-O2BC		
MS21072L4K	M1271OE-O48BC		
MS21072L5K	MA12710E-054BC		
MS21072LO4W	M1271OE-4OPW		
MS21072LO6W	M12710E-62PW		
MS21072LO8W	M1271OE-82PW		
MS21072L3W	M1271OE-O2PW		
MS21072L4W	M1271OE-O48PW		
MS21072L5W	MA1271OE-O54PW		
MS21072L6W	MA1271OE-O64PW		
MS2 1072-04	MK2031-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS2 1072-06	MK2031-06		
MS2 1072-08	MK2031-08		
MS2 1072-3	MK2031-3		
MS2 1072-4	MK2031-4		
MS2 1072-04K	MK2031-04BC		
MS2 1072-06K	MK2031-06BC		
MS2 1072-08K	MK2031-08BC		
MS2 1072-3K	MK2031-3BC		
MS2 1072-4K	MK2031-4BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21072-O4W	MK2031-04P	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. (Cont'd)
MS21072-O6W	MK2031-06P		
MS21072-O8W	MK2031-08P		
MS21072-3W	MK2031-3P		
MS21072-4W	MK2031-4P		
MS21072LO4	MK2001-04		
MS21072LO6	MK2001-06		
MS21072L08	MK2001-08		
MS21072L3	MK2001-3		
MS21072L4	MK2001-4		
MS21072L04K	MK2001-04BC		
MS21072L06K	MK2001-068C		
MS21072L08K	MK2001-088C		
MS21072L3K	MK2001-3BC		
MS21072L4K	MK2001-4BC		
MS21072LO4W	MK2001-04P		
MS21072LO6W	MK2001-06P		
MS21072LO8W	MK2001-08P		
MS21072L3W	MK2001-3P		
MS21072L4W	MK2001-4P		
MS21072-O4	VN201-B1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod: Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21072-06	VN201-B1-62		
MS21072-08	VN201-B1-82		
MS21072-3	VH201-B1-02		
MS21072-4	VN201-B1-048		
MS21072-5	VN201-B1-054		
MS21072-6	VN201-B1-064		
MS21072-04K	VN201-B2-40		
MS21072-O6K	VN201-B2-62		
MS21072-O8K	VN201-B2-82		
MS21072-3K	VN201-B2-02		
MS21072-4K	VN201-B2-048		
MS21072-5K	VN201-B2-054		
MS21072-O4W	VN201-B3-40		
MS21072-O6W	VN201-B3-62		
MS21072-O8W	VN201-B3-82		
MS21072-3W	VN201-B3-02		
MS21072-4W	VN201-B3-048		
MS21072-5W	VN201-B3-054		
MS21072-6W	VN201-B3-064		
MS21072LO4	VN201-D1-40		
MS21072LO6	VN201-D1-62		
MS21072LO8	VN201-D1-82		
MS21072L3	VN201-D1-02		
MS21072L4	VN201-D1-048		
MS21072L5	VN201-D1-054		
MS21072L6	VN201-D1-064		
MS21072L04K	VN201-D2-40		
MS21072L06K	VN201-D2-62		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS2 1072L08K	VN201-D2-82	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. (Cont'd)
MS2 1072L3K	VN201-D2-02		
MS2 1072L4K	VN201 -D2-048		
MS2 1072L5K	VN201 -D2-054		
MS2 1072L04W	VN201-D3-40		
MS2 1072L06W	VN201 -D3-62		
MS21072LO8W	VN201-D3-82		
MS21072L3W	VN201-D3-02		
MS21072L4W	VN201 -D3-048		
MS21072L5W	VN201 -D3-054		
MS21072L6W	VN201-D3-064		
MS21072-O4	RM100CO4L	NADC Report No. 305Q76023 of 14 May 1976	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21072-04K	RM100C04LK		
MS21072-O4W	RM100C04LW		
MS21072LO4	RM100C04LM		
MS21072LO4K	RM100C04LMK		
MS21072LO4W	RM100C04LMW		
MS21072-06	RM100C06L		
MS21072-O6K	RM100C06LK		
MS21072-O6W	RM100C06LW		
MS21072LO6	RM100C06LM		
MS21072LO6K	RM100C06LMK		
MS21072LO6W	RM100C06LMW		
MS21072-08	RM100C08		
MS21072-08K	RM100C08K		
MS21072-08W	RM100C08W		
MS21072L08	RM100CO8M		
MS21072LO8K	RM100C08MK		
MS21072L08W	RM100C08MW		
MS21072-3	RM100C3		
MS21072-3K	RM100C3K		
MS21072-3W	RM100C3W		
MS21072L3	RM100C3M		
MS21072L3K	RM100C3MK		
MS21072L3W	RM100C3MW		
MS21072-4	RM100C4		
MS21072-4K	RM100C4K		
MS21072-4W	RM100C4W		
MS21072L4	RM100C4M		
MS21072L4K	RM100C4MK		
MS21072L4W	RM100C4MW		
MS21072-5	RM100C5		
MS21072-5K	RM100C5K		
MS21072-5W	RM100C5W		
MS21072L5	RM100C5M		
MS21072L5K	RM100C5MK		
MS21072L5W	RM100C5MW		

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 0f 20 November 1970.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21072-6 **MS21072L6** MS21072-6W **MS21072L6W**	**RM1OOC6** **RM100C6M** RM100C6W **RM100C6MW**	**Report No. 305083088 of 26 Jan 1983**	**Republic Fastener Mfg. Corp. (Cont'd)**
MS21072-3 **MS21072-3K**	**AJM-53** **AJM-53K**	**Report No. 305Q83104 of 12 Aug 1983**	**Simmonds Fastener Technologies Inc. 181 A West Orangethorpc Placentia, CA 92670**
MS21072-4 **MS21072-4K**	**AJM-54** **AJM-54K**	**305Q83112 Or 28 Nov 1983**	Plant: Simmonds
MS21072-O8 MS21072-08K	AJM-508 AJM-508K	601Q8401 of 24 Feb 1984	5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex **France**

NOTE: (1) **Manufacturing process: Cold formed**
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with **FAR 52.225-3** (Buy American **Act)** and DFARS 52.225-7012 **(Preference for Domestic** Specialty Metals). The contractor should include these provisions in every subcontract and purchase order. . . . . .

MS21072-06 MS21072L06	AJSM-506 AJSM-506M	NADC Report 60108518 of 30 Dec 1985

NOTE: (1) Manufacturing process: Cold forging
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21072L08 MS21072L3	AJM-508 AJM-53M	Report No. 601Q8609 of 8 Aug 1986
MS21072L04	AJM-54M	601Q8612 of 6 Ott 1986

NOTE: (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil - Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21073 NUT, SELF-LOCKING, PLATE, CORNER, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 125 ksi Ftu, 450°F			
MS21073-O4	MTL7S440CPC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21073-O6	MTL7S632CPC		
MS21073-O8	MT7S832CPC		
MS21073-3	MT7S1032CPC		
MS21073-4	MT7S428CPC		
MS21073-5	MT7S524CPC		
MS21073-6	MT7S624CPC		
MS21073L04	MTL7S440		
MS21073L06	MTL7S632		
MS21073LO8	MT7S832		
MS21073L3	MT7S1032		
MS21073L4	MT7S428		
MS21073L5	MT7S524		
MS21073L6	MT7S624		
MS21073-O4K	MTL7S440BCCPC		
MS21073-O6K	MTL7S632BCCPC		
MS21073-O8K	MT7S832BCCPC		
MS21073-3K	MT7S1032BCCPC		
MS21073-4K	MT7S428BCCPC		
MS21073-5K	MT7S524BCCPC		
MS21073LO4K	MTL7S4408C		
MS21073LO6K	MTL7S632BC		
MS21073LO8K	MT7S832BC		
MS21073L3K	MT7S1032BC		
MS21073L4K	MT7S428BC		
MS21073L5K	MT7S524BC		
MS21073-O4	F12LHTA5M-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21073-O6	F12LHTA5M-62		
MS21073-02	F52LHTA55M-26		
MS21073-O8	F52LHTA55M-82		
MS21073-3	F52LHTA55M-02		
MS21073-4	F52LHTA5514-048		
MS21073-5	F52LHTA55M-054		
MS21073-6	F52LHTA55M-064		
MS21073LO4	RM12LHTA5M-40		
MS21073LO6	RM12LHTA5M-62		
MS21073L02	RM52LHTA55M-26		
MS21073LO8	RM52LHTA55M-82		
MS21073L3	RN52LHTA55M-02		
MS21073L4	RM52LHTA55M-048		
MS21073L5	RM52LHTA55M-054		
MS21073L6	RM52LHTA55M-064		
MS21073-O4K	F12LHTA5M-40BC		
MS21073-O6K	F12LHTA5M-62BC		
MS21073-O8K	F52LHTA55M-82BC		
MS21073-3K	F52LHTA55M-02BC		
MS21073-4K	F52LHTA55M-048BC		
MS21073-5K	F52LHTA55M-054BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21073LO4K	**RM12LHTA5M-40BC**	**Report No.** NAEC-AML-2429 of 15 Mar 1966	**Elastic Stop** Nut A Division of Harvard Industries, **Inc.** (Cent'd)
MS21073LO6K	RM12LHTA5M-62BC		
MS21073L08K	RM52LHTA55M-82BC		
MS21073L3K	RM52LHTA55M-02BC		
MS21073L4K	RH52LHTA55M-048BC		
MS21073L5K	RH52LHTA55M-054BC		
MS21073-04	M12620NM-40	Report No. NAEC-AML-2369 **of 15 Mar 1966**	SPS Technologies 2701 South Harbor **Blvd.** **Santa Aria, CA 92702** **Plant: Same address**
MS21073-06	M12620NM-62		
MS21073-O8	**M12620NM-82**		
NS21073-3	**M12620NM-02**		
MS2J073-4	**M12620NM-048**		
MS21073-5	**MA12620NM-054**		
MS21073-6	**MA12620NM-064**		
MS21073L04	**M12620-40**		
MS21073LO6	**M12620-62**		
MS21073LO8	**M12620-82**		
MS21073L3	**M12620-02**		
MS21073L4	**M12620-048**		
MS21073L5	**MA12620-054**		
MS21073L6	**MA12620-064**		
MS21073-04K	**M12620NM-40BC**		
MS21073-06K	**M12620NM-62BC**		
MS21073-O8K	**M12620NM-82BC**		
MS21073-3K	**M12620NM-02BC**		
MS21073-4K	**M12620NM-048BC**		
MS21073-5K	**MA12620NM-0548C**		
MS21073L04K	**M12620-40BC**		
MS21073LO6K	**M12620-62BC**		
MS21073LO8K	**M12620-82BC**		
MS21073L3K	**M12620-02BC**		
MS21073L4K	**M12620-048BC**		
MS21073L5K	**MA12620-054BC**		
MS21073-04	MK300-04CW	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Fullerton, CA 92634 Plant: Same address
MS21073-06	MK3000-06CW		
MS21073-O8	MK3000-08CW		
MS21073-3	MK3000-3CW		
MS21073-4	MK3000-4CW		
MS21073-5	MK3300-5CW		
MS21073-O4K	MK3000-04BCCW		
MS21073-O6K	MK3000-06BCCW		
MS21073-O8K	MK3000-08BCCW		
MS21073-3K	MK3000-3BCCM		
MS21073-4K	MK3000-4BCCW		
MS21073-5K	MK3300-5BCCW		
MS21073LO4	MK3000-04		
MS21073LO6	MK3000-06		
MS21073LO8	MK3000-08		
MS21073L3	MK3000-3		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21073L4	MK3000-4	Report No. NAEC-ML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. (Cent'd)
MS21073L5	MK3300-5		
MS21073LO4K	MK3000-04BC		
MS21073LO6K	MK3000-06BC		
MS21073L08K	MK3000-08BC		
MS21073L3K	MK3000-3BC		
MS21073L4K	MK3000-4BC		
MS21073L5K	MK3300-5BC		
MS21073-O4	VN203-C1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21073-O6	VN203-C1-62		
MS21073-08	VN203-C1-82		
MS21073-3	VN203-C1-02		
MS21073-4	VN203-C1-048		
MS21073-5	VN203-C1-054		
MS21073-6	VN203-C1-064		
MS21073L04	VN203-A1-40		
MS21073LO6	VN203-A1-62		
MS21073LO8	VN203-A1-82		
MS21073L3	VN203-A1-02		
MS21073L4	VN203-A1-048		
MS21073L5	VN203-A1-054		
MS21073L6	VN203-A1-064		
MS21073-O4K	VN203-C2-40		
MS21073-O6K	VN203-C2-62		
MS21073-O8K	VN203-C2-82		
MS21073-3K	VN203-C2-02		
MS21073-4K	VN203-C2-048		
MS21073-5K	VN203-C2-054		
MS21073LO4K	VN203-A2-40		
MS21073L06K	VN203-A2-62		
MS21073L08K	VN203-A2-82		
MS21073L3K	VN203-A2-02		
MS21073L4K	VN203-A2-048		
MS21073L5K	VN203-A2-054		
MS21073-08	RM300X08	Report No. 305Q76023 of 14 May 1976	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21073LO8	RM300A08		
MS21073-O8K	RM300X08K		
MS21073LO8K	RM300A08K		
MS21073-3	RM300X3		
MS21073L3	RM300A3		
MS21073-3K	RM300X3K		
MS21073L3K	RM300A3K		
MS21073-O4	RM300X04L		
MS21073LO4	RM300A04L		
MS21073-04K	RM300X04LK		
MS21073LO4K	RM300A04LK		
MS21073-O6	RM300X06L		
MS21073L06	RM300A06L		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21073-O6K MS21073LO6K MS21073-4 **MS21073L4** **MS21073-4K**	RM300X06LK RM300A06LK RM300X4 **RM300A4** **RM300X4K**	Report No. 305Q76023 0f 14 May **1976**	Republic Fastener **Mfg. Corp.** (Cent'd)
MS21073L4K **MS21073-5** **MS21073L5** **MS21073-5K** **MS21073L5K**	**RM300A4K** **RM300X5** **RM300A5** **RM300X5K** **RM300A5K**	**Report No.** **305Q76023 0f** **14 May 1976**	
MS21073-6 MS21073L6	RM300X6 RM300A6	Report No. 305Q83088 of 26 Jan 1983	
MS21073-3 MS21073L3	BLM-93 BLM-93Fl	NADC Report 601Q8710 **of** 22 Jul 1987	Simmonds Fastener Technologies, **Inc.** 181 A West Orangethorpe Placentia, CA. 92670 **Plant:** **Simnonds** **5, rue** Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: For Government Designation with "L" QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21074 NUT, SELF-LOCKING, PLATE, CORNER, REDUCED RIVET SPACING, **LOW HEIGHT, CRES, 125** ksi Ftu, 450° & 800"F

MS21U74-04 MS21074-O6 MS21074-O8 MS21074-3 MS21074-4 MS21074-5 MS21074-6 MS21074-O4K MS21074-O6K MS21074-08K MS21074-3K MS21074-4K	MTL7C440 MTL7C632 MT7C832 MT7C1032 MT7C428 MT7C524 MT7C624 MTL7C440BC MTL7C632BC MT7C832BC MT7C1032BC MT7C428BC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Ana, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21074-5K	MT7C524BC	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace operations (Cent'd)
MS21074-04W	MTL7C440PWB		
MS21074-O6W	MTL7C632PWB		
MS21074-08W	MT7C832PWB		
MS21074-3W	MT7C1032PWB		
MS21074-4W	MT7C428PWB		
MS21074-5W	MT7C524PWB		
MS21074-6W	MT7C624PWB		
MS21074LO4	MTL7C440M		
MS21074L06	MTL7C632M		
MS21074L08	MT7CB32M		
MS21074L3	MT7C1032M		
MS21074L4	MT7C428M		
MS21074L5	MT7C524M		
MS21074L6	MT7C624M		
MS21074LO4K	MTL7C440BCM		
MS21074LO6K	MTL7C632BCM		
MS21074LO8K	MT7C832BCM		
MS21074L3K	MT7C1032BCM		
MS21074L4K	MT7C428BCM		
MS21074L5K	MT7C524BCM		
MS21074L04W	MTL7C440PM		
MS21074L06W	MTL7C632PM		
MS21074LO8W	MT7C832PM		
MS21074L3W	MT7C1032PM		
MS21074L4W	MT7C428PM		
MS21074L5W	NT7C524PM		
MS21074L6W	MT7C624PM		
MS21074L04	RMLHTA5M2860-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21074LO6	RMLHTA5M2860-62		
MS21074LO2	RMLHTA55M2860-26		
MS21074LO8	RMLHTA55M2860-82		
MS21074L3	RMLHTA55M2860-02		
MS21074L4	RMLHTA55M2860-048		
MS21074L5	RMLHTA55M2860-054		
MS21074L6	RMLHTA55M2860-064		
MS21074LO4K	RMLHTA5M2860-40BC		
MS21074LO6K	RMLHTA5M2860-62BC		
MS21074LO8K	RMLHTA55M2860-82BC		
MS21074L3K	RMLHTA55M2860-025C		
MS21074L4K	RMLHTA55M42860-048BC		
MS21074L5K	RMLHTA55M2860-054BC		
MS21074LO4W	RMLHTA5M2860P-40		
MS21074LO6W	RMLHTA5M2860P-62		
MS21074LO2W	RMLHTA55M2860P-26		
MS21074L08W	RMLHTA55M2860P-82		
MS21074L3W	RMLHTA55M2860P-02		
MS21074L4W	RMLHTA55M2860P-048		
MS21074L5W	RMLHTA55H2860P-054		

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME ADDRESS
MS21074L6W	RMLHTA55M2860P-064	**Report No.** NAEC-AML-2429 of 15 Mar 1966	**Elastic Stop** Nut A Division of Harvard Industries, Inc. (Cent'd)
MS21074-04	LHTA5M2860-40		
MS21074-06	LHTA5M2860-62		
MS21074-02	LHTA55M2860-26		
MS21074-08	LHTA55M2860-82		
MS21074-3	LHTA55M2860-02		
MS21074-4	LHTA55M2860-048		
MS21074-5	LHTA55M2860-054		
MS21074-6	LHTA55M2860-064		
MS21074-4K	LHTA5M2860-40BC		
MS21074-06K	LHTA5M2860-628C		
MS21074-08K	LHTA55N2860-82BC		
MS21074-3K	LHTA55M2860-02BC		
MS21074-4K	LHTA55M2860-048BC		
MS21074-5K	LHTA55M2860-054BC		
MS21074-04W	LHTA5M2860P-40		
MS21074-06W	LHTA5M2860P-62		
MS21074-02W	LHTA55M2860P-26		
MS21074-08W	LHTA55M2860P-82		
MS21074-3W	LHTA55M2860P-02		
MS21074-4W	LHTA55M2860P-048		
MS21074-5W	LHTA55M2860P-054		
MS21074-6W	LHTA55M2860P-064		
MS21074-04	M12720-40	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 S. Harbor Blvd. **Santa Aria, CA 92702** **Plant: Same address**
MS21074-O6	M12720-62		
MS21074-O8	M12720-82		
MS21074-3	M12720-02		
MS21074-4	M12720-048		
MS21074-5	MA12720-054		
MS21074-6	MA12720-064		
MS21074-O4K	M12720-40BC		
MS21074-O6K	M12720-62BC		
MS21074-O8K	M12720-82BC		
MS21074-3K	M12720-02BC		
MS21074-4K	M12720-048BC		
MS21074-5K	MA12720-054BC		
MS21074-04W	M12720-40PW		
MS21074-O6W	M12720-62PW		
MS21074-O8W	M12720-82PW		
MS21074-3W	M12720-02PW		
MS21074-4W	M12720-048PW		
MS21074-5W	MA12720-054PW		
MS21074-6W	MA12720-064PW		
MS21074LO4	M12720E-40		
MS21074LO6	M12720E-62		
MS21074LO8	M12720E-82		
MS21074L3	M12720E-02		
MS21074L4	M12720E-048		
MS21074L5	MA12720E-054		
MS21074L6	MA12720E-064		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21074LO4K	M12720E-40BC	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies (Cent'd)
MS21074L06K	M12720E-62BC		
MS21074L08K	M12720E-82BC		
MS21074L3K	M12720E-02BC		
MS21074L4K	M12720E-048BC		
MS21074L5K	MA12720E-054BC		
MS21074LO4W	M12720E-40PW		
MS21074LO6W	M12720E-62PW		
MS21074LO8W	M12720E-82PW		
MS21074L3W	M12720E-02PW		
MS21074L4W	M12720E-048PW		
MS21074L5W	MA12720E-054PW		
MS21074L6W	MA12720E-064PW		
MS21074-O4	MK3031-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. - P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant:- Same address . .
MS21074-06	MK3031-06		
MS21074-08	MK3031-08		
MS21074-3	MK3031-3		
MS21074-4	MK3031-4		
MS21074-5	MK3331-5		
MS21074-O4K	MK3031-04BC		
MS21074-O6K	MK3031-06BC		
MS21074-08K	MK3031-08BC		
MS21074-3K	MK3031-3BC		
MS21074-4K	MK3031-4BC		
MS21074-5K	MK3331-5BC		
MS21074-04W	MK3031-04P		
MS21074-O6W	MK3031-06P		
MS21074-O8W	MK3031-08P		
MS21074-3W	MK3031-3P		
MS21074-4W	MK3031-4P		
MS21074-5W	MK3331-5P		
MS21074L04	MK3001-04		
MS21074LO6	MK3001-06		
MS21074LO8	MK3001-08		
MS21074L3	MK3001-3		
MS21074L4	MK3001-4		
MS21074L5	MK3301-5		
MS21074L04K	MK3001-04BC		
MS21074LO6K	MK3001-06BC		
MS21074LO8K	MK3001-08BC		
MS21074L3K	MK3001-3BC		
MS21074L4K	MK3001-4BC		
MS21074L5K	MK3301-5BC		
MS21074LO4W	MK3001-04P		
MS21074L06W	MK3001-06P		
MS21074LO8W	MK3001-08P		
MS21074L3W	MK3001-3P		
MS21074L4W	MK3001-4P		
MS21074L5W	MK3301-5P		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21074-04	**VN203-B1-40**	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. **Redondo Beach, CA** 90278
MS21074-06	VN203-B1-62		
MS21074-08	VN203-B1-82		
MS21074-3	VN203-B1-02		
MS21074-4	**VN203-B1-048**		
MS21074-5	**VN203-B1-054**		
MS21074-6	**VN203-B1-064**		
MS21074-04K	**VN203-B2-40**		
MS21074-O6K	VN203-B2-62		
MS21074-08K	VN203-B2-82		
MS21074-3K	VN203-B2-02		
MS21074-4K	VN203-B2-048		
MS21074-5K	VN203-B2-054		
MS21074-04W	VN203-B3-40		
MS21074-O6W	VN203-B3-62		
MS21074-O8W	VN203-B3-82		
MS21074-3W	VN203-B3-02		
MS21074-4W	VN203-B3-048		
MS21074-5W	VN203-B3-054		
MS21074-6W	VN203-B3-064		
MS21074L04	VN203-D1-40		
MS21074L06	VN203-D1-62		
MS21074L08	VN203-D1-82		
MS21074L3	VN203-D1-02		
MS21074L4	VN203-D1-048		
MS21074L5	VN203-D1-054		
MS21074L6	VN203-D1-064		
MS21074L04K	VN203-D2-40		
MS21074L06K	VN203-D2-62		
MS21074LO8K	VN203-D2-82		
MS21074L3K	VN203-D2-02		
MS21074L4K	VN203-D2-048		
MS21074L5K	VN203-D2-054		
MS21074L04W	VN203-D3-40		
MS21074LO6W	VN203-D3-62		
MS21074LO8W	VN203-D3-82		
MS21074L3W	VN203-D3-02		
MS21074L4W	VN203-D3-048		
MS21074L5W	VN203-D3-054		
MS21074L6W	VN203-D3-064		
MS21074-O4	RM300C04L	NADC Report No. 305Q76023 of **14 May** 1976	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
MS21074LO4	RM300C04LM		
MS21074-O4K	RM300C04LK		
MS21074L04K	RM300C04LMK		
MS21074-O4W	RM300C04LW		
MS21074L04W	RM300C04LMW		
MS21074L3	RM300C3M		
MS21074L3K	RM300C3MK		
MS21074L3M	RM300C3MW		
MS21074-3	RM300C3		
MS21074-3K	RM300C3K		
MS21074-3W	RM300C3W		

Source: https://assist.dla.mil -- Downloaded: 2026l0-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21074LO8	RM300C08M	NADC Report No. 305Q76023 of 14 May 1976	Republic Fastener Mfg. Corp. (Cont'd)
MS21074LO8K	RM300C08MK		
MS21074LO8W	RM300C08MW		
MS21074-08	RM300C08		
MS21074-O8K	RM300C08K		
RS21074-08M	RM300C08W		
MS21074-06	RM300C06L	Report No. 305Q76023 of 14 May 1976	
MS21074-O6K	RM300C06LK		
MS21074L06K	RM300C06LMK		
MS21074LO6	RM300C06LM		
MS21074-O6W	RM300C06LW		
MS21074LO6W	RM300C06LMW		
MS21074-4	RM300C4		
MS21074L4	RM300C4M		
MS21074-4K	RM300C4K		
MS21074L4K	RM300C414K		
MS210764W	RM300C4W		
MS21074L4W	RM300C4MW		
MS21074-5	RM300C5		
MS21074L5	RM300C5M		
MS21074-5K	RM300C5K		
MS21074L5K	RM300C5MK		
MS21074-5W	RM300C5W		
MS21074L5W	RM300C5MW		
MS21074-6	RM300C6	Report No. 305Q83088 of 26 Jan 1983	
MS21074L6	RM300C6M		
MS21074-6N	RM300C6W		
MS21074L6W	RM300C6MW		
MS21074L-3	BLM-53	Report No. 601Q8612 of 6 Ott 1986	Simmonds Fastener' Technologies Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21074L3	BLM-5314	601Q8710 0f 22 Jul 1987	Plant: " Simmonds 5, rue Michelet, B.P.~52 F. 921.52 Suresnes,Cedex France

NOTE: (1) Manufacturing process: Cold Stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 0f 20 November 1970.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21075 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, REDUCED RIVET SPACING, LOW HEIGHT, STEEL, 12S ksi Ftu, 450°F			
MS21075-04 MS21075-06 MS21075-08 MS21075-3 MS21075-4 MS21075L04 MS21075L06 MS21075L08 MS21075L3 MS21075L4	MTPHL65S440SCPC MTPHL65S632SCPC MT65832SCPC MTPH65S832SCPC MT65S1032SCPC MTPH65S1032SCPC MT65S428SCPC MTPHL65S440S MTPHL65S632S MTPH65S832S MT65S832S MTPH65S1032S MT65S1032S MT65S428S	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Warner Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS21075-04 MS21075-06 MS21075-08 MS21075-3 MS21075-4 MS21075-5 MS21075L04 MS21075L06 MS21075L08 MS21075L3 MS21075L4 MS21075L5	F52LHTA531M-40 F52LHTA531M-62 F52LHTA521M-82 F52LHTA521M-02 F52LHTA521M-048 F52LHT1521M-054 RM52LHTA531M-40 RM52LHTA531M-62 RM52LHTA521M-82 RM52LHTA521M-02 RM52LHTA521M-048 RM52LHTA521M-054	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 - Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21075-06 MS21075-08 MS21075-3 MS21075-4 MS21075-5 MS21075L06 MS21075L08 MS21075L3 MS21075L4 MS21075L5	M13600N-62 M13600N-82 M13600N-02 M13600N-048 M13600N-054 M13600N62 M13600N82 M13600N02 M13600N048 M13600-054	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 South Harbor Blvd. Santa Aria, CA 92702 Plant: Same address
MS21075-04 MS21075-06 MS21075-08 MS21075-3 MS21075-4 MS21075-5 MS21075L04 MS21075L06 MS21075L08 MS21075L3 MS21075L4 MS21075L5	MF1000-04CW MF1000-06CW MF1000-08CW MF1000-3CW MF1000-4CW MF1300-5CW MF1000-04 MF1000-06 MF1000-08 MF1000-3 MF1000-4 MF1300-5	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21075-04 MS21075L04 MS21075-06 MS21075LO6 MS21075-08 MS21075L08 MS21075-3 MS21075L3 MS21075-4 MS21075L4	RFM20X04L RFM20A04L RFM20X06L RFM20A06L RFM20X08 RFM20A08 RFM20X3 RFM20A3 RFM20X4 RFM2OA4	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address
NOTE: "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124.			
MS21075-5 MS21075L5	RFM20X5 RFM20A5	Report No. 305Q83088 of 26 Jan 1983	
MS21075-3 MS21075L3	MF5000-3CW MF5000-3	Report No. 305Q74016 of 22 Nov 1974	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. " Fullerton, CA '92634-" Plant: Same address
NOTE : NOTE: "CW" indecates cadmium plated with Kaywax			
MS21075-08 MS21075LO8	MF5000-08CW MF5000-08	Report No. 305Q75013 of 23 Jun 1975	
NOTES: (1) "CR" cadmium plated with Kaywax added. (2) "L" Kaylube; molybdenum disulphide, dry lubricant coated.			
MS21075-04 MS21075LO4 MS21075-06 MS21075LO6 MS21075-4 MS21075L4	MF5000-04CW MF5000-04 MF5000-06CW MF5000-06 MF5000-4CW MF5000-4	NADC Report No. 305Q77037 of 12 Jul 1977	
NOTE: (1) "CW" cadmium plated with Kaywax added. (2) MF5000 cadmium plated, Kaylube MOS_2 (dry film lubricant). (3) "L" designates dry film.			
MS21075-5 MS21075L5	MF5000-5CW MF5000-5	NADC Report No. 305Q7905 of 5 Jun 1979	
NOTE : "CW" cadmium plated with Kaywax added.			

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21075L3	EMF1000-3	NADC Report No. 601Q8705 of 20 May 1987	Microdot Aerospace Limited Blackthorn Road Colnbrook, Slough SL3 0AG England **Plant: Same Address**
MS21075L3	EMF5000-3		
MS21075L4	EMF1000-4	601Q8706 of 22 May 1987	

NOTE: (1) **Manufacturing process: Strip "**
(2) **Lubricant:** (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be In accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Speclaity **Metals). The** contractor should include these provisions in every-subcontract and purchase order.

MS21075-04	VN252-C1-40	Report No. NAEC-AML-2425 of 15 Mar 1966	VOI-SHAN VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 Plant: 2700 Compton Blvd. Redondo Beach, CA 90278
MS21075-O6	VN252-C1-62		
MS21075-08	VN252-C1-82		
MS21075-3	VN252-C1-02		
MS21075-4	VN252-C1-048		
MS21075-5	VN252-C1-054		
MS21075LO4	VN252-A1-40		
MS21075LO6	VN252-A1-62		
MS21075L08	VN252-A1-82		
MS21075L3	VN252-A1-02		
MS21075L4	VN252-A1-048		
MS21075L5	VN252-A1-054		

MS21075L3	LAM-93	Report No. 305Q83111 of 19 Oct 1983	Simmonds Fastener Technologies Inc. 181 A West Orangethorpe Placentia, CA 92670
MS21075-O8	LAM-908	601Q8401 of 24 Feb 1984	Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France .
MS21075L08	LAM-908M		

NOTE : (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government **Designation with "L") QPL-8937**
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21075-3	LAM-93	NADC Report 601Q8417 of 25 Ott 1984	Simmonds Fastener Technologies Inc. (Cent'd)
MS21075-4 MS21075L4	LAM-94 LAM-94M	NADC Report 601Q8505 of 30 May 1985	
MS21075-O4 MS21075LO4 MS21075-O6 MS21075L06	LASMR-904 LASMR-904M LASMR-906 LASMR-906M	NADC Report 6O1Q851O of 10 Jun 1985	
MS21075-5 MS21075L5	LAMR-95 LAMR-95M	NADC Report 601Q8612 of 6 Oct 1986	

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Governmet Designation with "L") QPL-8937-
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Spectalty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21076 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 ksi Ftu, 450° & 800°F

MS21076-O4 MS21076-O6 MS21076-O8 MS21076-3 MS21076-4 MS21076LO4 MS21076LO6 MS21076LO8 MS21076L3 MS21076L4	MTPHL65C440C MTPHL65C632C MTPH65C832C MT65C832C MTPH65C1032C MT65C1032C MT65C428C MTPHL65C440CM MTPHL65C632CM MTPH65C832CM MT65C832CM MTPH65C1032CM MT65C1032CM MT65C428CM	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry-Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Ana, CA 92707-0157 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21076L04	RMLHTA3452-40	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, Aft 72455
MS21076L06	RMLHTA3452-62		
MS21076L08	RMLHTA3300-82		
MS21076L3	RMLHTA33C0-02		
MS21076L4	RMLHTA3300-048		
MS21076L5	RMLHTA3300-054		
MS21076-04	LHTA3452-40		
MS21076-06	LHTA3452-62		
MS21076-08	LHTA3300-82		
MS21076-3	LHTA3300-02		
MS21076-4	LHTA3300-048		
MS21076-5	LHTA3300-054		
MS21076-O6	M13700-62	Report No. NAEC-AML-2369 of 15 Mar 1966	SPS Technologies 2701 South Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21076-O8	M13700-82		
MS21076-3	M13700-02		
MS21076-4	M13700-048		
MS21076-5	M13700-054		
MS21076L04	M13700E-40		
MS21076LO6	M13700E-62		
MS21076LO8	M13700E-82		
MS21076L3	M13700E-02		
MS21076L4	M13700E-048		
MS21076L5	M13700E-054		
MS21076-O4	MF1031-04	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21076-O6	MF1031-O6		
MS21076-O8	MF1031-08		
MS21076-3	MF1031-3		
MS21076-4	MF1031-4		
MS21076-5	MF1331-5		
MS21076LO4	MF1O01-04		
MS21076LO6	MF1001-06		
MS21076LO8	MF1001-08		
MS21076L3	MF10O1-3		
MS21076L4	MF1OO1-4		
MS21076L5	MF1301-5		
MS21076-3	MF5031-3	Report No. 305Q74016 of 22 Nov 1974	
MS21076L3	MF5001-3		
MS21076-08	MF5031-08		
MS21076LO8	MF5001-08		
MS21076-O4	MF5031-04	NADC Report No. 305Q77037 of 12 Jul 1977	
MS21076L04	MF5001-04		
MS21076-O6	MF5031-06		
MS21076LO6	MF5001-06		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21076-4 MS21076L4	MF5031-4 MF5001-4	NADC Report No. 305Q77037 of 12 Jul 1977	Microdot KAYNAR **Div.** (Cent'd)
NOTE: (1) "L" designates dry film.			
MS21076-5 MS21076L5	MF5031-5 MF5001 -5	NADC Report No. 305079050 of 5 Jun 1979	
MS21076-3	EMF1031-3	NADC Report No. 601Q8705 of 20 May 1987	Microdot Aerospace limited Blackthorn Road Colnbrook, Slough SL3 OAG England Plant: Same Address

NOTE : (1) Manufacturing process: Strip
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement **of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and** OFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21076-O4 MS21076LO4 MS21076-O6 MS21076LO6 MS21076-O8 MS21076LO8 MS21076-3 MS21076L3 MS21076-4 MS21076L4	RFM 20C04L RFM 20C04LM RFM 20C06L RFM 20C06LM RFM 20C08 RFM 20C08M RFM 20C3 RFM 20C3M RFM 20C4 RFM 20C4M	Report No. 305Q73001 of 6 Feb 1973	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 Plant: Same address

NOTE : "L" designates dry film lubricant approved by the Naval Air Development Center letter MAEM 7124 of 20 November 1970.

MS21076-5 MS21076L5	RFM20C5 RFM20C5M	Report No. 305Q83088 of 26 Jan 1983

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S MANE AND ADDRESS
MS21076-O4 MS21076-O6 MS21076-O8 NS21076-3 MS21076-4 MS21076-5 MS21076L04 MS21076LO6 MS21076L08 MS21076L3 MS21076L4 MS21076L5	VN252-B1-40 VN252-B1-62 VN252-B1-82 VN252-B1-02 VN252-B1-048 VN252-B1-054 VN252-D1-40 VN252-D1-62 VN252-D1-82 VN252-D1-02 VN252-D1-048 VN252-D1-054	Report No. NAEC-ANL-2425 of 15 Mar 1966	WI-SHAH VSI Aerosp. Prod. Div. 8463 Higuera Street Culver City, CA 90230 **Plant:** **2700 Compton Blvd.** **Redondo Beach, CA 90278**
MS21076-O8 MS21076-3	LAM-508 LAM-53	Report No. 601Q8401 of 24 Feb 1984	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670
MS21076L06	LASMR-506M	601Q8407 of 20 Apt 1984	Plant: Simmonds S, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE: (1) Manufacturing process: Cold formed
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should Include these provisions in every subcontract and purchase order.

MS21076L3 MS21076-4 MS21076L4	LAM-53M LAM-54 LAM-54M	NADC Report 601Q8507 of 31 May 1985	Simmonds Fastener Technologies, Inc. (Cont'd)
MS21076L08	LAM-508M	601Q8S17 of 16 Dec 1985	
MS21076-O6	LASMR-506	601Q8604 0f 12 Mar 1986	

NOTE : (1) Manufacturing process: Cold stamping
(2) Lubricant: (For Government Designation with "L") QPL-8937
(3) Provisions Governing Procurement: Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S Designation .	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21077 NUT, SELF-LOCKING, PLATE, TWO LUG, FLOATING, NONMETALLIC INSERT, STEEL, 125 ksi Ftu, 250°F			
MS21077-06 MS21077-08 MS21077-3 MS21077-4 MS21077-5 MS21077-6 MS21077-06K M521077-OSK MS21077-3K MS21077-4K MS21077-5K MS21077-6K	FNA401-62 FNA401-82 FNA401-02 FNA401-048 FNA401-054 FMA401-064 FNA401-62BC FNA401-82BC FNA401-02BC FNA401-048BK FNA401-054BC FNA401-064BC	Report No. NAEC-ANL-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Plant: Same address and plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21077-06 MS21077-08 MS21077-3 MS21077-4	SNLA-069-06 SNLA-069-08 SNLA-069-3 SNLA-069-4	NADC Report 601Q8511 of 21 Jun 1985	Simmonds Fastener" Technologies, Inc. 181 A. blest Orangethorpe Placentia, CA 92670 Plant: . . Simmonds 5 rue Michelet, B.P. 52 F: 92152 Suresnes 'Cedex France

NOTE : (1) Manufacturing process: Machined
(2) Locking element material is nylon (Blue)
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21077-5 MS21077-6	SNLA-069-5 SNLA-069-6	NADC Report 601Q8604 of 12 Mar 1986

NOTE : (1) Manufacturing process: Cold stamping
(2) Insert: Blue nylon
(3) Provisions Governing Procurement., Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 202610-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21078 NUT, SELF-LOCKING, PLATE, TWO LUG, NONMETALLIC INSERT, STEEL, 125 ksi Ftu, 250"F			
MS21078-04	F22NA1-40	Report No. NAEC-AML-2429 of 15 Mar 1966 .	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same **address and 3200 Country Club** Road Pocahontas, AR 72455
MS21078-06	F22NA1-62		
MS21078-08	F22NA1-82		
MS21078-3	F22NA1-02		
MS21078-4	F22NA1-048		
MS21078-5	F22NA1-054		
MS2107&6	F42NA1-064		
MS21078-7	F52NA1Q-070		
MS21078-8	F52NA1Q-080		
MS21078-9	F52NA1Q~098		
MS21078-10	F52NA1Q-108		
MS21078-04K	F22NA1-40BC		
MS21078-06K	F22NA1-62BC		
MS21078-08K	F22NA1-82BC		
MS21078-3K	F22NA1-02BC		
MS21078-4K	F22NA1-048BC		
MS21078-5K "	F22NA1-054BC		
MS21078-6K	F42NA1-064BC		
MS21078-6	F42NA1-624	AMD Report No. MA769418 of 6 Oct 1969	Greer-Smyrna A Microdot Company P.O. Box 68 Smyrna, TN 37167 Plant: Mayfield Dr. Smyrna, TN 37167
MS21078-8	F52NA1-820		
MS21078-3	GAL-63	NADC Report 601Q8604 of **12** Mar 1986	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: Cold stamping
(2) Locking Insert: Blue nylon
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21079 NUT, SELF-LOCKING, GANG CHANNEL, NONMETALLIC INSERT, 125 ksi Ftu, 250°F			
MS21079-08-X MS21079-3-X MS21079-4-X MS21079-5-X MS21079-6-X	F22NG41-82-JX F22NG41-02-JX F22NG41-048-JX F22NG41-054-JX F22NG41-064-JX	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21080 NUT, SELF-LOCKING, PLATE, ONE LUG, NONMETALLIC INSERT, STEEL, 125 ksi Ftu, 250°F			
MS21080-06 MS21080-08 MS21080-3 MS21080-4 MS21080-5 MS21080-6 MS21080-06K MS21080-08K MS21080-3K MS21080-4K MS210810-5K MS21080-6K	F22NA17A-62 F22NA17A-82 F22NA17A-02 F22NA17A-048 F22NA17A-054 F42NA17A-064 F22NA17A-628C F22NA17A-82BC F22NA17A-02BC F22NA17A-048BC F22NA17A-054BC F42NA17A-064BC	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21080-3	AJAL-63	NADC Report 601Q8604 of 12 Mar 1986	Simmonds Fastener Technologies, Inc. 181 A. Nest Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: Cold stamping
(2) Locking insert: Blue nylon
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 **(Buy American Act)** and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21081 NUT, SELF-LOCKING, PLATE, CORKER, NONMETALLIC INSERT, STEEL, 125 ksi Ftu, 250°F			
MS21081-06	F221NA5-62	Report No.	Elastic Stop Nut
MS21081-O8	F221NA5-82	NAEC-AML-2429	**A Division of**
MS21081-3	F221NA5-02	of 15 Mar 1966	**Harvard Industries, Inc.**
MS21081-4	F221NA5-048		2330 Vauxhall **Road**
MS21081-5	F221NA5-054		Union, NJ 07083
MS21081-6	F421NA5-064		
MS21081-7	F521NA5Q-070		Plant: Same **address and**
MS21081-8	F521NA5Q-080		3200 Country Club Road
MS21081-10	F521NA5Q-108		Pocahontas, AR 72455
MS2108146K	F221MA5-628C		
MS21081-08K	**F221**NA5-828C		
MS21081-3K	**F221**NA5-028C		
MS21081-4K	**F221**MA5-048BC		
MS21081-5K	**F221**MA5-054BC		
MS21081-6K	**F421**MA5-064BC		
MS21082 NUT, SELF-LOCKING, PLATE, ONE LUG, FLOATING, NOMETALLIC INSERT, STEEL 125 ksi Ftu, 250°F			
MS21082-08	FNA417-82	Report No.	Elastic Stop Nut .
MS21082-3	F NA417-02	NAEC-AML-2429	A Division of
MS21082-4	FNA417-048	**of** 15 Mar 1966	**Harvard Industries, Inc.**
MS21082-5	FNA417-054		**2330 Vauxhall Road**
MS21082-O8K	FNA417-82BC		**Union, NJ 07083**
MS21082-3K	FNA417-02BC		
MS21082-4K	FNA417-048BC		Plant: Same address and
MS21082-5K	FNA417-054BC		3200 Country Club Road
			Pocahontas, AR 72455
MS21083 NUT, SELF-LOCKING, HEXAGON, NONMETALLIC INSERT, LOW HEIGHT, 250°F			
MS21083B 04	Y92NTM-440	Report No.	Greer-Smyrna
MS21083B 08	Y92NTH-832	NAEC-AML-2242	A Microdot Company
MS21083B 3	Y92NTM-1032	of 6 Jul 1965	P.O. Box 68
			Smyrna, TN 37167
MS21083N 4	F52NTE-428	Report No.	
MS21083N 5	F52NTE-524	NAEC-AML-2331	Plant: Mayfield Dr.
MS21083N 6	F52NTE-624	of 1 Dec 1965	Smyrna, TN 37167
MS21083N 7	F52NTE-72OU		
MS21083N 8	F52NTE-820		
MS21083N 9	F52NTE-918		
MS21083N 10	F52NTE-1018		
MS21083N 12	F52NTE-1216		
MS21083C 4	L79NTE-428		
MS21083D 5	68NTE-524		
MS21083D 6	68NTE-624		
MS21083D 8	68NTE-820		
MS21083B 8	Y92NTE-820		

NOTE : (1) Manufacturing process: **Machined**
(2) Aluminum alloy and cres parts lubricated with Carbo Wax.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21083NO4 MS21083CO4 MS21083B06	F22NTM-440 L79NTM-440 Y92NTM-632	Report No. NAEC-AML-2146 of 9 Mar 1965 and NAEC-AML-ltr M-62-BRS 10410 (7701) of 13 Apr 1966	Greer-Smyrna (Cent'd)
NOTE : (1) Manufacturing precess: Machined			
MS21083D08	NTHJ-832	Report No. NAEC-AML-2457 of 10 May 1966	
MS21083DO4 MS21083DO6 MS21083D3 MS21083NO6 MS21083NO8 MS21083N3 MS2}083C06 MS21083CO8 MS21083C3	NTMJ-440 NTMJ-632 NTMJ-1032 F22NTM-632 F22NTM-832 F22NTM-1032 L79NTM-632 L79NTM-832 L79NTM-1032	Report No. NAEC-AML-2133 of 24 May 1966	
NOTE : Manufacturing process: Machined			
MS21083B5	Y92NTE-524	AML Report No. 78601-67 of 24 May 1967	
NOTE: Manufacturing process: Machined			
MS21083B3 MS21083C5 MS21083C6 MS21083C8 MS21083C16 MS21083N16 MS21083N2O	Y92NTM-1032 L79NTE-524 L79NTE-624 L79NTE-820 L79NTE-1612 F52NTE-1612 F52NTE-2012	NADC Report No. 305Q79055 of 24 Aug 1979	
NOTE : (1) Material: Green nylon. (2) "L''.manufacturlng part number designates Carbo-Wax. (3) Manufacturing process: Machined			
MS21083B5	Y79NTE-524	AML Report No. 78601-67 of 24 May 1967	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUAtIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21083NO4	F22NTM-40	Report No. NAEC-AML-2134 of 1 Oct 1965	Elastic Stop Nut A Division of **Harvard Industries, Inc. 2330 Vauxhall Road Union,** NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21083NO6	F22NTM-62		
MS21083NO8	F22NTM-82		
MS21083N3	F22NTM-02		
MS21083N4	F52NTE-048		
MS21083N5	F52NTE-054		
MS21083N6	F52NTE-064		
MS21083M7	F52NTE-070U		
MS21083N8	F52NTE-080		
MS21083N9	F52NTE-098		
MS21083N1O	F52NTE-108		
MS21083N12	F52NTE-126		
MS21083N14	F52NTE-144		
MS21083N16	F52NTE-162		
MS21083N18	F52NTE-182		
MS21083N2O	F52NTE-202		
MS21083N22	F52NTE-222		
MS21083N24	F52NTE-242		
MS21083CO4	L79NTM-40		
MS21083C06	L79NTM-62		
MS21083CO8	L79NTM-82		
MS21083C3	L79NTM-02		
MS21083C4	L79NTE-048		
MS21083C5	L79NTE-054		
MS21083C6	L79NTE-064		
MS21083C7	L79NTE-070U		
MS21083C8	L79NTE-080		
MS21083DO4	NTMJ-40		
MS21083DO6	NTMJ-62		
MS21083DO8	NTMJ-82		
MS21083D3	NTMJ-02		
MS21083D5	68NTE-054		
MS21083D6	68NTE-064		
MS21083D7	68NTE-070U		
MS21083D8	68NTE-080		
MS21083D9	68NTE-098		
MS21083D1O	68NTE-108		
MS21083D12	68NTE-126		
MS21083BO4	Y92NTM-40		
MS21083B06	Y92NTM-62		
MS21083B08	Y92NTM-82		
MS21083B3	Y92NTM-02		
MS21083B4	Y92NTE-048		
MS21083B5	Y92NTE-054		
MS21083B6	Y92NTE-064		
MS21083B7	Y92NTE-070U		
MS21083B8	Y92NTE-080		
MS21083B9	Y92NTE-098		
MS21083B1O	Y92NTE-108		
MS21083B12	Y92NTE-126		
MS21083B14	Y92NTE-144		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21083BI6	Y92NTE-162	Report No.	Elastic stop Nut
MS21083BT8	Y92NTE-182	NAEC-AML-2134	A Division of
MS21083B2O	Y92NTE-202	of 1 Ott 1965	Harvard Industries, Inc. (Cent'd)
NOTE : (1) Manufacturing process: Machined			
(2) Stainless parts lubricated with Carbo Max.			
(3) Steel N22 and N24 lubricated with Carbo Wax.			
MS21083NO8	F22NTM-82	Report No.	
MS21083N3	F22NTM-02	NAEC-AML-2134	
MS21083N4	F22NTE-048	of 1 Oct 1965	
MS21083N5	F55NTE-054		
MS21083N6	F22NTE-064		
NOTE: Manufacturing.p recess: Forged or machined			
MS21083CO4	79N TM-40	Report No.	
MS21083CO6	79N TM-62	NAEC-AML-2134	
MS21083C08	79NTM-82	of 1 Ott 1965	
MS21083C3	79NTM-02		
MS21083C4	79NTE-048		
MS21083C5	79NTE-054		
MS21083C6	79NTE-064		
MS21083C7	79NTE-070U		
MS21083C8	79NTE-080		
NOTE: Manufacturing process: Forged or machined			
MS21083D4	68NTE-048	Report No.	
MS21083D14	68NTE-144	NAEC-AML-2134	
MS21083D16	68NTE-162	of 1 Ott 1965	
MS21083D18	68NTE-182		
MS21083O2O	68NTE-202		
MS21083C9	79NTE-098	NADC Report No.	
MS21083C1O	79NTE-108	305Q81O62 of	
MS21083C2O	79NTE-202	15 May 1981	
NOTE: (1) Manufacturing process: Machined or forged			
(2) All parts are passivated plus Carbo Wax.			
MS21086 NUT, SELF-LOCKING, PLATE, SIDE BY SIDE, REDUCED RIVET SPACING, LOW-HEIGHT, STEEL, 125 ksi Ftu, 450"F			
MS21086-O8	MT13S832CP	Report No.	Cherry Textron, Cherry
MS21086-3	MT13S1032CP	NAEC-AML-2428	Aerospace Operations
MS21086-4	MT13S428CP	of 15 Mar 1966	Cherry Division of,
MS21086-5	MT13S524CP		Textron, Inc.
MS21086-6	MT13S624CP		P.O. B0X 2157
MS21086LO8	MT13S832		1224 East Harrier Ave.
MS21086L3	MTI3S1032		Santa Ana, CA 92707-0157
MS21086L4	MT13S428		
MS21086L5	MT13S524		Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21086L6	MT13S624	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations (Cent'o
MS21086-08K	MT13S8328CCP		
MS21086-3K	MT13S1032BCCP		
MS21086-4K	MT13S428BCCP		
MS21086-5K	MT13S524BCCP		
MS21086LQ8K	MT13S832BC		
MS21086L3K	MT13S1032BC		
MS21086L4K	MT13S428BC		
MS21086L5K	MT13S524BC		
MS21086-08	F52LHTA575M-82	Report No. NAEC-AU-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21086-3	F52LHTA575M-02		
MS21086-4	F52LHTA575M-048		
MS21086-5	F52LHTA575M-054		
MS21086-6	F52LHTA575M-064		
MS21086LO8	RM52LHTA575M-82		
MS21086L3	RM52LHTA575M-02		
MS21086L4	RM52LHTA575M-048		
MS21086L5	RM52LHTA575M-054		
MS21086L6	RM52LHTA575M-064		
MS21086-08K	F52LHTA575-82BC		
MS21085-3K	FS2LHTA575M-O2BC		
MS21086-4K	F52LHTA575M-048BC		
MS21086-5K	F52LHTA575M-054BC		
MS21086L08K	RM52LHTA575M-82BC		
MS21086L3K	RM52LHTA575M-02BC		
MS21086L4K	RM52LHTA575M-048BC		
MS21086L5K	RM52LHTA575M-054BC		
MS21086-08	M12640NM-82	AMD Report No. MA769328 of 22 Jan 1969	SPS Technologies 2701 S. Harbor Blvd. Santa Ana, CA 92702 Plant: Same address
MS21086-3	M12640NM-02		
MS21086-4	M12640NM-048		
MS21086-5	MA12640NM-054		
MS21086LO8	MA12640NM-82		
MS21086L3	MA12640NM-02		
MS21086L4	MA12640NM-048		
MS21086L5	MA12640NM-054		
MS21086-08K	MA12640NM-82BC		
MS21086-3K	MA12640NM-02BC		
MS21086-4K	MA12640NM-048BC		
MS21086-5K	MA12640NM-054BC		
MS21086L08K	MA12640-82 BC		
MS21086L3K	MA12640-02 BC		
MS21086L4K	MA12640-04 8BC		
MS21086L5K	MA12640-0 54BC		

NOTE : (1) Manufacturing process: Stamped or forged
(2) Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1434).

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21086-08	MK4000-08CW	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21086-3	MK4000-3CW		
MS21086-4	MK4000-4CW		
MS21086-5	MK4300-5CW		
MS21086-08K	MK4000-08BCCW		
MS21086-3K	MK4000-3BCCW		
MS21086-4K	MK4000-4BCCW		
MS21086-5K	MK4300-5BCCW		
MS21086L08	MK4000-08		
MS21086L3	MK4000-3		
MS21086L4	MK4000-4		
MS21086L5	MK4300-5		
MS21086L08K	MK4000-08BC		
MS21086L3K	MK4000-3BC		
MS21086L4K	MK4000-4BC		
MS21086L5K	MK4300-5BC		
MS21086-O8	R300X08	Report No. 305-5095 of . 17 Jun 1976	Republic Fastener Mfg. Corp. 1300 Rancho Conejo Blvd. Newbury Park, CA 91320 . Plant: Same address
MS21086LO8	R300A08		
MS21086-O8K	R300X08K		
MS21086L08K	R300A08K		
MS21086-3	R300X3		
MS21086L3	R300A3		
MS21086-3K	R300X3K		
MS21086L3K	R300A3K		
MS21086-4	R300X4		
MS21086L4	R300A4		
MS21086-4K	R300X4K		
MS21086L4K	R300A4K		
MS21087 NUT, SELF-LOCKING, PLATE, SIDE BY SIDE, REDUCED RIVET SPACING, LOW HEIGHT, CRES, 125 ksi Ftu, 450" & 800"F			
MS21087L08	MT13C832M	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations Cherry Division of Textron, Inc. P.O. Box 2157 1224 East Harrier Ave. Santa Ana, CA 92707-0157 Plant: Same address
MS21087L3	MT13C1032M		
MS21087L4	MT13C428M		
MS21087L5	MT13C524M		
MS21087L6	MT13C624M		
MS21087L08K	MT13C832BCM		
MS21087L3K	MT13C1032BCM		
MS21087L4K	MT13C428BCM		
MS21087L5K	MT13C524BCM		
MS21087L08W	MT13C832PM		
MS21087L3W	MT13C1032PM		
MS21087L4W	MT13C428PM		
MS21087L5W	NT13C524PM		
M21087L6W	MT13C624PM		
MS21087-08	MT13C832		
MS21087-3	MT13C1032		
MS21087-4	MT13C428		
MS21087-5	MT13C524		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21087-6	MT13C624	Report No. NAEC-AML-2428 of 15 Mar 1966	Cherry Textron, Cherry Aerospace Operations (Cent'd)
MS21087-O8K	MT13C832BC		
MS21087-3K	MT13C1032BC		
MS21087-4K	MT13C428BC		
MS21087-5K	MT13C524BC		
MS21087-O8W	MT13C832P		
MS21087-3W	MT13C1032P		
MS21087-4W	MT13C428P		
MS21087-5W	MT13C524P		
MS21087-6W	MT13C624P		

NOTE : (1) Manufacturing process: Machined
(2) Lubrication: Ferrocote #348

MS21087LO8	RM LHTA575M2860-82	Report No. NAEC-AML-2429 of 15 Mar 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 'Plant: Same address and 3200 Cuntry Club Road Pocahontas, AR 72455
MS21087L3	RM LHTA575M2860-02		
MS21087L4	RM LHTA575M2860-048		
MS21087L5	RM LHTA575M2860-054		
MS21087L6	RM LHTA575M2860-064		
MS21087LO8K	RM LHTA575M2860-82BC		
MS21087L3K	RM LHTA575M2860-02BC		
MS21087L4K	RM LHTA575M2860-048BC		
MS21087L5K	RM LHTA575M2860-054BC		
MS21087LO8W	RM LHTA575M2860P-82		
MS21087L3W	RM LHTA575M2860P-02		
MS21087L4W	RM LHTA575M2860P-048		
MS21087L5W	RM LHTA575M2860P-054		
MS21087L6W	RM LHTA575M2860P-064		
MS21087-O8	LH TA575M2860-82		
MS21087-3	LH TA575M2860-02		
MS21087-4	LH TA575M2860-048		
MS21087-5	LH TA575M2860-054		
MS21087-6	LH TA575M2860-064		
MS21087-08K	LH TA575M2860-82BC		
MS21087-3K	LH TA575M2860-02BC		
MS21087-4K	LH TA575M2860-048BC		
MS21087-5K	LH TA575M2860-054BC		
MS21087-O8W	LH TA575M2860P-82		
MS21087-3W	LH TA575M2860P-02		
MS21087-4W	LH TA575M2860P-048		
MS21087-5W	LH TA575M2860P-054		
MS21087-6W	LH TA575M2860P-064		

MS21087-O8	MK4031-08	Report No. NAEC-AML-2474 of 15 Jun 1966	Microdot, Inc. KAYNAR Div. P.O. Box 3001 800 S. State College Blvd. Fullerton, CA 92634 Plant: Same address
MS21087-3	MK4031-3		
MS21087-4	MK4031-4		
MS21087-5	MK4331-5		
MS21087-O8K	MK4031-08BC		
MS21087-3K	MK4031-3Bc		
MS21087-4K	MK4031-4BC		
MS21087-5K	MK4331-5BC		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21087-O8W	MK4031-08P	Report No.	Microdot, Inc.
MS21087-3W	MK4031-3P	NAEC-ML-2474	KAYNAR Div.
MS21087-4WH	MK4031-4P	of 15 Jun 1966	(Cent'd)
MS21087-5W	MK4331-5P		
MS21087LO8	MK4001-08		
MS21087L3	MK4001-3		
MS21087L4	MK4001-4		
MS21087L5	MK4301-5		
MS21087LO8K	MK4001-08BC		
MS21087L3K	MK4001-3BC		
MS21087L4K	MK4001-4BC		
MS21087L5K	MK4301-5BC		
MS21087LO8W	MK4001-08P		
MS21087L3W	MK4001-3P		
MS21087L4W	MK4001-4P		
MS21087L5W	MK4301-5P		
MS21087-O8	M12740-82	AMD Report No.	SPS Technologies
MS21087-3	M102740-02	MA769328 of	2701 S.-Harbor Blvd.
MS21087-4	M12740-048	22 Jan 1969	Santa Ana, CA 92702
MS21087-5	MA12740-054		
MS21087L08	M12740E-82		Plant: Same address
MS21087L3	M12740E-02		
MS21087L4	M12740E-048		
MS21087L5	M12740E-054		
MS21087-08K	M12740-82BC		
MS21087-3K	M12740-02BC		
MS21087-4K	M12740-048BC		
MS21087-5K	MA12740-054BC		
MS21087L08K	M12740E-82BC		
MS21087L3K	M12740E-02BC		
MS21087L4K	M12740E-048BC		
MS21087L5K	M12740E-054BC		

NOTE : (1) Manufacturing process: Stamped or forged
(2) Molybdenum disulfide dry film lubricant as approved by NAMATCEN ltr XM-621-FTR:mlp J9 (1434).

MS21087-08	R300C08	NADC ltr	Republic Fastener
MS21087LO8	R300C08M	305-5095 of	Mfg. Corp.
MS21087-08K	R300C08K	17 Jun 1976	1300 Rancho Conejo Blvd.
MS21087LO8K	R300C08MK		Newbury Park, CA 91320
MS21087-08W	R300C08W		
MS21087LO8W	R300C08MW		Plant: Same address
MS21087-3	R300C3		
MS21087L3	R300C3M		
MS21087-3K	R300C3K		
MS21087L3K	R300C3MK		
MS21087-3W	R300C3W		
MS21087L3W	R300C3MW		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER' S NAME AND ADDRESS
MS21087-4 MS21087L4 MS21087-4K MS21087L4K MS21087-4W MS21087L4W	R300C4 R300C4M R300C4K R300C4MK R300C4W R300C4MW	NADC ltr 305-5095 of 17 Jun 1976	Republic Fastener Mfg. Corp.
MS21088 NUT, SELF-LOCKING, CHANNEL, FLOATING, LOW HEIGHT, CRES, 125 ksi Ftu, 250°F			
NOTE: (1) MS21088 Canceled. (2) Use MS21065 for Interchangeability.			
MS21089 NUT, SELF-LOCKING, CHANNEL, 100°CSK, FLOATING, LOW HEIGHT, CRES, 125 ksi Ftu, 250"F			
NOTE : (1) MS21089 Canceled. (2) Use MS21068 for interchangeability.			
MS21224 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, COUNTERBORED, ASSEMBLED NASHER, 250"F, NONMETALLIC INSERT (FOR SELF-RETAINING BOLTS)			
MS21224-3 **MS21224-4** **MS21224-5** **MS21224-6** MS21224-7 MS21224-8	**' NE8235-3** **NE8235-4** **NE8235-5** **NE8235-6** NE8235-7 NE8235-8	**AMD Report No. MA669012 of 5 Nov 1968**	**Elastic stop Nut. A Division of . Harvard Industries, Inc. 2330 Vauxhall** Road Union, NJ 07083 Plant: Same address and 3200 Country Club Road Pocahontas, AR 72455
MS21224-9	NE8235-9	Report No. MA772017 of 15 May 1972	
MS21224-10 MS21224-12 MS21224-16	NE8235-10 NE8235-12 NE8235-16	NADC Report No. 305Q81062 of 15 May 1981	
NOTE : Manufacturing process: Machined			
MS21224-3 MS21224-4 MS21224-5 MS21224-6 MS21224-1 MS21224-8	F12N7699-1032 F12N7699-428 F12N7699-524 F12N7699-624 F12N7699-720 F12N7699-820 .	AMD Report No. MA669029 of 30 Apr 1969	Greer-Smyrna A Microdot Company P.O. BOX 68 Smyrna, TN 37167 Plant: Mayfield Dr. Smyrna, TN 37167 .

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21224-3 MS21224-4 MS21224-5 MS21226-6	CR-5937 CR-5937 CR-5937 CR-5937	NADC Report 601Q8516 of 12 Nov 1985	Simmonds Fastener Technologies, Inc. 181 A. West Orangethorpe Placentia, CA 92670 Plant: Simmonds 5, rue Michelet, B.P. 52 F. 92152 Suresnes Cedex France

NOTE : (1) Manufacturing process: Machined
(2) Lubricant: (For Government Designation with "L") QPL-8937 =
(3) Provisions Governing Procurement. Procurement of these self-locking nuts shall be in accordance with FAR 52.225-3 (Buy American Act) and DFARS 52.225-7012 (Preference for Domestic Specialty Metals). The contractor should include these provisions in every subcontract and purchase order.

MS21225 NUT, SELF-LOCKING, CASTELLATED, HEXAGON, 800 DEG. F

MS21225-5	27764-5	NADC Report No. 305Q82077 of 21 Jun 1982	Elastic Stop Nut " A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union, NJ 07083 Plant: Same address

NOTE: Manufacturing process: Machined

MS21225-4	27764-4	NADC Report No. 601Q8408 of 26 Apr 1984	

NOTE: Manufacturing process: Machined

MS21225-4 MS21225-5	75147-428 75147-524	Report No. 305Q83106 of 12 Aug 1983	SPS Technologies Highland Avenue Jenkintown, PA 19046 Plant: Same address

NOTE: Manufactured process: Machined

MS21245 NUT, SELF-LOCKING, HEXAGON THIN, 450°F, 80 ksi Ftu

MS21245L8 MS21245L9 MS21245L12 MS21245L14	48FT-820 48FT-918 48FT-1216 48FT-1414	Report No. 305Q81063 of 27 May 1981	SPS Technologies Highland Avenue Jenkintown, PA 19046 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS21245-8 MS21245L20	47FT-820 48FT-2102	Report No. 305Q82073 of 18 Feb 1982	SPS Technologies (Cent'd)
NOTE: Manufacturing process: Machined			
MS21245-7 MS21245L7 MS21245-9 MS21245-10 MS21245L10	**47FT-720UN** 48FT-720UN 47FT-918 47FT-1018 48FT-1018	Report No. 305Q83107 **of** 1 Sep 1983	
NOTE: Manufacturing process: **Machined**			
MS90415 NUT, SELF-LOCKING, STEEL, 160 ksi, 450°F, 12 POINT, CAPTIVE WASHER			
MS90415-3 MS90415-4 MS90415-5 MS90415-6	LH8099-02 LH8099-048 LH8099-054 LH8099-064	Report No. NAEC-AML-2459 of 25 May 1966	Elastic Stop Nut A Division of Harvard Industries, Inc. 2330 Vauxhall Road Union. NJ 07083 Plant: Same address and 3200 Country Club Road **Pocahontas,** AR 72455

*U.S. GOVERNMENT PRINTING OFFICE: 1987-505-033/75389

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:17Z
Check the source to verify that this is the current version before use.