INCH-POUND

MIL-F-50945D (AR)
AMENDMENT 7
31 August 1995
SUPERSEDING
AMENDMENT 6
29 October 1992

MILITARY SPECIFICATION

FUZE, PD, M567/XM935 (M935) LESS BOOSTER

This amendment forms a part of MIL-F-50945D (AR), dated 08 September 1982, and is approved for use by the U.S. Army Armament Research, Development and Engineering Center, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 1

Title: Add "(M935)" after "M567/XM935"; and wherever it appears in the specification.

Title: Add "/M936" after "(M935)"; and where applicable.

PAGE 2

2.1.2, Add to title of 9272193, "or Body Assembly, Front, M935".

Add to title of 9272194, "or Body Assembly, Front, M935".

* Under DRAWINGS, Add the following:

"12972495 - Pellet".

PAGE 4

* 3.12.1: Delete in its entirety.

* 3.12.2: Delete in its entirety.

* 3.12.3: Delete in its entirety.

AMSC N/A **FSC 1390**
DISTRIBUTION STATEMENT A. **Approved for public release; distribution is unlimited.**

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

PAGE 10

4.3.1.2: Delete "Cap, Shipping... 9255255...10".

PAGE 18

Table I, First article inspection: delete "Cap, Shipping Dwg. 9255255, Examination for defects".

PAGE 20

Table I, under ballistic functioning at proving Ground: Add note (1) for Chg. 0, Set SQ and Chg. maximum, Set SQ.

Add note (1) as follows:

"(1) Samples for this test shall be separated into three groups; 30 samples temperature conditioned at plus 70 degrees F., 30 samples temperature conditioned at plus 145 degrees F., and 30 samples temperature conditioned at minus 50 degrees F. Temperature tolerance for conditioning shall be plus and minus 2.5 degrees F."

* Under contractor's test facility: Delete "Transportation vibration; Ballistic functioning; Chg 0 set SQ; Chg 0 Set SQ, TV; Chg 0, Set Delay, TV."

* Notes: Delete "d" and "e" in their entirety.

PAGE 21

* Table I, Notes: Delete "k" and substitute:

"(k) Samples tested at the contractor's facility shall be assembled to the M567 configuration, dwg. 9246242 or the M935 configuration, dwg. 9255258, as applicable, unless otherwise determined by the contracting officer."

PAGE 23

4.4.2.1, Delete Major 112 in its entirety.

PAGE 33

4.4.2.6 and 4.4.2.6.1: Add Major 113 which reads as follows:

"113 Lubrication missing or improperly applied ...0.40% ...3.2 ...Visual".

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

PAGE 35

4.4.2.7, Majors 101 and 102: Delete "0.40%" AQL and substitute "Note (a)" as follows:

"(a) Sample per paragraph 4.5.18.1".

PAGE 43

4.4.2.13, Add Major 106 which reads as follows:

"106 Lubrication missing or improperly applied ...0.40% ...3.2 ...Visual".

PAGE 44

4.4.2.14, Add Major 109 which reads as follows:

"109 Lubrication missing or improperly applied ...0.40% ...3.2...Visual".

PAGE 45

4.4.2.15, Delete Major 104 in its entirety.

PAGE 62

4.4.2.26, Add Major 105 which reads as follows:

"105 Lubrication missing or improperly applied ...0.40% ...3.2 ...Visual".

PAGE 72

4.4.2.35: Delete Major 105 in its entirety and substitute the following:

"Major 105 Tensile test ...(b) ...3.1 ...Gage".

Major 106 Add new CD as follows:

"Major 106 Wrap test ...(b) ...3.1 ...Gage".

Note (b): Add at end of note the following:

"Test per MIL-STD-105D, inspection level S-4, AQL 1.0 percent for wrap test and level S-1, AQL 1.5 percent for the tension test.

Examination of wrap test samples shall utilize 4 X magnification."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

PAGE 74

4.4.2.37, Critical 2: Change inspection method from "visual" to "gage".

PAGE 82

4.4.2.41, Critical 2: Change "Critical 2" to "Special A".

PAGE 83

4.4.2.42, Critical 2: Change inspection method from "visual" to "gage".

Major 109: Add as follows:

"109 Presence of tape over rear face of body assembly ...0.40% ...3.2 ...Visual".

Major 106: Delete in its entirety.

PAGE 85

4.4.2.44: Delete in its entirety.

PAGE 86

4.4.2.45, Critical 2: Change "Critical 2" to "Special A".

PAGE 87

4.4.2.46: Add Major 103 and Note (h) which reads as follows:

"103 Lubrication missing or improperly applied ...12 ...(h) ...3.2 ...Visual.

(h) Same 12 samples after being used for the Jolt and Jumble Test shall be disassembled to examine for missing or improperly applied lubrication/grease (components to be checked are striker, setback pin, setback spring, slider detent, safety latch and selector cap O-ring). If one or more samples are classed defective, the lot shall be rejected."

Under contractor test facility:

* Delete Criticals 2 and 3.

* Delete Majors 101, 102, and 103.

* Delete Notes b, c, d, e, f, g, and h.

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

PAGE 88

4.4.2.46, Majors 102 and Major 104: Delete "15" sample size and substitute "5".

Under sample units: Delete "166" and substitute "146".

Majors 101 and 103, add Note (f) as follows:

"(f) Samples for this test shall be separated into three groups; 22 samples temperature conditioned at plus 70 degrees F., 20 samples temperature conditioned at plus 145 degrees F., and 20 samples temperature conditioned at minus 50 degrees F. Temperature tolerance for conditioning shall be plus and minus 2.5 degrees F."

PAGE 89

4.4.2.47: Add Major 103 and Note (h) which reads as follows:

"103 Lubrication missing or improperly applied ...12 ...(h) ...3.2 ...Visual.

"(h) Same 12 samples after being used for the Jolt and Jumble Test shall be disassembled to examine for missing or improperly applied lubrication/grease (components to be checked are striker, setback pin, setback spring, slider detent, safety latch and selector cap O-ring). If one or more samples are classed defective, the lot shall be rejected."

Under contractor test facility:

* Delete Criticals 2 and 3.

* Delete Majors 101, 102, and 103.

* Delete Notes b, c, d, e, f, g, and h.

PAGE 90

4.4.2.47, Majors 102 and Major 104: Delete "15" sample size and substitute "5".

Under sampling units: Delete "166" and substitute "146".

Majors 101 and 103: Delete Note (f) and substitute:

"(f) Samples for this test shall be separated into three groups; 22 samples temperature conditioned at plus 70 degrees F., 20 samples temperature conditioned at plus 145 degrees F., and 20 samples temperature conditioned at minus 50 degrees F. Temperature tolerance for conditioning shall be plus and minus 2.5 degrees F."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

PAGE 91

4.4.2.48, Add to title: "or Body Assembly, Front, M935".

PAGE 92

4.4.2.49, Add to title: "or Body Assembly, Front, M935".

PAGE 93

4.4.2.50, Delete Major 101 in its entirety.

PAGE 96

4.5.6, Change line 1 to read as follows:

"The assembly shall be hand-held or placed in".

PAGE 97

* 4.5.9.1: Delete in its entirety.

PAGE 98

4.5.10, Delete "the shipping cap (dwg. 9255255) shall be removed and".

* Delete the first three sentences and substitute:

"The test shall be performed with M567 (dwg. 9246242) or the M935 (dwg. 9255258) as applicable."

PAGE 99

* 4.5.11.1: Delete in its entirety.

4.5.11.2: Add at end of paragraph as follows:

"Samples shall be temperature conditioned at the required temperatures for a minimum of six (6) hours and test fired within two minutes after removal from the conditioning chamber."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

Change the following to read:

4.5.18.1 Examination for location and depth of spring pin cavity. The location and depth of the spring pin cavity shall be inspected in the following manner.

4.5.18.1.1 Initial production examination. Beginning with the first production shift, ten (10) consecutive drilled units shall be inspected and found defect free prior to rate production. Then inspect five (5) units every two (2) hours until the end of the shift. Five (5) units shall be inspected at the end of the shift. If a defect is found in any of the five (5) units, the production represented by the units shall be rejected and the machine set-up shall be adjusted until ten (10) consecutive units are defect free.

4.5.18.1.2 Second production interval. After successfully completing the sampling of 4.5.18.1.1 for three consecutive eight hour production shifts with no defects, the sampling plan may be reduced to five (5) drilled units being inspected every four (4) hours and at the beginning and at the end of the shift. If a defect is found, the production represented by the sample shall be rejected and the sampling plan of 4.5.18.1.1 shall be reinstated.

4.5.18.1.3 Third production interval. After successfully completing the sampling of 4.5.18.1.2 for five consecutive eight hour shifts, the sampling plan may be reduced to three (3) drilled units being inspected every four (4) hours and at the beginning and at the end of the shift. If a defect is found, the production represented by the sample shall be rejected and the sampling plan of 4.5.18.1.1 shall be reinstated.

4.5.18.1.4 Tooling change. A change of tooling will require a first piece inspection prior to continuing production. The sampling plan will be the same as that prior to the tooling change. The above plan shall be applicable to each drilling machine equipment set up.

4.5.18.1.5 Production lapse. A stop in production of over one month will require starting the inspection at the initial production shift plan

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

* 4.5.20.1: Delete in its entirety and substitute:

"4.5.20.1 Functioning test. The sample fuzes shall be assembled to boosters and auxiliary boosters as appropriate. The fuzes shall then be assembled to the high explosive cartridge appropriate to the fuzes being tested (M374A3 for the M567 or M720 for the M935) and fired from the appropriate mortar between 45 and 75 degrees QE. When recovery of non-functioning fuzes is desired, the loaded sample fuzes (with boosters and auxiliary boosters as appropriate) shall be assembled to the appropriate inert material filled cartridges that simulate the weight and density of the normal HE fill and with an addition of a black powder pellet (12972495) to the rear of the boosters for a more distinctive function signature. If any fuze fails to cause the shell to function high order, that fuze shall be classified as defective (dud). If any fuze in either the SQ or delay setting mode causes the round to function prematurely, that fuze shall be classified as having a critical defect. The proving ground shall utilize a geophonic sensing device to determine delay functionings at maximum charge. Samples shall be temperature conditioned at the required temperatures for a minimum of six (6) hours and test fired within two (2) minutes after removal from the conditioning chamber."

PAGE 101

4.5.20.1, Line 3: Delete "M374A2 and".

Add at end of paragraph as follows: "Samples shall be temperature conditioned at the required temperatures for a minimum of six (6) hours and test fired within two minutes after removal from the conditioning chamber."

4.5.20.1.3, add at end of paragraph as follows:

"Groups of thirty-one shall be temperature conditioned as follows: eleven samples at plus 70 degrees F., ten samples @ plus 145 degrees F., and ten samples at minus 50 degrees F. Temperature tolerance for conditioning shall be plus and minus 2.5 degrees F. Samples shall be temperature conditioned at the required temperatures for a minimum of six (6) hours and test fired within two minutes after removal from the conditioning chamber."

PAGE 104

6.7.2, Under quantity column, delete "15" and substitute "5."

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.

6.9, Add new paragraph as follows:

"6.9 Special defect. A defect, other than critical, that judgement and experience indicate may, depending upon the degree of variance from the design requirement:

a. Result in hazardous or unsafe conditions for individuals using, maintaining or depending upon the product or

b. Prevent performance of the tactical function of a major end item."

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (modifications, additions, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in this notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the last previous amendment.

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1390-0834)

Source: https://assist.dla.mil -- Downloaded: 2026-10-22T20:44Z
Check the source to verify that this is the current version before use.