MILITARY SPECIFICATION
HORIZON REFERENCE SET, SHIP MOUNTED FOR LAMPS MK III HELICOPTER

This amendment forms a part of Military Specification MIL-H-85281A (AS) dated 15 July 1981, and is approved for use by the Naval Air Systems Command, Department of the Navy, and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 4

3.3.1.6.1: Delete subparagraphs b, c, d and e and substitute:

"b. A differential, after initial stabilization, of greater than two angular degrees for more than two seconds between the input signal and the reference bar position when the reference bar is within the range of normal operating limits (see 3.3.1.3).

"c. Loss of 115 VAC 400 Hz input power to the set.

"d. Partial or complete failure of the internal power supply."

3.3.1.6.2: Delete subparagraphs c and d and substitute:

"c. For a two degree error fault (see 3.3.1.6.1b), align and lock the reference bar in a position parallel to the installation platform and remove power from the servo system within 10 seconds.

"d. For all other fault conditions of 3.3.1.6.1, immediately remove power from the servo system and lock the bar in place."

PAGE 5

3.3.1.7.1: Delete second sentence and substitute "If the Control-Indicator is not installed, the Electronic Component Assembly shall provide sole control when optional interconnections are installed as specified on installation control drawings."

PAGE 7

3.4.2: Delete the period at the end of the sentence and add "except when employed on parts selected in accordance with an approved parts control program."

3.4.3.1: Delete "satisfactorily operate" and substitute "be capable of operating"; delete the word "maximum".

FSC 1710

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:35Z
Check the source to verify that this is the current version before use.

3.4.3.3, lines 2 and 3: Insert "directly" after "(73° ± 18°F)" and insert "luminance" after "five-hour".

PAGE 14

*4.7.3.14: Add "The upper vibration frequency limit shall be 33 Hz." after the last sentence in the paragraph.

The margins of this amendment are marked with an asterisk to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the pase previous amendment.

Preparing Activity
NAVY - AS
(Project 1710-N040)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T10:35Z
Check the source to verify that this is the current version before use.