MIL-P-63066(AR)
AMENDMENT 4
10 November 1983
SUPERSEDING
AMENDMENT 3
28 April 1983

MILITARY SPECIFICATION

PROJECTILE, 155MM, SPECIAL TEST, FOR
M692 and M731 LOADING, ASSEMBLING AND PACKING OF

This amendment forms a part of Military Specification MIL-P-63066(PA), dated 1 June 1976, and is approved for use by the US Army Armament, Munitions and Chemical Command and is available for use by all Departments and Agencies of the Department of Defense.

PAGE 4

3.10: Add the following paragraph:

"3.10: Radiographic examination for Kill Mechanism. The loaded projectile shall be radiographically examined to show the absence of a Kill Mechanism in all mines contained within the projectile as specified in 4.5.9."

PAGE 9

4.4.2.1: Delete paragraph 4.4.2.1 in its entirety.

PAGE 10

4.4.2.2: Delete paragraph 4.4.2.2 in its entirety.

PAGE 11

4.4.2.3: Delete this paragraph and insert new paragraph 4.4.2.3 (Page 11).

* 4.4.2.3: Delete "Drawing Number 9298350" to "Drawing Number 10542902-3".

PAGE 13

4.4.2.5: Delete this paragraph and insert new paragraph 4.4.2.5 (Page 13).

FSC 1320

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

PAGE 16

* 4.4.2.7: Delete "Drawing Number 9298350" to "Drawing Number 10542902-3".

PAGE 18

4.4.2.9: Add the following:

"108 - Marking missing or incorrect - 0.40% - 3.2 - Visual"

4.4.2.16: Delete this paragraph and insert new paragraph 4.4.2.16 (Page 25).

PAGE 30

* 4.4.2.21: Delete in its entirety and replace with new page 30 included Page 6.

PAGE 31

4.4.2.22: Delete this paragraph and insert new paragraph 4.4.2.22 (Page 31).

PAGE 32

* 4.4.2.23: Delete in its entirety and replace with new page 32 included Page 8.

PAGE 41

4.5.9: Add the following paragraph:

"4.5.9: Radiographic Examination of Projectile for Kill Mechanism. The projectile shall be radiographically examined with multiple views as required to positively determine the absence of a Kill Mechanism in all mines within the test projectile. Any Projectile containing a Kill Mechanism shall not be used for firings and the results should be reported immediately to the technical agency listed in 6.6."

PAGE 42

* 6.7: Submission of plans for approval, delete "Picatinny Arsenal, ATTN: SARPA-QA-A-S" and substitute "US Army Armament Research and Development Center, ATTN: DRSMC-QAT-M(D)".

Custodian: Delete "PA" and substitute "AR".

Preparing activity: Delete "PA" and substitute "AR".

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.3	Housing, Timing and Fuzing (Prior to assembly of inert filler)				9298450
					NEXT HIGHER ASSEMBLY
					9298399
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Special					
a.	Barrier assembly not present or not properly positioned in S&A		100%	3.2	X-Ray
Major					
101	Shorting bar broken or damaged		100%	3.2	Visual
102	Battery ball depressed below normal position		100%	3.2	Gage
103	Foreign material in kill mechanism cavity		0.40%	3.2	Visual
104	Largest diameter in kill mechanism cavity not prepared for bonding		0.40%	3.2	Visual
105	Sensor plug(s) missing or damaged		0.40%	3.2	Visual
Minor					
201	Poor workmanship		1.0%	3.8	Visual

NOTES:

(11)

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET	DRAWING NUMBER
4.4.2.5	Special Test Mine (prior to final assembly of the mine)	1 OF 1	9298399
			NEXT HIGHER ASSEMBLY: 9298399

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1.	Presence of Kill Mechanism and Overlay Assembly		100%	3.2	Visual
Major 101	Housing not marked to indicate inert filler		100%	3.2	Visual
Minor 201	Poor workmanship		1.0%	3.8	Visual

NOTES:

4 (13)

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET		DRAWING NUMBER
4.4.2.16	Projectile (immediately after assembly of ogive and prior to assembly of charge and sleeve assembly)		1 OF 1		9298319
					NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical 1	Marking or paint color incorrect		100%	3.2	Visual
Major 101	Gap between body and ogive beyond specified limits		100%	3.2	Gage
102	Concentricity of ogive to bourrelets (2 places)		100%	3.2	Gage
103	Radiographic Examination (Column segments not axially aligned)		100%	3.4	4.5.5
Minor 201	Poor workmanship		1.0%	3.8	Visual

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

(25)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.21	Projectile (after assembly of charge and sleeve assembly and prior to assembly of lifting plug)				9298319
					NEXT HIGHER ASSEMBLY 9298319
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Weight		100%	3.2	4.5.6
102	Retaining ring missing or improperly assembled		0.40%	3.2	Visual
103	Foreign matter in fuze cavity		0.40%	3.2	Visual
104	Lifting plug threads not greased		0.40%	3.2	Visual
105	Threads damaged		0.40%	3.2	Visual
106	Weight marking missing or incorrect		0.40%	3.2	Visual
107	Lifting plug or gasket missing or damaged		100%	3.2	Visual
Minor					
201	Evidence of poor workmanship		0.65%	3.8	Visual

NOTES:

DRSMC-QA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 20261023T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE	SHEET 1 OF 1	DRAWING NUMBER
4.4.2.22	Projectile (prior to assembly of grommet)		9298319
			NEXT HIGHER ASSEMBLY 9298319

CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical					
1	Presence of Kill Mechanism		100%	3.10	X-Ray
Major					
101	Lifting plug turns when disassembly torque is applied		0.40%	3.2	Test
102	Diameter of bourrelet, max (applicable after retouching paint)		0.40%	3.2	Gage
103	Rotating band damaged		0.40%	3.2	Visual
104	Obturator missing or damaged		0.40%	3.2	Visual
105	Stamped letter "A" missing from ogive (indicating air pressure test failure)		0.40%	3.2	Visual
106	Ballistic functioning test (High Zone)	1 Rd		3.3	4.5.7
107	Base metal of base plug exposed		100%	3.2	Visual
Minor					
201	Protective coating with a total of bare areas in excess of 1/4 square inch		0.65%	3.2	Visual
202	Marking missing or unidentifiable		0.65%	3.2	Visual
203	Poor workmanship		1.0%	3.8	Visual

NOTES:

(31)

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

CLASSIFICATION OF DEFECTS & TESTS

PARAGRAPH	TITLE		SHEET 1 OF 1		DRAWING NUMBER
4.4.2.23	Pallet (loaded)				8837839
					NEXT HIGHER ASSEMBLY: --
CATEGORY	EXAMINATION OR TEST	NO. OF SAMPLE UNITS	AQL OR 100%	REQUIREMENT PARAGRAPH	PARAGRAPH REFERENCE /INSPECTION METHOD
Critical	None defined				
Major					
101	Projectile lifting plug missing or damaged, or wrong type (not fusible)		0.40%	3.2	Visual
102	Projectile grommet assembly missing, damaged, or improperly assembled		0.40%	3.2	Visual
103	Board broken or split		0.40%	3.2	Visual
104	Cover support missing (8 places)		100%	3.2	Visual
Minor					
201	Strap width incorrect		0.65%	3.2	Visual
202	Strapping improperly assembled		0.65%	3.2	Visual
203	Marking missing, incorrect or unidentified		0.65%	3.2	Visual

NOTES:

DRSMC-OA (D) Form 160, 1 Aug 83 replaces edition of 1 Jul 77 which may be used until exhausted.

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.

The margins of this amendment are marked with an asterisk or vertical lines to indicate where changes (additions, modifications, corrections, deletions) from the previous amendment were made. This was done as a convenience only and the Government assumes no liability whatsoever for any inaccuracies in these notations. Bidders and contractors are cautioned to evaluate the requirements of this document based on the entire content irrespective of the marginal notations and relationship to the previous amendment."

Custodian:
Army-AR

Preparing activity:
Army-AR

(Project 1320-A769)

Source: https://assist.dla.mil -- Downloaded: 2026-10-23T02:09Z
Check the source to verify that this is the current version before use.