QUALIFICATIONS CERTIFIED
JUNE 1987

QPL-7885-23
4 October 992
SUPERSEDING
QPL-7885-22
3 May 1989

QUALIFIED PRODUCTS LIST

OF FSC 5320

PRODUCTS QUALIFIED UNDER MILITARY SPECIFICATION

MIL-R-7885

RIVETS: BLIND, STRUCTURAL, PULL-STEM, AND CHEMICALLY EXPANDED

This list has been prepared for use by or for the Government in the acquisition of products covered by the subject specification and such listing of a product is not Intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

THE ACTIVITY RESPONSIBLE FOR THIS QUALIFIED PRODUCTS LIST IS THE NAVAL AIR SYSTEMS COMMAND (ATTENTION: COMMANDING OFFICER, NAVAL AIR WARFARE CENTER AIRCRAFT DIVISION LAKEHURST, SYSTEMS REQUIREMENT DEPARTMENT, CODE SR3, LAKEHURST, NJ 08733-5100)

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI- CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS20600 Rivet, Blind, Structural Pull Stem, Self-Plugging, Protruding Head, Type 11			
MS20600B4W(1-6) MS20600B5W(1-8) MS20600B6W(1-12) MS20600B8W(3-14)	MS20600B4W(l-6) MS20600B5W(1-8) MS20600B6W(1-2) MS20600B8W(3-14	BuAer ltr AE-6333/144 of 25 Feb 1958	Huck Mfg. Co. 8001 Imperial Drive Waco, TX 76714-8117 Plant: Same address and 3724 East Columbia St. Tucson, AZ 85714
MS20600AD4W(1-6) MS20600AD5W(1-8) MS20600AD6W(1-12) MS20600AD8W(3-14)	MS20600AD4W(1-6) MS20600AD5W(1-8) MS20600AD6W(1-12) MS20600AD8W(3-14)	BuAer ltr AE-6333/135 of 7 Feb 1958	

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS20600AD4W(1-6)	RV200-4-(1-6)	BuAer ltr AE-6333/133 of 11 Feb 1958	Olympic Fastening Systems, Inc. 11445 Dolan Ave. Downey, CA 90241 Plant: Same address
MS20600AD5W(1-8)	RV200-5-(1-8)		
MS20600AD6W(1-12)	RV200-6-(1-12)		
MS20600AD8W(3-14)	RV200-8-(3-14)		
MS20600B4W(1-6)	RV250-4-(1-6)		
MS20600B5W(1-8)	RV250-5-(1-8)		
MS20600B6W(1-12)	RV250-6-(1-12)		
MS20600B8W(3-14)	RV250-8-(3-14)		
MS20600M4W(1-6)	RV290-4-(1-6)B		
MS20600M5W(1-8)	RV290-5-(1-8)B		
MS20600146W(1-12)	RV290-6-(1-12)B		
MS20600M8W(3-14)	RV290-8-(3-14)B		
MS20600MP4W(1-6)	RV290-4-(1-6)		
MS20600MP5W(1-8)	RV290-5-(1-8)		
MS20600MP6W(1-12)	RV290-6-(1-12)		
MS20600MP8W(3-14)	RV290-8-(3-14)		
MS20600AD4W(1-6)	CR9163-4-(1-6)	Report No. AML-22046/60 of 10 Dec 1959	Cherry Textron, Cher Aerospace Operation Cherry Division of Textron, Inc. P.O. BOX 2157 1224 East Harrier Ave. Santa Aria, CA 92707-0157 Plant: Same address
MS20600AD5W(1-8)	CR9163-5-(1-8)		
MS20600AD6W(1-12)	CR9163-6-(1-12)		
MS20600AD8W(3-14)	CR9163-8-(3-14)		
MS20600B4W(1-6)	CR9157-4-(1-6)		
MS20600B5W(1-8)	CR9157-5-(1-8)		
MS20600B6W(1-12)	CR9157-6-(1-12)		
MS20600B8W(3-14)	CR9157-8-(3-14)		
MS20600M4W(1-6)	CR9563R-4-(1-6)		
MS20600M5W(1-8)	CR9563R-5-(1-8)		
MS20600M6W(1-12)	CR9563R-6-(1-12)		
MS20600M8W(3-14)	CR9563R-8-(3-14)		
MS20600MP4W(1-6)	CR9563-4-(1-6)		
MS20600MP5W(1-8)	CR9563-5-(1-8)		
MS20600MP6W(1-12)	CR9563-6-(1-12)		
MS20600MP8W(3-14)	CR9563-8-(3-14)		
MS20600AD4W	AF6000-4	305Q77033	Allfast Fastening Systems, Inc. 15200 Don Julian Road P.O. BOX 3166 City of Industry, CA 91745-1098 Plant: Same address
MS20600B4W	AF6050-4		
MS20600M4W	AF6090-4		
MS20600MP4W	AF6090-4C		
MS20600AD5W	AF6000-5		
MS20600B5W	AF6050-5		
MS20600M5W	AF6090-5		
MS20600MP5W	AF6090-5C		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS20600AD6W	AF6C0O0-6	305Q77033	Allfast Fastening Systems, Inc. (Cent'd)
MS20600B6W	AF6050-6		
MS20600M6W	AF6090-6		
MS20600MP6W	AF6090-6C		
MS20600AD8W	AF6000-8		
MS20600B8W	AF6050-8		
MS20600M8W	AF6090-8		
MS20600MP8W	AF6090-8C		
MS20601 **Rivet, Blind, Structural Pull Stem, Self-Plugging, 100° Flush Head, Type II**			
MS20601B4W(1-6)	**MS20601B4W(1-6)**	**BuAer ltr**	**Huck Manufacturing**
MS20601B5W(2-8)	**MS20601B5W(2-8)**	**AE-6333/144**	**8001 Imperial Drive**
MS20601B6W(2-12)	**MS20601B6W(2-12)**	**of 25 Feb 1958**	**Waco, TX 76714-8117**
MS20601B8W(3-14)	**MS20601B8W(3-14)**		**Plant:** Same address and 3724 East Columbia St. **Tucson, AZ 85714**
MS20601AD4W(1-6)	MS20601AD4W(1-6)	BuAer ltr	
MS20601AD5W(2-8)	MS20601AD5W(2-8)	AE-6333/135	
MSS20601AD6W(2-12)	**MS20601AD6W(2-12)**	**of 7 Feb 1958**	
MS20601AD8W(3-14)	**MS20601AD8W(3-14)**		
MS20601AD4W(1-6)	**RV201-4-(1-6)**	**BuAer ltr**	**Olympic Fastening Systems,** Inc.
MS20601AD5W(2-8)	**RV201-5-(2-8)**	**AE-6333/133**	**11445** Dolan Ave.
MS20601AD6W(2-12)	**RV201-6-(2-12)**	**of 11 Feb 1958**	**Downey, CA 90241**
MS20601AD8W(3-14)	**RV201-8-(3-14)**		
MS20601B4W(1-6)	RV251-4-(1-6)		Plant: Same address
MS20601B5W(2-8)	**RV251-5-(2-8)**		
MS20601B6W(2-12)	**RV251-6-(2-12)**		
MS20601B8W(3-14)	**RV251-8-(3-14)**		
MS20601M4W(1-6)	**RV291-4-(1-6)B**		
MS20601M5W(2-8)	**RV291-5-(2-8)B**		
MS20601M6W(2-12)	**RV291-6-(2-12)B**		
MS20601M8W(3-14)	**RV291-8-(3-14)B**		
MS20601MP4W(1-6)	**RV291-4-(1-6)**		
MS20601MP5W(2-8)	**RV291-5-(2-8)**		
MS20601MP6W(2-12)	**RV291-6-(2-12)**		
MS20601MP8W(3-14)	**RV291-8-(3-14)**		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
MS20601AD4W(1-6) MS20601AD5W(2-8) MS20601AD6W(2-12) MS20601AD8W(3-14) MS20601B4W(1-6) MS20601B5W(2-8) MS20601B6W(2-12) MS20601B8W(3-14) MS20601M4W(1-6) MS20601M5W(2-8) MS20601M6W(2-12) MS20601M8W(3-14) MS20601MP4W(1-6) MS20601MP5W(2-8) MS20601MP6W(2-12) MS20601MP8W(3-14)	CR9162-4-(1-6) CR9162-5-(2-8) CR9162-6-(2-12) CR9162-8-(3-14) CR9156-4-(1-6) CR9156-5-(2-8) CR9156-6-(2-12) CR9156-8-(3-14) CR9562R-4-(1-6) CR9562R-5-(2-8) CR9562R-6-(2-12) CR9562R-8-(3-14) CR9562-4-(1-6) CR9562-5-(2-8) CR9562-6-(2-12) CR9562-8-(3-14)	Report No. AML 22046/60 of 10 Dec 1959	Cherry Textron, Cherry Aerospace Operations, Cherry Division of Textron, Inc. P.O. Box 2157 1224 E. Harrier Ave. Santa Ana, CA 92707-0157 Plant: Same address
MS20601AD4W MS20601B4W MS20601M4W MS20601MP4W MS20601AD5W MS20601B5W MS20601M5W MS20601MP5W MS20601AD6W MS20601B6W MS20601M6W MS20601MP6W MS20601AD8W MS20601B8W MS20601M8W MS20601MP8W	AF6001-4 AF6051-4 AF6091-4 AF6091-4C AF6001-5 AF6051-5 AF6091-5 AF6091-5C AF6001-6 AF6051-6 AF6091-6 AF6091-6C AF6001-8 AF6051-8 AF6091-8 AF6091-8C	305Q77033	Allfast Fastening Systems, Inc. 15200 Don Julian Road P.O. BOX 3166 City of Industry, CA 91745-1098 Plant: Same address
MS7885/6-4 MS7885/6-5 M7885/6-6 M788517-4 M788517-5 M788517-6	CR3243-4 CR3243-5 CR3243-6 CR3242-4 CR3242-5 CR3242-6	Report No. 305Q82080 of 6 Aug 1982	Cherry Textron, Cherry Aerospace Operations, Cherry Division of Textron, Inc. P.O. 80X 2157 1224 East Warner Ave Santa Ana, CA 9270 Plant: Same address
M788512-4 M788512-5 M788512-6	CR3213-4 CR3213-5 CR3213-6	Report No. 601Q8405 of 13 Mar 1984	

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
M7885/3-4 M7885/3-5 M7885/3-6	CR3212-4 CR3212-5 CR3212-6	Report No. 601Q8405 of 13 Mar 1984	Cherry Textron, Cherry Aerospace Operations, (Cent'd)
M7885/2-4 M7885/2-5 M7885/2-6	CR3213-4 CR3213-5 CR3213-6	Report No. 601Q8410 of 18 Jun 1984	Voi-Shan mfg. Co. 8463 Higuera Street Culver City, CA 90230
M7885/3-4 M7885/3-5 M7885/3-6	CR3212-4 CR3212-5 CR3212-6		Plant: 4001 Inglewood Ave. Redondo Beach, CA 90278
M7885/6-4 M7885/6-5 M7885/6-6	CR3243-4 CR3243-5 CR3243-6		
M7885/7-4 M7885/7-5 M7885/7-6	CR3242-4 CR3242-5 CR3242-6		
M7885/6-5 M7885/6-6 M7885/7-5 M7885/7-6	OHCP-B05 OHCP-B06 OHCF-B05 OHCF-B06	Report No. 601Q8515 of 7 Ott 1985	Huck Manufacturing Co. A Subsidiary of Federal-Mogul 900 Watson Center Road Carson, CA 90745
M7885/6-4 M7885/7-4	OHCP-B04 OHCF-B04	Report No. 601Q8702 of 26 Jan 1987	Plant: Same Address and 3724 East Columbia St. Tucson, AZ 85714
M7885/2-4 M7885/2-5 M7885/2-6	HC3213-4 HC3213-5 HC3213-6	Report No. 601Q9201 of 13 Jan 1992	
M7885/3-4 M7885/3-5 M7885/3-6	HC3212-4 HC3212-5 HC3212-6		
M7885/6-4 M7885/7-4	AF3243-4 AF3242-4	Report No. 601Q8610 of 12 Sep 1986	Allfast Fastening Systems, Inc. 15200 Don Julian Rd. P.O. Box 3166 City of Industry, CA 91745-1098 Plant: Same address

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION	TEST OR QUALIFICATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
M7885/2-5	AFC3213-5	Report No. 601Q8709 of 18 Jun 1987	Allfast Fastening Systems, Inc. (Cent'd)
M7885/3-5	AFC3212-5		
M7885/6-5	AFC3243-5		
M7885/7-5	AFC3242-5		
M7885/8-4	AFC-3553-4	Report No. 601Q8721 of 9 Dec 1987	
M7885/8-5	AFC-3553-5		
M7885/8-6	AFC-3553-6		
M7885/9-4	AFC-3552-4		
M7885/9-5	AFC-3552-5		
M7885/9-6	AFC-3552-6		
M7885/4-4	AF3523-4	Report No. 601Q8901 of 5 Jan 1989	
M7885/4-5	AF3523-5		
M7885/4-6	AF3523-6		
M7885/5-4	AF3522-4		
M7885/5-5	AF3522-5		
M7885/5-6	AF3522-6		
M7885/8-4	AF3553-4		
M7885/8-5	AF3553-5		
M7885/8-6	AF3553-6		
M7885/9-4	AF3552-4		
M7885/9-5	AF3552-5		
M7885/9-6	AF3552-6		
M7885/2-4	AF3213-4	Report No. 601Q8902 of 9 Jan 1989	
M7885/2-5	AF3213-5		
M7885/2-6	AF3213-6		
M7885/3-4	AF3212-4		
M7885/3-5	AF3212-5		
M7885/3-6	AF3212-6		
M7885/6-4	AF3243-4		
M7885/6-5	AF3243-5		
M7885/6-6	AF3243-6		
M7885/7-4	AF3242-4		
M7885/7-5	AF3242-5		
M7885/7-6	AF3242-6		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.

GOVERNMENT DESIGNATION	MANUFACTURER' S DESIGNATION	TEST OR QUALIFI-CATION REFERENCE	MANUFACTURER'S NAME AND ADDRESS
M7885/6-4	**CR3243-04**	**Report No.**	**John Hassall** Inc.
M7885/6-5	CR3243-05	601Q9215 of	Cantiague Rock Road
M7885/6-6	CR3243-06	14 Sept 1992	Westbury, NY 11590
M7885/7-4	**CR3242-04**		**Plant: Same Address**
M7885/7-5	**CR3242-05**		
M7885/7-6	**CR3242-06**		

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T13:07Z
Check the source to verify that this is the current version before use.