ADOPTION NOTICE

ANSI-Z1.1,1.2,1.3, "GUIDE FOR QUALITY CONTROL CHARTS, CONTROL CHART METHOD OF ANALYZING DATA, CONTROL CHART OF METHOD OF CONTROLLING QUALITY DURING PRODUCTION", was adopted on 13-MAR-89 for use by the Department of Defense (DoD). Proposed changes by DoD activities must be submitted to the DoD Adopting Activity: Commander, U.S. Army TACOM-ARDEC, ATTN: AMSTA-AR-QAW-E, Picatinny Arsenal, NJ 07806-5000. Copies of this document may be purchased from the American National Standards Institute 25 West 43rd Street, 4th Fl. New York, New York, United States, 20036. http://web.ansi.org/

Custodians:
Army - AR
Air Force - 05
DLA - DH

Adopting Activity:
Army - AR

Reviewer Activities:
Army - CR

AREA QCIC

DISTRIBUTION STATEMENT A: Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-26T15:04Z
Check the source to verify that this is the current version before use.