MILITARY SPECIFICATION

GAGE, PRESSURE, DIAL INDICATING

This amendment forms a part of MIL-G-8170D, dated 21 April 1987, and is approved for use by all Departments and Agencies of the Department of Defense.

PAGE 3

3.2 Line 2 delete "document" and add: "documents".

Change "4.3.2.1" to "3.4.2.1".

PAGE 5

Delete "4.3" in its entirety and add new:

"4.3 Inspections conditions. Unless otherwise specified, all test conditions and standards shall be per ANSI-B40.1 section 6."

Delete "4.4.1" in its entirety and add new:

"4.4.1 First article tests. First articles tests shall be per ANSI-B40.1 Appendix A, as modified by table III. The repeatability and rupture tests may be omitted. Test procedures and tolerances shall be per table I and table II.

Add: 4.4.2 First article samples. Three gages, identical to production units, shall be subjected to the first article tests. Proof pressure tested or fatigue tested gages shall be identified as such and are unacceptable for sale to the Government".

PAGE 6

Delete "4.5.1" in its entirety and add new:

"4.5.1 Individual tests. Each gage submitted for acceptance under contract shall be subjected to the individual tests. These tests shall consist of the accuracy, hysteresis, friction, and position error tests per ANSI-B40.1 Appendix A. Test procedures and tolerances shall be per table I and table II".

Delete "4.5.2" in its entirety and add new:

"4.5.2 Sampling tests. The sampling tests shall consist of all first article tests excluding the proof pressure and fatigue tests. A minimum sample of 5 out of each 100 (or less) gages produced shall be subjected to the sampling tests".

Delete Tables II and III and add new:

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited.

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T09:58Z
Check the source to verify that this is the current version before use.

TABLE II. Position error, vibration, proof pressure, and hysteresis.

Test	Test Pressure (psi)	Tolerances
Position error	100	2.0
Vibration error	100	---
Pointer oscillation	---	4.0
Pointer variation	---	3.0
Proof pressure	600	3.0
Hysteresis	TABLE I	TABLE I

TABLE III. Test Parameters.

Parameter	Value
Maximum operating temperature	71°C
Minimum operating temperature	-54°C
Maximum storage temperature	85°C
Minimum storage temperature	-65°C
Proof pressure	600 psi

Custodian:
AIR FORCE -99
NAVY -AS

Preparing activity:
AIR FORCE -71

Project No.
6620-0460

Source: https://assist.dla.mil -- Downloaded: 2026-10-17T09:58Z
Check the source to verify that this is the current version before use.